

Draft + FINAL

Phase I Environmental Baseline Survey

**of
Naval Weapons Industrial Reserve Plant
Bethpage, New York**



**Northern Division
Naval Facilities Engineering Command
Contract Number N62472-90-D-1298
Contract Task Order 0283**

Volume II - Appendices

October 1997

**CF Braun
Engineering Corporation**

651446



**Final
Phase I Environmental
Baseline Survey**

of

**Naval Weapons Industrial Reserve Plant
Bethpage, New York**



**Northern Division
Naval Facilities Engineering Command
Contract Number N62472-90-D-1298
Contract Task Order 0283**

Volume II - Appendices

January 1998

**CF Braun
Engineering Corporation**

APPENDIX A

EXECUTIVE SUMMARY TO EDR REPORT

The EDR Area Study Report

Study Area
NWIRP Bethpage -Northrup Grumman Corp.
Bethage, New York

April 28, 1997

Inquiry number 172329.1s

EDR Environmental
Data
Resources, Inc.
Creators of Toxicheck®

The Source **For Environmental Risk Management Data**

3530 Post Road
Southport, Connecticut 06490

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

To maintain currency of the following federal and state databases, EDR contacts the appropriate governmental agency on a monthly or quarterly basis, as required.

Elapsed ASTM days: Provides confirmation that this EDR report meets or exceeds the 90-day updating requirement of the ASTM standard.

FEDERAL ASTM RECORDS:

CERCLIS: Comprehensive Environmental Response, Compensation, and Liability Information System

Source: EPA/NTIS

Telephone: 703-603-8904

CERCLIS: CERCLIS contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA). CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

Date of Government Version: 12/31/96

Date Made Active at EDR: 03/03/97

Database Release Frequency: Monthly

Date of Data Arrival at EDR: 01/16/97

Elapsed ASTM days: 46

Date of Last EDR Contact: 04/07/97

ERNS: Emergency Response Notification System

Source: EPA/NTIS

Telephone: 202-260-2342

ERNS: Emergency Response Notification System. ERNS records and stores information on reported releases of oil and hazardous substances.

Date of Government Version: 12/31/96

Date Made Active at EDR: 03/18/97

Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 02/05/97

Elapsed ASTM days: 41

Date of Last EDR Contact: 04/07/97

NPL: National Priority List

Source: EPA

Telephone: 703-603-8852

NPL: National Priorities List (Superfund). The NPL is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund Program. NPL sites may encompass relatively large areas. As such, EDR provides polygon coverage for over 1,000 NPL site boundaries produced by EPA's Environmental Photographic Interpretation Center (EPIC).

Date of Government Version: 12/01/96

Date Made Active at EDR: 03/03/97

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 01/08/97

Elapsed ASTM days: 54

Date of Last EDR Contact: 04/03/97

RCRIS: Resource Conservation and Recovery Information System

Source: EPA/NTIS

Telephone: 703-308-7907

RCRIS: Resource Conservation and Recovery Information System. RCRIS includes selective information on sites which generate, transport, store, treat and/or dispose of hazardous waste as defined by the Resource Conservation and Recovery Act (RCRA).

Date of Government Version: 10/31/96

Date Made Active at EDR: 03/03/97

Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 01/09/97

Elapsed ASTM days: 53

Date of Last EDR Contact: 02/27/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

FEDERAL NON-ASTM RECORDS:

CONSENT: Superfund (CERCLA) Consent Decrees

Source: EPA Regional Offices

Telephone: Varies

Major legal settlements that establish responsibility and standards for cleanup at NPL (Superfund) sites. Released periodically by United States District Courts after settlement by parties to litigation matters.

Date of Government Version: Varies

Database Release Frequency: Varies

Date of Last EDR Contact: Varies

Date of Next Scheduled EDR Contact: 09/01/95

CORRACTS: Corrective Action Report

Source: EPA

Telephone: 703-308-7907

CORRACTS: CORRACTS identifies hazardous waste handlers with RCRA corrective action activity.

Date of Government Version: 12/01/96

Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 04/07/97

Date of Next Scheduled EDR Contact: 07/07/97

FINDS: Facility Index System

Source: EPA/NTIS

Telephone: 703-908-2493

FINDS: Facility Index System. FINDS contains both facility information and "pointers" to other sources that contain more detail. EDR includes the following FINDS databases in this report: PCS (Permit Compliance System), AIRS (Aerometric Information Retrieval System), DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes), FURS (Federal Underground Injection Control), C-DOCKET (Criminal Docket System used to track criminal enforcement actions for all environmental statutes), FFIS (Federal Facilities Information System), STATE (State Environmental Laws and Statutes), and PADS (PCB Activity Data System).

Date of Government Version: 09/30/95

Database Release Frequency: Quarterly

Date of Last EDR Contact: 12/30/96

Date of Next Scheduled EDR Contact: 07/07/97

HMIRS: Hazardous Materials Information Reporting System

Source: U.S. Department of Transportation

Telephone: 202-366-4555

HMIRS: Hazardous Materials Incident Report System. HMIRS contains hazardous material spill incidents reported to DOT.

Date of Government Version: 12/31/95

Database Release Frequency: Annually

Date of Last EDR Contact: 01/27/97

Date of Next Scheduled EDR Contact: 04/28/97

MLTS: Material Licensing Tracking System

Source: Nuclear Regulatory Commission

Telephone: 301-415-7169

MLTS is maintained by the Nuclear Regulatory Commission and contains a list of approximately 8,100 sites which possess or use radioactive materials and which are subject to NRC licensing requirements. To maintain currency, EDR contacts the Agency on a quarterly basis.

Date of Government Version: 02/13/96

Database Release Frequency: Quarterly

Date of Last EDR Contact: 04/14/97

Date of Next Scheduled EDR Contact: 07/14/97

NPL LIENS: Federal Superfund Liens

Source: EPA

Telephone: 205-564-4267

NPL LIENS: Federal Superfund Liens. Under the authority granted the USEPA by the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA) of 1980, the USEPA has the authority to file liens against real property in order to recover remedial action expenditures or when the property owner receives notification of potential liability. USEPA compiles a listing of filed notices of Superfund Liens.

Date of Government Version: 10/15/91

Database Release Frequency: No Update Planned

Date of Last EDR Contact: 03/03/97

Date of Next Scheduled EDR Contact: 05/26/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

PADS: PCB Activity Database System

Source: EPA

Telephone: 202-260-3992

PADS: PCB Activity Database. PADS identifies generators, transporters, commercial storers and/or brokers and disposers of PCB's who are required to notify the EPA of such activities.

Date of Government Version: 08/26/96

Database Release Frequency: Semi-Annually

Date of Last EDR Contact: 01/02/97

Date of Next Scheduled EDR Contact: 05/19/97

RAATS: RCRA Administrative Action Tracking System

Source: EPA

Telephone: 202-564-4104

RAATS: RCRA Administration Action Tracking System. RAATS contains records based on enforcement actions issued under RCRA pertaining to major violators and includes administrative and civil actions brought by the EPA. For administration actions after September 30, 1995, data entry in the RAATS database was discontinued. EPA will retain a copy of the database for historical records. It was necessary to terminate RAATS because a decrease in agency resources made it impossible to continue to update the information contained in the database.

Date of Government Version: 04/17/95

Database Release Frequency: N/A

Date of Last EDR Contact: 03/18/97

Date of Next Scheduled EDR Contact: 06/16/97

ROD: Records Of Decision

Source: NTIS

Telephone: 703-416-0703

Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid in the cleanup.

Date of Government Version: 03/31/95

Database Release Frequency: Annually

Date of Last EDR Contact: 03/05/97

Date of Next Scheduled EDR Contact: 06/02/97

TRIS: Toxic Chemical Release Inventory System

Source: EPA/NTIS

Telephone: 202-260-2320

TRIS: Toxic Release Inventory System. TRIS identifies facilities which release toxic chemicals to the air, water and land in reportable quantities under SARA Title III Section 313.

Date of Government Version: 12/31/92

Database Release Frequency: Annually

Date of Last EDR Contact: 03/04/97

Date of Next Scheduled EDR Contact: 06/30/97

TSCA: Toxic Substances Control Act

Source: EPA/NTIS

Telephone: 202-260-1444

TSCA: Toxic Substances Control Act. TSCA identifies manufacturers and importers of chemical substances included on the TSCA Chemical Substance Inventory list. It includes data on the production volume of these substances by plant site. USEPA has no current plan to update and/or re-issue this database.

Date of Government Version: 01/31/95

Database Release Frequency: Annually

Date of Last EDR Contact: 03/21/97

Date of Next Scheduled EDR Contact: 06/16/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

STATE OF NEW YORK ASTM RECORDS:

LUST: Spills Information Database

Source: Department of Environmental Conservation
Telephone: 518-457-2462

LUST: Leaking Underground Storage Tank Incident Reports. LUST records contain an inventory of reported leaking underground storage tank incidents. Not all states maintain these records, and the information stored varies by state.

Date of Government Version: 12/31/97
Date Made Active at EDR: 04/21/97
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 02/12/97
Elapsed ASTM days: 68
Date of Last EDR Contact: 01/27/97

SHWS: Inactive Hazardous Waste Disposal Sites in New York State

Source: Department of Environmental Conservation
Telephone: 518-457-0747

SHWS: State Hazardous Waste Sites. State hazardous waste site records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. Available information varies by state.

Date of Government Version: 04/30/96
Date Made Active at EDR: 06/06/96
Database Release Frequency: Annually

Date of Data Arrival at EDR: 05/06/96
Elapsed ASTM days: 31
Date of Last EDR Contact: 03/04/97

SWF/LF: Facility Register

Source: Department of Environmental Conservation
Telephone: 518-457-2051

SWF/LF: Solid Waste Facilities/Landfill Sites. SWF/LF type records typically contain an inventory of solid waste disposal facilities or landfills in a particular state. Depending on the state, these may be active or inactive facilities or open dumps that failed to meet RCRA Subtitle D Section 4004 criteria for solid waste landfills or disposal sites.

Date of Government Version: 12/31/96
Date Made Active at EDR: 04/21/97
Database Release Frequency: Semi-Annually

Date of Data Arrival at EDR: 02/20/97
Elapsed ASTM days: 60
Date of Last EDR Contact: 02/10/97

UST: Petroleum Bulk Storage (PBS, CBS, MOSF) Database (UST)

Source: Department of Environmental Conservation
Telephone: 518-457-4351

UST: Registered Underground Storage Tanks. UST's are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA) and must be registered with the state department responsible for administering the UST program. Available information varies by state program.

Date of Government Version: 12/31/96
Date Made Active at EDR: 04/07/97
Database Release Frequency: Quarterly

Date of Data Arrival at EDR: 02/18/97
Elapsed ASTM days: 48
Date of Last EDR Contact: 02/03/97

STATE OF NEW YORK NON-ASTM RECORDS:

AST: Petroleum Bulk Storage (AST)

Source: Department of Environmental Conservation
Telephone: 518-457-4351

AST: Registered Aboveground Storage Tanks.

Date of Government Version: 09/30/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 02/03/97
Date of Next Scheduled EDR Contact: 05/05/97

SPILLS: Spills Information Database

Source: Department of Environmental Conservation
Telephone: 518-457-2462

SPILLS: Data collected on spills reported to NYSDEC as required by one or more of the following: Article 12 of the Navigation Law, 6 NYCRR Section 613.8 (from PBS regs), or 6 NYCRR Section 595.2 (from CBS regs). It includes spills active as of April 1, 1986, as well as spills occurring since this date.

Date of Government Version: 12/31/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 01/27/97
Date of Next Scheduled EDR Contact: 04/28/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

NEW YORK COUNTY RECORDS

CORTLAND COUNTY:

Cortland County UST Listing (AST)

Source: Cortland County Health Department
Telephone: 607-753-5035

Date of Government Version: 11/15/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

Cortland County UST Listing (UST)

Source: Cortland County Health Department
Telephone: 607-753-5035

Date of Government Version: 11/15/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

NASSAU COUNTY:

NCPHO Article XI Database (AST)

Source: Nassau County Health Department
Telephone: 516-571-3314

Date of Government Version: 12/01/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

NCPHO Article XI Database (UST)

Source: Nassau County Health Department
Telephone: 516-571-3314

Date of Government Version: 02/04/97
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

ROCKLAND COUNTY:

Petroleum Bulk Storage Database (AST)

Source: Rockland County Health Department
Telephone: 914-364-2605

Date of Government Version: 12/18/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

Petroleum Bulk Storage Database (UST)

Source: Rockland County Health Department
Telephone: 914-364-2605

Date of Government Version: 12/18/96
Database Release Frequency: Quarterly

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

SUFFOLK COUNTY:

Underground Storage Tank Database (AST)

Source: Suffolk County Department of Health Services
Telephone: 516-854-2521

Date of Government Version: 03/01/96
Database Release Frequency: Annually

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Underground Storage Tank Database (UST)

Source: Suffolk County Department of Health Services
Telephone: 516-854-2521

Date of Government Version: 02/21/97
Database Release Frequency: Annually

Date of Last EDR Contact: 03/11/97
Date of Next Scheduled EDR Contact: 06/09/97

Historical and Other Database(s)

Depending on the geographic area covered by this report, the data provided in these specialty databases may or may not be complete. For example, the existence of wetlands information data in a specific report does not mean that all wetlands in the area covered by the report are included. Moreover, the absence of any reported wetlands information does not necessarily mean that wetlands do not exist in the area covered by the report.

Former Manufactured Gas (Coal Gas) Sites: The existence and location of Coal Gas sites is provided exclusively to EDR by Real Property Scan, Inc. ©Copyright 1993 Real Property Scan, Inc. For a technical description of the types of hazards which may be found at such sites, contact your EDR customer service representative.

Disclaimer Provided by Real Property Scan, Inc.

The information contained in this report has predominantly been obtained from publicly available sources produced by entities other than Real Property Scan. While reasonable steps have been taken to insure the accuracy of this report, Real Property Scan does not guarantee the accuracy of this report. Any liability on the part of Real Property Scan is strictly limited to a refund of the amount paid. No claim is made for the actual existence of toxins at any site. This report does not constitute a legal opinion.

DELISTED NPL: Delisted NPL Sites

Source: EPA
Telephone: 703-603-8769

DELISTED NPL: The National Oil and Hazardous Substances Pollution Contingency Plan (NCP) establishes the criteria that the EPA uses to delete sites from the NPL. In accordance with 40 CFR 300.425.(e), sites may be deleted from the NPL where no further response is appropriate.

NFRAP: No Further Remedial Action Planned

Source: EPA/NTIS
Telephone: 703-416-0702

NFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

FRDS: Federal Reporting Data System

Source: EPA/Office of Drinking Water
Telephone: 202-260-2805

FRDS provides information regarding public water supplies and their compliance with monitoring requirements, maximum contaminant levels (MCL's), and other requirements of the Safe Drinking Water Act of 1986.

Area Radon Information: The National Radon Database has been developed by the U.S. Environmental Protection Agency (USEPA) and is a compilation of the EPA/State Residential Radon Survey and the National Residential Radon Survey. The study covers the years 1986 - 1992. Where necessary data has been supplemented by information collected at private sources such as universities and research institutions.

GOVERNMENT RECORDS SEARCHED / DATA CURRENCY TRACKING

Oil/Gas Pipelines/Electrical Transmission Lines: This data was obtained by EDR from the USGS in 1994. It is referred to by USGS as GeoData Digital Line Graphs from 1:100,000-Scale Maps. It was extracted from the transportation category including some oil, but primarily gas pipelines and electrical transmission lines.

Sensitive Receptors: There are individuals who, due to their fragile immune systems, are deemed to be especially sensitive to environmental discharges. These typically include the elderly, the sick, and children. While the exact location of these sensitive receptors cannot be determined, EDR indicates those facilities, such as schools, hospitals, day care centers, and nursing homes, where sensitive receptors are likely to be located.

USGS Water Wells: In November 1971 the United States Geological Survey (USGS) implemented a national water resource information tracking system. This database contains descriptive information on sites where the USGS collects or has collected data on surface water and/or groundwater. The groundwater data includes information on more than 900,000 wells, springs, and other sources of groundwater.

Flood Zone Data: This data, available in select counties across the country, was obtained by EDR in 1994 from the Federal Emergency Management Agency (FEMA). Data depicts 100-year and 500-year flood zones as defined by FEMA.

Epicenters: World earthquake epicenters, Richter 5 or greater

Source: Department of Commerce, National Oceanic and Atmospheric Administration

Water Dams: National Inventory of Dams

Source: Federal Emergency Management Agency

Telephone: 202-646-2801

WATER DAMS: National computer database of more than 74,000 dams maintained by the Federal Emergency Management Agency.

New York Public Water Wells

Source: New York Department of Health

Telephone: 518-458-6731

EXECUTIVE SUMMARY

A search of available environmental records was conducted by Environmental Data Resources, Inc. (EDR).

The address of the subject property for which the search was intended is:

NWIRP BETHPAGE -NORTHRUP FRUMMAN CORP.
BETHAGE, NY 11714

No mapped sites were found in EDR's search of available ("reasonably ascertainable ") government records within the requested search area for the following Databases:

Delisted NPL:	NPL Deletions
SWF/LF:	Facility Register
RAATS:	RCRA Administrative Action Tracking System
HMIRS:	Hazardous Materials Information Reporting System
NPL Lien:	Federal Superfund Liens
TSCA:	Toxic Substances Control Act
MLTS:	Material Licensing Tracking System
CONSENT:	Superfund (CERCLA) Consent Decrees
Coal Gas:	Former Manufactured gas (Coal Gas) Sites.

Unmapped (orphan) sites are not considered in the foregoing analysis.

EXECUTIVE SUMMARY

Search Results:

Page numbers refer to the EDR Radius Map report where detailed data on individual sites be reviewed.

Sites listed in ***bold italics*** are in multiple databases.

NPL: Also known as Superfund, the National Priority List database is a subset of CERCLIS and identifies over 1,200 sites for priority cleanup under the Superfund program. The source of this database is the U.S. EPA.

A review of the NPL list, as provided by EDR, and dated 12/01/1996 has revealed that there is 1 NPL site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<i>RUCO POLYMER CORP</i>	<i>NEW SOUTH RD</i>	<i>0</i>	<i>2</i>

RCRIS: The Resource Conservation and Recovery Act database includes selected information on sites that generate, store, treat, or dispose of hazardous waste as defined by the Act. The source of this database is the U.S. EPA.

A review of the RCRIS-TSD list, as provided by EDR, and dated 10/31/1996 has revealed that there are 2 RCRIS-TSD sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<i>LILCO HICKSVILLE OP. CENTER</i>	<i>175 E OLD COUNTRY ROAD</i>	<i>57</i>	<i>53</i>
<i>GRUMMAN AEROSPACE CORP</i>	<i>S OYSTER BAY RD</i>	<i>231</i>	<i>461</i>

SHWS: The State Hazardous Waste Sites records are the states' equivalent to CERCLIS. These sites may or may not already be listed on the federal CERCLIS list. Priority sites planned for cleanup using state funds (state equivalent of Superfund) are identified along with sites where cleanup will be paid for by potentially responsible parties. The data comes from the Department of Environmental Conservation's Inactive Hazardous waste Disposal Sites in New York State.

A review of the SHWS list, as provided by EDR, and dated 04/30/1996 has revealed that there are 2 SHWS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
<i>GRUMMAN AEROSPACE-BETHPAGE FAC</i>	<i>STEWART AVENUE</i>	<i>66</i>	<i>68</i>
<i>RUCO POLYMER CORP. (HOOKER CHE</i>	<i>NEW SOUTH ROAD</i>	<i>89</i>	<i>140</i>

CERCLIS: The Comprehensive Environmental Response, Compensation and Liability Information System contains data on potentially hazardous waste sites that have been reported to the USEPA by states, municipalities, private companies and private persons, pursuant to Section 103 of the Comprehensive Environmental Response, Compensation and Liability Act (CERCLA).

CERCLIS contains sites which are either proposed to or on the National Priorities List (NPL) and sites which are in the screening and assessment phase for possible inclusion on the NPL.

A review of the CERCLIS list, as provided by EDR, and dated 12/31/1996 has revealed that there are 2 CERCLIS sites within the searched area.

EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
RUCO POLYMER CORP	NEW SOUTH RD	0	2
SERVO CORP OF AMERICA	111 NEW S RD	63	61

CERCLIS-NFRAP: As of February 1995, CERCLIS sites designated "No Further Remedial Action Planned" (NFRAP) have been removed from CERCLIS. NFRAP sites may be sites where, following an initial investigation, no contamination was found, contamination was removed quickly without the need for the site to be placed on the NPL, or the contamination was not serious enough to require Federal Superfund Action or NPL consideration. EPA has removed approximately 25,000 NFRAP sites to lift the unintended barriers to the redevelopment of these properties and has archived them as historical records so EPA does not needlessly repeat the investigations in the future. This policy change is part of the EPA's Brownfields Redevelopment Program to help cities, states, private investors and affected citizens to promote economic redevelopment of unproductive urban sites.

A review of the CERC-NFRAP list, as provided by EDR, and dated 12/31/1996 has revealed that there are 2 CERC-NFRAP sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
LILCO HICKSVILLE OP. CENTER	175 E OLD COUNTRY ROAD	57	53
GRUMMAN AEROSPACE CORP	S OYSTER BAY RD	231	461

CORRACTS: CORRACTS is a list of handlers with RCRA Corrective Action Activity. This report shows which nationally-defined corrective action core events have occurred for every handler that has had corrective action activity.

A review of the CORRACTS list, as provided by EDR, and dated 12/01/1996 has revealed that there are 3 CORRACTS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
RUCO POLYMER CORP	NEW SOUTH RD	0	2
LILCO HICKSVILLE OP. CENTER	175 E OLD COUNTRY ROAD	57	53
GRUMMAN AEROSPACE CORP	S OYSTER BAY RD	231	461

LUST: The Leaking Underground Storage Tank Incident Reports contain an inventory of reported leaking underground storage tank incidents. The data comes from the Department of Environmental Conservation's Spills Information Database.

A review of the LUST list, as provided by EDR, and dated 12/31/1997 has revealed that there are 131 LUST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
RUCO POLYMER CORP	NEW SOUTH RD	0	2
NEGRON RESIDENCE	54 SUNRISE STREET	1	5
UNK	26 ANDOVER LANE	7	9
SHELL OIL	404 S OYSTER BAY RD	9	11
SHELL OIL CO	404 S OYSTER BAY RD	9	11
SHELL	404 S OYSTER BAY RD	9	12
GETTY S/S	400 SO OYSTER BAY ROAD	9	13

EXECUTIVE SUMMARY

Exemption 6

Site	Address	Map ID	Page
WRIGHT FUEL	789 OLD COUNTRY ROAD	10	13
[REDACTED]	[REDACTED]	25	22
RELIANCE	68 GROHMANS LANE	28	26
[REDACTED]	[REDACTED]	29	27
UNK	510 OLD COUNTRY ROAD	30	27
EXXON CO USA #37149	499 E OLD COUNTRY RD	32	30
NORTHVILLE	496 PLAINVIEW RD	32	32
NORTHVILLE INDUSTRIES	496 PLAINVIEW RD	32	32
NORTHVILLE S/S	496 PLAINVIEW RD	32	33
[REDACTED]	[REDACTED]	34	35
RUCO POLYMER	BLDG 1 NEW SOUTH ROAD	35	36
[REDACTED]	[REDACTED]	37	38
[REDACTED]	[REDACTED]	38	38
[REDACTED]	[REDACTED]	51	49
[REDACTED]	[REDACTED]	56	52
LONG ISLAND DEVELOPMENT	101 NEW SOUTH ROAD	60	56
MEENAN OIL	121 NEW SOUTH RD	63	58
BERTAN ASSOCIATES INC	121 NEW SOUTH RD	63	59
STRUCTURAL INDUSTRIES INC	96 NEW SOUTH RD	63	60
SLOMINS	92 E OLD COUNTRY RD	64	63
GETTY PETROLEUM	723 SOUTH OYSTER BAY ROAD	66	65
GRUMMAN CORP OPERATIONS	STEWART AVENUE	66	65
GRUMMAN	STEWART AVE / SO OYSTER B	66	67
GRUMMAN BETHPAGE	STEWART AVENUE	66	67
GRUMMAN AEROSPACE-BETHPAGE FAC	STEWART AVENUE	66	68
MOBIL OIL	755 SOUTH OYSTER BAY ROAD	81	130
ABBAY RENT ALL	301 SOUTH BROADWAY	83	132
HICKSVILLE FIRESTONE	300 S BROADWAY	83	134
COMMANDER	53 LAWNVIEW AVE	86	136
[REDACTED]	[REDACTED]	88	137
[REDACTED]	[REDACTED]	88	138
GRUMMAN AEROSPACE	BUILDING 04-01-1	92	144
GRUMMAN AEROSPACE	BUILDING #1	92	144
GRUMMAN AEROSPACE	GRUMMAN FACILITY BLDG 1	92	145
GRUMMAN AEROSPACE	BUILDING 116-01-1	92	145
GRUMMAN AEROSPACE	GRUMMAN AEROSPACE	92	146
GRUMMAN AEROSPACE	EAST END OF PLANT #3	92	147
GRUMMAN BLDG #3	STEWART AVENUE	92	148
GRUMMAN PLANT #20	STEWART AVE	92	148
GRUMMAN AEROSPACE	SO OYSTER BAY RD BLDG #1	92	150
GRUMMAN CORP	RTE 107	92	150
GRUMMAN AEROSPACE	BUILDING #2 GRUMMAN	92	151
GRUMMAN AEROSPACE	BLDG 28	92	151
GRUMMAN AEROSPACE	BLDG 111	92	152
GRUMMAN AEROSPACE	BLDG 115	92	153
BONANZA FABRIC CO	35 KARIN LANE	96	156
[REDACTED]	[REDACTED]	97	157
PACE FUEL CO	400 S BROADWAY	99	158
EAGLE INSURANCE COMPANY	999 STEWART AVENUE	102	160
[REDACTED]	[REDACTED]	103	161
[REDACTED]	[REDACTED]	103	162
NESS S/S	502 S BROADWAY	104	165
UNK CUSTOMER	502 S BROADWAY	104	166
SHELL GAS STATION	STEWART AVE / FARMERS AVE	108	170
SHELL OIL CO	STEWART & FARMERS	108	171
ERM NORTHEAST	335 NEW SOUTH RD	113	176

EXECUTIVE SUMMARY

Exemption 6

Site	Address	Map ID	Page
VARIETY PETROL (P&G FUEL)	317 NEW SOUTH RD	113	178
LILCO	EVERGREEN / SPRUCE AVE	114	178
[REDACTED]	[REDACTED]	119	183
[REDACTED]	[REDACTED]	120	183
METRO S/S	900 STEWART AVENUE	123	186
BETHPAGE U.F.S.D.	CHERRY AVE	123	187
[REDACTED]	[REDACTED]	124	188
BROADWALL MANAGEMENT	44 CHERRY AVENUE	127	190
[REDACTED]	[REDACTED]	129	192
GRUMMAN	BLDG #15	132	194
GRUMMAN	BLDG #3	132	194
GRUMMAN	WAREHOUSE #8	132	195
NORTHROP GRUMMAN	PLANT #15	132	196
GRUMMAN	PLANT #1 FUEL DEPOT	132	196
GRUMMAN	GRUMMAN PLANT #17	132	197
GRUMMAN	PLANT #3	132	197
GRUMMAN INC	PLANT #3	132	198
HICKSVILLE WATER AUTHORIT	4 DEAN ST	136	214
[REDACTED]	[REDACTED]	139	220
PUBLIC ELECTRIC	794 BROADWAY	146	224
[REDACTED]	[REDACTED]	152	229
MINEOLA MACK INC	880 S OYSTER BAY RD	154	231
[REDACTED]	[REDACTED]	156	233
BLUE FLAME	3 WASHINGTON PKWY	157	233
[REDACTED]	[REDACTED]	162	238
AVIS CAR RENTAL	980 SOUTH BROADWAY	178	254
[REDACTED]	[REDACTED]	179	255
[REDACTED]	[REDACTED]	183	257
SEALIT	75 BLOOMINGDALE ROAD	189	263
BRADCO SUPPLY	85 BLOOMINGDALE ROAD	191	266
GULF S/S	BROADWAY / HICKSVILLE	192	267
NYNEX VEHICLE	SHERMAN AVE/SO 6TH STREET	193	268
[REDACTED]	[REDACTED]	198	272
ERIKSEN AUTO OWNER	588 STEWART AVENUE	213	282
SLOMINS OIL CO	125 LAUMAN LN	221	288
BETHPAGE PUBLIC LIBRARY	47 POWELL AVE	223	296
BETHPAGE PUBLIC LIBRARY	POWELL AVENUE	223	297
[REDACTED]	[REDACTED]	224	298
[REDACTED]	[REDACTED]	227	299
71 STONE CUTTER RD	71 STONE CUTTER RD	230	301
NORTHROP GRUMMAN	SO OYSTER BAY ROAD	231	306
GRUMMAN AEROSPACE CORPORA	NEW SOUTH ROAD	231	307
GRUMMAN	MULBERRY STREET BLDG 12	231	449
GRUMMAN	PLANT #2 HANGER	231	450
GRUMMAN PLANT 11	83 LUDY ST	231	451
GRUMMAN CORP	STEWART AVE - WHSE #8	231	452
NORTHROP GRUMMAN	STEWART AVENUE	231	458
GRUMMAN AEROSPACE CORP	S OYSTER BAY RD	231	461
NORTHROP GRUMMAN CORP	B12 NEW SOUTH STREET	231	465
GRUMMAN	STEWART AVENUE	231	467
UNK	3529 CORTNEY LANE	232	470
SUNOCO	489 STEWART AVENUE	233	472
[REDACTED]	[REDACTED]	234	475
GIFFORD OIL	24 HUNTER LANE	239	483
[REDACTED]	[REDACTED]	243	486
Not reported	556 CENTRAL AVENUE	248	489

EXECUTIVE SUMMARY

Exemption 6

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
Not reported	3697 COLLECTOR LANE	251	494
MEENAN OIL CO	89 CONSTABLE LA	259	500
		260	500
		263	503
	77 BRENNER AVE	265	504
MEENAN OIL	20 TRAPPER LANE	269	507
COMMANDER	72 CONSTELLATION ROAD	270	507
WILLIAM SIMONE OWNER	17 CEIL PLACE	271	508
MEENAN OIL	4 SATELITE LANE	279	515
MEENAN OIL	4 SATELLITE LANE	279	516
		280	516
		285	520

UST: The Underground Storage Tank database contains registered USTs. USTs are regulated under Subtitle I of the Resource Conservation and Recovery Act (RCRA). The data comes from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS, CBS, MOSF) Database.

A review of the UST list, as provided by EDR, and dated 12/31/1996 has revealed that there are 20 UST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
BELLECLARE NURSERY	671 OLD COUNTRY RD.	16	18
PLAINVIEW SHELL INC.	500 OLD COUNTRY RD.	32	30
OUR LADY OF MERCY CHURCH	500 S. OYSTER BAY ROAD	39	40
STRUCTURAL INDUSTRIES INC	96 NEW SOUTH RD	63	60
GRUMMAN AEROSPACE CORP.	STEWART AVE.	79	78
MOBIL S/S #17-KKJ	755 S. OYSTER BAY RD.	81	131
SALVATI FOODS, INC.	595 S. BROADWAY	115	179
OFFICE BUILDING	560 S. BROADWAY	115	181
13-34 CAFFRY AVE	13-34 CAFFREY AVENUE	134	199
PLT. 8	4 DEAN ST	136	202
HICKSVILLE W.D. PLANT 8	4 DEAN ST.	136	205
PLT. #3	4 DEAN ST	136	208
PLT. 10	4 DEAN ST	136	209
BRADCO SUPPLY CORP.	85 BLOOMINGDALE RD.	191	264
SLOMINS INC	125 LAUMAN LANE	221	287
GRECO BROS. BULK TERMINAL	LAUMAN LA & HICKSVILLE RD.	222	290
BETHPAGE SERVICE STATION	515 STEWART AVE.	228	300
GRUMMAN AEROSPACE CORP.	MAIL STOP D08-001	231	311
BETHPAGE STRIP SHOPPING	326-360 BROADWAY	235	478
STRIP STORES AT	419-429 CENTRAL AVE.	254	496

AST: The Aboveground Storage Tank database contains registered ASTs. The data comes from the Department of Environmental Conservation's Petroleum Bulk Storage (PBS, CBS, MOSF) Database.

A review of the AST list, as provided by EDR, and dated 09/30/1996 has revealed that there are 36 AST sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
AMERICAN DRIVE-IN CLEANRS	418 S OYSTER BAY RD	12	14
PLAINVIEW MANOR S/C., INC	587 OLD COUNTRY RD	24	22

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
L & D SERVICE STATION	723 S OYSTER BAY RD	66	64
FRANKIE D'S SERV STA	1234 STEWART AVE	77	76
GRUMMAN AEROSPACE CORP.	STEWART AVE.	79	78
MOBIL S/S #17-KKJ	755 S. OYSTER BAY RD.	81	131
HICKSVILLE FIRESTONE	300 S BROADWAY	83	132
ABBEY RENT ALL	301 S BROADWAY	83	132
GRAND PRIX PERFORMANCE LT	777 S OYSTER BAY RD	90	142
COMMERCIAL BLDG. #2	327 NEW SOUTH RD	113	176
BETHPAGE METRO	900 STEWART AVE	123	185
PLT. #4	4 DEAN ST	136	201
PLT. #11	4 DEAN ST	136	204
HICKSVILLE W.D. PLANT 8	4 DEAN ST.	136	205
PLT. #9	4 DEAN ST	136	206
PLT. #2	4 DEAN ST	136	207
PLT. 10	4 DEAN ST	136	209
PLT. #5	4 DEAN ST	136	213
PLT. #7	4 DEAN ST	136	215
PLT. #6	4 DEAN ST	136	216
KING BEAR	735 S BROADWAY	138	219
GABRIELLI TRUCK SALES LTD	880 S OYSTER BAY RD	154	232
NASSAU BLUE FLAME INC	3 WASHINGTON PKWY	157	234
TBG COGEN PARTNERS	939 S BROADWAY	172	245
TBG COGEN PARTNERS	939 S BROADWAY	172	248
TBG COGEN PARTNERS	939 S BROADWAY	172	250
BRADCO SUPPLY CORP.	85 BLOOMINGDALE RD.	191	264
TWO GUYS AUTO REPAIR	HICKSVILLE RD. & BROADWAY	192	266
J.C. PRECISION AUTOMOTIVE	590 HICKSVILLE RD	216	284
GRECO BROS. BULK TERMINAL	LAUMAN LA & HICKSVILLE RD.	222	290
100 WEST 15 ST	100 WEST 15 ST	231	306
GRUMMAN AEROSPACE CORPORATION	S. OYSTER BAY ROAD	231	309
GRUMMAN AEROSPACE CORP.	MAIL STOP D08-001	231	311
GRUMMAN AEROSPACE CORPORATION	MAIL STOP:D08-GHQ	231	436
PAGE SERVICE STATION	497 STEWART AVE	233	473
BETHPAGE STRIP SHOPPING	326-360 BROADWAY	235	478

RCRIS: The Resource Conservation and Recovery Act database includes selected information on sites that generate, store, treat, or dispose of hazardous waste as defined by the Act. The source of this database is the U.S. EPA.

A review of the RCRIS-SQG list, as provided by EDR, and dated 10/31/1996 has revealed that there are 61 RCRIS-SQG sites within the searched area.

Site	Address	Map ID	Page
RUCO POLYMER CORP	NEW SOUTH RD	0	2
S.S. PREMISES C/O SHELL OIL CO	404 S OYSTER BAY RD	9	10
SHEAR MARTIN DMD	777 OLD COUNTRY RD	11	14
R & N CLEANERS DBA IZZYS TLC	720 OLD COUNTRY RD	13	15
COUNTRY CLEANERS	657 OLD COUNTRY ROAD	17	18
LEE'S FRENCH CLEANERS	607 OLD COUNTRY ROAD	23	21
EXXON CO USA #37149	499 E OLD COUNTRY RD	32	30
S.S. PREMISES C/O SHELL OIL CO	500 OLD COUNTRY RD	32	31
MERIT OYSTER BAY	496 PLAINVIEW RD	32	33
OUR LADY OF MERCY CHURCH	500 SOUTH OYSTER BAY ROAD	39	40

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
197 NEWBRIDGE S/S CORP - GULF	197 OLD COUNTRY RD	55	52
STRUCTURAL INDUSTRIES INC	96 NEW SOUTH RD	63	60
GETTY PETROLEUM CORP	723 S OYSTER BAY RD	66	65
LEE HANG K DBA CLASSIC CLEANER	56 E OLD COUNTRY RD	67	71
CLOVER FOREIGN AUTO REPAIR	36 E OLD COUNTRY RD	69	72
SPEDALE PHOTOGRAPHERS	110 NEW SOUTH RD	71	73
INLAND PLASTICS	120 NEW SOUTH RD	72	73
1234 STEWART AVENUE	1234 STEWART AVE	77	77
CORNICHE OF HICKSVILLE	285-4 S BROADWAY	82	132
HIP - EAST NASSAU REGION	350 S BROADWAY	88	138
GRAND PRIX PERFORMANCE	777 S OYSTER BAY RD	90	141
USA AUTO MALL	777 S OYSTER BAY RD	90	142
BIDCO MANUFACTURING CORP	8 COMMERCIAL ST	93	153
AETNA PRODUCTS	11 COMMERCIAL ST	93	154
MERCURY LIGHTING CORP	10 COMMERCIAL ST	93	155
DEXTER MAGNETIC MATERIALS DIV	400 KARIN LN	95	156
R & J CLEANERS	447 S BROADWAY	100	159
GRAND PRIX PERFORMANCE LTD	500 S BROADWAY	104	163
AMERADA HESS STATION 32489	502 S BROADWAY	104	166
CINDYS CLEANERS	495-30 S BROADWAY	104	167
SALS AUTO BODY	477 S BROADWAY	104	167
RONZONI FOODS CORPORATION	50 LUDY ST	105	168
TRIPLE J.V.C. AUTO COLLISION,	55 LUDY ST	105	168
BROADWAY PLAZA CLEANERS	532 S BROADWAY	112	175
CENTURY COLLISION INC	321 NEW SOUTH RD	113	177
SHAMROCK AUTO CENTER INC	589 S BROADWAY	115	179
AMERADA HESS OIL	575 S BROADWAY	115	181
MINEOLA MACK INC	880 S OYSTER BAY RD	154	231
FAME TRUCKING INC	246 8 TH ST	155	232
A ERNIES AUTO BODY INC	870 S BROADWAY	159	235
TRUE AUTO RESTORATIONS INC	870 S BROADWAY - E SECTION	159	236
DC FEMIA AUTO COLLISION	44 WASHINGTON PKWY	161	237
NATIONAL METAL SPRAYING	40 JEFFRY LN	166	242
PRIDE UTILITIES INC	70 WASHINGTON PKWY	170	243
T B G COGEN PARTNERS	939 S BROADWAY	172	247
PETER'S FRENCH CLEANERS	422 JERUSALEM AVE	176	253
YALE RADIATOR & AUTO REPAIR	37 BLOOMINGDALE RD	177	254
CONTINENTAL COLLISION	77B BLOOMINGDALE RD	189	262
SEAL IT INC	75 BLOOMINGDALE RD	189	263
JAMOCO HEATING & COOLING CORP	105 BLOOMINGDALE RD	197	272
DYNAMIC PAINTING CORP	7 WILLIS CT	205	276
RENAISSANCE DESIGN & BUILDING	91 ENGINEERS DR	206	277
BOCES NASSAU TECH BETHPAGE AV	610 HICKSVILLE RD	211	281
SON-LEW LAUNDRY CTR INC	596 STEWART AVE	213	283
ABSOLUTE GRAPHICS INC	184 QUALITY PLAZA	214	283
PHOENIX LABORATORIES INC	175 LAUMAN LANE	218	285
PROGRESSIVE CIRCUITS INC	180-R LAUMAN LN	218	286
BETHPAGE BEST CLEANERS	360 BROADWAY	226	299
TRANSMISSION TECHNICIANS	305 BROADWAY	241	485
BETHPAGE AUTO BODY	309 BROADWAY	241	485
EAGAL NEST	500 CENTRAL AVE	249	492

EXECUTIVE SUMMARY

RCRIS: The Resource Conservation and Recovery Act database includes selected information on sites that generate, store, treat, or dispose of hazardous waste as defined by the Act. The source of this database is the U.S. EPA.

A review of the RCRIS-LQG list, as provided by EDR, and dated 10/31/1996 has revealed that there are 46 RCRIS-LQG sites within the searched area.

Site	Address	Map ID	Page
FERN PLACE ELEMENTARY SCHOOL	ORCHARD ST & FERN PL	3	7
AMERICAN DRIVE IN CLEANERS	418 S OYSTER BAY RD	12	15
TODD EVAN CLEANERS OF PLAINVIEW	720 OLD COUNTRY RD	13	15
PLAZA FRENCH CLEANERS	524 OLD COUNTRY RD	30	29
PLAINVIEW SHELL INC	S OYSTER BAY RD & OLD COUNTRY	32	31
OCCIDENTAL CHEMICAL CORP	1 NEW SOUTH RD	35	38
HILLS CLEANERS	32 MCARTHUR AVE	49	47
LILCO HICKSVILLE OP. CENTER	175 E OLD COUNTRY ROAD	57	53
BERTAN ASSOCIATES INC	121 NEW SOUTH RD	63	59
SERVO CORP OF AMERICA	111 NEW S RD	63	61
JOHNS SOUTH BAY MOBIL	755 S OYSTER BAY RD	81	130
HICKSVILLE FIRESTONE	300 S BROADWAY	83	134
IMPRESSIVE IMAGE INC	9 COMMERCIAL ST	93	154
SUNOCO-BOB THALL	400 S BROADWAY	99	158
THALL SVC STATION CORP	400 S BROADWAY	99	159
GRAND JEEP EAGLE DEALERSHIP	500 BROADWAY	104	163
T R W MEDIAL ELECTRONIC CORP	485-29 S BROADWAY	104	167
GRUMMAN AEROSPACE CORP	83 LUDY ST	105	169
SHELL OIL CO	STEWART & FARMERS	108	171
VOIGT PROPERTY	335 NEW SOUTH RD	113	176
HICKSVILLE DEPT OF PUBLIC WORK	NEW SOUTH RD & MORRIS ST	116	181
BETHPAGE U F S D	CHERRY AVE	123	187
HI TECH CLEANERS	337 JERUSALEM AVE	137	218
KING BEAR AUTO SERVICE CENTER	735 S BROADWAY	138	219
GENERAL ELECTRIC SUPPLY CO	848 S OYSTER BAY RD	140	220
CORAL GRAPHIC SERVICES INC	840 S BROADWAY	158	234
BETHPAGE TRANSMISSION	870 BROADWAY	159	235
FIRESTONE SAVMOR AUTO SERVICE	870 S BROADWAY	159	236
JOHN GRACE & CO	34 WASHINGTON PKWY	161	238
BLUE FLAME	17 HAZEL ST	165	241
NEW YORK TELEPHONE	920 S OYSTER BAY RD ROOM 300	168	243
PHOTO WORKS	25 BLUMINGDALE RD	174	252
C & D TYPE SETTERS INC	960 S BROADWAY	175	252
MINUTE MAN CLEANERS	425 JERUSALEM AVE	181	257
TEXACO USA A DIVISION OF TEXAC	1000 S BROADWAY	182	257
SUNOCO SVC STA	125 BLOOMINGDALE RD	201	273
AMERICAN LITHOTECH	631 HICKSVILLE RD	207	279
HICKSVILLE POST OFFICE	260 ENGINEERS DR	210	281
ABSOLUTE PHOTO INC	184 QUALITY PLAZA	214	283
SLOMINS INC	125 LAUMAN LANE	221	287
GRUMMAN AEROSPACE CORP	NEW SOUTH RD	231	310
GRUMMAN AEROSPACE CORP	S OYSTER BAY RD	231	461
S & S SUNOCO SERVICE	489 STEWART AVE	233	471
EASTERN EXTERMINATING CO INC	326 BROADWAY	235	477
LVF CONTRACTING	STEWART AVE & LAFAYETTE AVE	244	487
TAHOE CLEANERS	436 N WANTAUGH AVE	267	506

EXECUTIVE SUMMARY

PADS: The PCB Activity Database identifies generators, transporters, commercial storers and/or brokers and disposers of PCBs who are required to notify the United States Environmental Protection Agency of such activities. The source of this database is the U.S. EPA.

A review of the PADS list, as provided by EDR, and dated 08/26/1996 has revealed that there are 3 PADS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
LILCO HICKSVILLE OP. CENTER	175 E OLD COUNTRY ROAD	57	53
T B G COGEN PARTNERS	939 S BROADWAY	172	247
GRUMMAN AEROSPACE CORP	S OYSTER BAY RD	231	461

ERNS: The Emergency Response Notification System records and stores information on reported releases of oil and hazardous substances. The source of this database is the U.S. EPA.

A review of the ERNS list, as provided by EDR, and dated 12/31/1996 has revealed that there is 1 ERNS site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
40 ISLAND ST	40 ISLAND ST	19	19

FINDS: The Facility Index System contains both facility information and "pointers" to other sources of information that contain more detail. These include: RCRIS; Permit Compliance System (PCS); Aerometric Information Retrieval System (AIRS); FATES (FIFRA [Federal Insecticide Fungicide Rodenticide Act] and TSCA Enforcement System, FTTS [FIFRA/TSCA Tracking System]; CERCLIS; DOCKET (Enforcement Docket used to manage and track information on civil judicial enforcement cases for all environmental statutes); Federal Underground Injection Control (FURS); Federal Reporting Data System (FRDS); Surface Impoundments (SIA); TSCA Chemicals in Commerce Information System (CICS); PADS; RCRA-J (medical waste transporters/disposers); TRIS; and TSCA. The source of this database is the U.S. EPA/NTIS.

A review of the FINDS list, as provided by EDR, and dated 09/30/1995 has revealed that there are 105 FINDS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
FERN PLACE ELEMENTARY SCHOOL	ORCHARD ST & FERN PL	3	7
S.S. PREMISES C/O SHELL OIL CO	404 S OYSTER BAY RD	9	10
SHEAR MARTIN DMD	777 OLD COUNTRY RD	11	14
AMERICAN DRIVE IN CLEANERS	418 S OYSTER BAY RD	12	15
TODD EVAN CLEANERS OF PLAINVIE	720 OLD COUNTRY RD	13	15
R & N CLEANERS DBA IZZYS TLC	720 OLD COUNTRY RD	13	15
COUNTRY CLEANERS	657 OLD COUNTRY ROAD	17	18
LEE'S FRENCH CLEANERS	607 OLD COUNTRY ROAD	23	21
PLAZA FRENCH CLEANERS	524 OLD COUNTRY RD	30	29
EXXON CO USA #37149	499 E OLD COUNTRY RD	32	30
PLAINVIEW SHELL INC	S OYSTER BAY RD & OLD COUNTRY	32	31
S.S. PREMISES C/O SHELL OIL CO	500 OLD COUNTRY RD	32	31
WALTER'S AUTO GROUP	430 PLAINVIEW RD	33	34
OCCIDENTAL CHEMICAL CORP	1 NEW SOUTH RD	35	36
OUR LADY OF MERCY CHURCH	500 SOUTH OYSTER BAY ROAD	39	40
HILLS CLEANERS	32 MCARTHUR AVE	49	47
197 NEWBRIDGE S/S CORP - GULF	197 OLD COUNTRY RD	55	52

EXECUTIVE SUMMARY

Site	Address	Map ID	Page
LILCO HICKSVILLE OP. CENTER	175 E OLD COUNTRY ROAD	57	53
BERTAN ASSOCIATES INC	121 NEW SOUTH RD	63	59
STRUCTURAL INDUSTRIES INC	96 NEW SOUTH RD	63	60
SERVO CORP OF AMERICA	111 NEW S RD	63	61
GETTY PETROLEUM CORP	723 S OYSTER BAY RD	66	65
LEE HANG K DBA CLASSIC CLEANER	56 E OLD COUNTRY RD	67	71
CLOVER FOREIGN AUTO REPAIR	36 E OLD COUNTRY RD	69	72
SPEDALE PHOTOGRAPHERS	110 NEW SOUTH RD	71	73
INLAND PLASTICS	120 NEW SOUTH RD	72	73
JOHNS SOUTH BAY MOBIL	755 S OYSTER BAY RD	81	130
CORNICHE OF HICKSVILLE	285-4 S BROADWAY	82	132
HICKSVILLE FIRESTONE	300 S BROADWAY	83	134
HIP - EAST NASSAU REGION	350 S BROADWAY	88	138
USA AUTO MALL	777 S OYSTER BAY RD	90	142
NARDA MICROWAVE CORP	75 COMMERCIAL ST	91	143
BIDCO MANUFACTURING CORP	8 COMMERCIAL ST	93	153
IMPRESSIVE IMAGE INC	9 COMMERCIAL ST	93	154
AETNA PRODUCTS	11 COMMERCIAL ST	93	154
MERCURY LIGHTING CORP	10 COMMERCIAL ST	93	155
DEXTER MAGNETIC MATERIALS DIV	400 KARIN LN	95	156
PAG INSULATION	44 FELICE CRESCENT	98	158
SUNOCO-BOB THALL	400 S BROADWAY	99	158
THALL SVC STATION CORP	400 S BROADWAY	99	159
R & J CLEANERS	447 S BROADWAY	100	159
GRAND PRIX PERFORMANCE LTD	500 S BROADWAY	104	163
GRAND JEEP EAGLE DEALERSHIP	500 BROADWAY	104	163
AMERADA HESS STATION 32489	502 S BROADWAY	104	166
CINDYS CLEANERS	495-30 S BROADWAY	104	167
T R W MEDIAL ELECTRONIC CORP	485-29 S BROADWAY	104	167
SALS AUTO BODY	477 S BROADWAY	104	167
RONZONI FOODS CORPORATION	50 LUDY ST	105	168
TRIPLE J.V.C. AUTO COLLISION,	55 LUDY ST	105	168
GRUMMAN AEROSPACE CORP	83 LUDY ST	105	169
SHELL OIL CO	STEWART & FARMERS	108	171
BROADWAY PLAZA CLEANERS	532 S BROADWAY	112	175
VOIGT PROPERTY	335 NEW SOUTH RD	113	176
CENTURY COLLISION INC	321 NEW SOUTH RD	113	177
SHAMROCK AUTO CENTER INC	589 S BROADWAY	115	179
AMERADA HESS OIL	575 S BROADWAY	115	181
HICKSVILLE DEPT OF PUBLIC WORK	NEW SOUTH RD & MORRIS ST	116	181
BETHPAGE U F S D	CHERRY AVE	123	187
HI TECH CLEANERS	337 JERUSALEM AVE	137	218
KING BEAR AUTO SERVICE CENTER	735 S BROADWAY	138	219
GENERAL ELECTRIC COMPANY INC	848 S OYSTER BAY RD	140	220
COLONIAL TRANSPARENT PDTS CO	870 S OYSTER BAY RD	147	226
MINEOLA MACK INC	880 S OYSTER BAY RD	154	231
FAME TRUCKING INC	246 8 TH ST	155	232
CORAL GRAPHIC SERVICES INC	840 S BROADWAY	158	235
A ERNIES AUTO BODY INC	870 S BROADWAY	159	235
BETHPAGE TRANSMISSION	870 BROADWAY	159	235
FIRESTONE SAVMOR AUTO SERVICE	870 S BROADWAY	159	236
TRUE AUTO RESTORATIONS INC	870 S BROADWAY - E SECTION	159	236
DC FEMIA AUTO COLLISION	44 WASHINGTON PKWY	161	237
JOHN GRACE & CO	34 WASHINGTON PKWY	161	238
BLUE FLAME	17 HAZEL ST	165	241
NATIONAL METAL SPRAYING	40 JEFFRY LN	166	242

EXECUTIVE SUMMARY

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
NEW YORK TELEPHONE	920 S OYSTER BAY RD ROOM 300	168	243
T B G COGEN PARTNERS	939 S BROADWAY	172	247
PHOTO WORKS	25 BLUMINGDALE RD	174	252
C & D TYPE SETTERS INC	960 S BROADWAY	175	252
PETER'S FRENCH CLEANERS	422 JERUSALEM AVE	176	253
YALE RADIATOR & AUTO REPAIR	37 BLOOMINGDALE RD	177	254
MINUTE MAN CLEANERS	425 JERUSALEM AVE	181	257
TEXACO USA A DIVISION OF TEXAC	1000 S BROADWAY	182	257
CONTINENTAL COLLISION	77B BLOOMINGDALE RD	189	262
JAMOCO HEATING & COOLING CORP	105 BLOOMINGDALE RD	197	272
CASCADE WATER SERVICE., INC	113 BLOOMINGDALE RD	200	273
SUNOCO SVC STA	125 BLOOMINGDALE RD	201	273
DYNAMIC PAINTING CORP	7 WILLIS CT	205	276
RENAISSANCE DESIGN & BUILDING	91 ENGINEERS DR	206	277
AMERICAN LITHOTECH	631 HICKSVILLE RD	207	279
HICKSVILLE POST OFFICE	260 ENGINEERS DR	210	281
BOCES NASSAU TECH BETHPAGE AV	610 HICKSVILLE RD	211	281
SON-LEW LAUNDRY CTR INC	596 STEWART AVE	213	283
ABSOLUTE GRAPHICS INC	184 QUALITY PLAZA	214	283
PHOENIX LABORATORIES INC	175 LAUMAN LANE	218	285
PROGRESSIVE CIRCUITS INC	180-R LAUMAN LN	218	286
SLOMINS INC	125 LAUMAN LANE	221	287
BETHPAGE BEST CLEANERS	360 BROADWAY	226	299
GRUMMAN AEROSPACE CORP	NEW SOUTH RD	231	310
GRUMMAN AEROSPACE CORP	S OYSTER BAY RD	231	461
S & S SUNOCO SERVICE	489 STEWART AVE	233	471
EASTERN EXTERMINATING CO INC	326 BROADWAY	235	477
TRANSMISSION TECHNICIANS	305 BROADWAY	241	485
BETHPAGE AUTO BODY	309 BROADWAY	241	485
LVF CONTRACTING	STEWART AVE & LAFAYETTE AVE	244	487
EAGAL NEST	500 CENTRAL AVE	249	492
TAHOE CLEANERS	436 N WANTAUGH AVE	267	506

TRIS: The Toxic Chemical Release Inventory System identifies facilities that release toxic chemicals to the air, water, and land in reportable quantities under SARA Title III, Section 313. The source of this database is the U.S. EPA.

A review of the TRIS list, as provided by EDR, and dated 12/31/1992 has revealed that there are 2 TRIS sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
RUCO POLYMER CORP	NEW SOUTH RD	0	2
GRUMMAN AEROSPACE CORP	S OYSTER BAY RD	231	461

SPILLS: The Spills Information Database from The Department of Environmental Conservation.

A review of the NY Spills list, as provided by EDR, and dated 12/31/1996 has revealed that there are 211 NY Spills sites within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
Exemption 6		2	5

EXECUTIVE SUMMARY

Exemption 6

Site	Address	Map ID	Page
FERN PLACE SCHOOL	FERN PLACE / ORCHARD ST	3	6
GENERAL UTILITIES	35 ANDOVER LN	4	7
RELIANCE UTILITIES	29 RELDA STREET	5	8
[REDACTED]	[REDACTED]	6	8
[REDACTED]	[REDACTED]	8	10
[REDACTED]	[REDACTED]	14	16
GIFFORDS OIL	41 CORNELL LN	15	16
CATHERINE DIPAOLO	671 OLD COUNTRY ROAD	16	17
LILCO	48 ISLAND STREET	18	18
CRESCENT PACKING	635 OLD COUNTRY ROAD	20	19
[REDACTED]	[REDACTED]	21	20
[REDACTED]	[REDACTED]	22	21
[REDACTED]	[REDACTED]	25	23
MOBIL S/S	537 OLD COUNTRY ROAD	26	23
[REDACTED]	[REDACTED]	26	24
[REDACTED]	[REDACTED]	27	25
Not reported	517 OLD COUNTRY RD	30	28
[REDACTED]	[REDACTED]	31	29
Not reported	430-440 PLAINVIEW RD	33	34
LILCO	1 NEW SOUTH RD	35	35
MET ROLLOFF CARTING	291 PLAINVIEW RD	36	37
[REDACTED]	[REDACTED]	38	39
[REDACTED]	[REDACTED]	40	40
[REDACTED]	PLAINVIEW RD / MCKINLEY	41	41
[REDACTED]	[REDACTED]	42	42
[REDACTED]	[REDACTED]	43	42
[REDACTED]	[REDACTED]	44	43
[REDACTED]	[REDACTED]	45	44
[REDACTED]	[REDACTED]	46	45
Not reported	34 BARNUM AVENUE	46	45
COMM PETRO	31 GABLES DR	47	46
GIFFORD OIL CO	12 LIBERTY AVE	48	47
NATHAN WEINGARTEN & SONS	31 BELMONT AVENUE	50	48
COMMANDER	35 BELLMONT AVENUE	50	49
LILCO	29 BARNUM STREET	52	50
[REDACTED]	[REDACTED]	53	51
[REDACTED]	[REDACTED]	54	51
LILCO	34 BURTON AVENUE	58	54
[REDACTED]	[REDACTED]	59	55
[REDACTED]	[REDACTED]	59	56
ROYS TOWING SERVICE	777 SO OYSTER BAY ROAD	61	57
ALPINE TREE & SCHRUB	11 BRADLEY STREET	62	58
BERTANE INC	121 NEW SOUTH RD	63	59
SERVO CORP OF AMERICA	111 NEW SOUTH RD	63	62
[REDACTED]	[REDACTED]	65	64
[REDACTED]	[REDACTED]	66	66
GRUMMAN AEROSPACE-BETHPAGE FAC	STEWART AVENUE	66	68
[REDACTED]	[REDACTED]	68	71
BLUE FLAME OIL	53 CHESHIRE	70	72
Not reported	120 NEW SOUTH RD	72	73
UNK	47 ESSEX ROAD	73	74
[REDACTED]	[REDACTED]	74	74
[REDACTED]	[REDACTED]	75	75
[REDACTED]	[REDACTED]	76	76
[REDACTED]	[REDACTED]	78	77
[REDACTED]	[REDACTED]	80	129

EXECUTIVE SUMMARY

Exemption 6

Site	Address	Map ID	Page
UNKK	BROADWAY / 4TH STREET	83	133
RELIANCE FUEL OIL	30 CEDAR AVE	84	135
OYSTER BAY TOWN	GRAND AVENUE / 4TH STREET	85	135
UNK VEHICLES	BALSAM PL / STEWART AVE	87	137
VAGELAS INC	COMMERCIAL / NEW SOUTH RD	89	139
RUCO POLYMER CORP. (HOOKER CHE	NEW SOUTH ROAD	89	140
NORTHROP GRUMMON FACILTY	1111 STEWART AVENUE	92	143
GRUMMAN AEROSPACE	GRUMMAN AEROSPACE	92	146
AETNA PRODS INCORP	11 COMMERCIAL ST	93	154
PERILLO OIL	7 CEDAR AVE	94	155
[REDACTED]	[REDACTED]	101	160
[REDACTED]	[REDACTED]	103	160
[REDACTED]	[REDACTED]	103	162
GRAND PRIX AUTO	500 S BROADWAY	104	164
LILCO	60 COMMERCE PL	106	169
FOREST CHEM INDUSTRIES	70 COMMERCE PL	107	170
2 COMMERCE ST/BAYONNE/NJ	2 COMMERCE STREET	109	172
NEIGHBOR	27 8TH ST	110	173
[REDACTED]	[REDACTED]	111	173
LILCO	536 S BROADWAY	112	174
LILCO	520 S BROADWAY	112	175
SID HARVEY	317 NEW SOUTH RD	113	177
ITC AT HESS S/S	575 S BROADWAY	115	180
[REDACTED]	[REDACTED]	117	181
[REDACTED]	[REDACTED]	118	182
MEENAN OIL CO	12 SPRUCE AVENUE	121	184
[REDACTED]	[REDACTED]	122	185
LILCO	25 FERNEY ST	125	188
[REDACTED]	[REDACTED]	126	189
[REDACTED]	[REDACTED]	128	190
[REDACTED]	[REDACTED]	128	191
[REDACTED]	[REDACTED]	130	192
LILCO	103 LEE AVE	131	193
[REDACTED]	[REDACTED]	133	199
[REDACTED]	[REDACTED]	135	200
UNK	47 LINDEN BLVD	141	221
LILCO	21 CHATHAM CT	142	222
[REDACTED]	[REDACTED]	143	222
[REDACTED]	[REDACTED]	144	223
[REDACTED]	[REDACTED]	145	224
LILCO	870 S OYSTER BAY RD	147	225
[REDACTED]	[REDACTED]	148	226
[REDACTED]	[REDACTED]	149	227
[REDACTED]	[REDACTED]	150	227
[REDACTED]	[REDACTED]	151	228
[REDACTED]	[REDACTED]	153	230
[REDACTED]	[REDACTED]	160	237
[REDACTED]	[REDACTED]	163	239
[REDACTED]	[REDACTED]	164	240
C&K PETROLEUM	17 HAZEL ST	165	240
WERNER TRUCK CO	39 JEFFRY LN	166	241
MAGNOLIA GARDENS APTS	899 BROADWAY	167	242
[REDACTED]	[REDACTED]	169	243
[REDACTED]	[REDACTED]	171	244
GENERAL ELECTRIC	939 S BROADWAY	172	246
TBG CO GEN PARTNERS	939 S BROADWAY	172	247

EXECUTIVE SUMMARY

Exemption 6

Site	Address	Map ID	Page
[REDACTED]	[REDACTED]	173	251
[REDACTED]	[REDACTED]	177	253
YALE RADIATOR & AUTO REPAIR	37 BLOOMINGDALE RD	177	254
[REDACTED]	[REDACTED]	180	255
CONTRACTOR (SHELL ONLY)	173 NORTH 6TH ST	180	256
[REDACTED]	[REDACTED]	183	258
DIOMEDE	717 STEWART AVENUE	184	259
RELANCE	167 9TH STREET	185	259
[REDACTED]	[REDACTED]	186	260
[REDACTED]	[REDACTED]	187	261
UNK CONTRACTOR	MEADE AVE/1ST / 2ND ST	188	261
UNK	218 LEE AVE	190	264
BRACO SUPPLY CO	85 BLOOMINGDALE RD	191	265
[REDACTED]	[REDACTED]	194	269
[REDACTED]	[REDACTED]	195	269
[REDACTED]	[REDACTED]	195	270
[REDACTED]	[REDACTED]	196	271
MEENAN	170 SCOOTER LN	199	273
[REDACTED]	[REDACTED]	202	274
[REDACTED]	[REDACTED]	203	275
[REDACTED]	[REDACTED]	204	275
UNK	127 ENGINEERS DR	206	276
SHOREWOOD PKG	55 ENGINEERS LN	206	277
DRIVER:WAYNE T COX	625 HICKSVILLE ROAD	207	278
MEENAN OIL	7 STORY LN	208	279
[REDACTED]	[REDACTED]	209	280
TOWN OF O.B DPW	WISHING LA / BUNKER LA	212	281
RELANCE	61 FRIENDLY RD	215	284
[REDACTED]	[REDACTED]	217	285
APT BLDG	380 BROADWAY	219	286
MAYTELL CONSTRUCTION CO	146 LAUMAN LANE	220	287
[REDACTED]	[REDACTED]	225	298
[REDACTED]	[REDACTED]	229	300
GRUMMAN CORP	SO OYSTER BAY ROAD	231	301
GRUMMAN	PLANT 20 GRUMMAN	231	302
GRUMMAN AEROSPACE	GRUMMAN JET FUEL DEPOT	231	302
GRUMMAN AEROSPACE CORP	STEWART AVENUE	231	303
GRUMMAN AEROSPACE	PLANT #14	231	304
GRUMMAN AERO	LOADING DOCK AT PLANT 30	231	305
GRUMMAN BETHPAGE PLANT #3	SO. OYSTER BAY ROAD	231	305
GRUMMAN AEROSPACE	FINAL PAINT HANGER-PLANT2	231	308
GRUMMAN AEROSPACE CORP	NEW SOUTH RD	231	310
GRUMMAN AEROSPACE	SCALE HANGER PLANT #4	231	450
GRUMMAN	PLANT #2, RECHARGE BASINS	231	452
NORTHROP GRUMMAN PLANT 20	SOUTH OYSTER BAY ROAD	231	453
GRUMMAN AEROSPACE	SO OYSTER BAY ROAD BLDG20	231	454
GRUMMAN PLANT #25	SO OYSTER BAY ROAD	231	455
GRUMMAN	SO OYSTER BAY ROAD	231	456
GRUMMAN AERO	PLANT #3	231	457
GRUMMAN CORP	PLANT 30,BETHPAGE COMPLEX	231	458
GRUMMAN AEROSPACE	PLANT #3	231	459
GRUMMAN AERO	GRUMMAN AERO	231	465
GRUMMAN CORP	PLANT #14	231	466
GRUMMAN	STEWART AVENUE	231	467
GRUMMAN	GRUMMANS GARAGE	231	469
GRUMMAN CORP	STEWART AVE BLDG 30	231	470

EXECUTIVE SUMMARY

Exemption 6

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
SUNOCO S/S	489 STEWART AVENUE	233	472
Not reported	497 STEWART AVENUE	233	474
[REDACTED]	[REDACTED]	234	475
UNK	322 BROADWAY	235	476
Not reported	WASHINGTON ST / BROADWAY	235	477
[REDACTED]	[REDACTED]	236	482
LILCO	3585 COURTNEY LANE	237	483
VACANT COMMERCIAL BLDG	1 LEXINGTON AVENUE	238	483
Not reported	64 BARRISTER ROAD	240	484
Not reported	PRENTICE ROAD/FIDDLER	242	485
[REDACTED]	[REDACTED]	245	487
[REDACTED]	[REDACTED]	246	487
[REDACTED]	[REDACTED]	247	488
Not reported	556 CENTRAL AVENUE	248	489
[REDACTED]	[REDACTED]	248	490
EAGLES NEST	500 CENTRAL AVENUE	249	491
Not reported	10 COLLECTOR LANE	250	492
ON PAVEMENT IFO	10 COLLECTOR LANE	250	493
[REDACTED]	[REDACTED]	252	494
TOWN OF HEMPSTEAD	GLENER / STONECUTTER RD	253	495
CITGO S/S	486 WANTAGH AVENUE	255	497
[REDACTED]	[REDACTED]	256	498
[REDACTED]	[REDACTED]	257	498
[REDACTED]	[REDACTED]	258	499
Not reported	3675 FARM RANCH ROAD	261	501
[REDACTED]	[REDACTED]	261	502
[REDACTED]	[REDACTED]	262	502
RELIANCE	12 FARMEDGE ROAD	264	504
UNK	26 SILVERSMITH LANE	266	505
[REDACTED]	[REDACTED]	268	506
Not reported	121 FARMEDGE ROAD	272	509
[REDACTED]	[REDACTED]	273	510
[REDACTED]	[REDACTED]	274	511
[REDACTED]	[REDACTED]	275	511
Not reported	16 COMET LANE	275	512
[REDACTED]	[REDACTED]	276	513
RELIANCE	46 EDNA LANE	277	514
GIFFORDS OIL	20 CELESTIAL LANE	278	515
Not reported	2 SHERMAN PLACE	281	517
[REDACTED]	[REDACTED]	282	518
MEENAN OIL	29 CELESTIAL LANE	283	518
LILCO	3675 STOKES AVENUE	284	519

RODS: Record of Decision. ROD documents mandate a permanent remedy at an NPL (Superfund) site containing technical and health information to aid the cleanup.

A review of the ROD list, as provided by EDR, and dated 03/31/1995 has revealed that there is 1 ROD site within the searched area.

<u>Site</u>	<u>Address</u>	<u>Map ID</u>	<u>Page</u>
RUCO POLYMER CORP	NEW SOUTH RD	0	2

MAP FINDINGS SUMMARY

<u>Database</u>	<u>Total Plotted</u>
NPL	1
Delisted NPL	0
RCRIS-TSD	2
State Haz. Waste	2
CERCLIS	2
CERC-NFRAP	2
CORRACTS	3
State Landfill	0
LUST	131
UST	20
AST	36
RAATS	0
RCRIS Sm. Quan. Gen.	61
RCRIS Lg. Quan. Gen.	46
HMIRS	0
PADS	3
ERNS	1
FINDS	105
TRIS	2
NPL Liens	0
TSCA	0
MLTS	0
NY Spills	211
ROD	1
CONSENT	0
Coal Gas	0

* Sites may be listed in more than one database

APPENDIX B
PRIOR USE INVESTIGATION

APPENDIX B PRIOR USE INVESTIGATION

To support the preparation of the Phase I EBS for NWIRP Bethpage, NAVFAC's offices in Lester, Pennsylvania were visited to review real estate records. The primary purpose of this visit was to identify the last owner of property acquired by the Navy to create NWIRP Bethpage. Based on an initial screen of the names of owners from whom the Navy acquired parcels, the objective was to compile a list of "suspicious" parcels, i.e., those owned by commercial or industrial interests, that could potentially have used the property in a manner capable of causing environmental concern. The results, presented below, did not reveal any such parcels.

B.1 INITIAL SCREEN

The records search was completed on May 28, 1997. Records were kept by NAVFAC Northern Division's Real Estate Division, which provided the files for review. Each file was examined in order to identify potential commercial or industrial land ownership whose past activities could have contributed to property contamination.

B.2 DETERMINATION OF PRIOR USE OF SUSPICIOUS PARCELS

The next step was to determine which of the parcels listed in Table C-1 contained activities which were capable of causing environmental concern. A circa 1941 Aerial Photograph was also used to determine prior uses of suspicious parcels. The 1941 aerial photograph shows that all three areas (Main Navy 105-Acre Parcel, Plant 20 Parcel, and Plant 5) were undeveloped in 1941 and consisted of a mixture of pasture, corpland, and woods.

B.3 FINDINGS

The Navy acquired approximately 109.336 acres (Main Navy 105-Acre Parcel and Plant 20 Parcel) from Grumman Aircraft Engineering Corporation (Grumman's name at that time) on April 15, 1947. Since the Navy owns the building at Plant 5 and Grumman owns the land, there is no indication of a property transfer in the files. Apparently, Grumman still owns the land on which Plant 5 is located and Navy never held title to the property on which Plant 5 is situated.

According to Navy records, The Grumman Aircraft Engineering Corporation acquired the Main Navy 105 Acre Parcel and Plant 20 from the Tomona Realty Corporation in 1941. Prior to 1941, there is no evidence of site contaminating activities on the Main Navy Parcel and the Plant 20 Parcel since these properties appear to have been undeveloped prior to this date. Because Grumman Aerospace is the current owner of the property that Plant 5 site is situated, Grumman real estate records would have to be reviewed to identify property owners prior to Grumman Aerospace. Such a records review is not within the scope of this task.

TABLE B-1
LIST OF PARCELS ACQUIRED TO CREATE NWIRP BETHPAGE

Parcel/Plant	Last Owner Before Navy Acquisition	Notes
Main Navy 105 Acre Parcel	Grumman Aircraft Engineering Corporation	Tomona Realty Company transferred parcel to Grumman Aircraft Engineering Corporation in 1941
Plant 20 Parcel	Grumman Aircraft Engineering Corporation	Tomona Realty Company transferred parcel to Grumman Aircraft Engineering Corporation in 1941
Plant 5	Grumman Aircraft Engineering Corporation (Current owner of land; Navy owns the building)	No property transfer occurred since Northrop Grumman still owns land

TABLE B-2
LAND USES OF NWIRP BETHPAGE PARCELS BASED ON
1947 AERIAL PHOTOGRAPH

Parcel/Plant	Last Granter Before Navy's Acquisition of Property	Land Use
Main Navy 105 Acre Parcel	Grumman Aircraft Engineering Corporation	Agriculture/Pasture/Wooded
Plant 20 Parcel	Grumman Aircraft Engineering Corporation	Agriculture/Pasture
Plant 5	Grumman Aircraft Engineering Corporation (Current owner of land; Navy owns the building)	Agriculture

Source: Untitled Aerial Photograph Dated 1941 (Available from Grumman Environmental Office).

APPENDIX C
VISUAL SITE INSPECTION DATA FORM

PHASE I ENVIRONMENTAL BASELINE SURVEY
NWIRP BETHPAGE

Real Property Unit _____

Grumman Number _____ Navy Number _____

Inspectors _____

Inspection Date _____

Escort _____ Phone _____ FAX _____

Description

Environmental Condition Of Property Rating	Number	Map Color
Areas where no storage, release or disposal of hazardous substances or petroleum products has occurred (including no migration of these substances from adjacent areas).	1	White
Areas where only storage of hazardous substances or petroleum products has occurred (but no release, disposal, or migration from adjacent areas has occurred).	2	Blue
Areas where storage, release, disposal and/or migration of hazardous substances or petroleum products has occurred, but at concentrations that do not require a removal or a remedial action.	3	Light Green
Areas where storage, release, disposal and/or migration of hazardous substances or petroleum products has occurred, and all remedial actions necessary to protect human health and the environment have been taken.	4	Dark Green
Areas where storage, release, disposal and/or migration of hazardous substances or petroleum products has occurred, removal and/or remedial actions are under way, but all required remedial actions have not yet been taken.	5	Yellow
Areas where storage, release, and/or migration of hazardous substances or petroleum products has occurred, but required response actions have not yet been implemented.	6	Red
Areas that are unevaluated or require additional evaluation.	7	Gray







Basis For Rating

Overview Of Potentially Necessary Phase II Investigation

PHASE I ENVIRONMENTAL BASELINE SURVEY
NWIRP BETHPAGE

Real Property Unit _____

Sketch

Sketch should show floor drains (*), Floor Trenches (), Floor Pits (), ASTs (), USTs (), PCB Transformers (), OWSs (), Cesspools (- - - O) and mark other spots where key observations were made (e.g., areas of stained soil or stressed vegetation). If notes are made on copies of existing drawings; indicate drawing name, number, date, and revision number.

Storage, Use, and Handling of Hazardous Materials and Petroleum Products

Yes No Unknown

Yes No Unknown

Attach applicable information.

Yes No Unknown

Yes No Unknown

Attach applicable information.

Discussion of previous uses of property (include dates):

Description of adjacent property

Roll	Frame	Subject
------	-------	---------

[illegible]

**PHASE I ENVIRONMENTAL BASELINE SURVEY
NWIRP BETHPAGE**

Real Property Unit _____

Interviewee Name _____ Phone _____ Fax _____

Title _____ Affiliation _____

Address _____

Years Familiar with Real Property Unit _____

History of Association with Real Property Unit _____

Interview Notes:

**PHASE I ENVIRONMENTAL BASELINE SURVEY
NWIRP BETHPAGE**

Real Property Unit _____

VISUAL SITE INSPECTION NOTES
Roads
Describe all public thoroughfares adjoining the property and any roads, streets, and parking lots on the property.
Air Pollution Sources/Odors
Describe all sources emission allowances, etc.
Potable Water Supply
Describe the source of potable water for the facility. (Lead content tested?)
Sewage Disposal System
Describe the sewage disposal system for the facility.
Storm Water
Describe the storm water characteristics of site.
Storage Tanks/Drums
Identify all underground storage tanks, drums, vent pipes, fill pipes, material stored, capacity, containment, etc. indicating underground storage tanks based on physical observations, interviews, or records review.
Pools of Liquid/Stains
Report all standing surface waters. Describe all pools or low areas containing liquids likely to be hazardous substances or petroleum products. Report any stained soil or stained surfaces. Describe all locations.

**PHASE I ENVIRONMENTAL BASELINE SURVEY
NWIRP BETHPAGE**

Real Property Unit _____

VISUAL SITE INSPECTION NOTES
Unidentified Substance Containers
Describe all open or damaged containers containing unidentified substances suspected of being hazardous substances or petroleum products. Include the approximate quantities, types of containers, and storage conditions.
PCBs/Electrical
Describe all electrical or hydraulic equipment known or suspected to contain PCBs. Survey conducted, When, Results?
Heating/Cooling
Describe the means of heating and cooling all buildings on the property (Fuel source, boiler size)
Drains and Sumps/Septic System
Describe all floor drains, sumps, and septic system.
Pits, Ponds, and Lagoons
Describe all pits, ponds, and lagoons on the property, especially if they are or were used in conjunction with waste disposal or waste treatment. Also describe pits, ponds, or lagoons on adjoining properties.
Wetlands
Describe location and approximate area.
Stressed Vegetation
Describe any areas of stressed vegetation (from a cause other than insufficient water) found on the property.

**PHASE I ENVIRONMENTAL BASELINE SURVEY
NWIRP BETHPAGE**

Real Property Unit _____

VISUAL SITE INSPECTION NOTES
Solid Waste
Describe any areas that are apparently filled or graded by non-natural causes, areas filled by fill of unknown origin, or mounds or depressions which suggest that trash or other solid waste disposal may have occurred.
Wastewater
Describe any wastewater or other liquids other than storm water which discharge into a ditch or stream on or adjacent to the property.
Dry Wells
Describe all wells that are not sources of water or of known mineral extraction and are used or suspected to be used for disposal of liquid wastes.
Other Hazardous Materials
Describe location, storage, and use practices.
Asbestos-Containing Materials
Note any suspect asbestos-containing materials. (Survey conducted, When, Results?)
Lead-Based Paint
Note any suspect lead-based paint. (Survey conducted, When, Results?)
Radon
Note any affected areas. (Survey conducted, When, Results?)

**PHASE I ENVIRONMENTAL BASELINE SURVEY
NWIRP BETHPAGE**

Real Property Unit _____

VISUAL SITE INSPECTION NOTES
Radioactive Materials
Note locations, quantities, types, uses.
Unexploded Ordnance
Describe ordnance used and approximate area of use.
Medical Waste
Describe type of waste and process from which waste is generated. Describe storage practices.
Pesticides/Herbicides
Describe any pesticides/herbicides that have been stored or used and approximate area of impact.
Used Oil
Describe storage practices of used oil and process from which used oil is generated.
Groundwater
Describe estimated direction of groundwater flow. Describe any potential impact on groundwater.
Geographic and Topographic
Describe geography and topography of the subject location.

APPENDIX D
TEXT OF EDR REPORT

The EDR Area Study Report

Study Area
NWIRP Bethpage -Northrup Grumman Corp.
Bethage, New York

April 28, 1997

Inquiry number 172329.1s

EDR Environmental
Data
Resources, Inc.
Creators of Toxicheck®

The Source **For Environmental Risk Management Data**

3530 Post Road
Southport, Connecticut 06490

Nationwide Customer Service

Telephone: 1-800-352-0050
Fax: 1-800-231-6802

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Coal Gas Site Search: No site was found in a search of Real Property Scan's ENVIROHAZ database.

NPL
Region

RUCO POLYMER CORP
NEW SOUTH RD
HICKSVILLE, NY 11801

CORRACTS 1000268848
ROD NYD002920312
CERCLIS
RCRIS-SQG
LUST
NPL
TRIS

CERCLIS Classification Data:

Site Incident Category: CHEMICAL PLANT

Federal Facility: NO

Ownership Status: PRIVATE

NPL Status: CURRENTLY ON THE FINAL NPL

EPA Notes: THE HOOKER/RUCO SITE IS AN ACTIVE PLASTICS MANUFACTURING FACILITY.
RCRA: SMALL GENERATOR.

CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	11/01/1979
Assessment:	PRELIMINARY ASSESSMENT	Completed:	09/01/1984
Assessment:	SCREENING SITE INSPECTION	Completed:	10/01/1984
Assessment:	FINAL LISTING ON NPL	Completed:	06/10/1986
Assessment:	PROPOSAL TO NPL	Completed:	10/15/1984
Assessment:	RMVL INVESTIGATION AT NPL	Completed:	08/21/1990
Assessment:	RMVL INVESTIGATION AT NPL	Completed:	02/03/1993
Assessment:	COMBINED RI/FS	Completed:	09/21/1988
Assessment:	REMEDIAL COMMUNITY RELATIONS	Completed:	Not reported
Assessment:	RI/FS WORKPLAN APPROVAL BY HQ	Completed:	09/21/1988
Assessment:	RECORD OF DECISION	Completed:	01/28/1994
Assessment:	COMBINED RI/FS	Completed:	01/28/1994
Assessment:	ADMINISTRATIVE RECORD	Completed:	Not reported
Assessment:	MANAGEMENT ASSISTANCE	Completed:	Not reported
Assessment:	COMBINED RI/FS	Completed:	09/28/1990
Assessment:	RECORD OF DECISION	Completed:	09/28/1990
Assessment:	ADMINISTRATIVE RECORD	Completed:	Not reported
Assessment:	COMBINED RI/FS	Completed:	Not reported
Assessment:	RECORD OF DECISION	Completed:	Not reported

CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

CERCLIS Alias Name(s):

RUCO POLYMER CORP
HOOKER CHEM /RUCO POLYMER

CORRACTS Data:

Prioritization: High

Status: RCRA Facility Investigation Completed, Referred to a Non-RCRA
Authority

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RUCO POLYMER CORP (Continued)

1000268848

NPL:

ID: 02NY052
Date Listed: 6/10/86 (FINAL)
EPA/ID: NYD002920312
Haz. Rank Score: 41.60
Status: LISTED ON NPL
Rank: 451
Group: 10
Ownership: Private
Permit: Air
Permit: NPDES
Site Activities: Chemical Process/Manuf.
Site Activities: Incinerator
Site Activities: Spill
Site Activities: Tank, above ground
Site Activities: Containers/Drums
Site Activities: Surface Impoundment
Site Activities: Tank, below ground
Site Condition: Contamination of Soil
Site Condition: Contam. Ground Water
Waste Type: Chlorinated Organics
Waste Type: Solvents

Contaminant: Media Affected:
VINYL CHLORIDE Not reported
1,1,2-TRICHLOROETHYLENE (TCE) Not reported
TETRACHLOROETHENE Not reported
PHENOL Not reported
1,2-TRANS-DICHLOROETHYLENE Not reported
1,1,1-TRICHLOROETHANE Not reported
VINYL ACETATE Not reported
STYRENE Not reported
BUTADIENE Not reported
ADIPIIC ACID Not reported
METHANOL Not reported
PHTHALIC ACID Not reported
METHYL ETHYL KETONE Not reported
PENTACHLOROPHENOL (PCP) Not reported
ZINC SULFATE Not reported

Distance to nearest Population: Not reported
Population within a 1 Mile Radius: Not reported
Population within a 2 Mile Radius: Not reported
Population within a 4 Mile Radius: Not reported
Vertical Distance to Aquifer: 21 Feet to 75 Feet
Ground Water Use: Not Used as Drinking Water, Alternative Source Available
Distance to nearest Surface Water: Not reported

ROD:

Full-text of USEPA Record of Decision(s) is available from EDR.

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RUCO POLYMER CORP (Continued)

1000268848

RCRIS:

Owner: HOOKER CHEMICALS & PLASTICS CORP
(516) 931-8100

Contact: PHILIP DEVRIES
(516) 931-8100

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D001	0.001 (P)	D002	0.000 (N)
D002	0.001 (P)	F001	0.000 (N)
F001	399.648 (P)	F003	0.000 (N)
F003	399.648 (P)	F005	0.000 (N)
F005	399.648 (P)	U002	0.000 (N)
U002	399.648 (P)	U028	0.000 (N)
U028	22.680 (M)	U044	0.000 (N)
U044	49.956 (P)	U112	0.000 (N)
U112	0.001 (P)	U122	0.000 (N)
U122	0.001 (P)	U140	0.000 (N)
U140	1.814 (M)	U147	0.000 (N)
U147	999.119 (P)	U154	0.000 (N)
U154	0.001 (P)	U159	0.000 (N)
U159	399.648 (P)	U190	0.000 (N)
U190	999.119 (P)	U196	0.000 (N)
U196	399.648 (P)	U210	0.000 (N)
U210	399.648 (P)	U213	0.000 (N)
U213	399.648 (P)	U220	0.000 (N)
U220	0.001 (P)	U223	0.000 (N)
U223	399.648 (P)	U226	0.000 (N)
U226	49.956 (P)	U239	0.000 (N)
U239	0.001 (P)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

Exemption 6

LUST:

Facility ID: 8804415
Facility Contact: Not reported
Investigator: GOERTZ
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: RUCO POLYMER
Address: NEW SOUTH ROAD
HICKSVILLE, NY
Spill Class: Not reported
Spill Closed Dt: 02/19/1992
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 08/18/1988 15:00
Cleanup Ceased: 02/19/1992

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: TANK SPEC INC
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 08/18/1988 16:47

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RUCO POLYMER CORP (Continued)

1000268848

Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/21/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/19/1988

1

LUST

S100666445
N/A

Exemption 6

PLAINVIEW, NY

LUST:

Facility ID: 9004238
Facility Contact: Not reported
Investigator: LEUNG
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 08/21/1990
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 07/17/1990 09:00
Cleanup Ceased: 08/21/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/22/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/23/1990

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MEENAN OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 07/17/1990 11:45

2

NY Spills

S102091779
N/A

PLAINVIEW, NY

SPILLS:

Facility ID: 9112285
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102091779

Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	03/03/1992		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	03/01/1992 14:00	Reported to Dept:	03/02/1992 15:08
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	03/03/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/04/1992		

3

FERN PLACE SCHOOL
FERN PLACE / ORCHARD ST
PLAINVIEW, NY

NY Spills

S102099931
N/A

SPILLS:

Facility ID:	9405277	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	Spill Type:	UST
Caller Name:	PAT GEROGHTY	Caller Agency:	CASTLE OIL
Caller Phone:	(718) 823-8800	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-2233
Spiller:	FERN PLACE SCHOOL		
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/19/1996		
Material Class:	Petroleum	Spilled Code:	0002
Quantity Spilled:	25 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	07/18/1994 13:00	Reported to Dept:	07/18/1994 13:34
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FERN PLACE SCHOOL (Continued)

S102099931

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/20/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/20/1994

3

**FERN PLACE ELEMENTARY SCHOOL
ORCHARD ST & FERN PL
PLAINVIEW, NY 11803**

**FINDS
RCRIS-LQG**

**1000305842
NYD980564165**

RCRIS:

Owner: PLAINVIEW OLD BETHPAGE
(212) 555-1212

Contact: LAWRENCE HERZOG
(516) 937-6412

Classification: Large Quantity Generator

Waste	Quantity
X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

4

**GENERAL UTILITIES
35 ANDOVER LN
HICKSVILLE, NY**

NY Spills

**S102140501
N/A**

SPILLS:

Facility ID: 9501022
Facility Contact: Not reported
Investigator: ACAMPORA
Caller Name: KEN
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GENERAL UTILITIES
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GENERAL UTILITIES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 04/27/1995
Material Class: Petroleum
Quantity Spilled: 5 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/25/1995 08:00
Tank Number: Not reported
Test method: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Commercial Vehicle
PBS Number: Not reported
Reported to Dept: 04/25/1995 09:15
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GENERAL UTILITIES (Continued)

S102140501

Gross Leak/Fail: Not reported
Cleanup Ceased: 04/27/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/28/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/26/1995

5

RELIANCE UTILITIES
29 RELDA STREET
PLAINVIEW, NY

NY Spills

S102096380
N/A

SPILLS:

Facility ID: 8910128
Facility Contact: Not reported
Investigator: MIRZA
Caller Name: DAVE WAGNER
Caller Phone: (516) 931-6800
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: RELIANCE UTILITIES
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 01/31/1990
Material Class: Petroleum
Quantity Spilled: 3 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 01/23/1990 10:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 01/31/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/05/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/25/1990

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE UTILITIES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Tank Truck
PBS Number: Not reported
Reported to Dept: 01/23/1990 10:13
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

6

HICKSVILLE, NY

NY Spills

S102136424
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102136424

SPILLS:

Facility ID:	9207730	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	RELIANCE FUEL OIL
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/04/1992	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	4 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	10/04/1992 12:51
Spill Date:	10/04/1992 11:50	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	10/04/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/05/1992		

7

UNK
26 ANDOVER LANE
HICKSVILLE, NY

LUST

S100668107
N/A

LUST:

Facility ID:	8710473	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	Not reported	Spill Type:	Facility
Caller Name:	CLINT SMITH	Caller Agency:	TOWN OF OYSTER BAY
Caller Phone:	(516) 921-7347	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	03/16/1988	Spill Source:	Passenger Vehicle
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported		
Spill Notifier:	Local Agency		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNK (Continued)

S100668107

Spill Date: 03/14/1988 12:00
Cleanup Ceased: 03/16/1988
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/13/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/17/1988

Reported to Dept: 03/15/1988 13:35

8

PLAINVIEW, NY

NY Spills

S102097311
N/A

SPILLS:

Exemption 6

Facility ID: 9008973
Facility Contact: Not reported
Investigator: MIRZA
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 12/21/1990
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 10/01/1990 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/21/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/24/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/16/1990

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: TENANT
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: Air
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 11/15/1990 13:12
Tank Capacity: 0 Gallons
Leak Rate: 0.00

9

S.S. PREMISES C/O SHELL OIL CO
404 S OYSTER BAY RD
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000140672
NYD981483910

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

S.S. PREMISES C/O SHELL OIL CO (Continued)

1000140672

RCRIS:

Owner: SHELL OIL CO
(212) 555-1212

Contact: JOHN SPINELLE
(800) 431-5566

Classification: Not reported

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	K052	0.000 (N)
X001	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

9

**SHELL OIL
404 S OYSTER BAY RD
HICKSVILLE, NY**

LUST

**S100172129
N/A**

LUST:

Facility ID: 8709241
Facility Contact: Not reported
Investigator: GOERTZ
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: SHELL OIL
Address: Not reported
Not reported
Spill Class: Not reported
Spill Closed Dt: 05/10/1988
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 01/29/1988 11:30
Cleanup Ceased: 05/10/1988
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/12/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/02/1988

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: Groundwater
Spill Source: Gas Station
PBS Number: Not reported
Reported to Dept: 01/29/1988 16:32

9

**SHELL OIL CO
404 S OYSTER BAY RD
HICKSVILLE, NY**

LUST

**S100177616
N/A**

LUST:

Facility ID: 9112135

Region of Spill: 1

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL OIL CO (Continued)

S100177616

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	CHARLIE PRICE	Caller Agency:	IPT
Caller Phone:	(516) 261-1590	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SHELL OIL CO		
Address	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/16/1992		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	02/26/1992 13:45	Reported to Dept:	02/26/1992 15:42
Cleanup Ceased:	09/16/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/18/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/27/1992		

9

**SHELL
404 S OYSTER BAY RD
HICKSVILLE, NY**

LUST

**S101102934
N/A**

LUST:

Facility ID:	9403037	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	NEDWICK ROBERT	Caller Agency:	ISLAND PUMP & TANK
Caller Phone:	(516) 261-1590	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SHELL S/S		
Address	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	06/01/1994 13:30	Reported to Dept:	06/01/1994 14:39
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL (Continued)

S101102934

Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 06/06/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/02/1994

9

**GETTY S/S
400 SO OYSTER BAY ROAD
HICKSVILLE, NY**

LUST

**S100669283
N/A**

LUST:

Facility ID:	9009085	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	WALSH	Spill Type:	Facility
Caller Name:	TIM WALSH	Caller Agency:	DEC
Caller Phone:	(516) 751-7900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GETTY S/S		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	03/11/1991	Spill Source:	Gas Station
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	11/15/1990 12:00
Spill Notifier:	DEC		
Spill Date:	11/15/1990 12:00		
Cleanup Ceased:	03/11/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	03/11/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/20/1990		

10

**WRIGHT FUEL
789 OLD COUNTRY ROAD
PLAINVIEW, NY**

LUST

**S100490835
N/A**

LUST:

Facility ID:	9113197	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LUCE	Spill Type:	Facility
Caller Name:	PAUL RUSS	Caller Agency:	WRIGHT FUEL
Caller Phone:	(516) 349-3200	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 433-3600
Spiller:	WRIGHT FUEL		
Address:	50 FAIRCHILD COURT PLAINVIEW, NY		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

WRIGHT FUEL (Continued)

S100490835

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 04/16/1992
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 03/29/1992 11:45
Cleanup Ceased: 04/16/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/09/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/31/1992
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 03/29/1992 12:08

11

PLAINVIEW, NY 11803

RCRIS-SQG 1000555610
FINDS NYD986981504

RCRIS:

Owner:

Contact:

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D011	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

Exemption 6

12

AMERICAN DRIVE-IN CLEANRS
418 S OYSTER BAY RD
HICKSVILLE, NY

AST

A100090077
N/A

Nassau County AST:

Facility ID:	000541	Tank ID:	0001
Tank Location:	Indoors, Aboveground	Capacity (Gal):	100
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Unknown		
Ext Protection:	NONE	Material Type:	Fresh/Product
Piping Type:	Other		
Description:	TETRACHLOROETHYLENE	Containment:	OTHER
Leak Detect:	OTHER	Product Gauge:	No
Dispense Method:	Suction	Install Date:	0183
Fill Type:	Pumped		
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

12

AMERICAN DRIVE IN CLEANERS
418 S OYSTER BAY RD
HICKSVILLE, NY 11801

FINDS
RCRIS-LQG

1000358704
NYD064748080

RCRIS:

Owner: Not reported

Contact: SOL BLECK
(516) 931-9396

Classification: Large Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

13

TODD EVAN CLEANERS OF PLAINVIEW
720 OLD COUNTRY RD
PLAINVIEW, NY 11803

FINDS
RCRIS-LQG

1000183132
NYD982279853

RCRIS:

Owner: UNKNOWN
(212) 555-1212

Contact: BENJAMIN MATROS
(516) 931-9163

Classification: Large Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

13

R & N CLEANERS DBA IZZYS TLC
720 OLD COUNTRY RD
PLAINVIEW, NY 11803

RCRIS-SQG
FINDS

1000124839
NYD081368276

RCRIS:

Owner: ISAREL WEISFELNER INC
(212) 555-1212

Contact: ISRAEL WEISFELNER
(516) 931-9163

Classification: Small Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

R & N CLEANERS DBA IZZYS TLC (Continued)

1000124839

Used Oil Recyc: No

Violation Status: Violations exist

There are 1 compliance/violation record(s) reported at this site:

Evaluation

Non-Financial Record Review

Area of Violation

Generator-All Requirements

Date of

Compliance

10/15/1987

14

HICKSVILLE, NY

NY Spills

S102135826

N/A

SPILLS:

Facility ID: 8607658
Facility Contact: Not reported
Investigator: O'NEILL
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

HICKSVILLE, NY
Spill Class: Not reported
Spill Closed Dt: 12/05/1991
Material Class: Petroleum
Quantity Spilled: 100 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Local Agency
Spill Date: 03/17/1987 10:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/05/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/06/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/19/1987

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 03/17/1987 11:40
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

15

**GIFFORDS OIL
41 CORNELL LN
HICKSVILLE, NY**

NY Spills

S102135977

N/A

SPILLS:

Facility ID: 9110133
Facility Contact: Not reported
Investigator: CAMPBELL

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GIFFORDS OIL (Continued)

S102135977

Caller Name:	HARRY LINKS	Caller Agency:	GIFFORDS
Caller Phone:	(516) 576-3000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GIFFORDS OIL		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	02/18/1992	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	10 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	12/24/1991 19:30
Spill Date:	12/24/1991 18:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/18/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/21/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/26/1991		

16

NY Spills

S102095135
N/A

PLAINVIEW, NY

SPILLS:

Facility ID:	8803603	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NCFM	Spill Type:	Facility
Caller Name:	INSPECT NEWMAN	Caller Agency:	NCFM
Caller Phone:	(516) 566-5817	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:			
	SYOSSET, NY		
Spill Class:	Not reported	Spilled Code:	0009
Spill Closed Dt:	07/27/1988	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	3 gallons	Spill Source:	Passenger Vehicle
Spill Cause:	Traffic Accident	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	07/26/1988 11:05
Spill Notifier:	Fire Department	Tank Capacity:	0 Gallons
Spill Date:	07/26/1988 09:30	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102095135

Cleanup Ceased: 07/27/1988
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/27/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/27/1988

16

BELLECLARE NURSERY
671 OLD COUNTRY RD.
PLAINVIEW, NY

UST

U001446888
N/A

Nassau County UST:

Facility ID:	055328	Tank ID:	0002
Tank Location:	Indoors, Belowground	Capacity:	00000550
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0673
Total Tanks:	1		

17

COUNTRY CLEANERS
657 OLD COUNTRY ROAD
PLAINVIEW, NY 11803

RCRIS-SQG
FINDS

1000322800
NYD981130875

RCRIS:

Owner: WON LEE
(516) 931-9747

Contact: WON LEE
(516) 931-9747

Classification: Small Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

18

LILCO
48 ISLAND STREET
PLAINVIEW, NY

NY Spills

S102096905
N/A

SPILLS:

Facility ID:	9003941	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102096905

Caller Name:	RICK SCHMITZ	Caller Agency:	LILCO
Caller Phone:	(516) 420-6143	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	LILCO		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	07/12/1990		
Material Class:	Petroleum	Spilled Code:	0017
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	07/09/1990 03:00	Reported to Dept:	07/10/1990 11:40
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	07/12/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	07/11/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/11/1990		

19
40 ISLAND ST
40 ISLAND ST
PLAINVIEW, NY

ERNS

8704086
N/A

20
CRESCENT PACKING
635 OLD COUNTRY ROAD
PLAINVIEW, NY

NY Spills

S102093332
N/A

SPILLS:

Facility ID:	8703619	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ACAMPORA	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 433-3533
Spiller:	CRESCENT PACKING		
Address:	18 MADISON AVENUE HICKSVILLE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	12/24/1990	Spilled Code:	0008
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	50 gallons	Resource Affected:	On Land
Spill Cause:	Traffic Accident	Spill Source:	Commercial Vehicle
Water Affected:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CRESCENT PACKING (Continued)

S102093332

Spill Notifier:	Local Agency	PBS Number:	Not reported
Spill Date:	08/03/1987 12:15	Reported to Dept:	08/03/1987 13:15
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/24/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/28/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/04/1987		

21

NY Spills

S102096456
N/A

PLAINVIEW, NY

SPILLS:

Facility ID:	8911251	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORDS OIL
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	[REDACTED]
Spiller:	[REDACTED]		
Address:	PLAINVIEW, NY		
Spill Class:	Not reported	Spilled Code:	0001
Spill Closed Dt:	02/27/1990	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	1 gallons	Spill Source:	Private Dwelling
Spill Cause:	Equipment Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	02/27/1990 10:23
Spill Notifier:	Other	Tank Capacity:	0 Gallons
Spill Date:	02/26/1990 10:58	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/27/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/28/1990		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

22

PLAINVIEW, NY

NY Spills

S102100169
N/A

Exemption 6

SPILLS:

Facility ID:	9407332	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LAMANNO	Spill Type:	Facility
Caller Name:		Caller Agency:	COMMANDER
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	4 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	08/31/1994 01:00	Reported to Dept:	08/31/1994 02:18
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	Fale		
Spill Record Last Update:	09/01/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/01/1994		

23

LEE'S FRENCH CLEANERS
607 OLD COUNTRY ROAD
PLAINVIEW, NY 11803

RCRIS-SQG 1000137893
FINDS NYD982282808

RCRIS:

Owner: LEE TAE KWON
(212) 555-1212

Contact: KWANG HO LEE
(516) 935-6120

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
F002	0.000 (N)	NONE	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LEE'S FRENCH CLEANERS (Continued)

1000137893

Used Oil Recyc: No

Violation Status: No violations found

24

PLAINVIEW MANOR S/C., INC
587 OLD COUNTRY RD
PLAINVIEW, NY

AST

A100090790
N/A

Nassau County AST:

Facility ID: 056265
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: WASTE OIL
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0006
Capacity (Gal): 180
Tank Material: STEEL

Material Type: Waste

Containment: DOUBLE WALL TANK
Product Gauge: Yes
Install Date: 0496

Facility ID: 056265
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, MOTOR
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0007
Capacity (Gal): 180
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DOUBLE WALL TANK
Product Gauge: Yes
Install Date: 0496

25

PLAINVIEW, NY

LUST

S101658197
N/A

LUST:

Facility ID: 9506287
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MILRO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 08/23/1995
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Local Agency
Spill Date: 08/22/1995 09:00
Cleanup Ceased: 08/23/1995
Last Inspection: Not reported

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/22/1995 09:32

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S101658197

Exemption 6

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/24/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/23/1995

25

NY Spills

S102090198
N/A

PLAINVIEW, NY

SPILLS:

Facility ID: 9104793
Facility Contact: Not reported
Investigator: LUCE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MILRO SERVICES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

PLAINVIEW
Spill Class: Not reported
Spill Closed Dt: 11/27/1991
Material Class: Petroleum
Quantity Spilled: 25 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 07/26/1991 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 11/27/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/29/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/05/1991

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/02/1991 15:42
Tank Capacity: 0 Gallons
Leak Rate: 0.00

26

MOBIL S/S
537 OLD COUNTRY ROAD
PLAINVIEW, NY

NY Spills

S102095248
N/A

SPILLS:

Facility ID: 8805208
Facility Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MOBIL S/S (Continued)

S102095248

Investigator:	ACAMPORA	Spill Type:	Facility
Caller Name:	JOE DEFRANCO	Caller Agency:	NCDH
Caller Phone:	(516) 535-2078	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-9391
Spiller:	MOBIL S/S		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	09/26/1988	Spilled Code:	0009
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	0 gallons	Resource Affected:	On Land
Spill Cause:	Deliberate	Spill Source:	Gas Station
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Citizen	Reported to Dept:	09/16/1988 12:13
Spill Date:	09/16/1988 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/26/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/27/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/19/1988		

26

NY Spills

S102102459
N/A

PLAINVIEW, NY

SPILLS:

Facility ID:	9507911	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	UST
Caller Name:		Caller Agency:	RELIANCE
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/28/1995	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	1 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	09/27/1995 20:54
Spill Date:	09/27/1995 18:16	Tank Capacity:	0 Gallons
Tank Number:	Not reported		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102102459

Test method: Not reported Leak Rate: 0.00
Gross Leak/Fail: Not reported
Cleanup Ceased: 09/28/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/27/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/29/1995

Facility ID: 9406430 Region of Spill: 1
Facility Contact: Not reported Facility Tele: Not reported
Investigator: MATTHEWS Spill Type: Facility
Caller Name: DAVE BENINCASA Caller Agency: RELIANCE
Caller Phone: (516) 475-4770 Caller Extension: Not reported
Notifier Name: Not reported Notifier Agency: Not reported
Notifier Phone: Not reported Notifier Extension: Not reported
Spiller Contact: Not reported Spiller Phone: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 02/16/1995
Material Class: Petroleum Spilled Code: 0001
Quantity Spilled: 2 gallons Quant Recovered: 0 gallons
Spill Cause: Human Error Resource Affected: On Land
Water Affected: Not reported Spill Source: Private Dwelling
Spill Notifier: Other PBS Number: Not reported
Spill Date: 08/11/1994 13:00 Reported to Dept: 08/11/1994 13:58
Tank Number: Not reported Tank Capacity: 0 Gallons
Test method: Not reported Leak Rate: 0.00
Gross Leak/Fail: Not reported
Cleanup Ceased: 02/16/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/17/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/12/1994

27

NY Spills

S102401702
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9606486 Region of Spill: 1
Facility Contact: [REDACTED] Facility Tele: [REDACTED]
Investigator: NONE Spill Type: UST
Caller Name: [REDACTED] Caller Agency: HOMEOWNER

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102401702

Exemption 6

Caller Phone:
Notifier Name:
Notifier Phone:
Spiller Contact:
Spiller:
Address

Caller Extension: Not reported
Notifier Agency: HOMEOWNER
Notifier Extension: Not reported
Spiller Phone:

HICKSVILLE, NY

Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 08/21/1996

Material Class: Petroleum

Quantity Spilled: 1 gallons

Spill Cause: Equipment Failure

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 08/20/1996 14:00

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 08/28/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 08/20/1996

Spilled Code: 0001

Quant Recovered: 1 gallons

Resource Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 08/20/1996 15:36

Tank Capacity: 0 Gallons

Leak Rate: 0.00

28

RELIANCE
68 GROHMANS LANE
PLAINVIEW, NY

LUST

S101340003
N/A

LUST:

Facility ID: 9409969

Facility Contact: Not reported

Investigator: NONE

Caller Name: JIM ALEXANDER

Caller Phone: (516) 338-1110

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Spiller: RELIANCE

Address: Not reported

Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 10/27/1994

Spill Cause: Tank Overfill

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 10/26/1994 09:00

Cleanup Ceased: 10/27/1994

Last Inspection: Not reported

Cleanup Meets Standard: True

Region of Spill: 1

Facility Tele: Not reported

Spill Type: Facility

Caller Agency: RELIANCE

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone: Not reported

Resource Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 10/26/1994 09:22

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RELiance (Continued)

S101340003

Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/27/1994

29

LUST

S101102812
N/A

PLAINVIEW, NY

Exemption 6

LUST:

Facility ID:	9401539	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	Spill Type:	Facility
Caller Name:	ANONY	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Citizen	PBS Number:	Not reported
Spill Date:	04/29/1994 12:00	Reported to Dept:	04/29/1994 16:30
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/04/1994		

30

UNK
510 OLD COUNTRY ROAD
PLAINVIEW, NY

LUST

S100666492
N/A

LUST:

Facility ID:	9006601	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LUCE	Spill Type:	Facility
Caller Name:	SUPERVISOR SIMON	Caller Agency:	NCFM
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNK (Continued)

S100666492

Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	09/20/1990		
Spill Cause:	Other	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Fire Department	PBS Number:	Not reported
Spill Date:	09/15/1990 16:10	Reported to Dept:	09/15/1990 17:19
Cleanup Ceased:	09/20/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/20/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/17/1990		

30

NY Spills

S102237604
N/A

HICKSVILLE, NY

SPILLS:

Facility ID:	9601450	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	Spill Type:	UST
Caller Name:	[REDACTED]	Caller Agency:	CITIZEN
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	[REDACTED]	Notifier Agency:	CITIZEN
Notifier Phone:	[REDACTED]	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0022
Quantity Spilled:	Unknown gallons	Quant Recovered:	0 gallons
Spill Cause:	Deliberate	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Citizen	PBS Number:	Not reported
Spill Date:	04/29/1996 10:34	Reported to Dept:	04/29/1996 10:34
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102237604

UST Involvement: False
Spill Record Last Update: 04/30/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered in Computer Data File: 04/29/1996

30

PLAZA FRENCH CLEANERS
524 OLD COUNTRY RD
PLAINVIEW, NY 11803

FINDS
RCRIS-LQG

1000442902
NYD986868396

RCRIS:

Owner: YOON HAKSUNG
 (212) 555-1212

Contact: YOON HAKSUNG
 (516) 932-5776

Classification: Large Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

31

HICKSVILLE, NY

NY Spills

S102139740
N/A

SPILLS:

Facility ID: 9405057
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GIFFORDS OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

HICKSVILLE, NY

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
 Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 07/13/1994
Material Class: Petroleum
Quantity Spilled: 4 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 07/13/1994 12:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 07/13/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 07/13/1994 13:34
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102139740

Exemption 6

Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/14/1994

32

PLAINVIEW SHELL INC.
500 OLD COUNTRY RD.
PLAINVIEW, NY

UST

U001854914
N/A

Nassau County UST:

Facility ID:	041012	Tank ID:	0005
Tank Location:	Indoors, Belowground	Capacity:	00000550
Tank Status:	6	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0162
Total Tanks:	1		

32

EXXON CO USA #37149
499 E OLD COUNTRY RD
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS
LUST

1000552335
NYD986947323

RCRIS:

Owner: EXXON CO USA
(713) 656-7761

Contact: ALDA S POOL
(713) 656-7709

Classification: Conditionally Exempt Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D018	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

LUST:

Facility ID:	9203976	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DEROSA	Spill Type:	Facility
Caller Name:	KAREN DEROSA	Caller Agency:	DEC
Caller Phone:	(516) 751-7900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	EXXON		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EXXON CO USA #37149 (Continued)

1000552335

Spill Closed Dt: 07/28/1992
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: DEC
Spill Date: 07/06/1992 11:45
Cleanup Ceased: 07/28/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 07/29/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/08/1992

Resource Affected: On Land
Spill Source: Gas Station
PBS Number: Not reported
Reported to Dept: 07/06/1992 11:45

32

**PLAINVIEW SHELL INC
S OYSTER BAY RD & OLD COUNTRY
PLAINVIEW, NY 11803**

**FINDS
RCRIS-LQG**

**1000258691
NYD010020675**

RCRIS:

Owner: PLAINVIEW SHELL INC
(212) 555-1212
Contact: LOU CANNATA
(516) 681-2447

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

32

**S.S. PREMISES C/O SHELL OIL CO
500 OLD COUNTRY RD
PLAINVIEW, NY 11803**

**RCRIS-SQG
FINDS**

**1000140682
NYD982178972**

RCRIS:

Owner: SHELL OIL COMPANY
(212) 555-1212
Contact: JOHN SPINELLE
(800) 431-5566

Classification: Not reported

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	K052	0.000 (N)
X001	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

S.S. PREMISES C/O SHELL OIL CO (Continued)

1000140682

Used Oil Recyc: No

Violation Status: No violations found

32

NORTHVILLE
496 PLAINVIEW RD
HICKSVILLE, NY

LUST

S100493642
N/A

LUST:

Facility ID:	9203191	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	SCOTT	Caller Agency:	F&N
Caller Phone:	(516) 586-4900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 499-6228
Spiller:	NORTHVILLE		
Address:	119 JERSEY ST WEST BABYLON, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	07/06/1992		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	06/15/1992 14:00	Reported to Dept:	06/16/1992 13:45
Cleanup Ceased:	07/06/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	07/07/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/17/1992		

32

NORTHVILLE INDUSTRIES
496 PLAINVIEW RD
HICKSVILLE, NY

LUST

S100493481
N/A

LUST:

Facility ID:	9201365	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	HAAS	Spill Type:	Facility
Caller Name:	LORETTA GORDON	Caller Agency:	NORTHVILLE IND
Caller Phone:	(516) 753-4247	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NORTHVILLE INDUSTRIES		
Address:	Not reported Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NORTHVILLE INDUSTRIES (Continued)

S100493481

Spill Closed Dt: 03/06/1995
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 05/04/1992 09:00
Cleanup Ceased: 03/06/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/06/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/07/1992

Resource Affected: On Land
Spill Source: Gas Station
PBS Number: Not reported
Reported to Dept: 05/04/1992 13:20

32

**MERIT OYSTER BAY
496 PLAINVIEW RD
HICKSVILLE, NY 11801**

RCRIS-SQG

**1001028353
NYR000005850**

RCRIS:

Owner: MERIT OIL OF NEW YORK INC
(610) 527-7900

Contact: ANDREW FORD
(610) 527-7900

Classification: Conditionally Exempt Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D018	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

32

**NORTHVILLE S/S
496 PLAINVIEW RD
HICKSVILLE, NY**

LUST

**S100493669
N/A**

LUST:

Facility ID:	9203434	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	SCOTT SCHUCK	Caller Agency:	F&N
Caller Phone:	(516) 586-4900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NORTHVILLE S/S		
Address	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	07/06/1992		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NORTHVILLE S/S (Continued)

S100493669

Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	06/22/1992 12:00	Reported to Dept:	06/22/1992 13:55
Cleanup Ceased:	07/06/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	07/07/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/29/1992		

33

WALTER'S AUTO GROUP
430 PLAINVIEW RD
HICKSVILLE, NY 11801

FINDS

1000401646
NYD982723256

33

430-440 PLAINVIEW RD
HICKSVILLE, NY

NY Spills

S102237423
N/A

SPILLS:

Facility ID:	9600413	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	UST
Caller Name:	RICHARD PARRISH	Caller Agency:	IMPACT ENVIRONMENTAL
Caller Phone:	(516) 269-8800	Caller Extension:	Not reported
Notifier Name:	CHARLOTTE BIBLOW	Notifier Agency:	RIFKIN, RADLER & KREMER
Notifier Phone:	(516) 357-3000	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	DIME SAVINGS BANK		
Address:	1 EAB PLAZA UNIONDALE, NY 11556-		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/09/1996	Spilled Code:	0009
Material Class:	Petroleum	Quant Recovered:	Unknown gallons
Quantity Spilled:	Unknown gallons	Resource Affected:	Groundwater
Spill Cause:	Housekeeping	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	04/09/1996 15:06
Spill Date:	01/01/1990 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/10/1996		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102237423

Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/09/1996

34

PLAINVIEW, NY

LUST

S101174173
N/A

LUST:

Facility ID: 9409041
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/07/1994
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 10/06/1994 14:00
Cleanup Ceased: 10/07/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/07/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/06/1994

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 10/06/1994 14:18

Exemption 6

35

LILCO
1 NEW SOUTH RD
HICKSVILLE, NY

NY Spills

S102401789
N/A

SPILLS:

Facility ID: 9607856
Facility Contact: Not reported
Investigator: UNASSIGNED
Caller Name: MR WEBLEY
Caller Phone: (516) 545-4007
Notifier Name: MR KLAUMP
Notifier Phone: (516) 545-4964
Spiller Contact: Not reported
Spiller: LILCO
Address: Not reported
NY
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: LILCO
Caller Extension: Not reported
Notifier Agency: LILCO
Notifier Extension: Not reported
Spiller Phone: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102401789

Spill Closed Dt:	Not reported	Spilled Code:	0016
Material Class:	Petroleum	Quant Recovered:	Unknown gallons
Quantity Spilled:	15 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Other Non Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	09/23/1996 15:05
Spill Date:	09/23/1996 11:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/24/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/23/1996		

35

OCCIDENTAL CHEMICAL CORP
1 NEW SOUTH RD
HICKSVILLE, NY 11802

FINDS
RCRIS-LQG 1000247991
NYD982280976

RCRIS:

Owner: RUCO POLYMER CORP
(212) 555-1212

Contact: A WESTON
(716) 286-3607

Classification: Large Quantity Generator

Waste	Quantity
D000	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Facility has an active water discharge permit (under PCS)
- Facility is monitored or permitted for air emissions under the Clean Air Act (under AFS/AIRS)
- Civil judicial and administrative enforcement case against facility (under DOCKET)

35

RUCO POLYMER
BLDG 1 NEW SOUTH ROAD
HICKSVILLE, NY

LUST

S100668631
N/A

LUST:

Facility ID: 8803416
Facility Contact: Not reported
Investigator: MIRZA
Caller Name: DR.BRADLEY HARRISON
Caller Phone: (516) 931-8104

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RUCO
Caller Extension: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RUCO POLYEMER (Continued)

S100668631

Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-8104
Spiller:	RUCO POLYEMER		
Address:	Not reported		
	HICKSVILLE, NY		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	01/09/1989	Spill Source:	Other Commercial/Industrial
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	07/20/1988 12:30
Spill Notifier:	Responsible Party		
Spill Date:	07/20/1988 12:00		
Cleanup Ceased:	01/09/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/10/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/21/1988		

36

MET ROLLOFF CARTING 291 PLAINVIEW RD HICKSVILLE, NY

NY Spills

S102136686
N/A

SPILLS:

Facility ID:	8703031	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ACAMPORA	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	MET ROLLOFF CARTING		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	1101
Spill Closed Dt:	12/24/1990	Quant Recovered:	0 gallons
Material Class:	Hazardous Material	Resource Affected:	On Land
Quantity Spilled:	60 gallons	Spill Source:	Commercial Vehicle
Spill Cause:	Equipment Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	07/15/1987 14:35
Spill Notifier:	Local Agency	Tank Capacity:	0 Gallons
Spill Date:	07/15/1987 14:30	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/24/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MET ROLLOFF CARTING (Continued)

S102136686

UST Involvement: False
Spill Record Last Update: 12/28/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/16/1987

37

PLAINVIEW, NY

LUST

**S100147265
N/A**

LUST:

Facility ID: 8804158
Facility Contact: Not reported
Investigator: HOFMANN
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]
PLAINVIEW, NY
Spill Class: Not reported
Spill Closed Dt: 01/09/1989
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 08/11/1988 09:00
Cleanup Ceased: 01/09/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/10/1989
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/12/1988

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE UTILITIES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Resource Affected: On Land
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 08/11/1988 10:30

Exemption 6

38

HICKSVILLE, NY

LUST

**S100560476
N/A**

LUST:

Facility ID: 9306833
Facility Contact: Not reported
Investigator: CAMPBELL
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: No spill occurred. No DEC Response. No corrective action required.

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100560476

Exemption 6

Spill Closed Dt: 11/29/1993
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 09/03/1993 10:30
Cleanup Ceased: 11/29/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/30/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/07/1993

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 09/03/1993 11:10

38

NY Spills

S102139086
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9306909
Facility Contact: Not reported
Investigator: CAMPBELL
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: RESIDENCE
Address: Not reported
Not reported
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 09/15/1993
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Citizen
Spill Date: 09/02/1993 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 09/15/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/12/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/09/1993

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CITIZEN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 09/07/1993 09:11
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

39	OUR LADY OF MERCY CHURCH 500 S. OYSTER BAY ROAD HICKSVILLE, NY	UST	U002264480 N/A
----	--	-----	-------------------

Nassau County UST:

Facility ID:	035010	Tank ID:	0003
Tank Location:	Indoors, Belowground	Capacity:	00006000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	Internal Lining		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1287
Total Tanks:	2		

Facility ID:	035010	Tank ID:	0004
Tank Location:	Indoors, Belowground	Capacity:	00004000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	Internal Lining		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1287
Total Tanks:	2		

39	OUR LADY OF MERCY CHURCH 500 SOUTH OYSTER BAY ROAD HICKSVILLE, NY 11801	RCRIS-SQG FINDS	1000121900 NYD982282485
----	---	--------------------	----------------------------

RCRIS:

Owner: DIOCESE ROCKVILLE CENTER
(212) 555-1212

Contact: JAMES E BOESEL
(516) 931-4351

Classification: Small Quantity Generator

Waste	Quantity
NONE	0.000 (N)



(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

40	 HICKSVILLE, NY	NY Spills	S102140586 N/A
----	---	-----------	-------------------

SPILLS:

Facility ID: 9503396
Facility Contact: Not reported
Investigator: AUSTIN
Caller Name: 
Caller Phone: 
Notifier Name: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RESIDENCE
Caller Extension: Not reported
Notifier Agency: Not reported

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102140586

Exemption 6

Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 06/28/1995
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 06/19/1995 13:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 06/28/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/30/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/20/1995

Notifier Extension: Not reported
Spiller Phone: Not reported
Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 06/19/1995 14:42
Tank Capacity: 0 Gallons
Leak Rate: 0.00

41

PLAINVIEW RD / MCKINLEY
HICKSVILLE, NY

NY Spills

S102138365
N/A

SPILLS:

Facility ID: 9003068
Facility Contact: Not reported
Investigator: GOMEZ
Caller Name: INSPECTOR SPINELLI
Caller Phone: (516) 566-5800
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]
Spill Class: Not reported
Spill Closed Dt: 06/19/1990
Material Class: Petroleum
Quantity Spilled: 5 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 06/17/1990 17:14
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 06/19/1990
Last Inspection: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]
Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 06/17/1990 17:47
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102138365

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/20/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/18/1990

42

NY Spills

S102139481
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9315509
Facility Contact: Not reported
Investigator: KISPRT
Caller Name: [REDACTED]
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. No DEC Response. No corrective action required.
Spill Closed Dt: 06/21/1994
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Housekeeping
Water Affected: Not reported
Spill Notifier: Citizen
Spill Date: 03/23/1994 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 06/21/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/21/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/31/1994

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]
Spilled Code: 0022
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 03/23/1994 10:00
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

43

NY Spills

S102139964
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9409139
Region of Spill: 1

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102139964

Exemption 6

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	CITIZEN
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/11/1994	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	10/09/1994 14:00
Spill Date:	10/09/1994 08:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	10/11/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	10/11/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/11/1994		

44

NY Spills

S102139390
N/A

HICKSVILLE, NY

SPILLS:

Facility ID:	9313390	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	GIFFORDS
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	02/15/1994	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102139390

Spill Date: 02/14/1994 09:45
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 02/15/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/15/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/14/1994

Reported to Dept: 02/14/1994 12:37
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

45

NY Spills

S102138857
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9301700
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 05/07/1993
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 05/06/1993 10:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 05/07/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/11/1993

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: HOMEOWNER
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 05/06/1993 11:52
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

46

[REDACTED]

NY Spills

S102102650
N/A

PLAINVIEW, NY

SPILLS:

Facility ID: 9509816
Facility Contact: MEJIA
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: [REDACTED]
Notifier Phone: [REDACTED]
Spiller Contact: [REDACTED]
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: (516) 822-2337
Spill Type: UST
Caller Agency: GIFFORDS ENERGY
Caller Extension: Not reported
Notifier Agency: GIFFORDS ENERGY
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Spill Class: PLAINVIEW, NY 11803-
Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 11/08/1995
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Unknown
Water Affected: Not reported
Spill Notifier: Local Agency
Spill Date: 11/08/1995 00:15
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 11/08/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/10/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/08/1995

Spilled Code: 0001
Quant Recovered: Unknown gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 11/08/1995 00:38
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

46

34 BARNUM AVENUE
PLAINVIEW, NY

NY Spills

S102236277
N/A

SPILLS:

Facility ID: 9511066
Facility Contact: IGNACIO MEJIA
Investigator: LAMANNO
Caller Name: ROBIN STIFFA
Caller Phone: (516) 576-3000
Notifier Name: BOB BARKER
Notifier Phone: (516) 576-3000
Spiller Contact: Not reported
Spiller: UNKNOWN
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: (516) 822-2337
Spill Type: UST
Caller Agency: GIFFORDS OIL CO
Caller Extension: Not reported
Notifier Agency: GIFFORDS OIL CO
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported
Material Class: Petroleum

Spilled Code: 0001

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236277

Quantity Spilled:	Unknown gallons	Quant Recovered:	Unknown gallons
Spill Cause:	Unknown	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Unknown
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/04/1995 10:40	Reported to Dept:	12/04/1995 10:52
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/05/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/04/1995		

47

**COMM PETRO
31 GABLES DR
HICKSVILLE, NY**

NY Spills

S102140144
N/A

SPILLS:

Facility ID:	9412047	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	RON GERACI	Caller Agency:	COMMANDER
Caller Phone:	(516) 922-7000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	COMM PETRO		
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/12/1994	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	12/09/1994 10:50
Spill Date:	12/09/1994 10:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/12/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/12/1994		
Corrective Action Plan Submitted:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

COMM PETRO (Continued)

S102140144

Date Spill Entered In Computer Data File: 12/12/1994

48

GIFFORD OIL CO
12 LIBERTY AVE
HICKSVILLE, NY

NY Spills

S102138704
N/A

SPILLS:

Facility ID: 9012085
Facility Contact: Not reported
Investigator: KISPERT
Caller Name: HARRY
Caller Phone: (516) 576-3000
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GIFFORD OIL CO
Address: 171 EAST AMES COURT
PLAINVIEW, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GIFFORDS OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 822-4780

Spill Class: Not reported
Spill Closed Dt: 03/07/1991
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/19/1991 22:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 03/07/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/08/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/20/1991

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 02/20/1991 00:48
Tank Capacity: 0 Gallons
Leak Rate: 0.00

49

HILLS CLEANERS
32 MCARTHUR AVE
HUNTINGTON, NY 11743

FINDS
RCRIS-LQG

1000291737
NYD981562234

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HILLS CLEANERS (Continued)

1000291737

RCRIS:

Owner: CHOONG HYUN CHOI
(212) 555-1212

Contact: HYUN CHOI CHOONG
(516) 423-0330

Classification: Large Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

50

NATHAN WEINGARTEN & SONS 31 BELMONT AVENUE PLAINVIEW, NY

NY Spills

S102089926
N/A

SPILLS:

Facility ID: 9101011
Facility Contact: Not reported
Investigator: NONE
Caller Name: IRVING W
Caller Phone: (516) 822-9379
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: NATHAN WEINGARTEN & SONS
Address: 176 MAIN PKWY
PLAINVIEW, NY

Spill Class: Not reported
Spill Closed Dt: 04/26/1991
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/25/1991 15:15
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 04/26/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/01/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/01/1991

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 04/25/1991 15:30
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

50

COMMANDER
35 BELLMONT AVENUE
PLAINVIEW, NY

NY Spills

S102101098
N/A

SPILLS:

Facility ID:	9413493	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	FRED YUDELSON	Caller Agency:	COMMANDER
Caller Phone:	(516) 922-7000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	COMMANDER		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	01/11/1995		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Human Error	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Tank Truck
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	01/10/1995 11:10	Reported to Dept:	01/10/1995 12:29
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	01/11/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/12/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/11/1995		

51

PLAINVIEW, NY

LUST

S102233140
N/A

LUST:

Facility ID:	9601411	Region of Spill:	1
Facility Contact:	[REDACTED]	Facility Tele:	(516) 938-2524
Investigator:	NONE	Spill Type:	UST
Caller Name:	[REDACTED]	Caller Agency:	HOMEOWNER
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	[REDACTED]	Notifier Agency:	HOMEOWNER
Notifier Phone:	[REDACTED]	Notifier Extension:	Not reported
Spiller Contact:	[REDACTED]	Spiller Phone:	[REDACTED]
Spiller:	[REDACTED]		
Address:	[REDACTED]		
	PLAINVIEW		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/29/1996		
Spill Cause:	Tank Failure	Resource Affected:	On Land

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102233140

Exemption 6

Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/27/1996 12:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/30/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/27/1996

Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 04/27/1996 13:09

52

LILCO
29 BARNUM STREET
PLAINVIEW, NY

NY Spills

S102100034
N/A

SPILLS:

Facility ID: 9406213
Facility Contact: Not reported
Investigator: NONE
Caller Name: GEORGE MARTIN
Caller Phone: (516) 391-6144
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: LILCO
Address: Not reported
Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/09/1994
Material Class: Petroleum
Quantity Spilled: 5 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 08/06/1994 09:17
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 08/09/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/09/1994

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: LILCO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0016
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 08/06/1994 12:06
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

53

PLAINVIEW, NY

NY Spills

S102101013
N/A

SPILLS:

Facility ID:	9412961	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORDS
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	RESIDENCE		
Address:	Not reported		
	Not reported		

Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	12/30/1994	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	12/29/1994 10:10
Spill Date:	12/29/1994 09:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/30/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/30/1994		

Exemption 6

54

PLAINVIEW, NY

NY Spills

S102101532
N/A

SPILLS:

Facility ID:	9416943	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORDS
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		

Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	Not reported	Spilled Code:	0001
Material Class:	Petroleum		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102101532

Exemption 6

Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	03/30/1995 15:00	Reported to Dept:	03/30/1995 15:28
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	Fale		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/03/1995		

55

197 NEWBRIDGE S/S CORP - GULF
197 OLD COUNTRY RD
HICKSVILLE, NY 11801

RCRIS-SQG 1000457373
FINDS NYD986925238

RCRIS:

Owner: CUMBERLAND FARMS INC
(212) 555-1212

Contact: RAYMOND FITZPATRICK
(516) 921-4300

Classification: Conditionally Exempt Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D008	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

56

PLAINVIEW, NY

LUST S100151135
N/A

LUST:

Facility ID:	9006009	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	CITIZEN
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	
Spiller:			
Address:	PLAINVIEW, NY		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100151135

Exemption 6

Spill Class: Not reported
Spill Closed Dt: 08/31/1990
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 08/30/1990 17:50
Cleanup Ceased: 08/31/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/04/1990
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/30/1990 18:00

57

LILCO HICKSVILLE OP. CENTER
175 E OLD COUNTRY ROAD
HICKVILLE, NY 11801

CORRACTS 1000178398
CERC-NFRAP NYD006866008
PADS
FINDS
RCRIS-LQG
RCRIS-TSD

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
Ownership Status: UNKNOWN
EPA Notes: Not reported

Federal Facility: NO
NPL Status: NOT ON NPL

CERCLIS-NFRAP Assessment History:

Assessment: PRELIMINARY ASSESSMENT
Assessment: DISCOVERY

Completed: 03/31/89
Completed: 02/28/89

CERCLIS-NFRAP Alias Name(s):

LILCO HICKSVILLE OP. CENTER

CORRACTS Data:

Prioritization: Low
Status: RCRA Facility Investigation Completed, Corrective Action Process is Terminated

RCRIS Corrective Action Summary:

Effective Date: 12/31/92
Legal Authority: RCRA 3004(u) or equivalent

RCRIS:

Owner: LONG ISLAND LIGHTING CO
(516) 755-6650

Contact: ROBERT TEETZ
(516) 391-6133

Classification: Large Quantity Generator, TSDF, Hazardous Waste Transporter

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D001	40.000 (T)	D002	0.000 (N)
D002	5.000 (T)	D003	2.000 (T)
D004	2.000 (T)	D005	2.000 (T)

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO HICKSVILLE OP. CENTER (Continued)

1000178398

D006	2.000 (T)	D007	2.000 (T)
D008	20.000 (T)	D009	0.000 (N)
D009	100.000 (T)	D010	2.000 (T)
D011	5.000 (T)	D018	10.000 (T)
F001	0.000 (N)	F001	1.000 (T)
F003	5.000 (T)	F003	5.000 (T)
F004	0.000 (N)	F004	1.000 (T)
F005	0.000 (N)	F005	5.000 (T)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: Violations exist

There are 6 compliance/violation record(s) reported at this site:

<u>Evaluation</u>	<u>Area of Violation</u>	<u>Date of Compliance</u>
Compliance Schedule Evaluation (CSE)	TSD-Closure/Post Closure Requirements	01/31/1995
	TSD-Other Requirements	01/31/1995
Compliance Evaluation Inspection (CEI)	TSD-Closure/Post Closure Requirements	01/31/1995
	TSD-Other Requirements	01/31/1995
Compliance Evaluation Inspection (CEI)	TSD-Other Requirements	12/29/1993
	TSD-Other Requirements	12/29/1993
Compliance Evaluation Inspection (CEI)	TSD-Other Requirements	06/02/1992
Non-Financial Record Review	Generator-All Requirements	10/20/1988
Non-Financial Record Review	Generator-All Requirements	05/16/1986

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Civil judicial and administrative enforcement case against facility (under DOCKET)
- Facility is a PCB generator, storer, transporter or permitted disposer (under PADS)

58

LILCO
34 BURTON AVENUE
PLAINVIEW, NY

NY Spills

S102095860
N/A

SPILLS:

Facility ID:	8903670	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	Not reported	Spill Type:	Facility
Caller Name:	MIKE LAURO	Caller Agency:	LILCO
Caller Phone:	(516) 420-6142	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	LILCO		
Address	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	0016
Spill Closed Dt:	07/13/1989	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	1 gallons	Spill Source:	Private Dwelling
Spill Cause:	Equipment Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	07/12/1989 14:20
Spill Notifier:	Responsible Party	Tank Capacity:	0 Gallons
Spill Date:	06/30/1989 12:00		
Tank Number:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102095860

Test method: Not reported Leak Rate: 0.00
Gross Leak/Fail: Not reported
Cleanup Ceased: 07/13/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/04/1989
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/14/1989

59

NY Spills

S102236509
N/A

PLAINVIEW, NY

SPILLS:

Facility ID: 9512258
Facility Contact: WILLIAM GIOIA
Investigator: Not reported
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: [REDACTED]
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: Not reported
Address: Not reported
Not reported
Spill Class: Not reported
Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: Unknown gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Local Agency
Spill Date: 12/30/1995 11:15
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/30/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/30/1995

Region of Spill: 1
Facility Tele: (516) 935-8566
Spill Type: UST
Caller Agency: RELIANCE RIGHT UTILITIES
Caller Extension: Not reported
Notifier Agency: SAME
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: Unknown gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 12/30/1995 11:33
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

59	PLAINVIEW, NY	NY Spills	S102236512 N/A
----	---------------	-----------	-------------------

SPILLS:

Facility ID: 9512268
Facility Contact: MIKE EMANUELLO
Investigator: Not reported
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: [REDACTED]
Notifier Phone: Not reported
Spiller Contact: [REDACTED]
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: (516) 338-1180
Spill Type: UST
Caller Agency: RELIANCE OIL
Caller Extension: Not reported
Notifier Agency: RELIANCE OIL
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

PLAINVIEW
Spill Class: Not reported
Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 12/30/1995 13:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/30/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/30/1995

Spilled Code: 0001
Quant Recovered: 1 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 12/30/1995 14:44
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

60	LONG ISLAND DEVELOPMENT 101 NEW SOUTH ROAD HICKSVILLE, NY	LUST	S100667459 N/A
----	---	------	-------------------

LUST:

Facility ID: 9108645
Facility Contact: Not reported
Investigator: NCDH
Caller Name: ALAN BRUSSELS
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: LONG ISLAND DEVELOPMENT
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 11/18/1991
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Health Department

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCDH
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LONG ISLAND DEVELOPMENT (Continued)

S100667459

Spill Date: 11/13/1991 11:15 Reported to Dept: 11/13/1991 11:30
Cleanup Ceased: 11/18/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/26/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered in Computer Data File: 11/13/1991

61

**ROYS TOWING SERVICE
777 SO OYSTER BAY ROAD
BETHPAGE, NY**

NY Spills

**S102093175
N/A**

SPILLS:

Facility ID:	9212733	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMPBELL	Spill Type:	Facility
Caller Name:	INSP ROBERT HARE	Caller Agency:	NCFM
Caller Phone:	(516) 566-5293	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 932-2685
Spiller:	ROYS TOWING SERVICE		
Address:	3160 HORSEBLOCK ROAD MEDFORD, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported	Spilled Code:	0008
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	30 gallons	Resource Affected:	On Land
Spill Cause:	Traffic Accident	Spill Source:	Commercial Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Fire Department	Reported to Dept:	02/10/1993 21:00
Spill Date:	02/10/1993 19:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	02/12/1993		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

62

ALPINE TREE & SCHRUB
11 BRADLEY STREET
PLAINVIEW, NY

NY Spills

S102096834
N/A

SPILLS:

Facility ID: 9003335
Facility Contact: Not reported
Investigator: PESTICIDE UNIT
Caller Name: TED STRATEZUS
Caller Phone: (516) 931-5399
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: ALPINE TREE & SCHRUB
Address: 40 AERO ROAD
BOHEMIA, NY
Spill Class: Not reported
Spill Closed Dt: 06/22/1990
Material Class: Not reported
Quantity Spilled: 0 UNITS NOT REPORTED
Spill Cause: Deliberate
Water Affected: Not reported
Spill Notifier: Citizen
Spill Date: 06/22/1990 15:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 06/22/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/26/1990

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CITIZEN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 567-8200

Spilled Code: Not reported
Quant Recovered: 0 UNITS NOT REPORTED
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 06/22/1990 19:30
Tank Capacity: 0 Gallons
Leak Rate: 0.00

63

MEENAN OIL
121 NEW SOUTH RD
HICKSVILLE, NY

LUST

S100174684
N/A

LUST:

Facility ID: 9100043
Facility Contact: Not reported
Investigator: ACAMPORA
Caller Name: MS TESTA
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: MEENAN OIL
Address: Not reported
Not reported
Spill Class: Not reported
Spill Closed Dt: 04/05/1991
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Responsible Party

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MEENAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: On Land
Spill Source: Tank Truck
PBS Number: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MEENAN OIL (Continued)

S100174684

Spill Date: 04/01/1991 15:15 Reported to Dept: 04/01/1991 15:25
Cleanup Ceased: 04/05/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/11/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/02/1991

63

BERTANE INC
121 NEW SOUTH RD
HICKSVILLE, NY

NY Spills

S102138435
N/A

SPILLS:

Facility ID: 9004626	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: NCDH	Spill Type: Facility
Caller Name: TOM MCCLOSKEY	Caller Agency: NCDH
Caller Phone: (516) 535-2404	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: BERTANE INC	
Address: Not reported	
Spill Class: Not reported	
Spill Closed Dt: 07/27/1990	Spilled Code: 0001
Material Class: Petroleum	Quant Recovered: 0 gallons
Quantity Spilled: 0 gallons	Resource Affected: Groundwater
Spill Cause: Equipment Failure	Spill Source: Other Commercial/Industrial
Water Affected: Not reported	PBS Number: Not reported
Spill Notifier: Health Department	Reported to Dept: 07/26/1990 09:15
Spill Date: 07/25/1990 12:00	Tank Capacity: 0 Gallons
Tank Number: Not reported	Leak Rate: 0.00
Test method: Not reported	
Gross Leak/Fail: Not reported	
Cleanup Ceased: 07/27/1990	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: Not reported	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 07/27/1990	

63

BERTAN ASSOCIATES INC
121 NEW SOUTH RD
HICKSVILLE, NY 11801

FINDS
LUST
RCRIS-LQG

1000396046
NYD980776405

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BERTAN ASSOCIATES INC (Continued)

1000396046

RCRIS:

Owner: Not reported

Contact: CHECK WALTER
(516) 433-3110

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
U159	0.000 (N)	U226	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

63

**STRUCTURAL INDUSTRIES INC
96 NEW SOUTH RD
HICKSVILLE, NY 11801**

**RCRIS-SQG 1000554648
FINDS NYD986971216
LUST
UST**

RCRIS:

Owner: STANLEY HIRSCH
(516) 822-5200

Contact: BARBARA MACCIO
(516) 822-5200

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)
D006	0.000 (N)	F003	0.000 (N)
F005	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

LUST:

Facility ID: 9306676
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: SCOTT SCHUCK
Caller Phone: (516) 586-4900
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: STRUCTURAL INDUSTRIES
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: F&N
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 822-5200

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 03/02/1995
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 08/31/1993 14:30
Cleanup Ceased: 03/02/1995
Last Inspection: Not reported

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 08/31/1993 14:41

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STRUCTURAL INDUSTRIES INC (Continued)

1000554648

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/02/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/01/1993

Facility ID: 8906944
Facility Contact: Not reported
Investigator: HOFMANN
Caller Name: RICH MAGEE
Caller Phone: (516) 566-5818
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: STRUCTURAL INDUSTRIES
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 822-5200

Spill Class: Not reported
Spill Closed Dt: 10/16/1989
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 10/15/1989 21:00
Cleanup Ceased: 10/16/1989
Last Inspection: Not reported

Resource Affected: In Sewer
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 10/16/1989 09:20

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/19/1989
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/17/1989

Nassau County UST:

Facility ID: 056447
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Unknown
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: 1

Tank ID: 0002
Capacity: 00007500
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

63

SERVO CORP OF AMERICA
111 NEW S RD
HICKSVILLE, NY 11801

CERCLIS
FINDS
RCRIS-LQG

1000433406
NYD002418911

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SERVO CORP OF AMERICA (Continued)

1000433406

CERCLIS Classification Data:

Site Incident Category: Not reported

Federal Facility: NO

Ownership Status: OTHER

NPL Status: NOT ON NPL

EPA Notes: Not reported

CERCLIS Assessment History:

Assessment: DISCOVERY

Completed: 04/10/1980

Assessment: PRELIMINARY ASSESSMENT

Completed: 01/15/1987

Assessment: SCREENING SITE INSPECTION

Completed: 06/26/1991

CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

RCRIS:

Owner: BLACKSTONE HENRY
(212) 555-1212

Contact: JOHN WILLENBROCK
(516) 938-9700

Classification: Large Quantity Generator

Waste	Quantity
D002	0.000 (N)
F017	0.000 (N)
NONE	0.000 (N)

Waste	Quantity
F002	0.000 (N)
K050	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: Violations exist

There are 1 compliance/violation record(s) reported at this site:

Evaluation

Compliance Evaluation Inspection (CEI)

Area of Violation

Generator-All Requirements

Date of

Compliance

11/17/1986

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Facility has an active water discharge permit (under PCS)

63

SERVO CORP OF AMERICA
111 NEW SOUTH RD
HICKSVILLE, NY

NY Spills

S102136964
N/A

SPILLS:

Facility ID: 8605764
Facility Contact: Not reported
Investigator: ACAMPORA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: SERVO CORP OF AMERICA
Address: 111 NEW SOUTH ROAD
HICKSVILLE
Spill Class: Not reported
Spill Closed Dt: 05/07/1987
Material Class: Petroleum
Quantity Spilled: 25 gallons
Spill Cause: Equipment Failure

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (938) 970-

Spilled Code: 0008
Quant Recovered: 0 gallons
Resource Affected: On Land

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SERVO CORP OF AMERICA (Continued)

S102136964

Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/04/1986	Reported to Dept:	12/11/1986 08:43
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/07/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	05/08/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/17/1986		

64

**SLOMINS
92 E OLD COUNTRY RD
HICKSVILLE, NY**

LUST

**S101340894
N/A**

LUST:

Facility ID:	9411611	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	MIKE ALFIERO	Caller Agency:	SLOMINS
Caller Phone:	(516) 932-7000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 932-7000
Spiller:	SLOMINS		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/01/1994		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	11/30/1994 12:00	Reported to Dept:	11/30/1994 14:57
Cleanup Ceased:	12/01/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/01/1994		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

65

BETHPAGE, NY

NY Spills

S102095087
N/A

Exemption 6

SPILLS:

Facility ID: 8803038
Facility Contact: Not reported
Investigator: HOFMANN
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY

Spill Class: Not reported
Spill Closed Dt: 01/10/1989
Material Class: Petroleum
Quantity Spilled: 10 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 07/07/1988 09:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 01/10/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/10/1989
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/12/1988

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 07/07/1988 14:06
Tank Capacity: 0 Gallons
Leak Rate: 0.00

66

L & D SERVICE STATION
723 S OYSTER BAY RD
PLAINVIEW, NY

AST

A100090892
N/A

Nassau County AST:

Facility ID: 057121
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Other
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: WASTE OIL
Leak Detect: ELECTRONIC
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0002
Capacity (Gal): 180
Tank Material: STEEL

Material Type: Waste
Containment: DOUBLE WALL TANK
Product Gauge: No
Install Date: 1192

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

66

GETTY PETROLEUM CORP
723 S OYSTER BAY RD
PLAINVIEW, NY 11803

RCRIS-SQG
FINDS

1000871563
NY0000071282

RCRIS:

Owner: GETTY PETROLEUM CORP
(516) 338-6000

Contact: JOHN CATAPANO
(516) 488-2500

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

66

GETTY PETROLEUM
723 SOUTH OYSTER BAY ROAD
PLAINVIEW, NY

LUST

S100172266
N/A

LUST:

Facility ID: 8710561
Facility Contact: Not reported
Investigator: GOERTZ
Caller Name: MATT
Caller Phone: (516) 249-3150
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GETTY PETROLEUM
Address: 30-23 GREENPOINT AVENUE
LONG ISLAND CITY, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: TYREE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (718) 729-6500

Spill Class: Not reported
Spill Closed Dt: 04/20/1988
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 03/17/1988 15:45
Cleanup Ceased: 04/20/1988

Resource Affected: Groundwater
Spill Source: Gas Station
PBS Number: Not reported
Reported to Dept: 03/17/1988 15:55

Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 04/20/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/18/1988

66

GRUMMAN CORP OPERATIONS
STEWART AVENUE
BETHPAGE, NY

LUST

S101102368
N/A

LUST:

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN CORP OPERATIONS (Continued)

S101102368

Facility ID:	9402644	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	ROBIN RHODE	Caller Agency:	NCDH
Caller Phone:	(516) 571-5060	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-1529
Spiller:	GRUMMAN CORP OPERATIONS		
Address:	MAIL STOP DO8-6HQ BETHPAGE		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/02/1995		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Health Department	PBS Number:	Not reported
Spill Date:	03/16/1994 12:00	Reported to Dept:	05/24/1994 10:00
Cleanup Ceased:	10/02/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	Fale		
Spill Record Last Update:	10/02/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	05/25/1994		

66

NY Spills

S102140198
N/A

HICKSVILLE, NY

SPILLS:

Facility ID:	9412916	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMPBELL	Spill Type:	Facility
Caller Name:	OFFICER MORAN	Caller Agency:	NCDP
Caller Phone:	(516) 573-6200	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	
Spiller:			
Address:	JERICO		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	02/03/1995		
Material Class:	Petroleum	Spilled Code:	0022
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Vandalism	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	DEC	PBS Number:	Not reported
Spill Date:	12/28/1994 10:10	Reported to Dept:	12/28/1994 12:07
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

Cleanup Ceased: 02/03/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/06/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/29/1994

S102140198

66

GRUMMAN
STEWART AVE / SO OYSTER B
BETHPAGE, NY

LUST

S100781235
N/A

LUST:

Facility ID:	9309349	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PARISH	Spill Type:	Facility
Caller Name:	KEVIN KISPERT	Caller Agency:	DEC
Caller Phone:	(516) 444-0320	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	GRUMMAN		
Address:	Not reported		

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	03/01/1994	Resource Affected:	On Land
Spill Cause:	Other	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	DEC	Reported to Dept:	11/01/1993 13:15
Spill Date:	11/01/1993 13:00		
Cleanup Ceased:	03/01/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	03/02/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/03/1993		

66

GRUMMAN BETHPAGE
STEWART AVENUE
BETHPAGE, NY

LUST

S100666789
N/A

LUST:

Facility ID:	9213848	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPERT DRO	Spill Type:	Facility
Caller Name:	JOHN SELVA	Caller Agency:	GRUMMAN

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN BETHPAGE (Continued)

S100666789

Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN BETHPAGE		
Address	PLANT #5 BETHPAGE		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported	Resource Affected:	On Land
Spill Cause:	Other	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	03/17/1993 14:55
Spill Date:	03/17/1993 14:00		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/06/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/18/1993		

66

**GRUMMAN AEROSPACE-BETHPAGE FACILITY
STEWART AVENUE
BETHPAGE, NY 11714**

**SHWS
LUST
NY Spills**

**S101008267
N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE-BETHPAGE FACILITY (Continued)

S101008267

SHWS:

Facility ID:	130003A	EPA ID:	NYD002047967
Owner:	Grumman Aerospace Corp Mail Stop B08-30 Bethpage, NY 11714		
Owner Telephone:	Not reported		
Operator:	U.S. Navy Grumman Corporation, Stewart Ave Bethpage, NY 11714		
Contact:	Not reported	Telephone	Not reported
Site Classification:	Significant threat to the public health or environment - action required.		
Region:	1		
Site Type:	Lagoon, Landfill		
Acres:	112	User:	Grumman Aerospace Corp.
HW Started:	1943	HW Ended:	present
HW Disposed:	Chromium sludge, Paint sludge, Metals, Chlorinated solvents		
Units:	unknown, unknown, unknown, unknown		
Air Data:	Unavailable	Surf. Water Data:	Unavailable
Gmd. Water Data:	Available	Soil Data:	Available
Sediment Data:	Available		
Ground Water Standards Contravention:	Yes		
Drinking Water Standards Contravention:	Yes		
Surface Water Standards Contravention:	No		
Air Standards Contravention:	No		
Enforcement Status:	Order Has Been Signed	Legal Action:	No
State Action:	Yes	Fed Action:	No
Remedial Action:	In Progress, Completed		
Remed action type:	RI-FS groundwater-OU II, and on-site soil-OU I		
Soil Type:	Sand		
Gmd Water Depth:	Approximately 55 feet		

Assessment of Environmental Problems:

Two of the municipal water supplies downgradient have been impacted and others are threatened.

Assessment of Health Problems:

Groundwater on-site is contaminated but it is not used as a potable water supply. Bethpage Water District (BWD) Plants 4, 5 and 6 are approximately 2500 feet south of the site. Contamination from the Grumman and Navy sites has been detected at BWD Plants 4 and 6. A Grumman funded treatment system is in operation at Plant 6. Trichloroethene was detected for the first time at concentrations below New York State Drinking Water Standards in samples from BWD Plant 4 during December 1992 and Grumman has provided funding for treatment at BWD Plant 4. The Navy will fund treatment for BWD Plant 5 in anticipation that plant 5 will be affected by the plume. No other routes of exposure have been identified.

LUST:

Facility ID:	9606777	Region of Spill:	1
Facility Contact:	JOHN SELZA	Facility Tele:	(516) 575-8176
Investigator:	UNASSIGNED	Spill Type:	UST
Caller Name:	JOHN SELZA	Caller Agency:	NORTHROP-GRUMMAN CORP.
Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	EMPLOYEE	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	JOHN SELZA	Spiller Phone:	(516) 575-8176

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE-BETHPAGE FACILITY (Continued)

S101008267

Spiller: NORTHROP-GRUMMAN CORP
Address: STEWART AVENUE
BETHPAGE, NY
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 08/27/1996 11:30
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/29/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/27/1996
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 08/27/1996 15:00

SPILLS:

Facility ID: 9608319
Facility Contact: JOHN SELZA
Investigator: PARISH
Caller Name: JOHN SELVA
Caller Phone: (516) 575-8176
Notifier Name: JOHN SELVA
Notifier Phone: (516) 575-8176
Spiller Contact: JOHN SELZA
Spiller: NORTHROP GRUMMAN CORP
Address: STEWART AVENUE
BETHPAGE, NY
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: Unknown gallons
Spill Cause: Unknown
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 10/03/1996 16:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/04/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/03/1996
Region of Spill: 1
Facility Tele: (516) 575-8176
Spill Type: UST
Caller Agency: NORTHROP GRUMMIN CORP
Caller Extension: Not reported
Notifier Agency: NORTHROP GRUMMIN CORP
Notifier Extension: Not reported
Spiller Phone: (516) 575-8176
Spilled Code: 0066
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Unknown
PBS Number: Not reported
Reported to Dept: 10/03/1996 16:16
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

67 LEE HANG K DBA CLASSIC CLEANERS
56 E OLD COUNTRY RD
MINEOLA, NY 11501

RCRIS-SQG
FINDS

1000693645
NYD986997104

RCRIS:

Owner: HANG K LEE
(516) 248-0111

Contact: HANG LEE
(516) 248-0111

Classification: Small Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

68

HICKSVILLE, NY

NY Spills

S102140439
N/A

SPILLS:

Facility ID: 9500019
Facility Contact: Not reported
Investigator: SCHULZ
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: HOMEOWNER
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 05/02/1995
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/02/1995 13:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 05/02/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/03/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/04/1995

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 04/02/1995 15:12
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

69

CLOVER FOREIGN AUTO REPAIR
36 E OLD COUNTRY RD
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000554462
NYD986969277

RCRIS:

Owner: CLOVER FOREIGN AUTO REPAIR
(516) 935-3280

Contact: BOB SWEENEY
(516) 935-3280

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D018	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

70

BLUE FLAME OIL
53 CHESHIRE
BETHPAGE, NY

NY Spills

S102095036
N/A

SPILLS:

Facility ID: 8802451
Facility Contact: Not reported
Investigator: WALEK
Caller Name: PAT MOUNT
Caller Phone: (516) 535-2404
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: BLUE FLAME OIL
Address: Not reported
Not reported

Spill Class: Not reported
Spill Closed Dt: 06/20/1988
Material Class: Petroleum
Quantity Spilled: 25 gallons
Spill Cause: Unknown
Water Affected: Not reported
Spill Notifier: Health Department
Spill Date: 06/17/1988 10:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 06/20/1988
Last Inspection: Not reported

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/28/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/24/1988

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCDH
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 931-6700

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: In Sewer
Spill Source: Tank Truck
PBS Number: Not reported
Reported to Dept: 06/17/1988 12:00
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

71	SPEDALE PHOTOGRAPHERS 110 NEW SOUTH RD HICKSVILLE, NY 11801	RCRIS-SQG FINDS	1000184614 NYD982794570
----	--	----------------------------------	--

RCRIS:

Owner: JULIUS SPEDALE
(212) 555-1212

Contact: JULIUS SPEDALE
(516) 681-0863

Classification: Small Quantity Generator

Waste	Quantity
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

72	INLAND PLASTICS 120 NEW SOUTH RD HICKSVILLE, NY 11802	RCRIS-SQG FINDS	1000556202 NYD986987618
----	--	----------------------------------	--

Used Oil Recyc: No

Violation Status: No violations found

72	120 NEW SOUTH RD HICKSVILLE, NY	NY Spills	S102136785 N/A
----	--	------------------	---------------------------------

SPILLS:

Facility ID: 8601554

Facility Contact: Not reported

Investigator: Not reported

Caller Name: Not reported

Caller Phone: Not reported

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Spiller: INLAND PLASTICS

Address: Not reported

Spill Class: Not reported

Spill Closed Dt: 05/19/1987

Material Class: Not reported

Quantity Spilled: 0 UNITS NOT REPORTED

Spill Cause: Deliberate

Water Affected: Not reported

Spill Notifier: Fire Department

Spill Date: 06/04/1986 16:30

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: 05/19/1987

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Region of Spill: 1

Facility Tele: Not reported

Spill Type: UST

Caller Agency: Not reported

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone: Not reported

Spilled Code: Not reported

Quant Recovered: 0 UNITS NOT REPORTED

Resource Affected: On Land

Spill Source: Other Commercial/Industrial

PBS Number: Not reported

Reported to Dept: 06/04/1986 16:30

Tank Capacity: 0 Gallons

Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102136785

Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/10/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/13/1986

73

UNK
47 ESSEX ROAD
BETHPAGE, NY

NY Spills

S102094534
N/A

SPILLS:

Facility ID:	8706308	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	RAYMOND	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	0022
Spill Closed Dt:	06/17/1989	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	0 gallons	Spill Source:	Passenger Vehicle
Spill Cause:	Deliberate	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	10/26/1987 15:20
Spill Notifier:	Affected Persons	Tank Capacity:	0 Gallons
Spill Date:	10/26/1987 15:20	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	06/17/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/21/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/29/1987		

74

PLAINVIEW, NY

NY Spills

S102102244
N/A

SPILLS:

Facility ID:	9505896	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	Spill Type:	UST
Caller Name:		Caller Agency:	GIFFORDS
Caller Phone:		Caller Extension:	Not reported

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102102244

Exemption 6

Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/07/1996
Material Class: Petroleum
Quantity Spilled: 10 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 08/14/1995 08:45
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/07/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/15/1995

Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]
Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/14/1995 09:15
Tank Capacity: 0 Gallons
Leak Rate: 0.00

75

HICKSVILLE, NY

NY Spills

S102139196
N/A

SPILLS:

Facility ID: 9309555
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: RESIDENCE
Address: Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/09/1993
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 11/06/1993 19:05
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]
Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 11/06/1993 21:16
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RESIDENCE (Continued)

S102139196

Cleanup Ceased: 11/09/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/09/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/09/1993

76

BETHPAGE, NY

NY Spills

S102097093
N/A

Exemption 6

SPILLS:

Facility ID: 9006011
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 08/31/1990
Material Class: Petroleum
Quantity Spilled: 3 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 08/30/1990 20:50
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 08/31/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/04/1990

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GIFFORD OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/30/1990 23:00
Tank Capacity: 0 Gallons
Leak Rate: 0.00

77

FRANKIE D'S SERV STA
1234 STEWART AVE
BETHPAGE, NY

AST

A100090634
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FRANKIE D'S SERV STA (Continued)

A100090634

Nassau County AST:

Facility ID:	055584	Tank ID:	0006
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	250
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]		
Piping Type:	Galvanized Steel	Material Type:	Fresh/Product
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	DOUBLE WALL TANK
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	1292
Total Tanks:	Not reported		

77

1234 STEWART AVENUE
1234 STEWART AVE
BETHPAGE, NY 11714

RCRIS-SQG 1001090477
NYU005000385

RCRIS:

Owner: BILL WOLF PETROLEUM CORP
(516) 997-9300

Contact: FRANK DECARLO
(516) 555-1212

Classification: Not reported

Waste	Quantity
NONE	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

78

BETHPAGE, NY

NY Spills S102237575
N/A

SPILLS:

Facility ID: 9601280

Facility Contact:

Investigator:

Caller Name:

Caller Phone:

Notifier Name:

Notifier Phone:

Spiller Contact:

Spiller:

Address

BETHPAGE, NY 11714-

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 04/25/1996

Material Class: Petroleum

Quantity Spilled: 1 gallons

Spill Cause: Equipment Failure

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 04/25/1996 11:00

Region of Spill: 1

Facility Tele:

Spill Type: UST

Caller Agency: Not reported

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone:

Spilled Code: 0001

Quant Recovered: 1 gallons

Resource Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 04/25/1996 11:53

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102237575

Exemption 6

Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/26/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/25/1996		

79

GRUMMAN AEROSPACE CORP.
STEWART AVE.
BETHPAGE, NY

AST
UST

U001854670
N/A

Nassau County UST:

Facility ID:	000001	Tank ID:	0372
Tank Location:	Indoors, Belowground	Capacity:	00010500
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	Internal Lining		
Ext Protection:	PAINTED [e.g. asphaltic]		
Description:	NITRIC & HYDROFLUORIC ACID MIX		
Leak Detect:	OTHER	Containment:	Diking
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0169
Total Tanks:	18		

Facility ID:	000001	Tank ID:	1092
Tank Location:	Indoors, Belowground	Capacity:	00005000
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Steel/Iron	Material Type:	Waste
Int Protection:	None		
Ext Protection:	NONE		
Description:	DYES/PIGMENTS, N.O.S.		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0175
Total Tanks:	18		

Facility ID:	000001	Tank ID:	1093
Tank Location:	Indoors, Belowground	Capacity:	00005000
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Steel/Iron	Material Type:	Waste
Int Protection:	None		
Ext Protection:	NONE		
Description:	DYES/PIGMENTS, N.O.S.		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0175
Total Tanks:	18		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Unknown
Int Protection: None
Ext Protection: NONE
Description: PHOTO CHEMICALS, NOS
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: 18

Tank ID: 1359
Capacity: 00000300
Tank Material: PLASTIC
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Galvanized Steel
Int Protection: None
Ext Protection: NONE
Description: EMPTY/AUXILARY TANK
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 18

Tank ID: 1403
Capacity: 00003000
Tank Material: Fiberglass Reinforced Plastic
Material Type: Waste

Containment: Double Wall Tank
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Galvanized Steel
Int Protection: None
Ext Protection: NONE
Description: EMPTY/AUXILARY TANK
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 18

Tank ID: 1404
Capacity: 00002500
Tank Material: Fiberglass Reinforced Plastic
Material Type: Waste

Containment: Double Wall Tank
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Wrapped Steel
Int Protection: None
Ext Protection: NONE
Description: WASTE OIL
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: 18

Tank ID: 2013
Capacity: 00000550
Tank Material: Fiberglass Reinforced Plastic
Material Type: Waste

Containment: Other
Product Gauge: Yes
Install Date: 0182

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: None
Ext Protection: NONE
Description: TANK, WASTE TREATMENT
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: 18

Tank ID: 9301
Capacity: 00065000
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 0172

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: None
Ext Protection: NONE
Description: TANK, WASTE TREATMENT
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Gravity
Total Tanks: 18

Tank ID: 9302
Capacity: 00040000
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 0172

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: None
Ext Protection: NONE
Description: TANK, WASTE TREATMENT
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Gravity
Total Tanks: 18

Tank ID: 9304
Capacity: 00065000
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 0172

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: Other
Ext Protection: NONE
Description: TANK, WASTE TREATMENT
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 18

Tank ID: 9305
Capacity: 00103000
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 0184

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: None
Ext Protection: NONE
Description: TANK, WASTE TREATMENT
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Gravity
Total Tanks: 18

Tank ID: 9306
Capacity: 00011770
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: None
Ext Protection: NONE
Description: TANK, WASTE TREATMENT
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: 18

Tank ID: 9308
Capacity: 00003300
Tank Material: Fiberglass Reinforced Plastic
Material Type: Waste

Containment: Other
Product Gauge: Yes
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: None
Ext Protection: NONE
Description: INORGANICS, MISC
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Gravity
Total Tanks: 18

Tank ID: 9328
Capacity: 00011800
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Other
Int Protection: None
Ext Protection: NONE
Description: FLUORIDE
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: 18

Tank ID: 9331
Capacity: 00011800
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: Yes
Install Date: 0184

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Steel/Iron
Int Protection: Internal Lining
Ext Protection: NONE
Description: SLUDGE, NOS
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 18

Tank ID: 9337
Capacity: 00010000
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 1284

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Steel/Iron
Int Protection: Internal Lining
Ext Protection: NONE
Description: SLUDGE, NOS
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 18

Tank ID: 9338
Capacity: 00010000
Tank Material: CONCRETE
Material Type: Waste

Containment: Other
Product Gauge: No
Install Date: 1284

Facility ID: 000001
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Double Walled Fiberglass
Int Protection: None
Ext Protection: CATHODIC PROTECTION
Description: OIL, FUEL #2
Leak Detect: ELECTRONIC
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: 18

Tank ID: 9339
Capacity: 00010000
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Double Wall Tank
Product Gauge: Yes
Install Date: 0394

Nassau County AST:

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RIDOLENE 53
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0047
Capacity (Gal): 1465
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0173

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0131
Capacity (Gal): 760
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0139
Capacity (Gal): 400
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0140
Capacity (Gal): 160
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: No
Install Date: 0161

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: CHROMIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0141
Capacity (Gal): 670
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0161

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0142
Capacity (Gal): 760
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Other
Description: SULPHURIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0143
Capacity (Gal): 670
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0161

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0144
Capacity (Gal): 760
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0213
Capacity (Gal): 190
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0161

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0214
Capacity (Gal): 250
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0161

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0215
Capacity (Gal): 350
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0161

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0216
Capacity (Gal): 350
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0161

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: TRICHLOROETHYLENE
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0256
Capacity (Gal): 250
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0186

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: TRICHLOROETHANE, 1,1,1-
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0259
Capacity (Gal): 50
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0261
Capacity (Gal): 760
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ALKALINE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0262
Capacity (Gal): 760
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: TRICHLOROETHANE, 1,1,1-
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0285
Capacity (Gal): 50
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: No
Install Date: 0160

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	0360
Tank Location:	Indoors, Aboveground	Capacity (Gal):	14000
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	POTASSIUM HYDROXIDE & NITRATE		
Leak Detect:	ELECTRONIC	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0186
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	0361
Tank Location:	Indoors, Aboveground	Capacity (Gal):	10500
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	RINSEWATER, ALKALINE		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0169
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	0363
Tank Location:	Indoors, Aboveground	Capacity (Gal):	10500
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Internal Lining		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	RINSEWATER, ACID		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0169
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	0365
Tank Location:	Indoors, Aboveground	Capacity (Gal):	10500
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	RINSEWATER, ALKALINE		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0169
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RIDOLENE 73
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0366
Capacity (Gal): 10500
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0169

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: ALKALINE SOLUTIONS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0371
Capacity (Gal): 10500
Tank Material: STEEL

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0169

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: SURFACTANTS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0384
Capacity (Gal): 115
Tank Material: OTHER

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0187

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ALODINE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0388
Capacity (Gal): 1570
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0173

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0399
Capacity (Gal): 4418
Tank Material: Fiberglass Reinforced Plastic

Material Type: Fresh/Product

Containment: NONE
Product Gauge: Yes
Install Date: 0180

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0400
Capacity (Gal): 4418
Tank Material: Fiberglass Reinforced Plastic

Material Type: Fresh/Product

Containment: NONE
Product Gauge: Yes
Install Date: 0180

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0449
Capacity (Gal): 1570
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0173

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: TURCO MASKANT
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0451
Capacity (Gal): 12630
Tank Material: OTHER

Material Type: Fresh/Product

Containment: VAULT
Product Gauge: Yes
Install Date: 0172

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Steel/Iron
Description: ZYGLO PENETRANT
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0490
Capacity (Gal): 2700
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0170

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Steel/Iron
Description: MAGNAFLUX
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0491
Capacity (Gal): 2200
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0170

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Steel/Iron
Description: MAGNAFLUX
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0493
Capacity (Gal): 6750
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0170

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: ALKALINE SOLUTIONS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0503
Capacity (Gal): 115
Tank Material: OTHER

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0187

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	0506
Tank Location:	Indoors, Aboveground	Capacity (Gal):	1300
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	CHROME DEACTIVATING SOLUTION		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0160
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	0508
Tank Location:	Indoors, Aboveground	Capacity (Gal):	1300
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	CHROME DEACTIVATING SOLUTION		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0160
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	0594
Tank Location:	Indoors, Aboveground	Capacity (Gal):	3200
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Internal Lining		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	SODIUM NITRATE		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Other	Install Date:	0177
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	0601
Tank Location:	Indoors, Aboveground	Capacity (Gal):	650
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	BASIC DEACTIVATING SOLUTION		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0168
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	0603
Tank Location:	Indoors, Aboveground	Capacity (Gal):	1300
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	CHROME DEACTIVATING SOLUTION		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0160
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	0604
Tank Location:	Indoors, Aboveground	Capacity (Gal):	1300
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	CHROME DEACTIVATING SOLUTION		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0160
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	0605
Tank Location:	Indoors, Aboveground	Capacity (Gal):	1300
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	CHROME DEACTIVATING SOLUTION		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0160
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	0606
Tank Location:	Indoors, Aboveground	Capacity (Gal):	1300
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	CHROME DEACTIVATING SOLUTION		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0160
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: NITRIC ACID & SODIUM SULFATE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0644
Capacity (Gal): 2350
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0161

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0645
Capacity (Gal): 2350
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: PHOSPHORIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0740
Capacity (Gal): 185
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0161

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: CAUSTICS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0780
Capacity (Gal): 748
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0173

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: PAINT, MISC
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0793
Capacity (Gal): 3600
Tank Material: STEEL

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0160

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: PAINT, MISC
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0794
Capacity (Gal): 3500
Tank Material: STEEL

Material Type: Waste
Containment: NONE
Product Gauge: Yes
Install Date: 0160

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: ALODINE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0815
Capacity (Gal): 3600
Tank Material: OTHER

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0183

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: FREON
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0930
Capacity (Gal): 50
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0186

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ALKALINE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0939
Capacity (Gal): 1570
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0174

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: TRICHLOROETHANE, 1,1,1-
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0941
Capacity (Gal): 500
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: No
Install Date: 0162

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RIDOLENE 53
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0956
Capacity (Gal): 6100
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0166

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ALKALINE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0957
Capacity (Gal): 6100
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0172

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ALODINE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0958
Capacity (Gal): 6100
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0166

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0959
Capacity (Gal): 6100
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0172

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Other
Description: SULFURIC & OXALIC ACID MIX
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1021
Capacity (Gal): 1465
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0174

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1022
Capacity (Gal): 1465
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0177

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ALODINE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1023
Capacity (Gal): 1465
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0174

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1024
Capacity (Gal): 1465
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0177

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1039
Capacity (Gal): 330
Tank Material: OTHER

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1052
Capacity (Gal): 157
Tank Material: OTHER

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0173

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: SURFACTANTS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1053
Capacity (Gal): 157
Tank Material: OTHER

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0173

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1054
Capacity (Gal): 157
Tank Material: OTHER

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0173

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TRICHLOROETHANE, 1,1,1-
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1055
Capacity (Gal): 157
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0173

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: NITRIC & HYDROFLUORIC ACID MIX
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1056
Capacity (Gal): 45
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0173

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	1057
Tank Location:	Indoors, Aboveground	Capacity (Gal):	23
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Other		
Description:	TANK, WATER RINSE	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Suction	Install Date:	0273
Fill Type:	Pumped		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1058
Tank Location:	Indoors, Aboveground	Capacity (Gal):	45
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Internal Lining		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Other		
Description:	NITRIC & HYDROFLUORIC ACID MIX	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Suction	Install Date:	0173
Fill Type:	Pumped		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1059
Tank Location:	Indoors, Aboveground	Capacity (Gal):	270
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	TANK, WATER RINSE	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Submersible	Install Date:	0170
Fill Type:	Pumped		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1063
Tank Location:	Indoors, Aboveground	Capacity (Gal):	157
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Other		
Description:	ISOPROPYL ALCOHOL	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Suction	Install Date:	0173
Fill Type:	Pumped		
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RIDOLENE 53
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1068
Capacity (Gal): 1570
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0174

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: RINSEWATER, ALKALINE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1069
Capacity (Gal): 1570
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0174

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ACIDS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1071
Capacity (Gal): 630
Tank Material: OTHER

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0177

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1104
Capacity (Gal): 185
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0176

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ALODINE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1106
Capacity (Gal): 185
Tank Material: Fiberglass Reinforced Plastic

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0176

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1107
Capacity (Gal): 185
Tank Material: Fiberglass Reinforced Plastic

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0176

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1112
Capacity (Gal): 9975
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0177

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1120
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1121
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ALKALINE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1122
Capacity (Gal): 18200
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: NITRIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1123
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1124
Capacity (Gal): 18200
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0179

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1125
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ALKALINE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1126
Capacity (Gal): 18200
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Other
Description: HYDROFLUORIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1127
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1128
Capacity (Gal): 18200
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0179

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: NITRIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1129
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1130
Capacity (Gal): 18200
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0179

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1131
Capacity (Gal): 9743
Tank Material: STEEL

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: WATER, MISC. INDUSTRIAL WASTES
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1132
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: NITRIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1133
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: NITRIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1134
Capacity (Gal): 9743
Tank Material: OTHER

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TRICHLOROETHANE, 1,1,1-
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1137
Capacity (Gal): 7700
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0180

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RIDOLENE 57
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1138
Capacity (Gal): 9200
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0180

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ALKALINE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1139
Capacity (Gal): 17400
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0180

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1140
Capacity (Gal): 9200
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0180

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ALODINE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1141
Capacity (Gal): 9200
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0180

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1142
Capacity (Gal): 17400
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0180

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: CHROMIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1144
Capacity (Gal): 9200
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0180

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: RINSEWATER, ACID
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 1145
Capacity (Gal): 17400
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0180

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ACIDS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1150
Capacity (Gal): 9200
Tank Material: OTHER

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0181

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ACIDS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1151
Capacity (Gal): 9200
Tank Material: OTHER

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0181

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ACIDS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1152
Capacity (Gal): 9200
Tank Material: OTHER

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0181

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1156
Capacity (Gal): 517
Tank Material: OTHER

Material Type: Fresh/Product
Containment: NONE
Product Gauge: No
Install Date: 0179

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: EMPTY/AUXILARY TANK
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1157
Capacity (Gal): 517
Tank Material: OTHER

Material Type: Fresh/Product
Containment: NONE
Product Gauge: No
Install Date: 0179

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: NITRIC & HYDROFLUORIC ACID MIX
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1184
Capacity (Gal): 10300
Tank Material: STEEL

Material Type: Waste
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0181

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: NITRIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1190
Capacity (Gal): 170
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0176

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TRADE NAME, ORGANIC
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1191
Capacity (Gal): 1800
Tank Material: OTHER

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0181

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Other
Description: ACIDS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1193
Capacity (Gal): 3700
Tank Material: OTHER

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0182

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: NONE
Piping Type: Other
Description: ACIDS, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1194
Capacity (Gal): 3700
Tank Material: OTHER

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0182

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	1207
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	10000
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	TETRACHLOROETHYLENE		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0183
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	1221
Tank Location:	Indoors, Aboveground	Capacity (Gal):	2500
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	TRICHLOROETHYLENE		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Submersible	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0185
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	1222
Tank Location:	Indoors, Aboveground	Capacity (Gal):	8800
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	RIDOLENE 57		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0185
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	1223
Tank Location:	Indoors, Aboveground	Capacity (Gal):	17400
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	TANK, WATER RINSE		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0185
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: NITRIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1224
Capacity (Gal): 8800
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: NITRIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1225
Capacity (Gal): 8800
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1226
Capacity (Gal): 17400
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ALODINE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1228
Capacity (Gal): 8800
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1229
Capacity (Gal): 17400
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: SULPHURIC ACID
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1230
Capacity (Gal): 8800
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1231
Capacity (Gal): 17400
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: SODIUM DICHROMATE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1232
Capacity (Gal): 8800
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1233
Capacity (Gal): 17400
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: GLYCOL
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1239
Capacity (Gal): 900
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: Yes
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: TRICHLOROETHYLENE
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1251
Capacity (Gal): 365
Tank Material: STEEL

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0186

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: SILICATES, NOS
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1252
Capacity (Gal): 38430
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0185

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1253
Capacity (Gal): 38430
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0185

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: METHANOL
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1254
Capacity (Gal): 6000
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0185

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: POTASSIUM NITRATE
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1263
Capacity (Gal): 1600
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0177

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM NITRITE
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1264
Capacity (Gal): 2700
Tank Material: STEEL

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0160

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: LEAD
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1265
Capacity (Gal): 375
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0181

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: ZINC
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1266
Capacity (Gal): 250
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0181

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: ETHYLENE GLYCOL
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1267
Capacity (Gal): 5300
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0187

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TETRACHLOROETHYLENE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1272
Capacity (Gal): 700
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0185

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1273
Capacity (Gal): 2958
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0188

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: ETHYLENE GLYCOL
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1274
Capacity (Gal): 1525
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0188

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: Internal Lining
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: TANK, WATER RINSE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1275
Capacity (Gal): 1525
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0188

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: SODIUM NITRATE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 1276
Capacity (Gal): 1960
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0188

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	1303
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	600
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	TRICHLOROETHANE, 1,1,1-	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Suction	Install Date:	1255
Fill Type:	Gravity		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1304
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	500
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	AMMONIA, ANHYDROUS	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	Yes
Dispense Method:	Suction	Install Date:	0169
Fill Type:	Other		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1345
Tank Location:	Indoors, Aboveground	Capacity (Gal):	30
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	TRICHLOROETHYLENE	Containment:	OTHER
Leak Detect:	OTHER	Product Gauge:	No
Dispense Method:	Suction	Install Date:	0793
Fill Type:	Pumped		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1346
Tank Location:	Indoors, Aboveground	Capacity (Gal):	14
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE	Material Type:	Fresh/Product
Piping Type:	Not reported		
Description:	PHOTO DEVELOPER	Containment:	DIKING AND PAD
Leak Detect:	OTHER	Product Gauge:	No
Dispense Method:	Not reported	Install Date:	1294
Fill Type:	Other		
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	1347
Tank Location:	Indoors, Aboveground	Capacity (Gal):	13
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Not reported	Material Type:	Fresh/Product
Description:	URISCREEN-PEROXIDE & NA PERBORATE	Containment:	DIKING AND PAD
Leak Detect:	OTHER	Product Gauge:	No
Dispense Method:	Not reported	Install Date:	1294
Fill Type:	Other		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1348
Tank Location:	Indoors, Aboveground	Capacity (Gal):	13
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Not reported	Material Type:	Fresh/Product
Description:	RINSEWATER, ACID	Containment:	DIKING AND PAD
Leak Detect:	OTHER	Product Gauge:	No
Dispense Method:	Not reported	Install Date:	1294
Fill Type:	Other		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1349
Tank Location:	Indoors, Aboveground	Capacity (Gal):	14
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Not reported	Material Type:	Fresh/Product
Description:	PHOTO DEVELOPER	Containment:	DIKING AND PAD
Leak Detect:	OTHER	Product Gauge:	No
Dispense Method:	Not reported	Install Date:	1294
Fill Type:	Other		
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	1350
Tank Location:	Indoors, Aboveground	Capacity (Gal):	13
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Not reported	Material Type:	Fresh/Product
Description:	URISCREEN-PEROXIDE & NA PERBORATE	Containment:	DIKING AND PAD
Leak Detect:	OTHER	Product Gauge:	No
Dispense Method:	Not reported	Install Date:	1294
Fill Type:	Other		
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Not reported
Description: RINSEWATER, ACID
Leak Detect: OTHER
Dispense Method: Not reported
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1351
Capacity (Gal): 13
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 1294

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Not reported
Description: PHOTO DEVELOPER
Leak Detect: OTHER
Dispense Method: Not reported
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1352
Capacity (Gal): 13
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 1294

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Not reported
Description: URISCREEN-PEROXIDE & NA PERBORATE
Leak Detect: OTHER
Dispense Method: Not reported
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1353
Capacity (Gal): 13
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 1294

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Not reported
Description: RINSEWATER, ACID
Leak Detect: OTHER
Dispense Method: Not reported
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1354
Capacity (Gal): 13
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 1294

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Not reported
Description: PHOTO DEVELOPER
Leak Detect: OTHER
Dispense Method: Not reported
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1355
Capacity (Gal): 13
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 1294

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Not reported
Description: URISCREEN-PEROXIDE & NA PERBORATE
Leak Detect: OTHER
Dispense Method: Not reported
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1356
Capacity (Gal): 13
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 1294

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Not reported
Description: RINSEWATER, ACID
Leak Detect: OTHER
Dispense Method: Not reported
Fill Type: Other
Total Tanks: Not reported

Tank ID: 1357
Capacity (Gal): 13
Tank Material: OTHER

Material Type: Fresh/Product
Containment: DIKING AND PAD
Product Gauge: No
Install Date: 1294

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, MOTOR
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 2004
Capacity (Gal): 275
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: Yes
Install Date: 0168

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	2090
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	517
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	PHOTO CHEMICALS, NOS		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0184
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	6006
Tank Location:	Indoors, Aboveground	Capacity (Gal):	175
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	ORGANICS, MISC		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Other	Install Date:	0184
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	6008
Tank Location:	Indoors, Aboveground	Capacity (Gal):	175
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	WASTEWATER TREATMENT CHEMICALS, NOS		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Submersible	Product Gauge:	No
Fill Type:	Other	Install Date:	0184
Total Tanks:	Not reported		
Facility ID:	000001	Tank ID:	7002
Tank Location:	Indoors, Aboveground	Capacity (Gal):	4800
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Description:	EMPTY/AUXILIARY TANK		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0160
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	9001
Tank Location:	Indoors, Aboveground	Capacity (Gal):	11000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0147
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9002
Tank Location:	Indoors, Aboveground	Capacity (Gal):	11000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0147
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9003
Tank Location:	Indoors, Aboveground	Capacity (Gal):	11000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0147
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9004
Tank Location:	Indoors, Aboveground	Capacity (Gal):	11000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0147
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	9005
Tank Location:	Indoors, Aboveground	Capacity (Gal):	15000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0147
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9006
Tank Location:	Indoors, Aboveground	Capacity (Gal):	15000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0170
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9007
Tank Location:	Indoors, Aboveground	Capacity (Gal):	15000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0170
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9008
Tank Location:	Indoors, Aboveground	Capacity (Gal):	15000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0170
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	9009
Tank Location:	Indoors, Aboveground	Capacity (Gal):	15000
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WATER, MISC. INDUSTRIAL WASTES		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0170
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9010
Tank Location:	Indoors, Aboveground	Capacity (Gal):	4700
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Internal Lining		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	SLUDGE WASTES, INORGANIC		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0177
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9011
Tank Location:	Indoors, Aboveground	Capacity (Gal):	4700
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Internal Lining		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	SLUDGE WASTES, INORGANIC		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0177
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9012
Tank Location:	Indoors, Aboveground	Capacity (Gal):	2000
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Internal Lining		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	INORGANICS, MISC		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Other	Install Date:	0177
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: CALCIUM CARBONATE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Other
Total Tanks: Not reported

Tank ID: 9013
Capacity (Gal): 300
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0177

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: CALCIUM CARBONATE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Other
Total Tanks: Not reported

Tank ID: 9014
Capacity (Gal): 300
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0177

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WASTE TREATMENT
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9303
Capacity (Gal): 3800
Tank Material: CONCRETE

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0143

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: TANK, WASTE TREATMENT
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9307
Capacity (Gal): 16000
Tank Material: Fiberglass Reinforced Plastic

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0184

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	9309
Tank Location:	Indoors, Aboveground	Capacity (Gal):	16000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	TANK, WASTE TREATMENT		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Submersible	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0184
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9310
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	20600
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Waste
Piping Type:	Other		
Description:	ACIDS, NOS	Containment:	DIKING AND PAD
Leak Detect:	NONE	Product Gauge:	Yes
Dispense Method:	Submersible	Install Date:	0184
Fill Type:	Pumped		
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9311
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	12690
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Waste
Piping Type:	Other		
Description:	CHARACTERISTIC OF CORROSIVITY	Containment:	DIKING AND PAD
Leak Detect:	NONE	Product Gauge:	Yes
Dispense Method:	Submersible	Install Date:	0184
Fill Type:	Pumped		
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9312
Tank Location:	Indoors, Aboveground	Capacity (Gal):	16900
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	NONE	Material Type:	Waste
Piping Type:	Other		
Description:	NITRIC ACID	Containment:	DIKING AND PAD
Leak Detect:	NONE	Product Gauge:	Yes
Dispense Method:	Submersible	Install Date:	0184
Fill Type:	Pumped		
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: SULPHURIC ACID
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9313
Capacity (Gal): 10000
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: ORGANICS, MISC
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9316
Capacity (Gal): 16000
Tank Material: Fiberglass Reinforced Plastic

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: CATHODIC PROTECTION
Piping Type: Other
Description: WATER TANK
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 9317
Capacity (Gal): 4000
Tank Material: STEEL

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ORGANICS, MISC
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9318
Capacity (Gal): 40
Tank Material: OTHER

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0184

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: HYDROGEN PEROXIDE
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9320
Capacity (Gal): 7000
Tank Material: OTHER

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0184

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: AMMONIUM NITRATE
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 9322
Capacity (Gal): 2000
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0188

Facility ID: 000001
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Other
Description: ORGANICS, MISC
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9323
Capacity (Gal): 980
Tank Material: STEEL

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0184

Facility ID: 000001
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Other
Description: SODIUM HYDROXIDE
Leak Detect: NONE
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 9329
Capacity (Gal): 8000
Tank Material: Fiberglass Reinforced Plastic

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0184

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U001854670

Facility ID:	000001	Tank ID:	9330
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	11800
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Internal Lining		
Ext Protection:	PAINTED [e.g. asphaltic]		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	HYDROFLUORIC ACID		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Submersible	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0184
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9332
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	5800
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	OTHER		
Piping Type:	Fiberglass	Material Type:	Waste
Description:	WATER TANK		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0184
Total Tanks:	Not reported		

Facility ID:	000001	Tank ID:	9333
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	5800
Tank Status:	In Service	Tank Material:	OTHER
Int Protection:	None		
Ext Protection:	OTHER		
Piping Type:	Fiberglass	Material Type:	Waste
Description:	WATER TANK		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0184
Total Tanks:	Not reported		

80

NY Spills

S102100303
N/A

PLAINVIEW, NY

SPILLS:

Facility ID:	9408431	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	CITIZEN
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/25/1994		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102100303

Exemption 6

Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	09/25/1994 17:30	Reported to Dept:	09/25/1994 19:30
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/25/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/26/1994		

81

MOBIL OIL
755 SOUTH OYSTER BAY ROAD
BETHPAGE, NY

LUST

S100781305
N/A

LUST:

Facility ID:	9309724	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	CHUCK PEZANO	Caller Agency:	CROMPCO
Caller Phone:	(215) 646-3161	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(703) 846-5714
Spiller:	MOBIL OIL CORP		
Address:	Not reported		
	Not reported		
Spill Class:	No spill occurred. (Not Possible)	Resource Affected:	On Land
Spill Closed Dt:	08/17/1994	Spill Source:	Gas Station
Spill Cause:	Tank Test Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	11/11/1993 09:54
Spill Notifier:	Tank Tester		
Spill Date:	11/11/1993 08:30		
Cleanup Ceased:	08/17/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	08/18/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/12/1993		

81

JOHNS SOUTH BAY MOBIL
755 S OYSTER BAY RD
BETHPAGE, NY 11714

FINDS
RCRIS-LQG

1000281333
NYD981555360

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

JOHNS SOUTH BAY MOBIL (Continued)

1000281333

RCRIS:

Owner: JOHN SOUTH BAY MOBIL
(516) 681-2068

Contact: JOHN PARISI
(516) 681-2068

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D008	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

81

MOBIL S/S #17-KKJ
755 S. OYSTER BAY RD.
BETHPAGE, NY

AST
UST

U001445843
N/A

Nassau County UST:

Facility ID:	041111	Tank ID:	0006
Tank Location:	Indoors, Belowground	Capacity:	00001000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	Internal Lining		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0490
Total Tanks:	2		

Facility ID:	041111	Tank ID:	0007
Tank Location:	Indoors, Belowground	Capacity:	00001000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Double Walled Fiberglass	Material Type:	Waste
Int Protection:	Internal Lining		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	WASTE OIL		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0490
Total Tanks:	2		

Nassau County AST:

Facility ID:	041111	Tank ID:	0008
Tank Location:	Indoors, Aboveground	Capacity (Gal):	300
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	OIL, MOTOR	Containment:	DOUBLE WALL TANK
Leak Detect:	ELECTRONIC	Product Gauge:	Yes
Dispense Method:	Suction	Install Date:	0892
Fill Type:	Pumped		
Total Tanks:	Not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

82	CORNICHE OF HICKSVILLE 285-4 S BROADWAY HICKSVILLE, NY 11801	RCRIS-SQG FINDS	1000315603 NYD982717472
----	---	----------------------------------	--

RCRIS:

Owner: HICKSVILLE CORNICHE INC
(212) 555-1212

Contact: HI EUN SHON
(516) 935-9525

Classification: Small Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

83	HICKSVILLE FIRESTONE 300 S BROADWAY HICKSVILLE, NY	AST	A100090553 N/A
----	---	------------	---------------------------------

Nassau County AST:

Facility ID: 055305
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: WASTE OIL
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0003
Capacity (Gal): 220
Tank Material: STEEL

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: No
Install Date: 0591

83	ABBEY RENT ALL 301 S BROADWAY HICKSVILLE, NY	AST	A100090543 N/A
----	---	------------	---------------------------------

Nassau County AST:

Facility ID: 055255
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0003
Capacity (Gal): 220
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0394

83	ABBEY RENT ALL 301 SOUTH BROADWAY HICKSVILLE, NY	LUST	S100668658 N/A
----	---	-------------	---------------------------------

LUST:

Facility ID: 8903512

Region of Spill: 1

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ABBEY RENT ALL (Continued)

S100668658

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	ALICE	Caller Agency:	NCDH
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(718) 428-0400
Spiller:	ABBEY RENT ALL		
Address	301 SOUTH BROADWAY HICKSVILLE, NY		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	02/13/1990	Spill Source:	Other Non Commercial/Industrial
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	07/07/1989 11:45
Spill Notifier:	Health Department		
Spill Date:	07/07/1989 11:45		
Cleanup Ceased:	02/13/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/15/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/11/1989		

83

**UNKK
BROADWAY / 4TH STREET
HICKSVILLE, NY**

NY Spills

**S102137024
N/A**

SPILLS:

Facility ID:	8607002	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	Not reported	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	0009
Spill Closed Dt:	02/17/1987	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	In Sewer
Quantity Spilled:	15 gallons	Spill Source:	Passenger Vehicle
Spill Cause:	Traffic Accident	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	02/17/1987 09:17
Spill Notifier:	Fire Department	Tank Capacity:	0 Gallons
Spill Date:	02/17/1987 08:20	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/17/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNKK (Continued)

S102137024

Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/17/1987

83

HICKSVILLE FIRESTONE
300 S BROADWAY
HICKSVILLE, NY 11801

FINDS
LUST
RCRIS-LQG

1000272865
NYD012729554

RCRIS:

Owner: CLIFF FRIETAG
(212) 555-1212
Contact: THOMAS DIETRICH
(516) 931-0170
Classification: Large Quantity Generator

Waste	Quantity
D000	0.000 (N)
NONE	0.000 (N)

Waste	Quantity
D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

LUST:

Facility ID: 9010583
Facility Contact: Not reported
Investigator: WALSH
Caller Name: BOB STRECKER
Caller Phone: (516) 271-0077
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: HICKSVILLE FIRESTONE
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 02/14/1992
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 01/02/1991 12:00
Cleanup Ceased: 02/14/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 01/14/1993
Corrective Action Plan Submitted: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GARRISON FUEL OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 931-0170

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 01/03/1991 09:15

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HICKSVILLE FIRESTONE (Continued)

1000272865

Date Spill Entered In Computer Data File: 01/04/1991

84

**RELIANCE FUEL OIL
30 CEDAR AVE
BETHPAGE, NY**

NY Spills

S102098836
N/A

SPILLS:

Facility ID:	9311747	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LAMANNO	Spill Type:	Facility
Caller Name:	JIM CRAWFORD	Caller Agency:	RELIANCE
Caller Phone:	(516) 475-4770	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	RELIANCE FUEL OIL		
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	2 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	12/31/1993 08:07	Reported to Dept:	01/03/1994 14:06
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/04/1994		

85

**OYSTER BAY TOWN
GRAND AVENUE / 4TH STREET
HICKSVILLE, NY**

NY Spills

S102136929
N/A

SPILLS:

Facility ID:	8604429	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	O'Neill	Spill Type:	UST
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 922-5800

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

OYSTER BAY TOWN (Continued)

S102136929

Spiller:	OYSTER BAY TOWN	
Address	Not reported	
	OYSTER BAY, NY	
Spill Class:	Not reported	
Spill Closed Dt:	10/28/1986	
Material Class:	Petroleum	Spilled Code: 0009
Quantity Spilled:	0 gallons	Quant Recovered: 0 gallons
Spill Cause:	Deliberate	Resource Affected: In Sewer
Water Affected:	Not reported	Spill Source: Other Non Commercial/Industrial
Spill Notifier:	Health Department	PBS Number: Not reported
Spill Date:	10/09/1986 15:00	Reported to Dept: 10/09/1986 15:50
Tank Number:	Not reported	Tank Capacity: 0 Gallons
Test method:	Not reported	Leak Rate: 0.00
Gross Leak/Fail:	Not reported	
Cleanup Ceased:	10/28/1986	
Last Inspection:	Not reported	
Cleanup Meets Standard:	True	
Recommended Penalty:	No Penalty	
Spiller Cleanup Date:	Not reported	
Enforcement Date:	Not reported	
Investigation Complete:	Not reported	
UST Involvement:	False	
Spill Record Last Update:	11/15/1995	
Corrective Action Plan Submitted:	Not reported	
Date Spill Entered In Computer Data File:	10/25/1986	

86

COMMANDER
53 LAWNVIEW AVE
HICKSVILLE, NY

LUST

S101103113
N/A

LUST:

Facility ID:	9403227	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	ROBERT SIRAGUSA	Caller Agency:	COMMANDER
Caller Phone:	(516) 922-7000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	COMMANDER		
Address	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/07/1994		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	06/06/1994 12:00	Reported to Dept:	06/06/1994 12:44
Cleanup Ceased:	06/07/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

COMMANDER (Continued)

S101103113

Spill Record Last Update: 06/08/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/07/1994

87

**UNK VEHICLES
BALSAM PL / STEWART AVE
BETHPAGE, NY**

NY Spills

**S102091540
N/A**

SPILLS:

Facility ID: 9109921
Facility Contact: Not reported
Investigator: DEROSA
Caller Name: WILLIAM POWELL
Caller Phone: (516) 573-3333
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: UNK VEHICLES
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCPD
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 12/19/1991
Material Class: Petroleum
Quantity Spilled: 10 gallons
Spill Cause: Traffic Accident
Water Affected: Not reported
Spill Notifier: Police Department
Spill Date: 12/18/1991 04:20
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/19/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/23/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/19/1991

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: In Sewer
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 12/18/1991 05:47
Tank Capacity: 0 Gallons
Leak Rate: 0.00

88

HICKSVILLE, NY

LUST

**S100147563
N/A**

LUST:

Facility ID: 8809382
Facility Contact: Not reported
Investigator: NCFM
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100147563

Spiller:
Address

WESTBURY, NY

Exemption 6

Spill Class: Not reported
Spill Closed Dt: 03/06/1989
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 03/05/1989 10:30
Cleanup Ceased: 03/06/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/07/1989
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/07/1989

Resource Affected: On Land
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 03/05/1989 12:37

88

HIP - EAST NASSAU REGION
350 S BROADWAY
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000790857
NYD987023462

RCRIS:

Owner: HIP OF GREATER NEW YORK
(212) 630-5000

Contact: GEORGE MARLO
(516) 938-0100

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D002	0.000 (N)
D009	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

88

HICKSVILLE, NY

LUST

S100667550
N/A

LUST:

Facility ID: 8806012
Facility Contact: Not reported
Investigator: NONE
Caller Name: INSPECTOR RICH MAGEE
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 938-4099

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100667550

Exemption 6

Spiller:
Address

HICKSVILLE, NY

Spill Class: Not reported
Spill Closed Dt: 10/18/1988
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 10/15/1988 12:11
Cleanup Ceased: 10/18/1988
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/22/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/19/1988

Resource Affected: On Land
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 10/17/1988 09:40

89

VAGELAS INC
COMMERCIAL / NEW SOUTH RD
HICKSVILLE, NY

NY Spills

S102136875
N/A

SPILLS:

Facility ID: 8603033
Facility Contact: Not reported
Investigator: Not reported
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: VAGELAS INC
Address: 25 BUCKINGHAM PLACE
MANHASSET, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 05/04/1987
Material Class: Petroleum
Quantity Spilled: 20 gallons
Spill Cause: Traffic Accident
Water Affected: Not reported
Spill Notifier: Health Department
Spill Date: 08/06/1986 02:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 05/04/1987
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/13/1995
Corrective Action Plan Submitted: Not reported

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Commercial Vehicle
PBS Number: Not reported
Reported to Dept: 08/06/1986 09:55
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

VAGELAS INC (Continued)

S102136875

Date Spill Entered In Computer Data File: 08/12/1986

89

**RUCO POLYMER CORP. (HOOKER CHEM)
NEW SOUTH ROAD
HICKSVILLE, NY 11801**

**SHWS
NY Spills**

**S101008268
N/A**

SHWS:

Facility ID:	130004	EPA ID:	NYD002920312
Owner:	Ruco Polymer Corp. New South Road Hicksville, NY 11802		
Owner Telephone:	Not reported		
Operator:	Not reported		
Contact:	Not reported	Telephone	Not reported
Site Classification:	Significant threat to the public health or environment - action required.		
Region:	1		
Site Type:	Lagoon		
Acres:	15	User:	Hooker Chemicals
HW Started:	1946	HW Ended:	late 70's
HW Disposed:	Plant #1 Ester Sump: Residual organics., 2 Ethylhexanol, alcohols, diethylene glycol., ethylene glycol, plasticizer, adipic acid., polyester, Plant #2 polymer solids, PCBs (BOO7) (FOO2)., Vinyl Chloride, trichloroethylene, vinyl acetate		
Units:	Residuals from, drying beds		
Air Data:	Unavailable	Surf. Water Data:	Unavailable
Grnd. Water Data:	Available	Soil Data:	Available
Sediment Data:	Unavailable		
Ground Water Standards Contravention:	Yes		
Drinking Water Standards Contravention:	No		
Surface Water Standards Contravention:	No		
Air Standards Contravention:	No		
Enforcement Status:	Negotiation In Progress	Legal Action:	No
State Action:	No	Fed Action:	Yes
Remedial Action:	In Progress		
Remed action type:	Off-site GW Invest.and on-site remedial design.		
Soil Type:	Sand & Gravel		
Grnd Water Depth:	50 feet		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RUCO POLYMER CORP. (HOOKER CHEM) (Continued)

S101008268

Assessment of Environmental Problems:

Groundwater adjacent to site has been documented to contain vinylchloride. Three inactive lagoons were filled with waste and covered. Soil and groundwater have been found to be contaminated with vinylchloride and other chlorinated hydrocarbons.

Assessment of Health Problems:

The potential exposure to site contaminants is through off-site migration of contaminated groundwater. The Bethpage Water District (BWD) operates three well fields (Plants 4, 5 & 6) which are located approximately 2500 feet down gradient of the RUCO site and the Grumman and Navy sites (see site #130003a and 130003b). Plants 4 and 6 have become impacted by groundwater contamination as of the Summer of 1993. Grumman has funded treatment for these two plants and is currently paying the BWD for O&M. The Navy has agreed to fund treatment for BWD Plant 5 in anticipation that it too will become impacted by groundwater contamination.

SPILLS:

Facility ID:	9607043	Region of Spill:	1
Facility Contact:	ADAM YABLONSKY	Facility Tele:	(516) 391-6171
Investigator:	UNASSIGNED	Spill Type:	UST
Caller Name:	ADAM YABLONSKY	Caller Agency:	LILCO
Caller Phone:	(516) 391-6171	Caller Extension:	Not reported
Notifier Name:	BOB LOTTEN	Notifier Agency:	LILCO
Notifier Phone:	(516) 545-4016	Notifier Extension:	Not reported
Spiller Contact:	ADAM YABLONSKY	Spiller Phone:	(516) 391-6590
Spiller:	LILCO		
Address	445 BROADHOLLOW ROAD MELVILLE, NY		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0016
Quantity Spilled:	10 gallons	Quant Recovered:	0 gallons
Spill Cause:	Traffic Accident	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	09/04/1996 05:20	Reported to Dept:	09/04/1996 06:17
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/09/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	09/04/1996		

90

**GRAND PRIX PERFORMANCE
777 S OYSTER BAY RD
BETHPAGE, NY 11714**

**RCRIS-SQG 1001119704
NYR000029942**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRAND PRIX PERFORMANCE (Continued)

1001119704

RCRIS:

Owner: R & J REALTY
(516) 938-8888

Contact: STEVE SCHERER
(516) 822-1550

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)	D006	0.000 (N)
D008	0.000 (N)	D018	0.000 (N)
D035	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

90

**USA AUTO MALL
777 S OYSTER BAY RD
BETHPAGE, NY 11714**

**RCRIS-SQG
FINDS**

**1000372483
NYD065956922**

RCRIS:

Owner: REP CORP
(516) 938-8888

Contact: RICHARD PARISI
(516) 827-3300

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)
D008	0.000 (N)	D018	0.000 (N)
D039	0.000 (N)	D040	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

90

**GRAND PRIX PERFORMANCE LT
777 S OYSTER BAY RD
BETHPAGE, NY**

AST

**A100090858
N/A**

Nassau County AST:

Facility ID: 056860
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, MOTOR
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0001
Capacity (Gal): 275
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0795

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRAND PRIX PERFORMANCE LT (Continued)

A100090858

Facility ID:	056860	Tank ID:	0002
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	240
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]		
Piping Type:	Steel/Iron	Material Type:	Waste
Description:	OIL, MOTOR		
Leak Detect:	OTHER	Containment:	DOUBLE WALL TANK
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0795
Total Tanks:	Not reported		

91

NARDA MICROWAVE CORP
75 COMMERCIAL ST
HICKSVILLE, NY 11801

FINDS

1000789577
NYD987010386

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Facility has an active water discharge permit (under PCS)

92

NORTHROP GRUMMON FACILITY
1111 STEWART AVENUE
BETHPAGE, NY

NY Spills

S102400817
N/A

SPILLS:

Facility ID:	9606555	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DECANDIA	Spill Type:	UST
Caller Name:	JOHN SELDA	Caller Agency:	NORTHROP GRUMMON CORP
Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NORTHROP GRUMMON FACILITY		
Address:	1111 STEWART AVENUE BETHPAGE, NY 11714-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0020
Quantity Spilled:	10 gallons	Quant Recovered:	10 gallons
Spill Cause:	Human Error	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	08/21/1996 11:00	Reported to Dept:	08/21/1996 16:01
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/03/1996		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NORTHROP GRUMMON FACILITY (Continued)

S102400817

Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/21/1996

92

**GRUMMAN AEROSPACE
BUILDING 04-01-1
BETHPAGE, NY**

LUST

**S100169213
N/A**

LUST:

Facility ID: 8901527
Facility Contact: Not reported
Investigator: LEUNG
Caller Name: MIKE TORREL
Caller Phone: (516) 349-8989
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: MAIL STOP B08
BETHPAGE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GEN UTILITIES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-8176

Spill Class: Not reported
Spill Closed Dt: 05/23/1989
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 05/12/1989 12:00
Cleanup Ceased: 05/23/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/24/1989

Resource Affected: Groundwater
Spill Source: Major Facility 400,000 gallons
PBS Number: Not reported
Reported to Dept: 05/16/1989 09:55

Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/17/1989

92

**GRUMMAN AEROSPACE
BUILDING #1
BETHPAGE, NY**

LUST

**S100171849
N/A**

LUST:

Facility ID: 8705197
Facility Contact: Not reported
Investigator: GOERTZ
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: Not reported
BETHPAGE, NY
Spill Class: Not reported
Spill Closed Dt: 10/14/1987
Spill Cause: Tank Test Failure

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-0387

Resource Affected: Groundwater

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S100171849

Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	09/21/1987 16:30	Reported to Dept:	09/22/1987 08:45
Cleanup Ceased:	10/14/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	10/14/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/25/1987		

92

**GRUMMAN AEROSPACE
GRUMMAN FACILITY BLDG 1
BETHPAGE, NY**

LUST

**S100171783
N/A**

LUST:

Facility ID:	8704386	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GOERTZ	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	GRUMMAN AEROSPACE		
Address:	Not reported HICKSVILLE, NY 11802		
Spill Class:	Not reported	Resource Affected:	Groundwater
Spill Closed Dt:	10/14/1987	Spill Source:	Other Commercial/Industrial
Spill Cause:	Tank Test Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	08/27/1987 07:40
Spill Notifier:	Fire Department		
Spill Date:	08/26/1987 16:00		
Cleanup Ceased:	10/14/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	10/14/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/31/1987		

92

**GRUMMAN AEROSPACE
BUILDING 116-01-1
BETHPAGE, NY**

LUST

**S100173006
N/A**

LUST:

Facility ID:	8901526	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S100173006

Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	MIKE TORREL	Caller Agency:	GEN UTILITIES
Caller Phone:	(516) 349-8989	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	GRUMMAN AEROSPACE		
Address:	MAIL STOP B08 BETHPAGE, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	05/01/1992		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Major Facility 400,000 gallons
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	05/16/1989 12:00	Reported to Dept:	05/16/1989 09:55
Cleanup Ceased:	05/01/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/05/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/17/1989		

92

GRUMMAN AEROSPACE
GRUMMAN AEROSPACE
BETHPAGE, NY

LUST
NY Spills

S100559911
N/A

LUST:

Facility ID:	9304043	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F TL MOSF	Spill Type:	UST
Caller Name:	SCOTT	Caller Agency:	F&N
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AEROSPACE		
Address:	Not reported Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/15/1996		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	06/29/1993 13:30	Reported to Dept:	06/29/1993 14:06
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S100559911

UST Involvement: True
Spill Record Last Update: 04/15/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/01/1993

SPILLS:

Facility ID: 8707733
Facility Contact: Not reported
Investigator: HOFMANN
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: Not reported
BETHPAGE, NY
Spill Class: Not reported
Spill Closed Dt: 12/31/1987
Material Class: Not reported
Quantity Spilled: 0 UNITS NOT REPORTED
Spill Cause: Human Error
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 12/08/1987 18:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/31/1987
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/04/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/09/1987

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-2385

Spilled Code: Not reported
Quant Recovered: 0 UNITS NOT REPORTED
Resource Affected: In Sewer
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 12/08/1987 20:05
Tank Capacity: 0 Gallons
Leak Rate: 0.00

92

**GRUMMAN AEROSPACE
EAST END OF PLANT #3
BETHPAGE, NY**

LUST

**S100665775
N/A**

LUST:

Facility ID: 8807681
Facility Contact: Not reported
Investigator: GOERTZ
Caller Name: JOHN OLHMANN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: Not reported
Not reported
Spill Class: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S100665775

Spill Closed Dt:	12/30/1988	Resource Affected:	On Land
Spill Cause:	Other	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	12/20/1988 11:55
Spill Date:	12/20/1988 09:30		
Cleanup Ceased:	12/30/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/03/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/21/1988		

92

**GRUMMAN BLDG #3
STEWART AVENUE
BETHPAGE, NY**

LUST

**S101173516
N/A**

LUST:

Facility ID:	9406455	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	UST
Caller Name:	GINA BENDETTI	Caller Agency:	TYREE
Caller Phone:	(516) 249-3150	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-1529
Spiller:	GRUMMAN AEROSPACE CORP		
Address:	MAIL STOP D08-GHQ BETHPAGE, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/04/1995	Resource Affected:	Groundwater
Spill Cause:	Tank Test Failure	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Tank Tester	Reported to Dept:	08/11/1994 16:23
Spill Date:	08/11/1994 15:30		
Cleanup Ceased:	12/04/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	12/05/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/12/1994		

92

**GRUMMAN PLANT #20
STEWART AVE
BETHPAGE, NY**

LUST

**S100491399
N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN PLANT #20 (Continued)

S100491399

LUST:

Facility ID: 9204511
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: GINA BENDETTI
Caller Phone: (516) 249-3150
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: TYREE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-1529

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 09/30/1992
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 07/20/1992 13:15
Cleanup Ceased: 09/30/1992
Last Inspection: Not reported

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 07/20/1992 13:24

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 10/01/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/21/1992

Facility ID: 9302603
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: SCOTT MATZEN
Caller Phone: (516) 586-4900
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN PLANT #12
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: F&N
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: No spill occurred. (Not Possible)
Spill Closed Dt: 07/27/1993
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 05/26/1993 11:45
Cleanup Ceased: 07/27/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/28/1993

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 05/26/1993 13:04

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN PLANT #20 (Continued)

S100491399

Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/27/1993

92

**GRUMMAN AEROSPACE
SO OYSTER BAY RD BLDG #1
BETHPAGE, NY**

LUST

**S100664793
N/A**

LUST:

Facility ID:	9207215	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PARISH	Spill Type:	Facility
Caller Name:	RICK WRIGHT	Caller Agency:	TRYEE
Caller Phone:	(516) 931-7659	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AEROSPACE		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/25/1992		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	09/22/1992 12:30	Reported to Dept:	09/22/1992 13:24
Cleanup Ceased:	09/25/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/07/1993		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/23/1992		

92

**GRUMMAN CORP
RTE 107
BETHPAGE, NY**

LUST

**S100666542
N/A**

LUST:

Facility ID:	9010127	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	HOFMANN	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-2385
Spiller:	GRUMMAN CORP		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	12/19/1990		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN CORP (Continued)

S100666542

Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/18/1990 10:45	Reported to Dept:	12/18/1990 11:00
Cleanup Ceased:	12/19/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/20/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/19/1990		

92

GRUMMAN AEROSPACE
BUILDING #2 GRUMMAN
BETHPAGE, NY

LUST

S100171769
N/A

LUST:

Facility ID:	8704145	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	O'NEILL	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	GRUMMAN AEROSPACE		
Address:	Not reported		
	BETHPAGE, NY		
Spill Class:	Not reported	Resource Affected:	Groundwater
Spill Closed Dt:	09/23/1987	Spill Source:	Other Commercial/Industrial
Spill Cause:	Tank Test Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	08/19/1987 13:45
Spill Notifier:	Tank Tester		
Spill Date:	08/19/1987 12:00		
Cleanup Ceased:	09/23/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/24/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/25/1987		

92

GRUMMAN AEROSPACE
BLDG 28
BETHPAGE, NY

LUST

S101173531
N/A

LUST:

Facility ID:	9408269	Region of Spill:	1
--------------	---------	------------------	---

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S101173531

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	UST
Caller Name:	TON DYKSTRA	Caller Agency:	TYREE
Caller Phone:	(516) 249-3150	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-1529
Spiller:	GRUMMAN AEROSPACE		
Address:	MAIL STOP DO8-6HQ BETHPAGE, NY 11714-3586		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/15/1996		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	09/21/1994 16:00	Reported to Dept:	09/21/1994 16:27
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/17/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/23/1994		

92

**GRUMMAN AEROSPACE
BLDG 111
BETHPAGE, NY**

LUST

**S100173439
N/A**

LUST:

Facility ID:	9001711	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	LORI JODICE	Caller Agency:	TYREE
Caller Phone:	(516) 249-3150	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	GRUMMAN AEROSPACE		
Address:	BLDG 111 BETHPAGE, NY		
Spill Class:	No spill occurred. (Not Possible)	Resource Affected:	On Land
Spill Closed Dt:	09/10/1993	Spill Source:	Other Commercial/Industrial
Spill Cause:	Tank Test Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	05/14/1990 13:43
Spill Notifier:	Tank Tester		
Spill Date:	05/14/1990 13:30		
Cleanup Ceased:	09/10/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S100173439

UST Involvement: False
Spill Record Last Update: 09/14/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/15/1990

92

**GRUMMAN AEROSPACE
BLDG 115
BETHPAGE, NY**

LUST

**S100168920
N/A**

LUST:

Facility ID: 8807239
Facility Contact: Not reported
Investigator: GOERTZ
Caller Name: SCOTT SCHUCK
Caller Phone: (516) 586-4900
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: Not reported
 Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: F&N
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-8176

Spill Class: Not reported
Spill Closed Dt: 01/10/1989
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 12/01/1988 16:30
Cleanup Ceased: 01/10/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/11/1989
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/05/1988

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 12/02/1988 08:75

93

**BIDCO MANUFACTURING CORP
8 COMMERCIAL ST
HICKSVILLE, NY 11801**

**RCRIS-SQG
FINDS**

**1000790592
NYD987020773**

RCRIS:

Owner: BIDCO MANUFACTURING CORP
(516) 433-0740

Contact: HARVEY BIDNER
(516) 433-0740

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D011	0.000 (N)
NONE	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

BIDCO MANUFACTURING CORP (Continued)

1000790592

Used Oil Recyc: No

Violation Status: No violations found

93

**IMPRESSIVE IMAGE INC
9 COMMERCIAL ST
HICKSVILLE, NY 11801**

**FINDS
RCRIS-LQG**

**1000553036
NYD986954451**

RCRIS:

Owner: ROBERT M RUSIE
(516) 931-0142

Contact: CELIA CERLINI
(516) 931-0142

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

93

**AETNA PRODUCTS
11 COMMERCIAL ST
HICKSVILLE, NY 11801**

**RCRIS-SQG
FINDS**

**1000553354
NYD986957702**

RCRIS:

Owner: FORE IMPROVEMENT CORP
(516) 935-8383

Contact: PAUL MEYER
(516) 938-8100

Classification: Conditionally Exempt Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)
U226	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

93

**AETNA PRODS INCORP
11 COMMERCIAL ST
HICKSVILLE, NY**

NY Spills

**S102135295
N/A**

SPILLS:

Facility ID: 9101556
Facility Contact: Not reported
Investigator: NONE
Caller Name: OFFICER DALTON
Caller Phone: (516) 573-3333
Notifier Name: Not reported
Notifier Phone: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NC EMS
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AETNA PRODS INCORP (Continued)

S102135295

Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	AETNA PRODS INCORP		
Address:	11 COMMERCIAL STREET		
	HICKSVILLE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	05/09/1991		
Material Class:	Petroleum	Spilled Code:	0066
Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Deliberate	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	05/08/1991 12:00	Reported to Dept:	05/08/1991 14:20
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/09/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	05/13/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/09/1991		

93

MERCURY LIGHTING CORP 10 COMMERCIAL ST HICKSVILLE, NY 11801

RCRIS-SQG 1000981464
FINDS NY0001000082

RCRIS:

Owner: MERCURY LIGHTING CORP
(215) 575-2390

Contact: KENNETH JONES
(215) 575-2390

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)	F001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

94

PERILLO OIL 7 CEDAR AVE BETHPAGE, NY

NY Spills S102099056
N/A

SPILLS:

Facility ID:	9313512	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	CHUCK TYREE	Caller Agency:	PERILLO OIL
Caller Phone:	(516) 249-4141	Caller Extension:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PERILLO OIL (Continued)

S102099056

Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	PERILLO OIL		
Address	9 MURRAY ST FARMINGDALE		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	02/18/1994		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Human Error	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	02/17/1994 11:15	Reported to Dept:	02/17/1994 11:21
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/18/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/22/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/18/1994		

95

**DEXTER MAGNETIC MATERIALS DIV
400 KARIN LN
HICKSVILLE, NY 11801**

**RCRIS-SQG
FINDS**

**1000552702
NYD986951077**

RCRIS:

Owner: PHYLSS I REALITY
(212) 555-1212

Contact: CARLOS CARVALLO
(516) 822-3311

Classification: Conditionally Exempt Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

96

**BONANZA FABRIC CO
35 KARIN LANE
HICKSVILLE, NY**

LUST

**S100668624
N/A**

LUST:

Facility ID: 8800192
Facility Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BONANZA FABRIC CO (Continued)

S100668624

Investigator:	NCDH	Spill Type:	Facility
Caller Name:	JOHN ECHLER	Caller Agency:	NCDH
Caller Phone:	(516) 535-2405	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	BONANZA FABRIC CO		
Address:	35 KARIN LANE HICKSVILLE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	05/16/1988	Resource Affected:	Groundwater
Spill Cause:	Other	Spill Source:	Other Non Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Health Department	Reported to Dept:	04/06/1988 15:45
Spill Date:	04/06/1988 15:00		
Cleanup Ceased:	05/16/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	05/17/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/08/1988		

97

BETHPAGE, NY

LUST

**S100560263
N/A**

LUST:

Facility ID:	9306397	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	CITIZEN
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	RESIDENCE		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/26/1993	Resource Affected:	On Land
Spill Cause:	Tank Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Affected Persons	Reported to Dept:	08/25/1993 10:33
Spill Date:	08/24/1993 17:00		
Cleanup Ceased:	08/26/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RESIDENCE (Continued)

S100560263

Spill Record Last Update: 08/27/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/26/1993

**98 PAG INSULATION
44 FELICE CRESCENT
HICKSVILLE, NY 11801**

FINDS

**1000551083
NYD986920239**

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Facility is monitored or permitted for air emissions under the Clean Air Act (under AFS/AIRS)
- Civil judicial and administrative enforcement case against facility (under DOCKET)

**99 PACE FUEL CO
400 S BROADWAY
HICKSVILLE, NY**

LUST

**S100148922
N/A**

LUST:

Facility ID: 8702695
Facility Contact: Not reported
Investigator: ACAMPORA
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: PACE FUEL CO
Address: 1890 NEW YORK AVENUE
HUNTINGTON, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 427-2447

Spill Class: Not reported
Spill Closed Dt: 07/03/1987
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Local Agency
Spill Date: 07/03/1987 09:00
Cleanup Ceased: 07/03/1987

Resource Affected: On Land
Spill Source: Tank Truck
PBS Number: Not reported
Reported to Dept: 07/03/1987 09:50

Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/07/1987

**99 SUNOCO-BOB THALL
400 S BROADWAY
HICKSVILLE, NY 11801**

**FINDS
RCRIS-LQG**

**1000332080
NYD981492036**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUNOCO-BOB THALL (Continued)

1000332080

RCRIS:

Owner: BOB THALL
(212) 555-1212

Contact: BOB THALL
(516) 433-3043

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

99

THALL SVC STATION CORP
400 S BROADWAY
HICKSVILLE, NY 11801

FINDS
RCRIS-LQG

1000288210
NYD055950935

RCRIS:

Owner: ROBERT L THALL
(212) 555-1212

Contact: STEVEN THALL
(516) 433-3043

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

100

R & J CLEANERS
447 S BROADWAY
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000912055
NY0000385393

RCRIS:

Owner: KUAN-CHIEH PENG
(516) 938-6187

Contact: KUAN-CHIEH PENG
(516) 939-0776

Classification: Conditionally Exempt Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D007	0.000 (N)	D039	0.000 (N)
F002	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

R & J CLEANERS (Continued)

1000912055

Used Oil Recyc: No

Violation Status: No violations found

101

BETHPAGE, NY

NY Spills

S102092117
N/A

SPILLS:

Facility ID: 9202613
Facility Contact: Not reported
Investigator: DECANDIA
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CITIZEN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 06/12/1992
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Deliberate
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 06/01/1992 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 06/12/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/10/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/05/1992

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Unknown
PBS Number: Not reported
Reported to Dept: 06/03/1992 09:29
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

102

EAGLE INSURANCE COMPANY 999 STEWART AVENUE BETHPAGE, NY

LUST

S102447932
N/A

103

BETHPAGE, NY

NY Spills

S102236035
N/A

SPILLS:

Facility ID: 9509836
Facility Contact: LAWRENCE WOJTUSIAK
Investigator: AUSTIN

Region of Spill: 1
Facility Tele: (516) 681-1493
Spill Type: UST

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236035

Exemption 6

Caller Name:
Caller Phone:
Notifier Name:
Notifier Phone:
Spiller Contact:
Spiller:
Address

Caller Agency: MEEHAN OIL
Caller Extension: Not reported
Notifier Agency: MEEHAN OIL
Notifier Extension: Not reported
Spiller Phone:

BETHPAGE, NY

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 08/13/1996

Material Class: Petroleum

Quantity Spilled: 200 gallons

Spill Cause: Equipment Failure

Water Affected: Not reported

Spill Notifier: Other

Spill Date: 11/08/1995 11:40

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 08/14/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 11/08/1995

Spilled Code: 0001

Quant Recovered: 0 gallons

Resource Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 11/08/1995 11:49

Tank Capacity: 0 Gallons

Leak Rate: 0.00

103

LUST

S100491897
N/A

BETHPAGE, NY

LUST:

Facility ID: 9208514

Facility Contact: Not reported

Investigator: GIBBONS

Caller Name:

Caller Phone: (516) 576-3000

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Spiller:

Address

Region of Spill: 1

Facility Tele: Not reported

Spill Type: Facility

Caller Agency: GIFFORDS

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone:

BETHPAGE, NY

Spill Class: No spill occurred. No DEC Response. No corrective action required.

Spill Closed Dt: 04/27/1994

Spill Cause: Tank Failure

Water Affected: Not reported

Spill Notifier: Other

Spill Date: 10/23/1992 08:30

Cleanup Ceased: 04/27/1994

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Resource Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 10/23/1992 13:44

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S100491897

Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/28/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/26/1992

103

BETHPAGE, NY

NY Spills

S102099497
N/A

SPILLS:

Facility ID:	9401963	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	GIFFORDS
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	05/11/1994	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	05/10/1994 12:32
Spill Date:	05/10/1994 11:45	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/11/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	05/11/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/11/1994		

103

BETHPAGE, NY

LUST

S100664934
N/A

LUST:

Facility ID:	9210656	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GIBBONS	Spill Type:	Facility

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S100664934

Caller Name: [REDACTED] Caller Agency: GEN ENVIR SERVICES
 Caller Phone: [REDACTED] Caller Extension: Not reported
 Notifier Name: Not reported Notifier Agency: Not reported
 Notifier Phone: Not reported Notifier Extension: Not reported
 Spiller Contact: Not reported Spiller Phone: Not reported
 Spiller: [REDACTED]
 Address: Not reported
 Not reported
 Spill Class: Known release that creates potential for fire or hazard. DEC Response.
 Willing Responsible Party. Corrective action taken.
 Spill Closed Dt: 02/12/1993
 Spill Cause: Other Resource Affected: On Land
 Water Affected: Not reported Spill Source: Private Dwelling
 Spill Notifier: Other PBS Number: Not reported
 Spill Date: 12/14/1992 12:00 Reported to Dept: 12/15/1992 11:57
 Cleanup Ceased: 02/12/1993
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 02/16/1993
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 12/16/1992

104

GRAND PRIX PERFORMANCE LTD
 500 S BROADWAY
 HICKSVILLE, NY 11801

RCRIS-SQG 1000791026
 FINDS NYD987025251

RCRIS:

Owner: JOHN DEMONACO
(516) 931-2942

Contact: STEVE SCHERER
(516) 822-1550

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	D008	0.000 (N)
D018	0.000 (N)	D039	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

104

GRAND JEEP EAGLE DEALERSHIP
 500 BROADWAY
 HICKSVILLE, NY 11801

FINDS 1000791734
 RCRIS-LQG NYD987032521

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRAND JEEP EAGLE DEALERSHIP (Continued)

1000791734

RCRIS:

Owner: ANN DEMONACO
(516) 931-2942

Contact: ANN DEMONACO
(516) 931-2942

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D006	0.000 (N)
D008	0.000 (N)	D009	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

104

GRAND PRIX AUTO 500 S BROADWAY HICKSVILLE, NY

NY Spills

S102135423
N/A

SPILLS:

Facility ID: 9105540
Facility Contact: Not reported
Investigator: LUCE
Caller Name: ANDREA REISS
Caller Phone: (516) 928-7347
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRAND PRIX AUTO
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: TOWN OYSTER BAY
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 11/12/1991
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Deliberate
Water Affected: Not reported
Spill Notifier: Citizen
Spill Date: 08/09/1991 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 11/12/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/13/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/26/1991

Spilled Code: 0022
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 08/22/1991 10:12
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
104	HESS S/S 502 S BROADWAY HICKSVILLE, NY LUST: Facility ID: 9113034 Facility Contact: Not reported Investigator: T/T/F Caller Name: CHUCK PADANO Caller Phone: (215) 646-3161 Notifier Name: Not reported Notifier Phone: Not reported Spiller Contact: Not reported Spiller: HESS S/S Address: Not reported Not reported Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. Spill Closed Dt: 05/20/1992 Spill Cause: Tank Test Failure Water Affected: Not reported Spill Notifier: Responsible Party Spill Date: 03/24/1992 16:30 Cleanup Ceased: 05/20/1992 Last Inspection: Not reported Cleanup Meets Standard: True Recommended Penalty: No Penalty Spiller Cleanup Date: Not reported Enforcement Date: Not reported Investigation Complete: Not reported UST Involvement: False Spill Record Last Update: 11/09/1992 Corrective Action Plan Submitted: Not reported Date Spill Entered In Computer Data File: 03/25/1992 Facility ID: 9404252 Facility Contact: Not reported Investigator: RMS CAMPBELL Caller Name: DAWN JOHNSON Caller Phone: (908) 750-7068 Notifier Name: Not reported Notifier Phone: Not reported Spiller Contact: Not reported Spiller: HESS STATION #32489 Address: Not reported Not reported Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. Spill Closed Dt: Not reported Spill Cause: Tank Overfill Water Affected: Not reported Spill Notifier: Responsible Party Spill Date: 06/27/1994 11:00 Cleanup Ceased: Not reported Last Inspection: Not reported Cleanup Meets Standard: False Recommended Penalty: No Penalty Spiller Cleanup Date: Not reported Enforcement Date: Not reported	LUST Region of Spill: 1 Facility Tele: Not reported Spill Type: Facility Caller Agency: KAMPCO Caller Extension: Not reported Notifier Agency: Not reported Notifier Extension: Not reported Spiller Phone: (800) 336-1342 Resource Affected: Groundwater Spill Source: Gas Station PBS Number: Not reported Reported to Dept: 03/24/1992 16:55 Region of Spill: 1 Facility Tele: Not reported Spill Type: Facility Caller Agency: HESS Caller Extension: Not reported Notifier Agency: Not reported Notifier Extension: Not reported Spiller Phone: Not reported Resource Affected: On Land Spill Source: Gas Station PBS Number: Not reported Reported to Dept: 06/27/1994 11:26	S100493287 N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HESS S/S (Continued)

S100493287

Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 08/02/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/27/1994

104

AMERADA HESS STATION 32489
502 S BROADWAY
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000789578
NYD987010394

RCRIS:

Owner: AMERADA HESS CORP
(908) 750-6000

Contact: THOMAS WHITTAKER
(908) 750-6225

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D018	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Facility has an active water discharge permit (under PCS)

104

UNK CUSTOMER
502 S BROADWAY
HICKSVILLE, NY

LUST

S100493879
N/A

LUST:

Facility ID:	9205657	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	ROBERT SPEDDING	Caller Agency:	HESS
Caller Phone:	(908) 750-6828	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK CUSTOMER		
Address	Not reported		
	Not reported		

Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 08/17/1992
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 08/15/1992 18:00
Cleanup Ceased: 08/17/1992
Last Inspection: Not reported
Cleanup Meets Standard: True

Resource Affected: On Land
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 08/17/1992 11:39

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNK CUSTOMER (Continued)

S100493879

Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/10/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/24/1992

104

**CINDYS CLEANERS
495-30 S BROADWAY
HICKSVILLE, NY 11801**

**RCRIS-SQG
FINDS**

**1000305180
NYD982182057**

RCRIS:

Owner: RENATO MALDONADO
(516) 273-5458

Contact: RENATO MALDONADO
(516) 935-7650

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D007	0.000 (N)	D039	0.000 (N)
D040	0.000 (N)	F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

104

**T R W MEDIAL ELECTRONIC CORP
485-29 S BROADWAY
HICKSVILLE, NY 11801**

**FINDS
RCRIS-LQG**

**1000123895
NYD986872984**

RCRIS:

Owner: DIVISION OF TRW
(212) 555-1212

Contact: NICK OSTER
(516) 932-8700

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)	NONE	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

104

**SALS AUTO BODY
477 S BROADWAY
HICKSVILLE, NY 11801**

**RCRIS-SQG
FINDS**

**1000373491
NYD986894939**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SALS AUTO BODY (Continued)

1000373491

RCRIS:

Owner: LOU SEPLAVY
(212) 555-1212

Contact: DANIEL RYAN
(516) 681-6644

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)	F005	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

105

RONZONI FOODS CORPORATION
50 LUDY ST
HICKSVILLE, NY 11801

RCRIS-SQG 1000212440
FINDS NYD152084372

RCRIS:

Owner: PHILIP MORRIS
(212) 555-1212

Contact: ANTHONY BELVIGLIO
(516) 932-2700

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

105

TRIPLE J.V.C. AUTO COLLISION, INC
55 LUDY ST
HICKSVILLE, NY 11801

RCRIS-SQG 1000347932
FINDS NYD982730178

RCRIS:

Owner: JOHN COTONA
(212) 555-1212

Contact: JOHN COTONA
(516) 939-0020

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
F003	0.000 (N)	F005	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TRIPLE J.V.C. AUTO COLLISION, INC (Continued)

1000347932

Used Oil Recyc: No

Violation Status: No violations found

105

**GRUMMAN AEROSPACE CORP
83 LUDY ST
HICKSVILLE, NY 11714**

**FINDS
RCRIS-LQG**

**1000300850
NYD981182231**

RCRIS:

Owner: INDUSTRIAL REALTY CO
(212) 555-1212

Contact: JOHN OHLMANN
(516) 575-2385

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	F001	0.000 (N)
F003	0.000 (N)	F005	0.000 (N)
NONE	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

106

**LILCO
60 COMMERCE PL
HICKSVILLE, NY**

NY Spills

**S102135997
N/A**

SPILLS:

Facility ID: 9110773
Facility Contact: Not reported
Investigator: LEUNG
Caller Name: MIKE LAURO
Caller Phone: (516) 391-6142
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: LILCO
Address: Not reported
Not reported
Spill Class: Not reported
Spill Closed Dt: 01/21/1992
Material Class: Petroleum
Quantity Spilled: 5 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 01/15/1992 16:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 01/21/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: LILCO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0066
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 01/15/1992 16:35
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102135997

Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/22/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/16/1992

107

FOREST CHEM INDUSTRIES
70 COMMERCE PL
HICKSVILLE, NY

NY Spills

S102138015
N/A

SPILLS:

Facility ID: 8906770
Facility Contact: Not reported
Investigator: HOFMANN
Caller Name: JOHN HOFMANN
Caller Phone: (516) 751-7900
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: FOREST CHEM INDUSTRIES
Address: 70 COMMERCE PLACE
HICKSVILLE, NY 11801

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: DEC
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 681-5900

Spill Class: Not reported
Spill Closed Dt: 12/17/1990
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Deliberate
Water Affected: Not reported
Spill Notifier: DEC
Spill Date: 10/10/1989 11:45
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/17/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/20/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/11/1989

Spilled Code: 0022
Quant Recovered: 0 gallons
Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 10/10/1989 16:00
Tank Capacity: 0 Gallons
Leak Rate: 0.00

108

SHELL GAS STATION
STEWART AVE / FARMERS AVE
BETHPAGE, NY

LUST

S100781107
N/A

LUST:

Facility ID: 9308447
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: CHARLES PRICE
Caller Phone: (516) 261-1590

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: L I PUMP & TANK
Caller Extension: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL GAS STATION (Continued)

S100781107

Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-8531
Spiller:	SHELL GAS STATION		
Address:	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	07/24/1996		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	10/12/1993 16:45	Reported to Dept:	10/12/1993 17:45
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	07/25/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/14/1993		

108

**SHELL OIL CO
STEWART & FARMERS
BETHPAGE, NY 11714**

**FINDS
LUST
RCRIS-LQG**

**1000552235
NYD986946309**

RCRIS:

Owner: JOHN N LOONEY
(212) 555-1212

Contact: BROOKS PERLEE
(516) 942-4121

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D008	0.000 (N)	D027	0.000 (N)
F001	0.000 (N)	F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

LUST:

Facility ID:	8709242	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GOERTZ	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SHELL OIL		
Address:	Not reported		
	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHELL OIL CO (Continued)

1000552235

Spill Class:	Not reported	Resource Affected:	Groundwater
Spill Closed Dt:	04/06/1988	Spill Source:	Gas Station
Spill Cause:	Tank Test Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	01/29/1988 16:34
Spill Notifier:	Tank Tester		
Spill Date:	01/29/1988 15:15		
Cleanup Ceased:	04/06/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/08/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/02/1988		

109

**2 COMMERCE ST/BAYONNE/NJ
2 COMMERCE STREET
BAYONNE, NEW JERSEY, NY**

NY Spills

S102141057
N/A

SPILLS:

Facility ID:	9100599	Region of Spill:	2
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	SIGONA	Spill Type:	Facility
Caller Name:	P O GERLAND	Caller Agency:	USCG
Caller Phone:	(212) 668-7920	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	Not reported		
Address	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	0066
Spill Closed Dt:	04/16/1991	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	Surface Water
Quantity Spilled:	200 gallons	Spill Source:	Vessel
Spill Cause:	Unknown	PBS Number:	Not reported
Water Affected:	KILL VAN KULL	Reported to Dept:	04/16/1991 11:08
Spill Notifier:	Federal Government	Tank Capacity:	0 Gallons
Spill Date:	04/16/1991 10:15	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	04/16/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/17/1991		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

110

[REDACTED]

NY Spills

S102138492
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9006100
Facility Contact: Not reported
Investigator: MIRZA
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CITIZEN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

HICKSVILLE, NY
Spill Class: Not reported
Spill Closed Dt: 09/21/1990
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Human Error
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 09/02/1990 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 09/21/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/28/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/05/1990

Spilled Code: 0022
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 09/03/1990 11:45
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

111

[REDACTED]

NY Spills

S102140625
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9503874
Facility Contact: Not reported
Investigator: MATTHEWS
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 09/07/1995
Material Class: Petroleum
Quantity Spilled: 0 gallons

Spilled Code: 0066
Quant Recovered: 0 gallons

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102140625

Spill Cause:	Human Error	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Passenger Vehicle
Spill Notifier:	Citizen	PBS Number:	Not reported
Spill Date:	06/29/1995 12:00	Reported to Dept:	06/29/1995 13:56
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/07/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/11/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/06/1995		

112

LILCO
536 S BROADWAY
HICKSVILLE, NY

NY Spills

S102138546
N/A

SPILLS:

Facility ID:	9007641	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	RICH SCHMITZ	Caller Agency:	LILCO
Caller Phone:	(516) 420-6143	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	LILCO		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	0016
Spill Closed Dt:	10/15/1990	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	3 gallons	Spill Source:	Other Commercial/Industrial
Spill Cause:	Equipment Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	10/12/1990 14:45
Spill Notifier:	Responsible Party	Tank Capacity:	0 Gallons
Spill Date:	10/12/1990 13:00	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	10/15/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	10/17/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/15/1990		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

112			BROADWAY PLAZA CLEANERS 532 S BROADWAY HICKSVILLE, NY 11801	RCRIS-SQG FINDS	1000145670	NYD094822673
-----	--	--	--	--------------------	------------	--------------

RCRIS:

Owner: BROADWAY PLAZA CLEANERS
(212) 555-1212

Contact: LUCKY CHOI
(516) 433-4707

Classification: Small Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

112			LILCO 520 S BROADWAY HICKSVILLE, NY	NY Spills	S102137392 N/A
-----	--	--	--	-----------	-------------------

SPILLS:

Facility ID: 8709472
Facility Contact: Not reported
Investigator: Not reported
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: LILCO
Address: 175 EAST OLD COUNTRY ROAD
HICKSVILLE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 420-6138

Spill Class: Not reported
Spill Closed Dt: 02/09/1988
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/07/1988 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 02/09/1988
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/10/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/08/1988

Spilled Code: 0017
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 02/08/1988 10:32
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

113

**ERM NORTHEAST
335 NEW SOUTH RD
HICKSVILLE, NY**

LUST

S100494026
N/A

LUST:

Facility ID:	9206957	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	GINA BENDETTI	Caller Agency:	TYREE
Caller Phone:	(516) 249-3150	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 921-4300
Spiller:	ERM NORTHEAST		
Address:	175 FROELICH FARM BLVD WOODBURY, NY		
Spill Class:	No spill occurred. (Not Possible)	Resource Affected:	Groundwater
Spill Closed Dt:	12/08/1993	Spill Source:	Other Commercial/Industrial
Spill Cause:	Tank Test Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	09/16/1992 15:20
Spill Notifier:	Tank Tester		
Spill Date:	09/16/1992 14:00		
Cleanup Ceased:	12/08/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/09/1993		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/18/1992		

113

**VOIGT PROPERTY
335 NEW SOUTH RD
HICKSVILLE, NY 11801**

FINDS

RCRIS-LQG

1000912299
NY0000588467

RCRIS:

Owner: VOIGT RELTY CO
(516) 673-0037

Contact: AL VALERIO
(516) 673-0037

Classification: Large Quantity Generator, Hazardous Waste Transporter

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

113

**COMMERCIAL BLDG. #2
327 NEW SOUTH RD
HICKSVILLE, NY**

AST

A100090677
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

COMMERCIAL BLDG. #2 (Continued)

A100090677

Nassau County AST:

Facility ID:	055747	Tank ID:	0002
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	1500
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Galvanized Steel		
Description:	OIL, FUEL #2	Containment:	DOUBLE WALL TANK
Leak Detect:	OTHER	Product Gauge:	Yes
Dispense Method:	Suction	Install Date:	1093
Fill Type:	Pumped		
Total Tanks:	Not reported		

113

CENTURY COLLISION INC
321 NEW SOUTH RD
HICKSVILLE, NY 11801

RCRIS-SQG 1000422539
FINDS NYD054994280

RCRIS:

Owner: Not reported
Contact: JERRY KELAHER
(516) 433-6290
Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

113

[REDACTED]
HICKSVILLE, NY

NY Spills S102138537
N/A

SPILLS:

Facility ID:	9007279	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	HOFMANN	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	CONFIDENTIAL
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	[REDACTED]		

HICKSVILLE, NY
Spill Class: Not reported
Spill Closed Dt: 10/09/1990
Material Class: Petroleum
Quantity Spilled: 2 gallons
Spill Cause: Deliberate
Water Affected: Not reported
Spill Notifier: Citizen
Spill Date: 10/02/1990 07:20
Tank Number: Not reported
Test method: Not reported

Spilled Code: 0066
Quant Recovered: 0 gallons
Resource Affected: In Sewer
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 10/03/1990 09:57
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102138537

Gross Leak/Fail: Not reported
Cleanup Ceased: 10/09/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/10/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/04/1990

113

VARIETY PETROL (P&G FUEL)
317 NEW SOUTH RD
HICKSVILLE, NY

LUST

S101508024
N/A

LUST:

Facility ID:	9414903	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ACAMPORA	Spill Type:	Facility
Caller Name:	FM GUERIN	Caller Agency:	NCFM
Caller Phone:	(516) 359-1917	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	VARIETY PETROL		
Address:	40 GRANNY ROAD FARMINGVILLE		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported	Resource Affected:	On Land
Spill Cause:	Tank Overfill	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Fire Department	Reported to Dept:	02/13/1995 11:00
Spill Date:	02/13/1995 10:00		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/14/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/13/1995		

114

LILCO
EVERGREEN / SPRUCE AVE
BETHPAGE, NY

LUST

S101508040
N/A

LUST:

Facility ID:	9415203	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LAMANNO	Spill Type:	Facility

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S101508040

Caller Name:	ADAM YABLANSKY	Caller Agency:	LILCO
Caller Phone:	(516) 842-9075	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	LILCO		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	02/20/1995 12:00	Reported to Dept:	02/20/1995 14:20
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/22/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/21/1995		

115

SALVATI FOODS, INC.
595 S. BROADWAY
HICKSVILLE, NY

UST

U002171762
N/A

Nassau County UST:

Facility ID:	056844	Tank ID:	0001
Tank Location:	Indoors, Belowground	Capacity:	00005000
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	NONE		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Gravity	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	0472
Total Tanks:	1		

115

SHAMROCK AUTO CENTER INC
589 S BROADWAY
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000553993
NYD986964310

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHAMROCK AUTO CENTER INC (Continued)

1000553993

RCRIS:

Owner: SHAMROCK AUTO CENTER INC
(516) 931-3323

Contact: JOE DIGREGORIO
(516) 931-3323

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D008	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

115

ITC AT HESS S/S
575 S BROADWAY
HICKSVILLE, NY

NY Spills

S102138138
N/A

SPILLS:

Facility ID: 8910047
Facility Contact: Not reported
Investigator: MANCILLA
Caller Name: JOE ALMEIDA
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: ITC AT HESS S/S
Address: 299 EDISON AVENUE
WEST BABYLON, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: HESS
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 03/01/1990
Material Class: Petroleum
Quantity Spilled: 20 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 01/19/1990 14:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 03/01/1990
Last Inspection: Not reported

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Gas Station
PBS Number: Not reported
Reported to Dept: 01/19/1990 14:20
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 03/01/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/23/1990

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

115

**AMERADA HESS OIL
575 S BROADWAY
HICKSVILLE, NY 11801**

RCRIS-SQG

1000352827
NYD982536146

RCRIS:

Owner: AMERADA HESS OIL
(212) 555-1212

Contact: JOE AOMEIDA
(800) 336-1342

Classification: Small Quantity Generator

Waste Quantity
D001 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

115

**AMERADA HESS OIL
575 S BROADWAY
HICKSVILLE, NY 11801**

FINDS

1000788600
NYD982536146

115

**OFFICE BUILDING
560 S. BROADWAY
HICKSVILLE, NY**

UST

U003038632
N/A

Nassau County UST:

Facility ID: 057055
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Unknown
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: 1

Tank ID: 0001
Capacity: 00002000
Tank Material: UNKNOWN
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1260

116

**HICKSVILLE DEPT OF PUBLIC WORKS
NEW SOUTH RD & MORRIS ST
HICKSVILLE, NY 11801**

FINDS
RCRIS-LQG

1000272870
NYD982789737

Used Oil Recyc: No

Violation Status: No violations found

Exemption 6

117

HICKSVILLE, NY

NY Spills

S102136063
N/A

SPILLS:

Facility ID: 9112465
Facility Contact: Not reported
Investigator: NONE
Caller Name:

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GIFFORDS

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Continued)

S102136063

Exemption 6

Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	03/10/1992	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	2 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	03/06/1992 15:22
Spill Date:	03/06/1992 13:50	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	03/10/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	03/11/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/16/1992		

118

NY Spills

S102140587
N/A

GARDEN CITY, NY

SPILLS:

Facility ID:	9503409	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	RELIANCE
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	
Spiller:			
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/20/1995	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	3 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Affected Persons	Reported to Dept:	06/19/1995 15:35
Spill Date:	06/19/1995 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102140587

Cleanup Ceased: 06/20/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/20/1995

119

LUST

S100669243
N/A

HICKSVILLE, NY

LUST:

Facility ID: 9002850
Facility Contact: Not reported
Investigator: NCFM
Caller Name: INSPECTOR GUERIN
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

HICKSVILLE, NY

Spill Class: Not reported
Spill Closed Dt: 06/13/1990
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 06/12/1990 14:45
Cleanup Ceased: 06/13/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/13/1990

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 06/12/1990 15:30

120

LUST

S100148382
N/A

HICKSVILLE, NY

LUST:

Facility ID: 8911923
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MILRO SERVICES
Caller Extension: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S100148382

Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 433-7632
Spiller:			
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	03/16/1990		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	03/13/1990 12:00	Reported to Dept:	03/16/1990 11:50
Cleanup Ceased:	03/16/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/19/1990		

121

MEENAN OIL CO
12 SPRUCE AVENUE
BETHPAGE, NY

NY Spills

S102097729
N/A

SPILLS:

Facility ID:	9214398	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMPBELL	Spill Type:	Facility
Caller Name:	MR SANTORO	Caller Agency:	MEENAN OIL
Caller Phone:	(516) 783-1000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	MEENAN OIL CO		
Address	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/19/1993		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Human Error	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	03/30/1993 13:30	Reported to Dept:	03/30/1993 13:53
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	04/19/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MEENAN OIL CO (Continued)

S102097729

Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/20/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/31/1993

122

NY Spills

S102237455
N/A

HICKSVILLE, NY

Exemption 6

SPILLS:

Facility ID: 9600635
Facility Contact: [REDACTED]
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: [REDACTED]
Notifier Phone: [REDACTED]
Spiller Contact: [REDACTED]
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: CITIZEN
Caller Extension: Not reported
Notifier Agency: CITIZEN
Notifier Extension: Not reported
Spiller Phone: Not reported

HICKSVILLE

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 04/15/1996
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/13/1996 08:02
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/16/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/13/1996

Spilled Code: 0001
Quant Recovered: 1 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 04/13/1996 08:00
Tank Capacity: 0 Gallons
Leak Rate: 0.00

123

BETHPAGE METRO
900 STEWART AVE
BETHPAGE, NY

AST

A100090597
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BETHPAGE METRO (Continued)

A100090597

Nassau County AST:

Facility ID:	055456	Tank ID:	0001
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	275
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Waste
Piping Type:	Galvanized Steel		
Description:	WASTE OIL	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Suction	Install Date:	1085
Fill Type:	Gravity		
Total Tanks:	Not reported		

123

**METRO S/S
900 STEWART AVENUE
BETHPAGE, NY**

LUST

**S100172052
N/A**

LUST:

Facility ID:	8708438	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GOERTZ	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	METRO S/S		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Resource Affected:	Groundwater
Spill Closed Dt:	01/14/1988	Spill Source:	Gas Station
Spill Cause:	Tank Test Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	12/31/1987 14:35
Spill Notifier:	Other		
Spill Date:	12/31/1987 12:00		
Cleanup Ceased:	01/14/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	01/14/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/04/1988		

Facility ID:	9506133	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	MATTHEWS	Spill Type:	Facility
Caller Name:	BRIAN MATTHEWS	Caller Agency:	DEC
Caller Phone:	(516) 444-0320	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	METRO S/S		
Address:	Not reported		
	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

METRO S/S (Continued)

S100172052

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported

Spill Cause: Other

Water Affected: Not reported

Spill Notifier: DEC

Spill Date: 08/17/1995 14:00

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: False

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: Not reported

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 08/21/1995

Resource Affected: On Land

Spill Source: Gas Station

PBS Number: Not reported

Reported to Dept: 08/17/1995 14:00

123

**BETHPAGE U F S D
CHERRY AVE
BETHPAGE, NY 11714**

**FINDS
LUST
RCRIS-LQG**

**1000243980
NYD100370121**

RCRIS:

Owner: BETHPAGE U F S D
(212) 555-1212

Contact: THOMAS ACERRA
(516) 931-2900

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)
D002	0.000 (N)	D003	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Facility is monitored or permitted for air emissions under the Clean Air Act (under AFS/AIRS)

LUST:

Facility ID:	8703585	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	O'NEILL	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-2900
Spiller:	BETHPAGE SCHOOL DISTRICT		
Address:	CHERRY AVENUE BETHPAGE, NY		
Spill Class:	Not reported	Resource Affected:	Groundwater
Spill Closed Dt:	12/10/1987		
Spill Cause:	Tank Test Failure		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BETHPAGE U F S D (Continued)

1000243980

Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	08/01/1987 13:00	Reported to Dept:	08/01/1987 13:13
Cleanup Ceased:	12/10/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/11/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/04/1987		

124

HICKSVILLE, NY

LUST

S100148916
N/A

Exemption 6

LUST:

Facility ID:	8702517	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	WALEK	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	08/19/1987	Resource Affected:	On Land
Spill Cause:	Tank Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	06/29/1987 08:45
Spill Date:	06/28/1987 12:00		
Cleanup Ceased:	08/19/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/19/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/01/1987		

125

**LILCO
25 FERNEY ST
HICKSVILLE, NY**

NY Spills

S102137573
N/A

SPILLS:

Facility ID:	8802428	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102137573

Investigator:	WALEK	Spill Type:	Facility
Caller Name:	RICK SCHMITZ	Caller Agency:	LILCO
Caller Phone:	(516) 420-6058	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 420-6058
Spiller:	LILCO		
Address:	175 E.O.C ROAD HICKSVILLE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	06/22/1988		
Material Class:	Petroleum	Spilled Code:	0016
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	06/15/1988 15:36	Reported to Dept:	06/16/1988 16:25
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	06/22/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/28/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/24/1988		

126

HICKSVILLE, NY

NY Spills

S102237496
N/A

SPILLS:

Facility ID:	9600853	Region of Spill:	1
Facility Contact:		Facility Tele:	(516) 433-1611
Investigator:		Spill Type:	UST
Caller Name:		Caller Agency:	HOMEOWNER
Caller Phone:		Caller Extension:	Not reported
Notifier Name:		Notifier Agency:	HOMEOWNER
Notifier Phone:		Notifier Extension:	Not reported
Spiller Contact:		Spiller Phone:	
Spiller:			
Address:			
	HICKSVILLE -		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/18/1996		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	1 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	04/18/1996 07:30	Reported to Dept:	04/18/1996 10:12
Tank Number:	Not reported	Tank Capacity:	0 Gallons

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102237496

Test method: Not reported Leak Rate: 0.00
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/24/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/18/1996

127

BROADWALL MANAGEMENT
44 CHERRY AVENUE
WEST HEMPSTEAD, NY

LUST

S100491065
N/A

LUST:

Facility ID: 9201417 Region of Spill: 1
Facility Contact: Not reported Facility Tele: Not reported
Investigator: T/T/F Spill Type: Facility
Caller Name: GUY CAPONE Caller Agency: GASOLINE INSTALLATIONS
Caller Phone: (718) 647-7443 Caller Extension: Not reported
Notifier Name: Not reported Notifier Agency: Not reported
Notifier Phone: Not reported Notifier Extension: Not reported
Spiller Contact: Not reported Spiller Phone: (516) 968-4245
Spiller: BROADWALL MANAGEMENT
Address: 420 HEMPSTEAD TPKE
WEST HEMPSTEAD
Spill Class: No spill occurred. (Not Possible)
Spill Closed Dt: 08/24/1993
Spill Cause: Tank Test Failure Resource Affected: Groundwater
Water Affected: Not reported Spill Source: Other Commercial/Industrial
Spill Notifier: Tank Tester PBS Number: Not reported
Spill Date: 05/05/1992 13:15 Reported to Dept: 05/05/1992 15:38
Cleanup Ceased: 08/24/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/25/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/07/1992

128

HICKSVILLE, NY

NY Spills

S102236724
N/A

SPILLS:

Facility ID: 9513525 Region of Spill: 1
Facility Contact: MRS SPIEERE Facility Tele: (516) 933-1759
Investigator: NONE Spill Type: UST

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236724

Exemption 6

Caller Name:
Caller Phone:
Notifier Name:
Notifier Phone:
Spiller Contact:
Spiller:
Address

Caller Agency: OWNER
Caller Extension: Not reported
Notifier Agency: OWNER
Notifier Extension: Not reported
Spiller Phone:

HICKSVILLE, NY

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 01/25/1996

Material Class: Petroleum

Quantity Spilled: 1 gallons

Spill Cause: Equipment Failure

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 01/25/1996 14:30

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 01/26/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered in Computer Data File: 01/25/1996

Spilled Code: 0001
Quant Recovered: 1 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 01/25/1996 14:49
Tank Capacity: 0 Gallons
Leak Rate: 0.00

128

NY Spills

S102137786

N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 8900057

Facility Contact: Not reported

Investigator: NONE

Caller Name:

Caller Phone:

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Spiller:

Address: Not reported

Not reported

Spill Class: Not reported

Spill Closed Dt: 04/04/1989

Material Class: Petroleum

Quantity Spilled: 15 gallons

Spill Cause: Equipment Failure

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 04/04/1989 09:00

Tank Number: Not reported

Test method: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CITIZEN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 04/04/1989 09:28
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102137786

Gross Leak/Fail: Not reported
Cleanup Ceased: 04/04/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/05/1989

129

LUST

S100148303
N/A

BETHPAGE, NY

LUST:

Facility ID:	8910897	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GOMEZ	Spill Type:	Facility
Caller Name:		Caller Agency:	GENERAL UTILITIES
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	
Spiller:			
Address:	BETHPAGE, NY		
Spill Class:	Not reported	Resource Affected:	Groundwater
Spill Closed Dt:	10/30/1990	Spill Source:	Private Dwelling
Spill Cause:	Tank Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	02/14/1990 16:05
Spill Notifier:	Other		
Spill Date:	02/14/1990 12:00		
Cleanup Ceased:	10/30/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/01/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/15/1990		

130

NY Spills

S102140148
N/A

HICKSVILLE, NY

SPILLS:

Facility ID:	9412094	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	CUSTOMER

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102140148

Caller Phone:	(516) 931-8515	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/12/1994		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	2 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/09/1994 17:00	Reported to Dept:	12/09/1994 17:30
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/12/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/12/1994		

131

LILCO
103 LEE AVE
HICKSVILLE, NY

NY Spills

S102138598
N/A

SPILLS:

Facility ID:	9009335	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	MIKE LAURO	Caller Agency:	LILCO
Caller Phone:	(516) 420-6142	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 420-6142
Spiller:	LILCO		
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	11/28/1990	Spilled Code:	0016
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	5 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	11/27/1990 14:45
Spill Date:	11/27/1990 10:43	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102138598

Cleanup Ceased: 11/28/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/30/1990

132

GRUMMAN
BLDG #15
BETHPAGE, NY

LUST

S100169240
N/A

LUST:

Facility ID: 8901729
Facility Contact: Not reported
Investigator: LEUNG
Caller Name: TERRENCE NEILLY
Caller Phone: (516) 349-8989
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GENERAL UTILITIES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-8176

Spill Class: Not reported
Spill Closed Dt: 10/26/1990
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 05/19/1989 17:00

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 05/19/1989 18:12

Cleanup Ceased: 10/26/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/29/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/22/1989

132

GRUMMAN
BLDG #3
BETHPAGE, NY

LUST

S100174734
N/A

LUST:

Facility ID: 9100456
Facility Contact: Not reported
Investigator: KISPERT
Caller Name: BOB AGEE
Caller Phone: (516) 575-2385

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S100174734

Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-2385
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/10/1994		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	04/11/1991 08:00	Reported to Dept:	04/11/1991 09:35
Cleanup Ceased:	06/10/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/13/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	04/15/1991		

132

**GRUMMAN
WAREHOUSE #8
BETHPAGE, NY**

LUST

**S100666487
N/A**

LUST:

Facility ID:	9006322	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DEROSA	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	10/10/1990	Spill Source:	Other Commercial/Industrial
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	09/07/1990 15:30
Spill Notifier:	Responsible Party		
Spill Date:	09/07/1990 11:00		
Cleanup Ceased:	10/10/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	10/12/1990		
Corrective Action Plan Submitted:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S100666487

Date Spill Entered In Computer Data File: 09/11/1990

132

**NORTHROP GRUMMAN
PLANT #15
BETHPAGE, NY**

LUST

**S101340024
N/A**

LUST:

Facility ID:	9410499	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	AUSTIN	Spill Type:	Facility
Caller Name:	ALAN BRUSSELS	Caller Agency:	NCDH
Caller Phone:	(516) 575-8033	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8033
Spiller:	NORTHROP GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Health Department	PBS Number:	Not reported
Spill Date:	11/07/1994 12:00	Reported to Dept:	11/07/1994 13:45
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/08/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/07/1994		

132

**GRUMMAN
PLANT #1 FUEL DEPOT
BETHPAGE, NY**

LUST

**S100663921
N/A**

LUST:

Facility ID:	9106667	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	JOHN HOFMANN	Caller Agency:	DEC
Caller Phone:	(516) 751-7900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-2385
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S100663921

Spill Cause:	Other	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	DEC	PBS Number:	Not reported
Spill Date:	09/16/1991 15:56	Reported to Dept:	09/17/1991 08:30
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	10/09/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/23/1991		

132

**GRUMMAN
GRUMMAN PLANT #17
BETHPAGE, NY**

LUST

**S100177076
N/A**

LUST:

Facility ID:	9105709	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	GINA COSTINI	Caller Agency:	TYREE
Caller Phone:	(516) 249-3150	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	GRUMMAN		
Address	Not reported		
	Not reported		

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	02/27/1995	Resource Affected:	Groundwater
Spill Cause:	Tank Test Failure	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Tank Tester	Reported to Dept:	08/26/1991 15:23
Spill Date:	08/26/1991 13:30		
Cleanup Ceased:	02/27/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/27/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/28/1991		

132

**GRUMMAN
PLANT #3
BETHPAGE, NY**

LUST

**S100664347
N/A**

LUST:

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S100664347

Facility ID:	9109773	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPERT	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	12/18/1991		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/13/1991 08:00	Reported to Dept:	12/13/1991 09:10
Cleanup Ceased:	12/18/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/19/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/13/1991		

132

GRUMMAN INC PLANT #3 BETHPAGE, NY

LUST

S100664811
N/A

LUST:

Facility ID:	9207766	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DECANDIA	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN INC		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	10/05/1992 10:45	Reported to Dept:	10/05/1992 12:00
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN INC (Continued)

S100664811

Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/07/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/06/1992

133

[REDACTED]
HICKSVILLE, NY

NY Spills

S102139225
N/A

Exemption 6

SPILLS:

Facility ID:	9310149	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	JOE PELOGREENO	Caller Agency:	GIFFORDS
Caller Phone:	(516) 576-3000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	11/22/1993	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	11/20/1993 01:30
Spill Date:	11/19/1993 23:59	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	11/22/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/22/1993		

134

13-34 CAFFRY AVE
13-34 CAFFREY AVENUE
FAR ROCKAWAY, NY 11691

UST

U001835250
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

13-34 CAFFRY AVE (Continued)

U001835250

PBS UST:

Facility ID: 2-269786 CBS Number: Not reported
Town: Not reported SWIS ID: 6301
Telephone: (718) 471-0690 Location: Not reported
Operator: JOSE NAVARRO
Contact: Not reported
Emergency Contact: JOSE NAVARRO, (718) 471-0690
Facility Type: APARTMENT BUILDING
Total Tanks: 1 Old PBS Num: Not reported
Owner: TRILOKE REALTY CORP
28 WEST 27 STREET
NY, NY 10001
(516) 741-2262

Owner Type: Corporate/Commercial Owner Mark: First Owner
Owner Subtype: Not reported
Mailing Address: TRILOKE REALTY CORP
100 EAST OLD COUNTRY ROAD SUITE 11
NY 11501
(516) 741-2262
ATTN: TIMOTHY STAPLETON

Facility Status: Active Total Capacity: 7500
Certification: 07/09/1992 Expiration: 07/14/1997
Tank Status: In Service
Tank Location: UNDERGROUND
Tank ID: 001 Install Date: 00/00
Product Stored: NOS 5 OR 6 FUEL OIL Tank Type: Steel/carbon steel
Tank Internal: Not reported Pipe Internal: Not reported
Pipe Location: Not reported Pipe Type: GALVANIZED STEEL
Tank External: Not reported
Pipe External: Not reported
Second Containment: NONE
Leak Detection: NONE
Overfill Prot: Product Level Gauge Dispenser: Gravity
Date Tested: Not reported Next Test Date: N.T.R
Date Closed: Not reported Test Method: Not reported
Database Type: Petroleum Bulk Storage Facility

135

NY Spills

S102140351
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9415353 Region of Spill: 1
Facility Contact: Not reported Facility Tele: Not reported
Investigator: NONE Spill Type: Facility
Caller Name: [REDACTED] Caller Agency: RELIANCE
Caller Phone: [REDACTED] Caller Extension: Not reported
Notifier Name: Not reported Notifier Agency: Not reported
Notifier Phone: Not reported Notifier Extension: Not reported
Spiller Contact: Not reported Spiller Phone: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 02/24/1995
Material Class: Petroleum Spilled Code: 0001
Quantity Spilled: 1 gallons Quant Recovered: 0 gallons

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102140351

Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	02/23/1995 09:00	Reported to Dept:	02/23/1995 09:33
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/24/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/24/1995		

136

PLT. #4
4 DEAN ST
HICKSVILLE, NY 11802

AST

A100084304
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #4 (Continued)

A100084304

CBS AST:

Facility ID:

1-000083

Telephone:

(516) 931-0184

Owner:

HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Facility Status:

Active

Tank ID:

001

Total AST's:

1

Tank Status:

In Service

Tank Location:

ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE

Install Date:

12/69

Capacity (Gal):

Not reported

Tank Type:

Steel/carbon steel

Product Stored:

LEADED GASOLINE

Extrnl Protection:

NONE

Intrnl Protection:

NONE

Tank Containment:

NONE

Pipe Type:

STEEL/IRON

Pipe Location:

Aboveground

Pipe Internal:

NONE

Pipe External:

NONE

Pipe Containment:

NONE

Haz Percent:

25

Leak Detection:

NONE

Overfill Protection:

Product Level Gauge

Chemical:

Not reported

Tank Closed:

Not reported

Capacity (Gals):

3500

Region:

STATE

Case Number:

1310732

PBS Number:

Not reported

MOSF Number:

Not reported

SWIS Code:

2824

SPDES Number:

Not reported

ICS Number:

1-700100

Operator:

STANLEY GOSCINSKI

Facility Town:

OYSTER BAY

Emrgncy Contact:

RICHARD E. WOODWELL

Emrgncy Phone:

(516) 931-0184

Certified Date:

02/13/95

Expiration Date:

05/25/97

Owner type:

Local Government

Facility Type:

Municipality

Owner Sub Type:

Not reported

Mail Name:

HICKSVILLE WATER DISTRICT

Mail Contact:

RICHARD E. WOODWELL

4 DEAN ST.

HICKSVILLE, NY 11801

Mail Phone:

(516) 931-0184

136

PLT. 8

UST

U003031238

4 DEAN ST

N/A

HICKSVILLE, NY 11802

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. 8 (Continued)

U003031238

CBS UST:

Facility ID:	1-000075	ICS No:	1-500016
PBS No:	Not reported	MOSF No:	Not reported
SWIS Code:	2824	Facility Tel:	(516) 931-0184
Town:	OYSTER BAY	Total Tanks:	2
Operator:	STANLEY GOSCINSKI		
Emergency Contact:	RICHARD E. WOODWELL, (516) 931-0184		
Certification Date:	3/95/02/1	Expiration Date:	5/97/05/2
Owner:	HICKSVILLE WATER DISTRICT		

4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Owner Type: Local Government
Facility Type: MUNICIPALITY
Mail To: HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
ATTN: RICHARD E. WOODWELL
(516) 931-0184

SPDES No: Not reported
Owner Subtype: Not reported
Tank ID: 001
Tank Location: UNDERGROUND
Install Date: 12/76
CAS No: 1310732
Tank Type: Fiberglass coated steel
Tank Internal: NONE
Tank External: NONE
Pipe Internal: NONE
Pipe External: NONE
Pipe Containment: NONE
Leak Detection: NONE
Overfill Protection: Product Level Gauge
Chemical: Not reported
Tank Closed: Not reported
Database Type: Chemical Bulk Storage Facility

Facility Type: Active
Tank Status: In Service
Capacity (Gal): Not reported
Substance: LEADED GASOLINE
2nd Containmt: NONE
Pipe Type: NOT DEFINED
Pipe Location: Underground
Haz Percent: 25

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. 8 (Continued)

U003031238

Facility ID:	1-000075	ICS No:	1-500016
PBS No:	Not reported	MOSF No:	Not reported
SWIS Code:	2824	Facility Tel:	(516) 931-0184
Town:	OYSTER BAY	Total Tanks:	2
Operator:	STANLEY GOSCINSKI		
Emergency Contact:	RICHARD E. WOODWELL, (516) 931-0184		
Certification Date:	3/95/02/1	Expiration Date:	5/97/05/2
Owner:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 (516) 931-0184		
Owner Type:	Local Government		
Facility Type:	MUNICIPALITY		
Mail To:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 ATTN: RICHARD E. WOODWELL (516) 931-0184		
SPDES No:	Not reported	Facility Type:	Active
Owner Subtype:	Not reported	Tank Status:	In Service
Tank ID:	002	Capacity (Gal):	Not reported
Tank Location:	UNDERGROUND	Substance:	LEADED GASOLINE
Install Date:	12/76	2nd Containmt:	NONE
CAS No:	1310732	Pipe Type:	NOT DEFINED
Tank Type:	Fiberglass coated steel	Pipe Location:	Underground
Tank Internal:	NONE	Haz Percent:	25
Tank External:	NONE		
Pipe Internal:	NONE		
Pipe External:	NONE		
Pipe Containment:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Database Type:	Chemical Bulk Storage Facility		

136

PLT. #11
4 DEAN ST
HICKSVILLE, NY 11802

AST

A100084299
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #11 (Continued)

A100084299

CBS AST:
Facility ID: 1-000078 Telephone: (516) 931-0184
Owner: HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Facility Status: Active
Tank ID: 001 Total AST's: 1
Tank Status: In Service
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/88 Capacity (Gal): Not reported
Tank Type: Steel/carbon steel Product Stored: LEADED GASOLINE
Extrnl Protection: SACRIFICIAL ANODE
Intnl Protection: RUBBER LINER
Tank Containment: DOUBLED-WALLED TANK
Pipe Type: STEEL/IRON Pipe Location: Aboveground
Pipe Internal: NONE
Pipe External: NONE
Pipe Containment: NONE Haz Percent: 25
Leak Detection: INTERSTITIAL MONITORING
Overfill Protection: High Level Alarm/Product Level Gauge
Chemical: Not reported
Tank Closed: Not reported
Capacity (Gals): 2000 Region: STATE
Case Number: 1310732 PBS Number: Not reported
MOSF Number: Not reported SWIS Code: 2824
SPDES Number: Not reported ICS Number: 1-700097
Operator: STANLEY GOSCINSKI Facility Town: OYSTER BAY
Emrgncy Contact: RICHARD E. WOODWELL Emrgncy Phone: (516) 931-0184
Certified Date: 02/13/95 Expiration Date: 05/25/97
Owner type: Local Government Facility Type: Municipality
Owner Sub Type: Not reported
Mail Name: HICKSVILLE WATER DISTRICT
Mail Contact: RICHARD E. WOODWELL
4 DEAN ST.
HICKSVILLE, NY 11801
Mail Phone: (516) 931-0184

136

HICKSVILLE W.D. PLANT B
4 DEAN ST.
HICKSVILLE, NY

AST
UST

U002097372
N/A

Nassau County UST:
Facility ID: 001160 Tank ID: 0003
Tank Location: Indoors, Belowground Capacity: 00004000
Tank Status: In Service Tank Material: Fiberglass Reinforced Plastic
Piping Type: Steel/Iron Material Type: Fresh/Product
Int Protection: Internal Lining
Ext Protection: FIBERGLASS REINFORCED PLASTIC
Description: SODIUM HYDROXIDE
Leak Detect: OTHER Containment: Other
Dispense Method: Suction Product Gauge: Yes
Fill Type: Pumped Install Date: 0176
Total Tanks: 2

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HICKSVILLE W.D. PLANT 8 (Continued)

U002097372

Facility ID:	001160	Tank ID:	0004
Tank Location:	Indoors, Belowground	Capacity:	00004000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Int Protection:	Internal Lining		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	SODIUM HYDROXIDE		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0176
Total Tanks:	2		

Nassau County AST:

Facility ID:	001160	Tank ID:	0006
Tank Location:	Indoors, Aboveground	Capacity (Gal):	300
Tank Status:	In Service	Tank Material:	PLASTIC
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Fresh/Product
Description:	SODIUM HYPOCHLORITE		
Leak Detect:	NONE	Containment:	DIKING AND PAD
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0491
Total Tanks:	Not reported		

136

PLT. #9
4 DEAN ST
HICKSVILLE, NY 11802

AST

A100084300
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #9 (Continued)

A100084300

CBS AST:

Facility ID:

1-000079

Telephone:

(516) 931-0184

Owner:

HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Facility Status:

Active

Tank ID:

001

Total AST's:

1

Tank Status:

In Service

Tank Location:

ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE

Install Date:

12/71

Capacity (Gal):

Not reported

Tank Type:

Steel/carbon steel

Product Stored:

LEADED GASOLINE

Extrnl Protection:

NONE

Intrnl Protection:

NONE

Tank Containment:

NONE

Pipe Type:

STEEL/IRON

Pipe Location:

Underground

Pipe Internal:

NONE

Pipe External:

NONE

Pipe Containment:

NONE

Haz Percent:

25

Leak Detection:

NONE

Overfill Protection:

Product Level Gauge

Chemical:

Not reported

Tank Closed:

Not reported

Capacity (Gals):

4000

Region:

STATE

Case Number:

1310732

PBS Number:

Not reported

MOSF Number:

Not reported

SWIS Code:

2824

SPDES Number:

Not reported

ICS Number:

1-700104

Operator:

STANLEY GOSCINSKI

Facility Town:

OYSTER BAY

Emrgncy Contact:

RICHARD E. WOODWELL

Emrgncy Phone:

(516) 931-0184

Certified Date:

02/13/95

Expiration Date:

05/25/97

Owner type:

Local Government

Facility Type:

Municipality

Owner Sub Type:

Not reported

Mail Name:

HICKSVILLE WATER DISTRICT

Mail Contact:

RICHARD E. WOODWELL

4 DEAN ST.

HICKSVILLE, NY 11801

Mail Phone:

(516) 931-0184

136

PLT. #2

4 DEAN ST

HICKSVILLE, NY 11802

AST

A100084305

N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #2 (Continued)

A100084305

CBS AST:

Facility ID: 1-000085
Owner: HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Telephone: (516) 931-0184

Facility Status: Active

Tank ID: 001

Total AST's: 1

Tank Status: In Service

Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE

Install Date: 12/65

Capacity (Gal): Not reported

Tank Type: Steel/carbon steel

Product Stored: LEADED GASOLINE

Extrnl Protection: NONE

Intrnl Protection: NONE

Tank Containment: NONE

Pipe Type: STEEL/IRON

Pipe Location: Aboveground

Pipe Internal: NONE

Pipe External: NONE

Pipe Containment: NONE

Haz Percent: 50

Leak Detection: NONE

Overfill Protection: Product Level Gauge

Chemical: Not reported

Tank Closed: Not reported

Capacity (Gals): 750

Region: STATE

Case Number: 1310732

PBS Number: Not reported

MOSF Number: Not reported

SWIS Code: 2824

SPDES Number: Not reported

ICS Number: 1-700098

Operator: STANLEY GOSCINSKI

Facility Town: OYSTER BAY

Emrgncy Contact: RICHARD E. WOODWELL

Emrgncy Phone: (516) 931-0184

Certified Date: 02/13/95

Expiration Date: 05/25/97

Owner type: Local Government

Facility Type: Municipality

Owner Sub Type: Not reported

Mail Name: HICKSVILLE WATER DISTRICT

Mail Contact: RICHARD E. WOODWELL

4 DEAN ST.

HICKSVILLE, NY 11801

Mail Phone: (516) 931-0184

136

PLT. #3

4 DEAN ST

HICKSVILLE, NY 11802

UST

U003031240

N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #3 (Continued)

U003031240

CBS UST:

Facility ID:	1-000084	ICS No:	1-700099
PBS No:	Not reported	MOSF No:	Not reported
SWIS Code:	2824	Facility Tel:	(516) 931-0184
Town:	OYSTER BAY	Total Tanks:	1
Operator:	STANLEY GOSCINSKI		
Emergency Contact:	RICHARD E. WOODWELL, (516) 931-0184		
Certification Date:	3/95/02/1	Expiration Date:	5/97/05/2
Owner:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 (516) 931-0184		

Owner Type: Local Government
Facility Type: MUNICIPALITY
Mail To: HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
ATTN: RICHARD E. WOODWELL
(516) 931-0184

SPDES No:	Not reported	Facility Type:	Active
Owner Subtype:	Not reported	Tank Status:	In Service
Tank ID:	001	Capacity (Gal):	Not reported
Tank Location:	UNDERGROUND, VAULTED, WITH ACCESS	Substance:	LEADED GASOLINE
Install Date:	12/69	2nd Containmt:	DOUBLED-WALLED TANK
CAS No:	1310732	Pipe Type:	STEEL/IRON
Tank Type:	Steel/carbon steel	Pipe Location:	Underground
Tank Internal:	NONE	Haz Percent:	25
Tank External:	NONE		
Pipe Internal:	NONE		
Pipe External:	NONE		
Pipe Containment:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Database Type:	Chemical Bulk Storage Facility		

136

PLT. 10
4 DEAN ST
HICKSVILLE, NY 11802

AST
UST

U003031239
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. 10 (Continued)

U003031239

CBS UST:

Facility ID:	1-000076	ICS No:	1-500015
PBS No:	Not reported	MOSF No:	Not reported
SWIS Code:	2824	Facility Tel:	(516) 931-0184
Town:	OYSTER BAY	Total Tanks:	1
Operator:	STANLEY GOSCINSKI		
Emergency Contact:	RICHARD E. WOODWELL, (516) 931-0184		
Certification Date:	3/95/02/1	Expiration Date:	5/97/05/2
Owner:	HICKSVILLE WATER DISTRICT		

4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Owner Type: Local Government
Facility Type: MUNICIPALITY
Mail To: HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
ATTN: RICHARD E. WOODWELL
(516) 931-0184

SPDES No:	Not reported	Facility Type:	Active
Owner Subtype:	Not reported	Tank Status:	In Service
Tank ID:	001	Capacity (Gal):	Not reported
Tank Location:	UNDERGROUND	Substance:	LEADED GASOLINE
Install Date:	12/80	2nd Containmt:	NONE
CAS No:	1310732	Pipe Type:	NOT DEFINED
Tank Type:	Fiberglass coated steel	Pipe Location:	Underground
Tank Internal:	NONE	Haz Percent:	25
Tank External:	NONE		
Pipe Internal:	NONE		
Pipe External:	NONE		
Pipe Containment:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Database Type:	Chemical Bulk Storage Facility		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. 10 (Continued)

U003031239

Facility ID:	1-000077	ICS No:	1-500014
PBS No:	Not reported	MOSF No:	Not reported
SWIS Code:	2824	Facility Tel:	(516) 931-0184
Town:	OYSTER BAY	Total Tanks:	2
Operator:	STANLEY GOSCINSKI		
Emergency Contact:	RICHARD E. WOODWELL, (516) 931-0184		
Certification Date:	3/95/02/1	Expiration Date:	5/97/05/2
Owner:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 (516) 931-0184		
Owner Type:	Local Government		
Facility Type:	MUNICIPALITY		
Mail To:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 ATTN: RICHARD E. WOODWELL (516) 931-0184		
SPDES No:	Not reported	Facility Type:	Active
Owner Subtype:	Not reported		
Tank ID:	001	Tank Status:	In Service
Tank Location:	UNDERGROUND		
Install Date:	12/80	Capacity (Gal):	Not reported
CAS No:	1310732	Substance:	LEADED GASOLINE
Tank Type:	Fiberglass coated steel	2nd Containmt:	NONE
Tank Internal:	NONE	Pipe Type:	NOT DEFINED
Tank External:	NONE		
Pipe Internal:	NONE	Pipe Location:	Aboveground
Pipe External:	NONE		
Pipe Containment:	NONE	Haz Percent:	25
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Database Type:	Chemical Bulk Storage Facility		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. 10 (Continued)

U003031239

Facility ID:	1-000077	ICS No:	1-500014
PBS No:	Not reported	MOSF No:	Not reported
SWIS Code:	2824	Facility Tel:	(516) 931-0184
Town:	OYSTER BAY	Total Tanks:	2
Operator:	STANLEY GOSCINSKI		
Emergency Contact:	RICHARD E. WOODWELL, (516) 931-0184		
Certification Date:	3/95/02/1	Expiration Date:	5/97/05/2
Owner:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 (516) 931-0184		
Owner Type:	Local Government		
Facility Type:	MUNICIPALITY		
Mail To:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 ATTN: RICHARD E. WOODWELL (516) 931-0184		
SPDES No:	Not reported	Facility Type:	Active
Owner Subtype:	Not reported	Tank Status:	In Service
Tank ID:	002	Capacity (Gal):	Not reported
Tank Location:	UNDERGROUND	Substance:	LEADED GASOLINE
Install Date:	12/67	2nd Containmt:	NONE
CAS No:	1310732	Pipe Type:	OTHER
Tank Type:	Steel/carbon steel	Pipe Location:	Aboveground
Tank Internal:	NONE	Haz Percent:	25
Tank External:	NONE		
Pipe Internal:	NONE		
Pipe External:	NONE		
Pipe Containment:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Database Type:	Chemical Bulk Storage Facility		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. 10 (Continued)

U003031239

CBS AST:		
Facility ID:	1-000077	Telephone: (516) 931-0184
Owner:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 (516) 931-0184	
Facility Status:	Active	
Tank ID:	003	Total AST's: 1
Tank Status:	In Service	
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	
Install Date:	12/65	Capacity (Gal): Not reported
Tank Type:	Steel/carbon steel	Product Stored: LEADED GASOLINE
Extrnl Protection:	NONE	
Intrnl Protection:	NONE	
Tank Containment:	NONE	
Pipe Type:	OTHER	Pipe Location: Aboveground
Pipe Internal:	NONE	
Pipe External:	NONE	
Pipe Containment:	NONE	Haz Percent: 25
Leak Detection:	NONE	
Overfill Protection:	Product Level Gauge	
Chemical:	Not reported	
Tank Closed:	Not reported	
Capacity (Gals):	750	Region: STATE
Case Number:	1310732	PBS Number: Not reported
MOSF Number:	Not reported	SWIS Code: 2824
SPDES Number:	Not reported	ICS Number: 1-500014
Operator:	STANLEY GOSCINSKI	Facility Town: OYSTER BAY
Emrgncy Contact:	RICHARD E. WOODWELL	Emrgncy Phone: (516) 931-0184
Certified Date:	02/13/95	Expiration Date: 05/25/97
Owner type:	Local Government	Facility Type: Municipality
Owner Sub Type:	Not reported	
Mail Name:	HICKSVILLE WATER DISTRICT	
Mail Contact:	RICHARD E. WOODWELL 4 DEAN ST. HICKSVILLE, NY 11801 (516) 931-0184	
Mail Phone:		

136

PLT. #5
4 DEAN ST
HICKSVILLE, NY 11802

AST

A100084303
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #5 (Continued)

A100084303

CBS AST:
Facility ID: 1-000082 Telephone: (516) 931-0184
Owner: HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184
Facility Status: Active
Tank ID: 001 Total AST's: 1
Tank Status: In Service
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/65 Capacity (Gal): Not reported
Tank Type: Steel/carbon steel Product Stored: LEADED GASOLINE
Extrnl Protection: NONE
Intrnl Protection: NONE
Tank Containment: NONE
Pipe Type: STEEL/IRON Pipe Location: Aboveground
Pipe Internal: NONE
Pipe External: NONE
Pipe Containment: NONE Haz Percent: 25
Leak Detection: NONE
Overfill Protection: Product Level Gauge
Chemical: Not reported
Tank Closed: Not reported
Capacity (Gals): 1250 Region: STATE
Case Number: 1310732 PBS Number: Not reported
MOSF Number: Not reported SWIS Code: 2824
SPDES Number: Not reported ICS Number: 1-700101
Operator: STANLEY GOSCINSKI Facility Town: OYSTER BAY
Emrgncy Contact: RICHARD E. WOODWELL Emrgncy Phone: (516) 931-0184
Certified Date: 02/13/95 Expiration Date: 05/25/97
Owner type: Local Government Facility Type: Municipality
Owner Sub Type: Not reported
Mail Name: HICKSVILLE WATER DISTRICT
Mail Contact: RICHARD E. WOODWELL
4 DEAN ST.
HICKSVILLE, NY 11801
Mail Phone: (516) 931-0184

136

HICKSVILLE WATER AUTHORIT
4 DEAN ST
HICKSVILLE, NY

LUST

S100150043
N/A

LUST:

Facility ID: 8805214 Region of Spill: 1
Facility Contact: Not reported Facility Tele: Not reported
Investigator: T/T/F Spill Type: Facility
Caller Name: AL ROTH Caller Agency: F&N
Caller Phone: Not reported Caller Extension: Not reported
Notifier Name: Not reported Notifier Agency: Not reported
Notifier Phone: Not reported Notifier Extension: Not reported
Spiller Contact: Not reported Spiller Phone: (516) 931-0184
Spiller: HICKSVILLE WATER AUTHORIT
Address: Not reported
Not reported
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 10/24/1994
Spill Cause: Tank Test Failure Resource Affected: Groundwater

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HICKSVILLE WATER AUTHORITY (Continued)

S100150043

Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 09/16/1988 12:30
Cleanup Ceased: 10/24/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/27/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/19/1988

Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 09/16/1988 14:26

136

PLT. #7
4 DEAN ST
HICKSVILLE, NY 11802

AST

A100084301
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #7 (Continued)

A100084301

CBS AST:

Facility ID: 1-000080
Owner: HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Telephone: (516) 931-0184

Facility Status:

Active

Tank ID:

001

Total AST's: 1

Tank Status:

In Service

Tank Location:

ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE

Install Date:

12/65

Capacity (Gal): Not reported

Tank Type:

Steel/carbon steel

Product Stored: LEADED GASOLINE

Extrnl Protection:

NONE

Intrnl Protection:

NONE

Tank Containment:

NONE

Pipe Type:

STEEL/IRON

Pipe Location: Aboveground

Pipe Internal:

NONE

Pipe External:

NONE

Pipe Containment:

NONE

Haz Percent: 25

Leak Detection:

NONE

Overfill Protection:

Product Level Gauge

Chemical:

Not reported

Tank Closed:

Not reported

Capacity (Gals):

750

Region: STATE

Case Number:

1310732

PBS Number: Not reported

MOSF Number:

Not reported

SWIS Code: 2824

SPDES Number:

Not reported

ICS Number: 1-700103

Operator:

STANLEY GOSCINSKI

Facility Town: OYSTER BAY

Emrgncy Contact:

RICHARD E. WOODWELL

Emrgncy Phone: (516) 931-0184

Certified Date:

02/13/95

Expiration Date: 05/25/97

Owner type:

Local Government

Facility Type: Municipality

Owner Sub Type:

Not reported

Mail Name:

HICKSVILLE WATER DISTRICT

Mail Contact:

RICHARD E. WOODWELL

4 DEAN ST.

HICKSVILLE, NY 11801

Mail Phone:

(516) 931-0184

136

PLT. #6

4 DEAN ST
HICKSVILLE, NY 11802

AST

A100084302

N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #6 (Continued)

A100084302

CBS AST:

Facility ID:

1-000081

Telephone:

(516) 931-0184

Owner:

HICKSVILLE WATER DISTRICT
4 DEAN ST.
HICKSVILLE, NY 11801
(516) 931-0184

Facility Status:

Active

Tank ID:

001

Total AST's:

2

Tank Status:

In Service

Tank Location:

ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE

Install Date:

12/65

Capacity (Gal):

Not reported

Tank Type:

Steel/carbon steel

Product Stored:

LEADED GASOLINE

Extrnl Protection:

NONE

Intrnl Protection:

NONE

Tank Containment:

NONE

Pipe Type:

STEEL/IRON

Pipe Location:

Aboveground

Pipe Internal:

NONE

Pipe External:

NONE

Pipe Containment:

NONE

Haz Percent:

25

Leak Detection:

NONE

Overfill Protection:

Product Level Gauge

Chemical:

Not reported

Tank Closed:

Not reported

Capacity (Gals):

750

Region:

STATE

Case Number:

1310732

PBS Number:

Not reported

MOSF Number:

Not reported

SWIS Code:

2824

SPDES Number:

Not reported

ICS Number:

1-700102

Operator:

STANLEY GOSCINSKI

Facility Town:

OYSTER BAY

Emrgncy Contact:

RICHARD E. WOODWELL

Emrgncy Phone:

(516) 931-0184

Certified Date:

02/13/95

Expiration Date:

05/25/97

Owner type:

Local Government

Facility Type:

Municipality

Owner Sub Type:

Not reported

Mail Name:

HICKSVILLE WATER DISTRICT

Mail Contact:

RICHARD E. WOODWELL

4 DEAN ST.

HICKSVILLE, NY 11801

Mail Phone:

(516) 931-0184

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PLT. #6 (Continued)

A100084302

Facility ID:	1-000081	Telephone:	(516) 931-0184
Owner:	HICKSVILLE WATER DISTRICT 4 DEAN ST. HICKSVILLE, NY 11801 (516) 931-0184		
Facility Status:	Active	Total AST's:	2
Tank ID:	002		
Tank Status:	In Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/65	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	NONE		
Intrnl Protection:	NONE		
Tank Containment:	NONE		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	NONE		
Pipe Containment:	NONE	Haz Percent:	25
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	750	Region:	STATE
Case Number:	1310732	PBS Number:	Not reported
MOSF Number:	Not reported	SWIS Code:	2824
SPDES Number:	Not reported	ICS Number:	1-700102
Operator:	STANLEY GOSCINSKI	Facility Town:	OYSTER BAY
Emrgncy Contact:	RICHARD E. WOODWELL	Emrgncy Phone:	(516) 931-0184
Certified Date:	02/13/95	Expiration Date:	05/25/97
Owner type:	Local Government	Facility Type:	Municipality
Owner Sub Type:	Not reported		
Mail Name:	HICKSVILLE WATER DISTRICT		
Mail Contact:	RICHARD E. WOODWELL 4 DEAN ST. HICKSVILLE, NY 11801		
Mail Phone:	(516) 931-0184		

137

HI TECH CLEANERS
337 JERUSALEM AVE
HICKSVILLE, NY 11801

FINDS 1000694257
RCRIS-LQG NYD987005600

RCRIS:

Owner: CHARLEY RO
(516) 831-3252

Contact: CHARLEY RO
(516) 831-3252

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>
F001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

HI TECH CLEANERS (Continued)

1000694257

Used Oil Recyc: No

Violation Status: No violations found

138

**KING BEAR
735 S BROADWAY
HICKSVILLE, NY**

AST

A100090874
N/A

Nassau County AST:

Facility ID: 056949
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, MOTOR
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0001
Capacity (Gal): 240
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DOUBLE WALL TANK
Product Gauge: Yes
Install Date: 0891

Facility ID: 056949
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, MOTOR
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0002
Capacity (Gal): 240
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DOUBLE WALL TANK
Product Gauge: Yes
Install Date: 0891

138

**KING BEAR AUTO SERVICE CENTER
735 S BROADWAY
HICKSVILLE, NY 11801**

FINDS

RCRIS-LQG

1000231520
NYD981563513

RCRIS:

Owner: S M D ENTERPRISES INC
(212) 555-1212

Contact: SY DIAMOND
(516) 931-9714

Classification: Large Quantity Generator

Waste Quantity
X001 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

KING BEAR AUTO SERVICE CENTER (Continued)

1000231520

Used Oil Recyc: No

Violation Status: No violations found

139

HICKSVILLE, NY

LUST

S102233190
N/A

LUST:

Facility ID: 9605179

Facility Contact:

Investigator:

Caller Name:

Caller Phone:

Notifier Name:

Notifier Phone:

Spiller Contact:

Spiller:

Address

Region of Spill: 1

Facility Tele:

Spill Type: UST

Caller Agency: HOMEOWNER

Caller Extension: Not reported

Notifier Agency: HOMEOWNER

Notifier Extension: Not reported

Spiller Phone:

HICKSVILLE, NY -

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 07/22/1996

Spill Cause: Tank Failure

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 07/22/1996 09:00

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 07/23/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 07/22/1996

Resource Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 07/22/1996 09:32

Exemption 6

140

GENERAL ELECTRIC COMPANY INC
848 S OYSTER BAY RD
HICKSVILLE, NY 11802

FINDS

1000788076
NYD060317831

140

GENERAL ELECTRIC SUPPLY CO
848 S OYSTER BAY RD
HICKSVILLE, NY 11801

RCRIS-LQG

1000212460
NYD060317831

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GENERAL ELECTRIC SUPPLY CO (Continued)

1000212460

RCRIS:

Owner: GENERAL ELECTRIC
(212) 555-1212

Contact: JOSEPH HAYDEN
(516) 931-1890

Classification: Large Quantity Generator

Waste Quantity
D001 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

141

UNK
47 LINDEN BLVD
HICKSVILLE, NY

NY Spills

S102135847
N/A

SPILLS:

Facility ID: 8705000
Facility Contact: Not reported
Investigator: PARISH
Caller Name: TOM TROUSDELL
Caller Phone: (516) 566-5277
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: UNK
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NASS CTY FIRE MARSHALL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 09/24/1987
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Abandoned Drums
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 09/15/1987 19:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 09/24/1987
Last Inspection: 09/16/1987

Spilled Code: 0009
Quant Recovered: 40 gallons
Resource Affected: On Land
Spill Source: Unknown
PBS Number: Not reported
Reported to Dept: 09/15/1987 20:10
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/11/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/16/1987

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

142	LILCO 21 CHATHAM CT HICKSVILLE, NY	NY Spills	S102139085 N/A
-----	--	-----------	-------------------

SPILLS:

Facility ID:	9306865	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	ADAM YAZLONSKY	Caller Agency:	LILCO
Caller Phone:	(516) 842-9075	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	LILCO		
Address:	Not reported		
	Not reported		

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	09/03/1993	Spilled Code:	0016
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	09/03/1993 19:38
Spill Date:	09/03/1993 16:45	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/03/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/09/1993		

143	[REDACTED] HICKSVILLE, NY	NY Spills	S102237818 N/A
-----	------------------------------	-----------	-------------------

Exemption 6

SPILLS:

Facility ID:	9603134	Region of Spill:	1
Facility Contact:	[REDACTED]	Facility Tele:	[REDACTED]
Investigator:	NONE	Spill Type:	UST
Caller Name:	[REDACTED]	Caller Agency:	GRECO BROTHERS FUEL CORPO
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	[REDACTED]	Notifier Agency:	Not reported
Notifier Phone:	[REDACTED]	Notifier Extension:	Not reported
Spiller Contact:	[REDACTED]	Spiller Phone:	[REDACTED]
Spiller:	[REDACTED]		
Address:	[REDACTED]		

HICKSVILLE, NY 11801-

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	06/05/1996	Spilled Code:	0001
Material Class:	Petroleum		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102237818

Quantity Spilled: 2 gallons	Quant Recovered: 2 gallons
Spill Cause: Human Error	Resource Affected: On Land
Water Affected: Not reported	Spill Source: Private Dwelling
Spill Notifier: Other	PBS Number: Not reported
Spill Date: 06/05/1996 15:00	Reported to Dept: 06/05/1996 15:28
Tank Number: Not reported	Tank Capacity: 0 Gallons
Test method: Not reported	Leak Rate: 0.00
Gross Leak/Fail: Not reported	
Cleanup Ceased: Not reported	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 06/06/1996	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 06/05/1996	

144

NY Spills

S102102259
N/A

BETHPAGE, NY

SPILLS:

Facility ID: 9506069	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: NONE	Spill Type: Facility
Caller Name: [REDACTED]	Caller Agency: RELIANCE
Caller Phone: [REDACTED]	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: RESIDENCE	
Address: Not reported	
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: 08/18/1995	
Material Class: Petroleum	Spilled Code: 0001
Quantity Spilled: 1 gallons	Quant Recovered: 0 gallons
Spill Cause: Equipment Failure	Resource Affected: On Land
Water Affected: Not reported	Spill Source: Private Dwelling
Spill Notifier: Responsible Party	PBS Number: Not reported
Spill Date: 08/17/1995 09:00	Reported to Dept: 08/17/1995 09:14
Tank Number: Not reported	Tank Capacity: 0 Gallons
Test method: Not reported	Leak Rate: 0.00
Gross Leak/Fail: Not reported	
Cleanup Ceased: 08/18/1995	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 08/21/1995	
Corrective Action Plan Submitted: Not reported	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RESIDENCE (Continued)

S102102259

Date Spill Entered In Computer Data File: 08/18/1995

145

BETHPAGE, NY

NY Spills

S102092903
N/A

SPILLS:

Facility ID:	9210428	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	MILRO
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/10/1992		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	5 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	11/29/1992 12:00	Reported to Dept:	12/09/1992 16:04
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/10/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/14/1992		

Exemption 6

146

**PUBLIC ELECTRIC
794 BROADWAY
HICKSVILLE, NY**

LUST

S100782210
N/A

LUST:

Facility ID:	9310919	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMPBELL	Spill Type:	Facility
Caller Name:	ROBIN RHODE	Caller Agency:	NCDH
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PUBLIC ELECTRIC (Continued)

S100782210

Spiller: PUBLIC ELECTRIC
Address: Not reported
Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 04/22/1994
Spill Cause: Other
Resource Affected: Groundwater
Water Affected: Not reported
Spill Source: Other Non Commercial/Industrial
Spill Notifier: Health Department
PBS Number: Not reported
Spill Date: 12/08/1993 12:00
Reported to Dept: 12/08/1993 14:00
Cleanup Ceased: 04/22/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/25/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/09/1993

147

LILCO
870 S OYSTER BAY RD
HICKSVILLE, NY

NY Spills

S102140575
N/A

SPILLS:

Facility ID: 9503219
Facility Contact: Not reported
Investigator: SCHULZ
Caller Name: MIKE TUCKER
Caller Phone: (516) 391-6406
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: LILCO
Address: Not reported
Not reported
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 08/13/1996
Material Class: Petroleum
Quantity Spilled: 50 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 06/14/1995 19:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: LILCO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported
Spilled Code: 0016
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 06/14/1995 20:49
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102140575

Spill Record Last Update: 08/14/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/16/1995

147

COLONIAL TRANSPARENT PDTS CO
870 S OYSTER BAY RD
HICKSVILLE, NY 11801

FINDS

1000545961
NYD001339621

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Facility is monitored or permitted for air emissions under the Clean Air Act (under AFS/AIRS)
- Civil judicial and administrative enforcement case against facility (under DOCKET)

148

BETHPAGE, NY

NY Spills

S102095177
N/A

SPILLS:

Facility ID: 8803978
Facility Contact: Not reported
Investigator: WALEK
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CMI
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY
Spill Class: Not reported
Spill Closed Dt: 11/25/1988
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Vandalism
Water Affected: Not reported
Spill Notifier: Local Agency
Spill Date: 08/04/1988 16:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 11/25/1988
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/30/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/08/1988

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/05/1988 10:54
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

149

BETHPAGE, NY

NY Spills

S102099382
N/A

SPILLS:

Facility ID: 9401130
Facility Contact: Not reported
Investigator: NONE
Caller Name: INSPECTOR HARE
Caller Phone: (516) 566-5293
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

LEVITTOWN

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 04/25/1994
Material Class: Petroleum
Quantity Spilled: 6 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 04/23/1994 13:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 04/25/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/26/1994

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 04/23/1994 16:39
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

150

BETHPAGE, NY

NY Spills

S102089886
N/A

SPILLS:

Facility ID: 9100369
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GIFFORD
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY

Spill Class: Not reported
Spill Closed Dt: 04/10/1991
Material Class: Petroleum
Quantity Spilled: 4 gallons

Spilled Code: 0001
Quant Recovered: 0 gallons

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102089886

Exemption 6

Spill Cause: Equipment Failure

Water Affected: Not reported

Spill Notifier: Other

Spill Date: 04/09/1991 10:45

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: 04/10/1991

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 04/11/1991

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 04/10/1991

Resource Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 04/09/1991 11:23

Tank Capacity: 0 Gallons

Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

151

HICKSVILLE, NY

NY Spills

S102139852
N/A

SPILLS:

Facility ID: 9407193
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: COMMANDER
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 08/30/1994
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 08/26/1994 18:28
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 08/30/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/26/1994 21:39
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Spill Record Last Update: 08/31/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/30/1994

Exemption 6

152

BETHPAGE, NY

LUST

S100491053
N/A

LUST:

Facility ID: 9201264
Facility Contact: Not reported
Investigator: LUCE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GENERAL UTILITIES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 06/24/1992
Spill Cause: Tank Failure

Resource Affected: On Land

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100491053

Exemption 6

Water Affected: Not reported
Spill Notifier: Other
Spill Date: 04/24/1992 12:00
Cleanup Ceased: 06/24/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/10/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/05/1992

Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 05/01/1992 10:50

153

NY Spills

S102139693
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9404205
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 06/28/1994
Material Class: Petroleum
Quantity Spilled: 2 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 06/24/1994 08:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 06/28/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/29/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/28/1994

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Passenger Vehicle
PBS Number: Not reported
Reported to Dept: 06/24/1994 19:30
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

154

MINEOLA MACK INC
880 S OYSTER BAY RD
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS
LUST

1000209178
NYD012730743

RCRIS:

Owner: AMEDEO GABRIELLI
(212) 555-1212

Contact: AMEDEO GABRIELLI
(516) 981-7915

Classification: Small Quantity Generator

Waste Quantity
D001 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

LUST:

Facility ID:	9304746	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMPBELL	Spill Type:	Facility
Caller Name:	MIKE ELLETTO	Caller Agency:	YELLOWSTONE
Caller Phone:	(516) 547-7104	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	MINEOLA MACK		
Address	Not reported		

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 05/05/1994

Spill Cause: Other

Water Affected: Not reported

Spill Notifier: Other

Spill Date: 07/15/1993 12:10

Cleanup Ceased: 05/05/1994

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 05/05/1994

Corrective Action Plan Submitted: Not reported

Date Spill Entered in Computer Data File: 07/16/1993

Resource Affected: On Land

Spill Source: Other Commercial/Industrial

PBS Number: Not reported

Reported to Dept: 07/15/1993 12:20

Facility ID: 9304764

Facility Contact: Not reported

Investigator: CAMPBELL

Caller Name: ALAN BRUSSELS

Caller Phone: (516) 571-3314

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Region of Spill: 1

Facility Tele: Not reported

Spill Type: Facility

Caller Agency: NCDH

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MINEOLA MACK INC (Continued)

1000209178

Spiller: MINEOLA MACK
Address: Not reported
Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 04/29/1994
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Health Department
Spill Date: 07/15/1993 14:00
Cleanup Ceased: 04/29/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/05/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/16/1993
Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 07/15/1993 14:00

154

**GABRIELLI TRUCK SALES LTD
880 S OYSTER BAY RD
HICKSVILLE, NY**

AST

**A100090856
N/A**

Nassau County AST:

Facility ID:	056827	Tank ID:	0002
Tank Location:	Indoors, Aboveground	Capacity (Gal):	275
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Unknown		
Ext Protection:	UNKNOWN		
Piping Type:	Steel/Iron	Material Type:	Waste
Description:	WASTE OIL		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	1255
Total Tanks:	Not reported		

155

**FAME TRUCKING INC
246 8 TH ST
BETHPAGE, NY 11714**

**RCRIS-SQG
FINDS**

**1000199036
NYD980646038**

RCRIS:

Owner: ANGELA MAFRICI
(212) 555-1212

Contact: ANGELA MAFRICI
(516) 938-8596

Classification: Hazardous Waste Transporter

<u>Waste</u>	<u>Quantity</u>
NONE	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

FAME TRUCKING INC (Continued)

1000199036

Used Oil Recyc: No

Violation Status: No violations found

156

LUST

S101103105
N/A

HICKSVILLE, NY

LUST:

Facility ID:	9402184	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DECANDIA	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	CITIZEN
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response.		
	Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Citizen	PBS Number:	Not reported
Spill Date:	05/13/1993 12:00	Reported to Dept:	05/13/1994 13:34
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	Fale		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/16/1994		

Exemption 6

157

LUST

S100149723
N/A

BLUE FLAME
3 WASHINGTON PKWY
HICKSVILLE, NY

LUST:

Facility ID:	8704453	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ACAMPORA	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-6700
Spiller:	BLUE FLAME		
Address:	3 WASHINGTON PARKWAY		
	HICKSVILLE, NY 11801		
Spill Class:	Not reported		
Spill Closed Dt:	12/24/1990		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BLUE FLAME (Continued)

S100149723

Spill Cause:	Tank Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	08/28/1987 12:00	Reported to Dept:	08/28/1987 12:00
Cleanup Ceased:	12/24/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/27/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/01/1987		

157

NASSAU BLUE FLAME INC
3 WASHINGTON PKWY
HICKSVILLE, NY

AST

A100090779
N/A

Nassau County AST:

Facility ID:	056214	Tank ID:	0001
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	275
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	OTHER	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	OIL, FUEL #2	Containment:	OTHER
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Gravity	Install Date:	0584
Fill Type:	Pumped		
Total Tanks:	Not reported		
Facility ID:	056214	Tank ID:	0002
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	275
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	OTHER	Material Type:	Waste
Piping Type:	Steel/Iron		
Description:	WASTE OIL	Containment:	OTHER
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Suction	Install Date:	0584
Fill Type:	Gravity		
Total Tanks:	Not reported		

158

CORAL GRAPHIC SERVICES INC
840 S BROADWAY
HICKSVILLE, NY 11801

RCRIS-LQG

1000990164
NYR000001230

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CORAL GRAPHIC SERVICES INC (Continued)

1000990164

RCRIS:

Owner: FC PROPERTIES INC
(516) 576-2100

Contact: WILLIAM CURRAN
(516) 576-2100

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)
D007	0.000 (N)	D010	0.000 (N)
D011	0.000 (N)	D027	0.000 (N)
F001	0.000 (N)	F002	0.000 (N)
F003	0.000 (N)	F005	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

158

CORAL GRAPHIC SERVICES INC
840 S BROADWAY
HICKSVILLE, NY 11801

FINDS

1001010739
NY0001173137

159

A ERNIES AUTO BODY INC
870 S BROADWAY
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000217113
NYD050594878

RCRIS:

Owner: ERNEST DEMARCO
(212) 555-1212

Contact: JOSEPH ZARRILLO
(516) 938-2929

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)	F003	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

159

BETHPAGE TRANSMISSION
870 BROADWAY
HICKSVILLE, NY 11801

FINDS
RCRIS-LQG

1000243979
NYD012728010

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BETHPAGE TRANSMISSION (Continued)

1000243979

RCRIS:

Owner: NICK & STEVEN FERRARO
(212) 555-1212

Contact: BARRY PIVNICK
(516) 681-5210

Classification: Large Quantity Generator

Waste	Quantity
U220	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

159

FIRESTONE SAVMOR AUTO SERVICE
870 S BROADWAY
HICKSVILLE, NY 11801

FINDS
RCRIS-LQG

1000222624
NYD981489826

RCRIS:

Owner: RAY VILLAFANNA
(212) 555-1212

Contact: JOHN COVERAS
(516) 822-2857

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

159

TRUE AUTO RESTORATIONS INC
870 S BROADWAY - E SECTION
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000553680
NYD986961076

RCRIS:

Owner: BOB MISTRETTE
(212) 555-1212

Contact: BOB MISTRETTE
(516) 822-1042

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	D035	0.000 (N)
F003	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TRUE AUTO RESTORATIONS INC (Continued)

1000553680

Used Oil Recyc: No

Violation Status: No violations found

160

HICKSVILLE, NY

NY Spills

S102138461
N/A

SPILLS:

Facility ID: 9005468
Facility Contact: Not reported
Investigator: LUCE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MILRO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

HICKSVILLE, NY
Spill Class: Not reported
Spill Closed Dt: 09/14/1990
Material Class: Petroleum
Quantity Spilled: 75 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 08/16/1990 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 09/14/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/14/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/22/1990

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 08/17/1990 10:54
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

161

**DC FEMIA AUTO COLLISION
44 WASHINGTON PKWY
HICKSVILLE, NY 11801**

RCRIS-SQG
FINDS

1000228180
NYD982180606

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

DC FEMIA AUTO COLLISION (Continued)

1000228180

RCRIS:

Owner: UNKNOWN
(212) 555-1212

Contact: SAL FEMIA
(516) 681-6660

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
F003	0.000 (N)	F005	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

161

JOHN GRACE & CO
34 WASHINGTON PKWY
HICKSVILLE, NY 11801

FINDS
RCRIS-LQG

1000789191
NYD986999365

RCRIS:

Owner: STARBARE II PARTNERS LP
(201) 228-8675

Contact: MICHAEL CARPINO
(201) 228-8675

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D002	0.000 (N)	D007	0.000 (N)
D008	0.000 (N)	D011	0.000 (N)
F001	0.000 (N)	F002	0.000 (N)
F003	0.000 (N)	F005	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

Exemption 6

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Civil judicial and administrative enforcement case against facility (under DOCKET)

162

HICKSVILLE, NY

LUST

S102233093
N/A

LUST:

Facility ID: 9514958
Facility Contact: [REDACTED]
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: RELIANCE WRITE FUEL
Notifier Phone: Not reported
Spiller Contact: [REDACTED]

Region of Spill: 1
Facility Tele: [REDACTED]
Spill Type: UST
Caller Agency: HOMEOWNER
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102233093

Spiller: [REDACTED]
Address: [REDACTED]
HICKSVILLE, NY 11801-
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 02/22/1996
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/21/1996 18:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/23/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/21/1996
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 02/21/1996 22:53

Exemption 6

163

NY Spills

S102237395
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9600298
Facility Contact: [REDACTED]
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: SVC MAN 06
Notifier Phone: (516) 475-4770
Spiller Contact: [REDACTED]
Spiller: [REDACTED]
Address: [REDACTED]
HICKSVILLE
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 04/08/1996
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/06/1996 12:24
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Region of Spill: 1
Facility Tele: [REDACTED]
Spill Type: UST
Caller Agency: RELIANCE FUEL
Caller Extension: Not reported
Notifier Agency: RELIANCE FUEL
Notifier Extension: Not reported
Spiller Phone: ([REDACTED])
Spilled Code: 0001
Quant Recovered: 1 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 04/06/1996 15:05
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102237395

Spill Record Last Update: 04/09/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/06/1996

Exemption 6

164

NY Spills

S102138692
N/A

HICKSVILLE, NY

SPILLS:

Facility ID:	9011818	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORD OIL
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	02/12/1991	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	02/11/1991 11:36
Spill Date:	02/11/1991 08:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/12/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/13/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/12/1991		

165

C&K PETROLEUM
17 HAZEL ST
HICKSVILLE, NY

NY Spills

S102136889
N/A

SPILLS:

Facility ID:	8603321	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NCHD	Spill Type:	UST
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C&K PETROLEUM (Continued)

S102136889

Spiller:	C&K PETROLEUM	Spilled Code:	0008
Address:	Not reported	Quant Recovered:	0 gallons
	Not reported	Resource Affected:	On Land
Spill Class:	Not reported	Spill Source:	Tank Truck
Spill Closed Dt:	11/28/1986	PBS Number:	Not reported
Material Class:	Petroleum	Reported to Dept:	08/19/1986 14:50
Quantity Spilled:	30 gallons	Tank Capacity:	0 Gallons
Spill Cause:	Equipment Failure	Leak Rate:	0.00
Water Affected:	Not reported		
Spill Notifier:	Affected Persons		
Spill Date:	08/19/1986 11:45		
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	11/28/1986		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/13/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/25/1986		

165

BLUE FLAME
17 HAZEL ST
HICKSVILLE, NY 11801

FINDS 1000196683
RCRIS-LQG NYD981561004

RCRIS:

Owner: BLUE FLAME - THOMAS DUNN
(212) 555-1212

Contact: STEPHEN TYREE
(516) 249-3150

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

166

WERNER TRUCK CO
39 JEFFRY LN
HICKSVILLE, NY

NY Spills S102136403
N/A

SPILLS:

Facility ID:	9207242	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	JOANN CONTE	Caller Agency:	FLEET SERVICE
Caller Phone:	(516) 694-3117	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

WERNER TRUCK CO (Continued)

S102136403

Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	WERNER TRUCK CO		
Address:	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/23/1992		
Material Class:	Petroleum	Spilled Code:	0008
Quantity Spilled:	30 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	09/23/1992 00:01	Reported to Dept:	09/23/1992 01:08
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/23/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	10/01/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/23/1992		

166

NATIONAL METAL SPRAYING 40 JEFFRY LN HICKSVILLE, NY 11801

RCRIS-SQG 1000259721
FINDS NYD002049658

Used Oil Recyc: No
Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Facility is monitored or permitted for air emissions under the Clean Air Act (under AFS/AIRS)

167

MAGNOLIA GARDENS APTS 899 BROADWAY WESTBURY/NEW CASSEL, NY

NY Spills S102135946
N/A

SPILLS:

Facility ID:	8808676	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	HAAS	Spill Type:	Facility
Caller Name:	JOE DEFRANCO	Caller Agency:	NASSAU CTY HEALTH
Caller Phone:	(516) 535-2404	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	ATLANTIC FUELS		
Address:	OR HERBERT PETROLEUM?		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MAGNOLIA GARDENS APTS (Continued)

S102135946

Spill Class: Known release that creates a file or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)

Spill Closed Dt: Not reported

Material Class: Petroleum

Quantity Spilled: 4400 gallons

Spill Cause: Human Error

Water Affected: Not reported

Spill Notifier: Health Department

Spill Date: 12/16/1989 12:00

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: False

Recommended Penalty: Recommended Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 07/06/1993

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 02/07/1989

Spilled Code: 0001

Quant Recovered: 1784 gallons

Resource Affected: Groundwater

Spill Source: Tank Truck

PBS Number: Not reported

Reported to Dept: 02/03/1989 11:30

Tank Capacity: 0 Gallons

Leak Rate: 0.00

168

**NEW YORK TELEPHONE
920 S OYSTER BAY RD ROOM 300
BETHPAGE, NY 11714**

**FINDS 1000136892
RCRIS-LQG NYD982185712**

RCRIS:

Owner: NEW YORK TELEPHONE
(212) 555-1212

Contact: JACK OBRIEN
(914) 789-6141

Classification: Large Quantity Generator

Waste Quantity
NONE 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

Exemption 6

169

HICKSVILLE, NY

**NY Spills S102446283
N/A**

170

**PRIDE UTILITIES INC
70 WASHINGTON PKWY
HICKSVILLE, NY 11801**

**RCRIS-SQG 1001079917
NYR000016246**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PRIDE UTILITIES INC (Continued)

1001079917

RCRIS:

Owner: ALFRED WREG
(516) 467-3728

Contact: ROBERT WREGE
(516) 681-6663

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D039	0.000 (N)	F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

171

NY Spills

S102140061
N/A

HICKSVILLE, NY

SPILLS:

Facility ID: 9410615
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 11/09/1994
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 11/09/1994 15:18
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 11/09/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/10/1994

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 11/09/1994 15:19
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS



A100084335
N/A

Telephone:	(516) 349-8340
Total AST's:	2
Capacity (Gal):	Not reported
Product Stored:	LEADED GASOLINE
Pipe Location:	Aboveground
Haz Percent:	93
Region:	STATE
PBS Number:	Not reported
SWIS Code:	2824
ICS Number:	1-700334
Facility Town:	OYSTER BAY
Emrgncy Phone:	(516) 349-8340
Expiration Date:	06/27/97
Facility Type:	Other

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TBG COGEN PARTNERS (Continued)

A100084335

Facility ID:	1-000129	Telephone:	(516) 349-8340
Owner:	TBG COGEN PARTNERS 939 SOUTH BROADWAY HICKSVILLE, NY 11801 (516) 349-8340		
Facility Status:	Active	Total AST's:	2
Tank ID:	12		
Tank Status:	In Service		
Tank Location:	ABOVEGROUND		
Install Date:	05/89	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	JACKETED		
Intnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	VAULT	Haz Percent:	50
Leak Detection:	OTHER		
Overfill Protection:	High Level Alarm/Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported	Region:	STATE
Capacity (Gals):	2000	PBS Number:	Not reported
Case Number:	7664939	SWIS Code:	2824
MOSF Number:	1-3280	ICS Number:	1-700334
SPDES Number:	Not reported	Facility Town:	OYSTER BAY
Operator:	TODD NASS	Emrgncy Phone:	(516) 349-8340
Emrgncy Contact:	TODD NASS	Expiration Date:	06/27/97
Certified Date:	11/17/95	Facility Type:	Other
Owner type:	Corporate/Commercial		
Owner Sub Type:	Not reported		
Mail Name:	TBG COGEN PARTNERS		
Mail Contact:	JOHN SASSO 939 SOUTH BROADWAY HICKSVILLE, NY 11801		
Mail Phone:	(516) 349-8340		

172

GENERAL ELECTRIC
939 S BROADWAY
HICKSVILLE, NY

NY Spills

S102137719
N/A

SPILLS:

Facility ID:	8807458	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	MIRZA	Spill Type:	Facility
Caller Name:	DAVID COLLINS	Caller Agency:	GENERAL ELECTRIC
Caller Phone:	(516) 349-0418	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GENERAL ELECTRIC		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	0066
Spill Closed Dt:	12/31/1988	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	20 gallons		
Spill Cause:	Equipment Failure		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GENERAL ELECTRIC (Continued)

S102137719

Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/09/1988 10:30	Reported to Dept:	12/09/1988 10:55
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/31/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/03/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/13/1988		

172

T B G COGEN PARTNERS
939 S BROADWAY
HICKSVILLE, NY 11801

PADS 1000791459
RCRIS-SQG NYD987029691
FINDS

RCRIS:

Owner: TBG COGEN PARTNERS
(516) 349-8340

Contact: ANTHONY LIGATO
(516) 349-8340

Classification: Conditionally Exempt Small Quantity Generator

Waste	Quantity
X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Facility is a PCB generator, storer, transporter or permitted disposer (under PADS)

172

TBG CO GEN PARTNERS
939 S BROADWAY
HICKSVILLE, NY

NY Spills S102136332
N/A

SPILLS:

Facility ID: 9205267
Facility Contact: Not reported
Investigator: CAMPBELL
Caller Name: ANTHONY LIGATO
Caller Phone: (516) 349-8340
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: TBG CO GEN PARTNERS
Address: 939 SO BROADWAY
HICKSVILLE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: TBG
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TBG CO GEN PARTNERS (Continued)

S102136332

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 03/18/1993

Material Class: Petroleum

Quantity Spilled: 32 gallons

Spill Cause: Equipment Failure

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 08/07/1992 07:30

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: 03/18/1993

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 03/19/1993

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 08/10/1992

Spilled Code: 0022

Quant Recovered: 0 gallons

Resource Affected: On Land

Spill Source: Other Commercial/Industrial

PBS Number: Not reported

Reported to Dept: 08/07/1992 11:30

Tank Capacity: 0 Gallons

Leak Rate: 0.00

172

**TBG COGEN PARTNERS
939 S BROADWAY
HICKSVILLE, NY**

AST

**A100090163
N/A**

Nassau County AST:

Facility ID:	001217	Tank ID:	0011
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	2000
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Other		
Description:	SODIUM HYDROXIDE	Containment:	DIKING AND PAD
Leak Detect:	OTHER	Product Gauge:	Yes
Dispense Method:	Gravity	Install Date:	0492
Fill Type:	Pumped		
Total Tanks:	Not reported		
Facility ID:	001217	Tank ID:	0012
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	2000
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Other		
Description:	SULPHURIC ACID	Containment:	DIKING AND PAD
Leak Detect:	OTHER	Product Gauge:	Yes
Dispense Method:	Gravity	Install Date:	0492
Fill Type:	Pumped		
Total Tanks:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TBG COGEN PARTNERS (Continued)

A100090163

Facility ID: 001217
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: ERYTHORBIC ACID
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0051
Capacity (Gal): 400
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0492

Facility ID: 001217
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM HYDROXIDE
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0052
Capacity (Gal): 75
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0492

Facility ID: 001217
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM TRIPOLYPHOSPHATE
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0053
Capacity (Gal): 75
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0492

Facility ID: 001217
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM TRIPOLYPHOSPHATE
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0054
Capacity (Gal): 75
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0492

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TBG COGEN PARTNERS (Continued)

A100090163

Facility ID: 001217
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: SODIUM HYDROXIDE
Leak Detect: OTHER
Dispense Method: Submersible
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0055
Capacity (Gal): 100
Tank Material: STEEL

Material Type: Fresh/Product

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0492

Facility ID: 001217
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: FIBERGLASS REINFORCED PLASTIC
Piping Type: Steel/Iron
Description: PCB CONTAMINATED MATERIALS
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: Not reported

Tank ID: 0073
Capacity (Gal): 300
Tank Material: STEEL

Material Type: Waste

Containment: DIKING AND PAD
Product Gauge: Yes
Install Date: 0594

172

**TBG COGEN PARTNERS
939 S BROADWAY
HICKSVILLE, NY 11801**

AST

**A100086227
N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TBG COGEN PARTNERS (Continued)

A100086227

MOSF AST:
Facility ID: 1-3280 Telephone: (516) 349-8340
Facility Type: Other Facility Contact: ANTHONY E. LIGATO
Facility Status: ACTIVE FACILITY
Owner: TBG COGEN PARTNERS
939 S BROADWAY
HICKSVILLE, NY 11801
Owner Tel: (516) 349-8340
Owner Type: Corporate/Commercial CASNO: Not reported
Tank Status: In Service Tank ID: 7AG
Total Tanks: 1 Daily Throughput 83000 Gal(s)
Tank Location: ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE
Install Date: 12/88 Capacity (Gal): Not reported
Tank Type: Steel/carbon steel
Tank External: PAINTED/ASPHALT COATING/NONE
Product: NOS 1,2, OR 4 FUEL OIL Tank Internal: NONE
Pipe Location: Aboveground Pipe Type: STEEL/IRON
Pipe Internal: NONE Dispenser: Suction
Pipe External: PAINTED/ASPHALT COATING/NONE
Second Contain: PREFABRICATED STEEL DIKE
Leak Detection: GROUNDWATER WELL/CONCRETE PAD WITH CHANNELS
Overfill Protection: High Level Alarm, Product Level Gauge
Test Date: Not reported Date Closed: Not reported
Dispensing Mthd: Suction
SWIS Code: 28 Facility Town: OYSTER BAY
Mailing Name: TBG COGEN PARTNERS
939 S BROADWAY
NY 11801
Mailing Contact: ANTHONY E. LIGATO
Mailing Phone: (516) 349-8340
Legal Agent: TBG COGEN PARTNERS
939 S BROADWAY
HICKSVILLE, NY 11801
Date Legal Agent Filed with Secretary of State: Not reported
Name of Emergency Contact: ANTHONY E. LIGATO
Emergency Contact Telephone: (516) 349-8340
Chemical Bulk Storage Number: 1-000129
Pollution Discharge Elimination System Num: -
License Status: License Issued
Date License Application Received: 01/04/1993
Date License Issued: 04/14/1993
Date License Expires or Expired: 03/31/1998
Product Transfer Operation: Tank Truck

173

NY Spills

S102236920
N/A

HICKSVILLE, NY

Exemption 6

SPILLS:

Facility ID:	9514662	Region of Spill:	1
Facility Contact:		Facility Tele:	
Investigator:	NONE	Spill Type:	UST
Caller Name:		Caller Agency:	Not reported
Caller Phone:		Caller Extension:	Not reported
Notifier Name:		Notifier Agency:	Not reported
Notifier Phone:		Notifier Extension:	Not reported
Spiller Contact:		Spiller Phone:	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236920

Exemption 6

Spiller:
Address

HICKSVILLE, NY 11801-

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)

Spill Closed Dt: 02/16/1996

Material Class:

Petroleum

Spilled Code: 0001

Quantity Spilled: 1 gallons

Quant Recovered: 1 gallons

Spill Cause: Equipment Failure

Resource Affected: On Land

Water Affected: Not reported

Spill Source: Private Dwelling

Spill Notifier: Responsible Party

PBS Number: Not reported

Spill Date: 02/15/1996 17:00

Reported to Dept: 02/15/1996 17:40

Tank Number: Not reported

Tank Capacity: 0 Gallons

Test method: Not reported

Leak Rate: 0.00

Gross Leak/Fail: Not reported

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 02/21/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 02/15/1996

174

PHOTO WORKS
25 BLUMINGDALE RD
HICKSVILLE, NY 11801

FINDS

1000415373

RCRIS-LQG

NYD981488240

RCRIS:

Owner: MORRIS NESSIN
(212) 555-1212

Contact: MORRIS NESSIN
(516) 933-6110

Classification: Large Quantity Generator

Waste	Quantity
D000	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

175

C & D TYPE SETTERS INC
960 S BROADWAY
HICKSVILLE, NY 11801

FINDS

1000110027

RCRIS-LQG

NYD982186983

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

C & D TYPE SETTERS INC (Continued)

1000110027

RCRIS:

Owner: CHARLES SARGENT
(212) 555-1212

Contact: CHARLES SARGENT
(516) 822-8514

Classification: Large Quantity Generator

Waste Quantity
D000 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

176

PETER'S FRENCH CLEANERS
422 JERUSALEM AVE
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000212002
NYD980789622

RCRIS:

Owner: JARMIN CORP
(212) 555-1212

Contact: JARMIN YEN
(516) 931-0220

Classification: Small Quantity Generator

Waste Quantity
F002 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

177

HICKSVILLE, NY

NY Spills

S102137989
N/A

SPILLS:

Facility ID: 8906100
Facility Contact: Not reported
Investigator: NCFM
Caller Name: INSPECTOR TUSA
Caller Phone: (516) 521-3751
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller:
Address:

HICKSVILLE, NY
Spill Class: Not reported
Spill Closed Dt: 09/20/1989
Material Class: Petroleum
Quantity Spilled: 5 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0009
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Passenger Vehicle

Exemption 6

MAP FINDINGS

map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102137989

Spill Notifier:	Fire Department	PBS Number:	Not reported
Spill Date:	09/20/1989 17:40	Reported to Dept:	09/20/1989 18:50
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/20/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/22/1989		

177

YALE RADIATOR & AUTO REPAIR
37 BLOOMINGDALE RD
HICKSVILLE, NY 11801

RCRIS-SQG 1000198265
FINDS NYD168346880
NY Spills

Used Oil Recyc: No
Violation Status: No violations found

178

AVIS CAR RENTAL
980 SOUTH BROADWAY
BETHPAGE, NY

LUST S100147547
N/A

LUST:

Facility ID:	8809010	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NCFM	Spill Type:	Facility
Caller Name:	SUPERVISOR CHARLES PARKER	Caller Agency:	NC FIRE COMM
Caller Phone:	(516) 742-3191	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 933-7727
Spiller:	AVIS CAR RENTAL		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	02/21/1989	Spill Source:	Passenger Vehicle
Spill Cause:	Tank Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	02/19/1989 15:15
Spill Notifier:	Fire Department		
Spill Date:	02/19/1989 14:03		
Cleanup Ceased:	02/21/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

AVIS CAR RENTAL (Continued)

S100147547

Date Spill Entered In Computer Data File: 02/21/1989

179

BETHPAGE, NY

LUST

S100492507
N/A

LUST:

Facility ID:	9213083	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORDS
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	02/24/1993		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	02/23/1993 12:15	Reported to Dept:	02/23/1993 14:24
Cleanup Ceased:	02/24/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/24/1993		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/24/1993		

Exemption 6

180

BETHPAGE, NY

NY Spills

S102096589
N/A

SPILLS:

Facility ID:	9000289	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	HAAS	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORD ENERGY
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	BETHPAGE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	04/17/1990	Spilled Code:	0001
Material Class:	Petroleum		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102096589

Quantity Spilled: 4 gallons	Quant Recovered: 0 gallons
Spill Cause: Equipment Failure	Resource Affected: On Land
Water Affected: Not reported	Spill Source: Private Dwelling
Spill Notifier: Other	PBS Number: Not reported
Spill Date: 04/09/1990 07:00	Reported to Dept: 04/09/1990 11:35
Tank Number: Not reported	Tank Capacity: 0 Gallons
Test method: Not reported	Leak Rate: 0.00
Gross Leak/Fail: Not reported	
Cleanup Ceased: 04/17/1990	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 04/23/1990	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 04/10/1990	

180

CONTRACTOR (SHELL ONLY)
173 NORTH 6TH ST
BETHPAGE, NY

NY Spills

S102098778
N/A

SPILLS:

Facility ID: 9311282	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: PARISH	Spill Type: Facility
Caller Name: GIOSEPINA DEIORIO	Caller Agency: RESIDENCE-DAUGHTER
Caller Phone: (516) 681-9375	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: CONTRACTOR (SHELL ONLY)	
Address: Not reported	
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: 02/23/1995	Spilled Code: 0001
Material Class: Petroleum	Quant Recovered: 0 gallons
Quantity Spilled: 46 gallons	Resource Affected: On Land
Spill Cause: Human Error	Spill Source: Tank Truck
Water Affected: Not reported	PBS Number: Not reported
Spill Notifier: Affected Persons	Reported to Dept: 12/17/1993 14:38
Spill Date: 12/17/1993 13:30	Tank Capacity: 0 Gallons
Tank Number: Not reported	Leak Rate: 0.00
Test method: Not reported	
Gross Leak/Fail: Not reported	
Cleanup Ceased: 02/23/1995	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 02/27/1995	
Corrective Action Plan Submitted: Not reported	

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONTRACTOR (SHELL ONLY) (Continued)

S102098778

Date Spill Entered In Computer Data File: 12/20/1993

181

**MINUTE MAN CLEANERS
425 JERUSALEM AVE
HICKSVILLE, NY 11801**

**FINDS
RCRIS-LQG**

**1000428628
NYD980778005**

RCRIS:

Owner: Not reported

Contact: KIM BUMYONG
(516) 931-8548

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D002	0.000 (N)	NONE	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

182

**TEXACO USA A DIVISION OF TEXACO INC
1000 S BROADWAY
HICKSVILLE, NY 11801**

**FINDS
RCRIS-LQG**

**1000144460
NYD000694448**

RCRIS:

Owner: TEXACO USA
(609) 667-3800

Contact: H E PHILLIPS
(609) 667-3800

Classification: Large Quantity Generator, Hazardous Waste Transporter

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)
D001	3.265 (M)	D002	0.000 (N)
D008	0.000 (N)	D008	0.001 (P)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

183

**[REDACTED]
HICKSVILLE, NY**

LUST

**S102234301
N/A**

LUST:

Exemption 6

Facility ID: 9515615

Facility Contact: [REDACTED]

Investigator: Not reported

Caller Name: [REDACTED]

Caller Phone: [REDACTED]

Notifier Name: [REDACTED]

Notifier Phone: [REDACTED]

Spiller Contact: [REDACTED]

Region of Spill: 1

Facility Tele: [REDACTED]

Spill Type: UST

Caller Agency: RELIANCE OIL

Caller Extension: Not reported

Notifier Agency: RELIANCE OIL

Notifier Extension: Not reported

Spiller Phone: [REDACTED]

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102234301

Exemption 6

Spiller:	RELIANCE OIL	
Address:	Not reported	
	Not reported	
Spill Class:	Not reported	
Spill Closed Dt:	Not reported	
Spill Cause:	Tank Overfill	Resource Affected: On Land
Water Affected:	Not reported	Spill Source: Private Dwelling
Spill Notifier:	Responsible Party	PBS Number: Not reported
Spill Date:	03/05/1996 14:15	Reported to Dept: 03/05/1996 14:43
Cleanup Ceased:	Not reported	
Last Inspection:	Not reported	
Cleanup Meets Standard:	False	
Recommended Penalty:	No Penalty	
Spiller Cleanup Date:	Not reported	
Enforcement Date:	Not reported	
Investigation Complete:	Not reported	
UST Involvement:	False	
Spill Record Last Update:	03/05/1996	
Corrective Action Plan Submitted:	Not reported	
Date Spill Entered In Computer Data File:	03/05/1996	

183

NY Spills

S102139172
N/A

HICKSVILLE, NY

SPILLS:

Facility ID:	9308969	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	MILRO
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/26/1993		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	15 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	10/15/1993 14:00	Reported to Dept:	10/25/1993 09:49
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	10/26/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	10/27/1993		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102139172

Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/25/1993

184

NY Spills

S102089765
N/A

BETHPAGE, NY

SPILLS:

Facility ID: 9101415
Facility Contact: Not reported
Investigator: KISPERT
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address:

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NASS CTY FIRE MARSHALL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY 11714

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)

Spill Closed Dt: 07/08/1994
Material Class: Petroleum
Quantity Spilled: 20 gallons
Spill Cause: Traffic Accident
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 05/04/1991 01:20
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 05/04/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/12/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/06/1991

Spilled Code: 0009
Quant Recovered: 20 gallons
Resource Affected: On Land
Spill Source: Commercial Vehicle
PBS Number: Not reported
Reported to Dept: 05/04/1991 02:06
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

185

RELIANCE
167 9TH STREET
BETHPAGE, NY

NY Spills

S102102389
N/A

SPILLS:

Facility ID: 9507289
Facility Contact: Not reported
Investigator: NONE
Caller Name: BERNARD DEPACE
Caller Phone: (516) 822-2491
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RESIDENCE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RELIANCE (Continued)

S102102389

Spiller: RELIANCE
Address: Not reported
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 09/14/1995
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 09/14/1995 10:20
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 09/14/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/15/1995
Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 09/14/1995 10:28
Tank Capacity: 0 Gallons
Leak Rate: 0.00

186

NY Spills

S102236138
N/A

BETHPAGE, NY

SPILLS:

Facility ID: 9510371
Facility Contact: [REDACTED]
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: SERVICE TECH
Notifier Phone: Not reported
Spiller Contact: [REDACTED]
Spiller: [REDACTED]
Address: BETHPAGE
Region of Spill: 1
Facility Tele: [REDACTED]
Spill Type: UST
Caller Agency: GIFFORDS OIL CO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
Spill Closed Dt: 11/17/1995
Material Class: Petroleum
Quantity Spilled: Unknown gallons
Spill Cause: Unknown
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 11/17/1995 13:45
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 11/17/1995
Last Inspection: Not reported
Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 11/17/1995 14:48
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236138

Exemption 6

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/20/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/17/1995

187

NY Spills

S102092047
N/A

BETHPAGE, NY

SPILLS:

Facility ID:	9201916	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LUCE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	CITIZEN
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/24/1992		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	7 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	05/15/1992 19:30	Reported to Dept:	05/15/1992 20:32
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	06/24/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/10/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/19/1992		

188

UNK CONTRACTOR
MEADE AVE/1ST / 2ND ST
BETHPAGE, NY

NY Spills

S102099275
N/A

SPILLS:

Facility ID:	9400148	Region of Spill:	1
--------------	---------	------------------	---

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNK CONTRACTOR (Continued)

S102099275

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GIBBONS	Spill Type:	Facility
Caller Name:	RICHARD RALSTON	Caller Agency:	HOMEOWNER
Caller Phone:	(516) 935-1380	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK CONTRACTOR		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	05/25/1995		
Material Class:	Petroleum	Spilled Code:	0066
Quantity Spilled:	10 gallons	Quant Recovered:	0 gallons
Spill Cause:	Housekeeping	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Citizen	PBS Number:	Not reported
Spill Date:	04/04/1994 15:00	Reported to Dept:	04/05/1994 08:30
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/25/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	05/30/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/05/1994		

189

CONTINENTAL COLLISION
77B BLOOMINGDALE RD
HICKSVILLE, NY 11801

RCRIS-SQG 1000412461
FINDS NYD982541856

RCRIS:

Owner: JOHN FONT
(212) 555-1212

Contact: STEVEN LANDER
(516) 681-7997

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	F003	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CONTINENTAL COLLISION (Continued)

1000412461

Used Oil Recyc: No

Violation Status: No violations found

189

**SEALIT
75 BLOOMINGDALE ROAD
BETHPAGE, NY**

LUST

**S100664457
N/A**

LUST:

Facility ID: 9113120

Facility Contact: Not reported

Investigator: DEROSA

Caller Name: BOB BUESMAN

Caller Phone: (516) 521-2046

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Spiller: SEALIT

Address: Not reported

Not reported

Spill Class: Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 01/14/1993

Spill Cause: Other

Water Affected: Not reported

Spill Notifier: Fire Department

Spill Date: 03/26/1992 12:00

Cleanup Ceased: 01/14/1993

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 01/15/1993

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 03/31/1992

Region of Spill: 1

Facility Tele: Not reported

Spill Type: Facility

Caller Agency: NCFM

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone: Not reported

Resource Affected: On Land

Spill Source: Other Commercial/Industrial

PBS Number: Not reported

Reported to Dept: 03/26/1992 12:00

189

**SEAL IT INC
75 BLOOMINGDALE RD
HICKSVILLE, NY 11801**

RCRIS-SQG

**1001079826
NYR000015339**

RCRIS:

Owner: 69 BLOOMINGDALE - 120 ANDREWS ASSOC LP
(516) 935-1100

Contact: ALFRED BRANCACIO
(516) 935-3965

Classification: Small Quantity Generator

Waste	Quantity
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SEAL IT INC (Continued)

1001079826

Used Oil Recyc: No

Violation Status: No violations found

190

UNK
218 LEE AVE
HICKSVILLE, NY

NY Spills

S102136832
N/A

SPILLS:

Facility ID: 8602343
Facility Contact: Not reported
Investigator: Raymond
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: UNK
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 07/10/1986
Material Class: Hazardous Material
Quantity Spilled: 0 liters
Spill Cause: Abandoned Drums
Water Affected: Not reported
Spill Notifier: Police Department
Spill Date: 07/09/1986 13:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 07/09/1986
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/10/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/17/1986

Spilled Code: 0051
Quant Recovered: 0 liters
Resource Affected: Surface Water
Spill Source: Unknown
PBS Number: Not reported
Reported to Dept: 07/09/1986 13:31
Tank Capacity: 0 Gallons
Leak Rate: 0.00

191

BRADCO SUPPLY CORP.
85 BLOOMINGDALE RD.
HICKSVILLE, NY

AST
UST

U001446670
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BRADCO SUPPLY CORP. (Continued)

U001446670

Nassau County UST:

Facility ID:	054058	Tank ID:	0002
Tank Location:	Indoors, Belowground	Capacity:	00004000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	1089
Total Tanks:	1		

Nassau County AST:

Facility ID:	054058	Tank ID:	0009
Tank Location:	Indoors, Aboveground	Capacity (Gal):	275
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Other		
Description:	OIL, FUEL #2	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	No
Dispense Method:	Suction	Install Date:	1255
Fill Type:	Pumped		
Total Tanks:	Not reported		

191

**BRACO SUPPLY CO
85 BLOOMINGDALE RD
HICKSVILLE, NY**

NY Spills

**S102139767
N/A**

SPILLS:

Facility ID:	9405569	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DEROSA	Spill Type:	Facility
Caller Name:	DOUG SCHRIMPF	Caller Agency:	DIRECT ENV
Caller Phone:	(516) 253-0900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(908) 382-3400
Spiller:	BRACO SUPPLY CO		
Address:	13 PRODUCTION WAY AVENEL, NJ		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	09/19/1994		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	07/11/1994 12:00	Reported to Dept:	07/25/1994 10:59
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/19/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BRACO SUPPLY CO (Continued)

S102139767

Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/20/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/26/1994

191

**BRADCO SUPPLY
85 BLOOMINGDALE ROAD
HICKSVILLE, NY**

LUST

**S102235090
N/A**

LUST:

Facility ID:	9602166	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	RKS	Spill Type:	UST
Caller Name:	KEN DRAKE	Caller Agency:	GROUNDWATER & ENV SERVICE
Caller Phone:	(908) 919-0100	Caller Extension:	Not reported
Notifier Name:	KEN DRAKE	Notifier Agency:	GROUNDWATER & ENV SERVICE
Notifier Phone:	(908) 919-0100	Notifier Extension:	Not reported
Spiller Contact:	MIKE WEINBERGER	Spiller Phone:	(908) 382-3400
Spiller:	BRADCO		
Address:	13 PRODUCTION WAY, BOX 67 AVENEL, NY 07001-0067		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/17/1996	Resource Affected:	On Land
Spill Cause:	Other	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	05/14/1996 16:15
Spill Date:	05/09/1996 12:00		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/18/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/15/1996		

192

**TWO GUYS AUTO REPAIR
HICKSVILLE RD. & BROADWAY
MASSAPEQUA, NY**

AST

**A100090598
N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TWO GUYS AUTO REPAIR (Continued)

A100090598

Nassau County AST:

Facility ID: 055462
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: WASTE OIL
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0002
Capacity (Gal): 250
Tank Material: STEEL

Material Type: Waste

Containment: NONE
Product Gauge: Yes
Install Date: 1089

Facility ID: 055462
Tank Location: Indoors, Aboveground
Tank Status: In Service
Int Protection: None
Ext Protection: NONE
Piping Type: Steel/Iron
Description: OIL, MOTOR
Leak Detect: NONE
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0003
Capacity (Gal): 275
Tank Material: STEEL

Material Type: Fresh/Product

Containment: NONE
Product Gauge: No
Install Date: 0686

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

192	GULF S/S BROADWAY / HICKSVILLE MASSAPEQUA, NY	LUST	S100665764 N/A
-----	--	-------------	---------------------------

LUST:

Facility ID:	8806379	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GOERTZ	Spill Type:	Facility
Caller Name:	K.GOERTZ	Caller Agency:	DEC
Caller Phone:	(516) 751-7900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GULF S/S		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Resource Affected:	Groundwater
Spill Closed Dt:	12/07/1988	Spill Source:	Gas Station
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	10/24/1988 12:00
Spill Notifier:	DEC		
Spill Date:	10/28/1988 12:00		
Cleanup Ceased:	12/07/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/08/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/01/1988		

193	NYNEX VEHICLE SHERMAN AVE/SO 6TH STREET BETHPAGE, NY	LUST	S101102415 N/A
-----	---	-------------	---------------------------

LUST:

Facility ID:	9314784	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GIBBONS	Spill Type:	Facility
Caller Name:	SISMITA BISARAK	Caller Agency:	NYNEX
Caller Phone:	(212) 338-7126	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NYNEX VEHICLE		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	03/18/1994	Resource Affected:	On Land
Spill Cause:	Tank Failure	Spill Source:	Commercial Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	03/17/1994 12:06
Spill Date:	03/17/1994 11:04		
Cleanup Ceased:	03/18/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NYNEX VEHICLE (Continued)

S101102415

Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/21/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/17/1994

194

BETHPAGE, NY

NY Spills

**S102099777
N/A**

Exemption 6

SPILLS:

Facility ID:	9404158	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LAMANNO	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	MILRO
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	10 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	06/16/1994 12:00	Reported to Dept:	06/24/1994 10:17
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/27/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/24/1994		

195

BETHPAGE, NY

NY Spills

**S102098223
N/A**

SPILLS:

Facility ID:	9305390	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102098223

Investigator: NONE
 Caller Name: [REDACTED]
 Caller Phone: [REDACTED]
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: [REDACTED]
 Address: [REDACTED]
 Spill Type: Facility
 Caller Agency: RELIANCE RITE
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: [REDACTED]
 Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
 Willing Responsible Party. Corrective action taken.
 Spill Closed Dt: 08/02/1993
 Material Class: Petroleum
 Quantity Spilled: 3 gallons
 Spill Cause: Equipment Failure
 Water Affected: Not reported
 Spill Notifier: Other
 Spill Date: 07/31/1993 14:30
 Tank Number: Not reported
 Test method: Not reported
 Gross Leak/Fail: Not reported
 Cleanup Ceased: 08/02/1993
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 08/10/1993
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 08/02/1993
 Spilled Code: 0001
 Quant Recovered: 0 gallons
 Resource Affected: On Land
 Spill Source: Private Dwelling
 PBS Number: Not reported
 Reported to Dept: 07/31/1993 14:31
 Tank Capacity: 0 Gallons
 Leak Rate: 0.00

Exemption 6

195

NY Spills

S102098231
N/A

BETHPAGE, NY

SPILLS:

Facility ID: 9305482
 Facility Contact: Not reported
 Investigator: NONE
 Caller Name: [REDACTED]
 Caller Phone: [REDACTED]
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: [REDACTED]
 Address: [REDACTED]
 Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: SON OF HOMEOWNER
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported
 Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
 Willing Responsible Party. Corrective action taken.
 Spill Closed Dt: 08/03/1993
 Material Class: Petroleum
 Quantity Spilled: 5 gallons
 Spill Cause: Equipment Failure
 Water Affected: Not reported
 Spill Notifier: Responsible Party
 Spill Date: 07/31/1993 10:00
 Spilled Code: 0001
 Quant Recovered: 0 gallons
 Resource Affected: On Land
 Spill Source: Private Dwelling
 PBS Number: Not reported
 Reported to Dept: 08/03/1993 11:55

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102098231

Exemption 6

Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 08/03/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/10/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/05/1993

196

NY Spills

S102136904
N/A

HICKSVILLE, NY

SPILLS:

Facility ID:	8603611	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	Not reported	Spill Type:	UST
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	HICKSVILLE, NY		
Spill Class:	Not reported	Spilled Code:	0001
Spill Closed Dt:	05/04/1987	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	0 gallons	Spill Source:	Private Dwelling
Spill Cause:	Equipment Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	09/02/1986 13:00
Spill Notifier:	Citizen	Tank Capacity:	0 Gallons
Spill Date:	09/02/1986	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/04/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/14/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/16/1986		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

197	JAMOCO HEATING & COOLING CORP 105 BLOOMINGDALE RD HICKSVILLE, NY 11801	RCRIS-SQG	1000990295 NYR000002543
-----	--	-----------	----------------------------

RCRIS:

Owner: JAMOCO HEATING & COOLING CORP
(516) 681-4400

Contact: ARMAND NUZZI
(516) 681-4400

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	D002	0.000 (N)
D003	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

197	JAMOCO HEATING & COOLING CORP 105 BLOOMINGDALE RD HICKSVILLE, NY 11801	FINDS	1001010741 NY0001173160
-----	--	-------	----------------------------

198	[REDACTED] BETHPAGE, NY	LUST	S101657999 N/A
-----	----------------------------	------	-------------------

LUST:

Facility ID: 9500753
Facility Contact: Not reported
Investigator: AUSTIN
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: SLOMINS OIL CO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY
Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 06/28/1995
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 04/19/1995 09:00
Cleanup Ceased: 06/28/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/30/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/20/1995

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 04/19/1995 09:30

Exemption 6

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
199	MEENAN 170 SCOOTER LN HICKSVILLE, NY SPILLS: Facility ID: 9408976 Facility Contact: Not reported Investigator: NONE Caller Name: FRANK DAMANTI Caller Phone: (516) 783-1000 Notifier Name: Not reported Notifier Phone: Not reported Spiller Contact: Not reported Spiller: MEENAN Address: Not reported Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken. Spill Closed Dt: 10/06/1994 Material Class: Petroleum Quantity Spilled: 1 gallons Spill Cause: Human Error Water Affected: Not reported Spill Notifier: Responsible Party Spill Date: 10/05/1994 14:35 Tank Number: Not reported Test method: Not reported Gross Leak/Fail: Not reported Cleanup Ceased: 10/06/1994 Last Inspection: Not reported Cleanup Meets Standard: True Recommended Penalty: No Penalty Spiller Cleanup Date: Not reported Enforcement Date: Not reported Investigation Complete: Not reported UST Involvement: False Spill Record Last Update: Not reported Corrective Action Plan Submitted: Not reported Date Spill Entered In Computer Data File: 10/06/1994	NY Spills	S102139954 N/A
200	CASCADE WATER SERVICE., INC 113 BLOOMINGDALE RD HICKSVILLE, NY 11801	FINDS	1000961763 NY0000640433
201	SUNOCO SVC STA 125 BLOOMINGDALE RD HICKSVILLE, NY 11801	FINDS RCRIS-LQG	1000328704 NYD000698746

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUNOCO SVC STA (Continued)

1000328704

RCRIS:

Owner: PIONEER GENERAL STORE INC
(212) 555-1212

Contact: GENERAL PIONEER
(212) 555-1212

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

202

BETHPAGE, NY

NY Spills

S102101060
N/A

SPILLS:

Facility ID: 9413253
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RESIDENCE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 01/05/1995
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 01/04/1995 16:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 01/05/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/06/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/05/1995

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 01/04/1995 17:04
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

203

BETHPAGE, NY

NY Spills

S102091944
N/A

SPILLS:

Facility ID:	9200728	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LUCE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	HOMEOWNER
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/27/1992		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	04/19/1992 20:00	Reported to Dept:	04/20/1992 10:14
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	04/27/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/10/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/22/1992		

Exemption 6

204

HICKSVILLE, NY

NY Spills

S102137514
N/A

SPILLS:

Facility ID:	8800742	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	HOFMANN	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	HOMEOWNER
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	[REDACTED]
Spiller:	[REDACTED]		
Address:	HICKSVILLE, NY 11801		
Spill Class:	Not reported		
Spill Closed Dt:	05/04/1988	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 UNITS NOT REPORTED
Quantity Spilled:	0 UNITS NOT REPORTED		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102137514

Exemption 6

Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Citizen
Spill Date: 04/22/1988 08:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 05/04/1988
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/04/1988
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/26/1988

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 04/25/1988 09:42
Tank Capacity: 0 Gallons
Leak Rate: 0.00

205

DYNAMIC PAINTING CORP
7 WILLIS CT
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000790409
NYD987018934

RCRIS:

Owner: OTNICAJ 7 REALTY CORP
(212) 555-1212

Contact: GLEN JACINTO
(516) 681-6696

Classification: Small Quantity Generator

Waste Quantity
D001 0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: Violations exist, high priority violator

There are 1 compliance/violation record(s) reported at this site:

Evaluation
Compliance Evaluation Inspection (CEI)

Area of Violation
Generator-All Requirements
Generator-All Requirements

Date of
Compliance
09/29/1993
09/29/1993

206

UNK
127 ENGINEERS DR
HICKSVILLE, NY

NY Spills

S102137156
N/A

SPILLS:

Facility ID: 8504134
Facility Contact: Not reported
Investigator: DOT
Caller Name: RICHARD MAGEE
Caller Phone: (516) 535-7939
Notifier Name: Not reported
Notifier Phone: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNK (Continued)

S102137156

Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	02/22/1988		
Material Class:	Petroleum	Spilled Code:	0066
Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Abandoned Drums	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Unknown
Spill Notifier:	Fire Department	PBS Number:	Not reported
Spill Date:	02/24/1986 12:00	Reported to Dept:	02/24/1986 12:00
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/22/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/08/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/18/1986		

206

RENAISSANCE DESIGN & BUILDING INC
91 ENGINEERS DR
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000871522
NY0000062687

RCRIS:

Owner: J DEALBUQUERQUE & D MAYER
(516) 932-8501

Contact: DIANA SHERRARD
(516) 932-8501

Classification: Conditionally Exempt Small Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	D035	0.000 (N)
F003	0.000 (N)	F005	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

206

SHOREWOOD PKG
55 ENGINEERS LN
FARMINGDALE, NY

NY Spills

S102138263
N/A

SPILLS:

Facility ID: 9000341
Facility Contact: Not reported
Investigator: ACAMPORA
Caller Name: STEVE MONTANO

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: SHOREWOOD PKG

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SHOREWOOD PKG (Continued)

S102138263

Caller Phone:	(516) 694-2900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SHOREWOOD PKG		
Address:	55 ENGINEERS LANE FARMINGDALE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	04/12/1990	Spilled Code:	Not reported
Material Class:	Not reported	Quant Recovered:	0 UNITS NOT REPORTED
Quantity Spilled:	0 UNITS NOT REPORTED	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	04/10/1990 16:13
Spill Date:	04/10/1990 15:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	04/12/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/13/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/12/1990		

207

NY Spills

S102098046
N/A

SPILLS:

Facility ID:	9303560	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPRT	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	NCFM
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/10/1994	Spilled Code:	0009
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	10 gallons	Resource Affected:	In Sewer
Spill Cause:	Traffic Accident	Spill Source:	Passenger Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Fire Department	Reported to Dept:	06/18/1993 10:15
Spill Date:	06/18/1993 07:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102098046

Gross Leak/Fail: Not reported
Cleanup Ceased: 06/10/1994
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/13/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/21/1993

207

AMERICAN LITHOTECH
631 HICKSVILLE RD
BETHPAGE, NY 11714

FINDS
RCRIS-LQG

1000358734
NYD981489453

RCRIS:

Owner: AMERICAN LITHOTECH INC
(212) 555-1212

Contact: DAVID LURIE
(516) 931-6300

Classification: Large Quantity Generator

Waste	Quantity
D000	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

208

MEENAN OIL
7 STORY LN
HICKSVILLE, NY

NY Spills

S102137398
N/A

SPILLS:

Facility ID: 8709639
Facility Contact: Not reported
Investigator: HOFMANN
Caller Name: FRANK ALLIVA
Caller Phone: (516) 783-1000
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: MEENAN OIL
Address: 30-20 BURNS AVENUE
WANTAGH, NY

Spill Class: Not reported
Spill Closed Dt: 02/16/1988
Material Class: Petroleum
Quantity Spilled: 20 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/15/1988 15:00

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MEENAN OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Tank Truck
PBS Number: Not reported
Reported to Dept: 02/15/1988 15:05

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MEENAN OIL (Continued)

S102137398

Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/16/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/22/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/16/1988		

209

BETHPAGE, NY

NY Spills

S102095820
N/A

SPILLS:

Facility ID:	8903263	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GOERTZ	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	CITIZEN
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	[REDACTED]		

BETHPAGE, NY

Spill Class:	Not reported	Spilled Code:	0022
Spill Closed Dt:	06/29/1989	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	0 gallons	Spill Source:	Private Dwelling
Spill Cause:	Deliberate	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	06/28/1989 09:15
Spill Notifier:	Citizen	Tank Capacity:	0 Gallons
Spill Date:	06/28/1989 09:15	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	06/29/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	07/03/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/03/1989		

Exemption 6

MAP FINDINGS

Map ID			EDR ID Number
Direction			EPA ID Number
Distance	Site	Database(s)	

**210 HICKSVILLE POST OFFICE
260 ENGINEERS DR
HICKSVILLE, NY 11802**

**FINDS 1000272871
RCRIS-LQG NY9180090020**

RCRIS:

Owner: Not reported
Contact: JOHN DOLAN
(516) 933-2343
Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Federal facility has submitted specific environmental project budget plans (under FFIS)

**211 BOCES NASSAU TECH BETHPAGE AV
610 HICKSVILLE RD
BETHPAGE, NY 11714**

**RCRIS-SQG 1000221239
FINDS NYD136581915**

RCRIS:

Owner: GRUMMAN BETHPAGE CENTER
(212) 555-1212
Contact: JOHN GOLDEN
(516) 576-9180

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
NONE	0.000 (N)	NONE	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

**212 TOWN OF O.B DPW
WISHING LA / BUNKER LA
HICKSVILLE, NY**

**NY Spills S102138532
N/A**

SPILLS:

Facility ID: 9007207
Facility Contact: Not reported
Investigator: LUCE
Caller Name: ROBERT HARE
Caller Phone: (516) 566-5274
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: TOWN OF O.B DPW
Address: 150 MILLER AVENUE
SYOSSET, NY
Spill Class: Not reported
Spill Closed Dt: 10/09/1990

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 921-7347

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TOWN OF O.B DPW (Continued)

S102138532

Material Class:	Petroleum	Spilled Code:	0022
Quantity Spilled:	12 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Fire Department	PBS Number:	Not reported
Spill Date:	10/01/1990 11:50	Reported to Dept:	10/01/1990 13:25
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	10/09/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	10/10/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/02/1990		

213

ERIKSEN AUTO OWNER
588 STEWART AVENUE
BETHPAGE, NY

LUST

S100665688
N/A

LUST:

Facility ID:	8808488	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NCFM	Spill Type:	Facility
Caller Name:	INSPECTOR MAGEE	Caller Agency:	NCFM
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 935-5383
Spiller:	ERIKSEN AUTO OWNER		
Address:	10 CARRIERE STREET BETHPAGE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	01/26/1989		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Passenger Vehicle
Spill Notifier:	Health Department	PBS Number:	Not reported
Spill Date:	01/25/1989 13:58	Reported to Dept:	01/25/1989 15:01
Cleanup Ceased:	01/26/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/22/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/26/1989		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

213

SON-LEW LAUNDRY CTR INC
596 STEWART AVE
BETHPAGE, NY 11714

RCRIS-SQG
FINDS

1000139057
NYD982538621

RCRIS:

Owner: SON LEW LAUNDRY CENTER INC
(212) 555-1212

Contact: BLANCHE STALTARE
(516) 931-9636

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

214

ABSOLUTE GRAPHICS INC
184 QUALITY PLAZA
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000334057
NYD982743304

RCRIS:

Owner: JOHN MORGAN
(212) 555-1212

Contact: JOHN MORGAN
(516) 939-0250

Classification: Not reported

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

214

ABSOLUTE PHOTO INC
184 QUALITY PLAZA
HICKSVILLE, NY 11801

RCRIS-LQG

1000334058
NYD982743965

RCRIS:

Owner: JOSPEH GIAMPAPA
(212) 555-1212

Contact: JOSEPH GIAMPAPA
(516) 822-5400

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ABSOLUTE PHOTO INC (Continued)

1000334058

Used Oil Recyc: No

Violation Status: No violations found

215

**RELIANCE
61 FRIENDLY RD
HICKSVILLE, NY**

NY Spills

S102138164
N/A

SPILLS:

Facility ID: 8910638
Facility Contact: Not reported
Investigator: Not reported
Caller Name: TONY AGNESE
Caller Phone: (516) 931-6800
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: RELIANCE
Address: 477 WEST JOHN STREET
HICKSVILLE, NY 11802

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE FUEL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 02/09/1990
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Human Error
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/07/1990 14:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 02/09/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/12/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/07/1990

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 02/07/1990 14:29
Tank Capacity: 0 Gallons
Leak Rate: 0.00

216

**J.C. PRECISION AUTOMOTIVE
590 HICKSVILLE RD
BETHPAGE, NY**

AST

A100090632
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

J.C. PRECISION AUTOMOTIVE (Continued)

A100090632

Nassau County AST:

Facility ID:	055570	Tank ID:	0002
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	275
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Unknown		
Ext Protection:	UNKNOWN		
Piping Type:	Other	Material Type:	Waste
Description:	WASTE OIL		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	1284
Total Tanks:	Not reported		

217

NY Spills

S102090049
N/A

BETHPAGE, NY

Exemption 6

SPILLS:

Facility ID:	9102971	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NCDH	Spill Type:	Facility
Caller Name:		Caller Agency:	NCDH
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:			
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	06/26/1991	Spilled Code:	0022
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	0 gallons	Resource Affected:	On Land
Spill Cause:	Deliberate	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Health Department	Reported to Dept:	06/14/1991 14:30
Spill Date:	06/11/1991 11:50	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	06/26/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/27/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	06/17/1991		

218

PHOENIX LABORATORIES INC
175 LAUMAN LANE
HICKSVILLE, NY 11801

RCRIS-SQG
FINDS

1000207954
NYD003998259

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PHOENIX LABORATORIES INC (Continued)

1000207954

Used Oil Recyc: No

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Facility is monitored or permitted for air emissions under the Clean Air Act (under AFS/AIRS)

218

**PROGRESSIVE CIRCUITS INC
180-R LAUMAN LN
HICKSVILLE, NY 11801**

RCRIS-SQG
FINDS

1000236610
NYD986891521

RCRIS:

Owner: ZT ZS CORP
(212) 555-1212

Contact: JYOTI MEHTA
(516) 938-4456

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D002	0.000 (N)	F006	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

219

BETHPAGE, NY

NY Spills

S102090404
N/A

SPILLS:

Facility ID: 9106756
Facility Contact: Not reported
Investigator: KISPRT
Caller Name: SCOTT TUSA
Caller Phone: (516) 566-5286
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: XXXXXXXXXX

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: XXXXXXXXXX

Address: Not reported
Not reported

Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 03/15/1993
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Local Agency
Spill Date: 09/23/1991 12:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 03/15/1993

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 09/23/1991 14:11
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102090404

Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/17/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/26/1991

220

MAYTELL CONSTRUCTION CO
146 LAUMAN LANE
BETHPAGE, NY

NY Spills

S102090899
N/A

SPILLS:

Facility ID:	9011076	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PARISH	Spill Type:	Facility
Caller Name:	JIM SIVIGLIA	Caller Agency:	NCFM
Caller Phone:	(516) 566-5274	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-5650
Spiller:	MAYTELL CONSTRUCTION CO		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	08/04/1992		
Material Class:	Petroleum	Spilled Code:	0009
Quantity Spilled:	2 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Citizen	PBS Number:	Not reported
Spill Date:	01/17/1991 16:23	Reported to Dept:	01/17/1991 17:34
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	08/04/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/07/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/22/1991		

221

SLOMINS INC
125 LAUMAN LANE
HICKSVILLE, NY 11801

FINDS
RCRIS-LQG
UST

1000300093
NYD012869145

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SLOMINS INC (Continued)

1000300093

Used Oil Recyc: No

Violation Status: No violations found

Nassau County UST:

Facility ID:	055883	Tank ID:	0005
Tank Location:	Indoors, Belowground	Capacity:	00001000
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Galvanized Steel	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	0685
Total Tanks:	2		

Facility ID:	055883	Tank ID:	0006
Tank Location:	Indoors, Belowground	Capacity:	00001000
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Galvanized Steel	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	0685
Total Tanks:	2		

221

SLOMINS OIL CO
125 LAUMAN LN
HICKSVILLE, NY

LUST

S100174751
N/A

LUST:

Facility ID: 9511641
Facility Contact: Not reported
Investigator: Not reported
Caller Name: CATHY A GIBBONS
Caller Phone: (516) 444-0336
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: Not reported
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: Not reported
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: DEC
Spill Date: 07/10/1995 14:47
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: NYSDEC
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 12/14/1995 16:30

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SLOMINS OIL CO (Continued)

S100174751

Spill Record Last Update: 12/14/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/14/1995

Facility ID: 9100704
Facility Contact: Not reported
Investigator: DEROSA
Caller Name: PHIL FAZIN
Caller Phone: (516) 939-2959
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: SLOMINS OIL CO
Address: 125 LAUMAN STREET
HICKSVILLE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CROWN LEAK DETECTION
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 03/02/1992
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 04/17/1991 16:30
Cleanup Ceased: 03/02/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/04/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/19/1991

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 04/17/1991 18:40

Facility ID: 8910541
Facility Contact: Not reported
Investigator: NONE
Caller Name: RALPH ESPOSITO
Caller Phone: (516) 932-7000
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: SLOMINS OIL
Address: 125 LAUMAN LANE
HICKSVILLE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: SLOMINS OIL CO
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 932-7000

Spill Class: Not reported
Spill Closed Dt: 02/05/1990
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/05/1990 07:00
Cleanup Ceased: 02/05/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported

Resource Affected: On Land
Spill Source: Tank Truck
PBS Number: Not reported
Reported to Dept: 02/05/1990 02:39

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

SLOMINS OIL CO (Continued)

S100174751

UST Involvement: False
 Spill Record Last Update: Not reported
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 02/06/1990

222

GRECO BROS. BULK TERMINAL LAUMAN LA & HICKSVILLE RD. HICKSVILLE, NY 11714

AST
UST

U003080092
N/A

MOSF UST:

Facility ID: 1-3100
 SWIS Code: 28
 Contact: MICHAEL N. GRECO, (516) 681-1515
 Owner: GRECO BROS. FUEL CORP.
 P.O. BOX 208 239 BROADWAY
 BETHPAGE, NY 11714-

Facility Status: ACTIVE FACILITY
 Facility Town: OYSTER BAY

Owner Tel: (516) 938-5200
 Mail To: GRECO BROS. FUEL CORP.
 P.O. BOX 208
 239 BROADWAY
 NY 11714-
 ATTN: MICHAEL N. GRECO
 (516) 681-1515

Owner Type: UNDEFINED

Legal Agent: NICHOLAS J. DAMADEO
 400 SOUTH OYSTER BAY RD.
 HICKSVILLE, NY 11801-

Date Filed: 01/79
 Emerg Contact: MICHAEL N. GRECO, (516) 681-1515
 SPDES Num: Not reported

CBS Number: Not reported

Avg Throughpt: 3000
 License Issued: 04/01/1994
 Facility Type: Storage Terminal

Total Tanks: 6
 License Stat: Issued
 Exp Date: 03/31/1999

Transfer Operation: Tank Truck
 Applic Rcvd: 01/04/1994
 Tank Location: UNDERGROUND

Tank ID: 002

Tank Status: In Service
 Install Date: 09/84

Capacity (Gal): 20000
 Tank Type: Fiberglass reinforced plastic [FRP]
 Tank Internal: FIBERGLASS LINER [FRP]

CAS No: Not reported
 Product: KEROSENE

Tank External: NONE
 Pipe Location: Underground
 Pipe Internal: NONE
 Pipe External: NONE

Pipe Type: STEEL/IRON
 Dispenser: Suction

Second Contain: EXCAVATION LINER

Leak Detection: NONE

Overfill Protection: None

Test Date: 10/86

Date Closed: Not reported

Database Type: Major Oil Storage

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRECO BROS. BULK TERMINAL (Continued)

U003080092

Facility ID:	1-3100	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	MICHAEL N. GRECO, (516) 681-1515		
Owner:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY BETHPAGE, NY 11714-		
Owner Tel:	(516) 938-5200	Owner Type:	UNDEFINED
Mail To:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY NY 11714- ATTN: MICHAEL N. GRECO (516) 681-1515		
Legal Agent:	NICHOLAS J. DAMADEO 400 SOUTH OYSTER BAY RD. HICKSVILLE, NY 11801-		
Date Filed:	01/79	CBS Number:	Not reported
Emerg Contact:	MICHAEL N. GRECO, (516) 681-1515	Total Tanks:	6
SPDES Num:	Not reported	License Stat:	Issued
Avg Throughpt:	3000	Exp Date:	03/31/1999
License Issued:	04/01/1994		
Facility Type:	Storage Terminal		
Transfer Operation:	Tank Truck		
Applic Rcvd:	01/04/1994	Tank ID:	003
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	1000
Install Date:	04/74	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	DIESEL		
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	None		
Test Date:	10/86	Date Closed:	00/00
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRECO BROS. BULK TERMINAL (Continued)

U003080092

Facility ID:	1-3100	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	MICHAEL N. GRECO, (516) 681-1515		
Owner:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY BETHPAGE, NY 11714- (516) 938-5200	Owner Type:	UNDEFINED
Owner Tel:	(516) 938-5200		
Mail To:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY NY 11714- ATTN: MICHAEL N. GRECO (516) 681-1515		
Legal Agent:	NICHOLAS J. DAMADEO 400 SOUTH OYSTER BAY RD. HICKSVILLE, NY 11801- 01/79	CBS Number:	Not reported
Date Filed:	01/79	Total Tanks:	6
Emerg Contact:	MICHAEL N. GRECO, (516) 681-1515	License Stat:	Issued
SPDES Num:	Not reported	Exp Date:	03/31/1999
Avg Throughpt:	3000		
License Issued:	04/01/1994	Tank ID:	004
Facility Type:	Storage Terminal	Capacity (Gal):	1000
Transfer Operation:	Tank Truck	Tank Type:	Steel/carbon steel
Applic Rcvd:	01/04/1994	Tank Internal:	NONE
Tank Location:	UNDERGROUND	Pipe Type:	STEEL/IRON
Tank Status:	Closed-Removed	Dispenser:	Suction
Install Date:	04/74		
CAS No:	Not reported		
Product:	DIESEL		
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	None		
Test Date:	10/86	Date Closed:	00/00
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRECO BROS. BULK TERMINAL (Continued)

U003080092

Facility ID:	1-3100	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	MICHAEL N. GRECO, (516) 681-1515		
Owner:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY BETHPAGE, NY 11714-		
Owner Tel:	(516) 938-5200	Owner Type:	UNDEFINED
Mail To:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY NY 11714-		
	ATTN: MICHAEL N. GRECO (516) 681-1515		
Legal Agent:	NICHOLAS J. DAMADEO 400 SOUTH OYSTER BAY RD. HICKSVILLE, NY 11801-		
Date Filed:	01/79	CBS Number:	Not reported
Emerg Contact:	MICHAEL N. GRECO, (516) 681-1515		
SPDES Num:	Not reported	Total Tanks:	6
Avg Throughpt:	3000	License Stat:	Issued
License Issued:	04/01/1994	Exp Date:	03/31/1999
Facility Type:	Storage Terminal		
Transfer Operation:	Tank Truck		
Applic Rcvd:	01/04/1994	Tank ID:	005
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	11/73	Capacity (Gal):	3000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	UNLEADED GASOLINE	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	None		
Test Date:	10/86	Date Closed:	00/00
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRECO BROS. BULK TERMINAL (Continued)

U003080092

Facility ID:	1-3100	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	MICHAEL N. GRECO, (516) 681-1515		
Owner:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY BETHPAGE, NY 11714-		
Owner Tel:	(516) 938-5200	Owner Type:	UNDEFINED
Mail To:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY NY 11714- ATTN: MICHAEL N. GRECO (516) 681-1515		
Legal Agent:	NICHOLAS J. DAMADEO 400 SOUTH OYSTER BAY RD. HICKSVILLE, NY 11801-		
Date Filed:	01/79	CBS Number:	Not reported
Emerg Contact:	MICHAEL N. GRECO, (516) 681-1515		
SPDES Num:	Not reported	Total Tanks:	6
Avg Throughpt:	3000	License Stat:	Issued
License Issued:	04/01/1994	Exp Date:	03/31/1999
Facility Type:	Storage Terminal		
Transfer Operation:	Tank Truck		
Applic Rcvd:	01/04/1994	Tank ID:	006
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	09/73	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	LEADED GASOLINE	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	None		
Test Date:	10/86	Date Closed:	00/00
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRECO BROS. BULK TERMINAL (Continued)

U003080092

Facility ID:	1-3100	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	MICHAEL N. GRECO, (516) 681-1515		
Owner:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY BETHPAGE, NY 11714-		
Owner Tel:	(516) 938-5200	Owner Type:	UNDEFINED
Mail To:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY NY 11714- ATTN: MICHAEL N. GRECO (516) 681-1515		
Legal Agent:	NICHOLAS J. DAMADEO 400 SOUTH OYSTER BAY RD. HICKSVILLE, NY 11801-		
Date Filed:	01/79	CBS Number:	Not reported
Emerg Contact:	MICHAEL N. GRECO, (516) 681-1515		
SPDES Num:	Not reported	Total Tanks:	6
Avg Throughpt:	3000	License Stat:	Issued
License Issued:	04/01/1994	Exp Date:	03/31/1999
Facility Type:	Storage Terminal		
Transfer Operation:	Tank Truck		
Applic Rcvd:	01/04/1994	Tank ID:	007
Tank Location:	UNDERGROUND		
Tank Status:	In Service	Capacity (Gal):	1000
Install Date:	05/82	Tank Type:	Fiberglass coated steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	KEROSENE		
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	None		
Test Date:	10/86	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRECO BROS. BULK TERMINAL (Continued)

U003080092

MOSF AST:

Facility ID:	1-3100	Telephone:	(516) 681-1515
Facility Type:	Storage Terminal	Facility Contact:	MICHAEL N. GRECO
Facility Status:	ACTIVE FACILITY		
Owner:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY BETHPAGE, NY 11714		
Owner Tel:	(516) 938-5200		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	001
Total Tanks:	1	Daily Throughput	3000 Gal(s)
Tank Location:	ABOVEGROUND	Capacity (Gal):	Not reported
Install Date:	10/55		
Tank Type:	Steel/carbon steel		
Tank External:	SACRIFICIAL ANODE	Tank Internal:	EPOXY LINER
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Pipe Location:	Above/Underground Combination	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	CONCRETE DIKE/IMPERVIOUS UNDERLAYMENT		
Leak Detection:	GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	10/86	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRECO BROS. FUEL CORP. P.O. BOX 208 239 BROADWAY NY 11714		
Mailing Contact:	MICHAEL N. GRECO		
Mailing Phone:	(516) 681-1515		
Legal Agent:	NICHOLAS J. DAMADEO 400 SOUTH OYSTER BAY RD. HICKSVILLE, NY 11801		
Date Legal Agent Filed with Secretary of State:	01/79		
Name of Emergency Contact:	MICHAEL N. GRECO		
Emergency Contact Telephone:	(516) 681-1515		
Chemical Bulk Storage Number:	Not reported		
Pollution Discharge Elimination System Num:	Not reported		
License Status:	License Issued		
Date License Application Received:	01/04/1994		
Date License Issued:	04/01/1994		
Date License Expires or Expired:	03/31/1999		
Product Transfer Operation:	Tank Truck		

223

BETHPAGE PUBLIC LIBRARY
47 POWELL AVE
BETHPAGE, NY

LUST

S100492543
N/A

LUST:

Facility ID:	9213367	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	PAT VOLINO	Caller Agency:	VOLINO & SONS
Caller Phone:	(516) 334-0414	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-3907

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

BETHPAGE PUBLIC LIBRARY (Continued)

S100492543

Spiller:	BETHPAGE PUBLIC LIBRARY		
Address	47 POWELL AVE BETHPAGE, NY		
Spill Class:	No spill occurred. (Not Possible)		
Spill Closed Dt:	08/11/1993		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	03/03/1993 16:30	Reported to Dept:	03/04/1993 07:48
Cleanup Ceased:	08/11/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/12/1993		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/04/1993		

223

**BETHPAGE PUBLIC LIBRARY
POWELL AVENUE
BETHPAGE, NY**

LUST

**S100149020
N/A**

LUST:

Facility ID:	8704151	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	O'NEILL	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-2900
Spiller:	BETHPAGE PUBLIC LIBRARY		
Address	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	10/03/1988		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	08/19/1987 13:30	Reported to Dept:	08/19/1987 13:45
Cleanup Ceased:	10/03/1988		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	10/04/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/25/1987		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

224

LEVITTOWN, NY

LUST

S100666386
N/A

LUST:

Facility ID: 9001335
Facility Contact: Not reported
Investigator: LEUNG
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCDH
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

LEVITTOWN, NY
Spill Class: Not reported
Spill Closed Dt: 05/09/1990
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Health Department
Spill Date: 05/03/1990 12:00
Cleanup Ceased: 05/09/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/11/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/07/1990

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 05/04/1990 10:00

Exemption 6

225

LEVITTOWN, NY

NY Spills

S102096778
N/A

SPILLS:

Facility ID: 9002585
Facility Contact: Not reported
Investigator: LEUNG
Caller Name: [REDACTED]
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 06/07/1990
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Health Department
Spill Date: 05/30/1990 14:30
Tank Number: Not reported
Test method: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCDH
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: Groundwater
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 06/06/1990 13:30
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102096778

Exemption 6

Gross Leak/Fail: Not reported
Cleanup Ceased: 06/07/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/08/1990

226

BETHPAGE BEST CLEANERS
360 BROADWAY
BETHPAGE, NY 11714

RCRIS-SQG
FINDS

1000243983
NYD981086085

RCRIS:

Owner: YOO HANG JEON
(516) 935-3333

Contact: YOO HANG JEON
(516) 935-3333

Classification: Small Quantity Generator

Waste	Quantity
F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

227

LEVITTOWN, NY

LUST

S100666405
N/A

LUST:

Facility ID: 9002339
Facility Contact: Not reported
Investigator: LEUNG
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]

Address: Not reported
Not reported

Spill Class: Not reported
Spill Closed Dt: 06/13/1990
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Health Department
Spill Date: 05/30/1990 13:00
Cleanup Ceased: 06/13/1990
Last Inspection: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCDH
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: Groundwater
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 05/30/1990 13:00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100666405

Exemption 6

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/18/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/01/1990

228

BETHPAGE SERVICE STATION
515 STEWART AVE.
BETHPAGE, NY

UST

U001855327
N/A

Nassau County UST:

Facility ID:	056695	Tank ID:	0004
Tank Location:	Indoors, Belowground	Capacity:	00001000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Galvanized Steel	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0281
Total Tanks:	2		

Facility ID:	056695	Tank ID:	0005
Tank Location:	Indoors, Belowground	Capacity:	00000500
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Galvanized Steel	Material Type:	Waste
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	WASTE OIL		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Gravity	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0281
Total Tanks:	2		

229

LEVITTOWN, NY

NY Spills

S102099893
N/A

SPILLS:

Facility ID:	9404988	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	MATTHEWS DRO	Spill Type:	Facility
Caller Name:		Caller Agency:	MEENAN
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102099893

Exemption 6

Spill Closed Dt: 08/02/1995
Material Class: Petroleum
Quantity Spilled: 5 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 07/12/1994 09:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 08/02/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/04/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/12/1994

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 07/12/1994 09:30
Tank Capacity: 0 Gallons
Leak Rate: 0.00

230

LEVITTOWN, NY

LUST

S102448445
N/A

231

GRUMMAN CORP
SO OYSTER BAY ROAD
BETHPAGE, NY

NY Spills

S102096610
N/A

SPILLS:

Facility ID: 9000535
Facility Contact: Not reported
Investigator: MANCILLA
Caller Name: JOHN OHLMANN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN CORP
Address: Not reported
BETHPAGE, NY 11714

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 04/20/1990
Material Class: Petroleum
Quantity Spilled: 15 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/17/1990 07:20
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 04/20/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty

Spilled Code: 0008
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 04/17/1990 08:15
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN CORP (Continued)

S102096610

Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/02/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/20/1990

231

GRUMMAN
PLANT 20 GRUMMAN
BETHPAGE, NY

NY Spills

S102099261
N/A

SPILLS:

Facility ID: 9315562
Facility Contact: Not reported
Investigator: KISPRT
Caller Name: JOHN SELVA
Caller Phone: (516) 575-8176
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 07/11/1994

Material Class: Petroleum

Quantity Spilled: 11 gallons

Spill Cause: Human Error

Water Affected: Not reported

Spill Notifier: Responsible Party

Spill Date: 03/31/1994 14:45

Tank Number: Not reported

Test method: Not reported

Gross Leak/Fail: Not reported

Cleanup Ceased: 07/11/1994

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 07/12/1994

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 04/01/1994

Spilled Code: 0009

Quant Recovered: 0 gallons

Resource Affected: On Land

Spill Source: Other Commercial/Industrial

PBS Number: Not reported

Reported to Dept: 03/31/1994 15:10

Tank Capacity: 0 Gallons

Leak Rate: 0.00

231

GRUMMAN AEROSPACE
GRUMMAN JET FUEL DEPOT
BETHPAGE, NY

NY Spills

S102400868
N/A

SPILLS:

Facility ID: 8402665
Facility Contact: Not reported
Investigator: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S102400868

Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AEROSPACE		
Address:	GRUMMAN JET FUEL DEPOT BETHPAGE		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0011
Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Not reported	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Not reported
Spill Notifier:	Not reported	PBS Number:	Not reported
Spill Date:	12/17/1984 12:00	Reported to Dept:	Not reported
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/13/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	Not reported		

231

GRUMMAN AEROSPACE CORP STEWART AVENUE BETHPAGE, NY

NY Spills

S102237431
N/A

SPILLS:

Facility ID:	9600467	Region of Spill:	1
Facility Contact:	WILLIAM DOLHANCEY	Facility Tele:	(516) 576-8895
Investigator:	DECANDIA	Spill Type:	UST
Caller Name:	WILLIAM DOLHANCEY	Caller Agency:	FOSTER WHEELER ENVIR
Caller Phone:	(516) 576-8895	Caller Extension:	Not reported
Notifier Name:	DEAN R MURPHY	Notifier Agency:	WILLS TRUCKING
Notifier Phone:	(800) 800-6237	Notifier Extension:	Not reported
Spiller Contact:	GERRY SELFDRGE	Spiller Phone:	(800) 800-6237
Spiller:	WILLS TRUCKING		
Address:	PO BOX 5280 CLINTO, NJ 08809-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0008
Quantity Spilled:	5 gallons	Quant Recovered:	Unknown gallons
Spill Cause:	Traffic Accident	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Local Agency	PBS Number:	Not reported
Spill Date:	04/10/1996 10:15	Reported to Dept:	04/10/1996 14:17
Tank Number:	Not reported	Tank Capacity:	0 Gallons

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP (Continued)

S102237431

Test method: Not reported Leak Rate: 0.00
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 04/11/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/10/1996

231

GRUMMAN AEROSPACE
PLANT #14
BETHPAGE, NY

NY Spills

S102092009
N/A

SPILLS:

Facility ID: 9201433	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: KISPERT	Spill Type: Facility
Caller Name: JOHN OHLMANN	Caller Agency: GRUMMAN AERO
Caller Phone: (516) 575-2385	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: GRUMMAN AEROSPACE	
Address: Not reported	
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: 05/15/1992	Spilled Code: 0022
Material Class: Petroleum	Quant Recovered: 0 gallons
Quantity Spilled: 5 gallons	Resource Affected: In Sewer
Spill Cause: Equipment Failure	Spill Source: Other Commercial/Industrial
Water Affected: Not reported	PBS Number: Not reported
Spill Notifier: Responsible Party	Reported to Dept: 05/05/1992 15:05
Spill Date: 05/05/1992 14:30	Tank Capacity: 0 Gallons
Tank Number: Not reported	Leak Rate: 0.00
Test method: Not reported	
Gross Leak/Fail: Not reported	
Cleanup Ceased: 05/15/1992	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 11/10/1992	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 05/07/1992	

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

231	GRUMMAN AERO LOADING DOCK AT PLANT 30 BETHPAGE, NY	NY Spills	S102098347 N/A
-----	---	-----------	-------------------

SPILLS:

Facility ID:	9306814	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMPBELL	Spill Type:	Facility
Caller Name:	JOHN SELVA	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AERO		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/21/1993		
Material Class:	Petroleum	Spilled Code:	0008
Quantity Spilled:	15 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	09/01/1993 21:00	Reported to Dept:	09/03/1993 09:00
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/21/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/22/1993		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/03/1993		

231	GRUMMAN BETHPAGE PLANT #3 SO. OYSTER BAY ROAD BETHPAGE, NY	NY Spills	S102094094 N/A
-----	---	-----------	-------------------

SPILLS:

Facility ID:	8700037	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	O'BRIEN	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-2029
Spiller:	GRUMMAN BETHPAGE PLANT #3		
Address:	SOUTH OYSTER BAY ROAD BETHPAGE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	04/07/1987	Spilled Code:	0039
Material Class:	Nonpetroleum/Nonhazardous	Quant Recovered:	0 gallons
Quantity Spilled:	10 gallons		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN BETHPAGE PLANT #3 (Continued)

S102094094

Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 04/02/1987 04:15
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 04/07/1987
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/16/1987
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/06/1987

Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 04/02/1987 06:26
Tank Capacity: 0 Gallons
Leak Rate: 0.00

231

100 WEST 15 ST
100 WEST 15 ST
NY, NY 10011

AST

A100074358
N/A

PBS AST:

Facility ID: 2-248142
Facility Status: Active
Owner: 100 W15 ST OWNERS CORP % E.C. MANAGEMENT
100 WEST 15TH STREET
NY, NY 10011
(212) 255-6464

Telephone: (212) 255-6464
Total Ast's: 1

Tank ID: 001
Tank Status: In Service
Tank Location: ABOVEGROUND
Product Stored: NOS 1,2, OR 4 FUEL OIL
Install Date: Not reported
Tank External: Not reported
Tank Containment: VAULT
Pipe Location: Underground
Pipe Internal: Not reported
Pipe External: Not reported
Leak Detection: NONE
Overfill Prot: Product Level Gauge
Date Tested: Not reported
Date Closed: Not reported
Region: 2

Capacity (Gal): 1500

Tank Type: Steel/carbon steel
Tank Internal: Not reported

Pipe Type: STEEL/IRON

Dispenser: Suction
Next Test Date: N.T.R
Test Method: Not reported

231

NORTHROP GRUMMAN
SO OYSTER BAY ROAD
BETHPAGE, NY

LUST

S101340215
N/A

LUST:

Facility ID: 9413982
Facility Contact: Not reported
Investigator: MATTHEWS
Caller Name: BRIAN MATTHEWS
Caller Phone: (516) 444-0331
Notifier Name: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: DEC
Caller Extension: Not reported
Notifier Agency: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NORTHROP GRUMMAN (Continued)

S101340215

Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	NORTHROP GRUMMAN		
Address	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Major Facility 400,000 gallons
Spill Notifier:	DEC	PBS Number:	Not reported
Spill Date:	01/18/1995 09:00	Reported to Dept:	01/18/1995 09:00
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/23/1995		

MAP FINDINGS

Map ID	Direction	Distance	Site	Database(s)	EDR ID Number	EPA ID Number
--------	-----------	----------	------	-------------	---------------	---------------

231			GRUMMAN AEROSPACE CORPORA NEW SOUTH ROAD BETHPAGE, NY	LUST	S102232574	N/A
-----	--	--	--	------	------------	-----

LUST:

Facility ID:	9511211	Region of Spill:	1
Facility Contact:	RON PATOC	Facility Tele:	(516) 575-7833
Investigator:	RBC	Spill Type:	UST
Caller Name:	STEVE BRANCIFORTE	Caller Agency:	NDE ENVIRONMENTAL
Caller Phone:	(800) 964-7311	Caller Extension:	Not reported
Notifier Name:	STEVE BRANCIFORTE	Notifier Agency:	NDE ENVIRONMENTAL
Notifier Phone:	(800) 964-7311	Notifier Extension:	Not reported
Spiller Contact:	RON PATOC	Spiller Phone:	(516) 575-7833
Spiller:	GRUMMAN AEROSPACE CORPORA		
Address:	NEW SOUTH ROAD BETHPAGE, NY 11714-		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	12/06/1995 12:25	Reported to Dept:	12/06/1995 12:25
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/07/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/06/1995		

231			GRUMMAN AEROSPACE FINAL PAINT HANGER-PLANT2 BETHPAGE, NY	NY Spills	S102096326	N/A
-----	--	--	---	-----------	------------	-----

SPILLS:

Facility ID:	8909492	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN AEROSPACE
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AEROSPACE		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	01/02/1990	Spilled Code:	0066
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	0 gallons	Resource Affected:	In Sewer
Spill Cause:	Equipment Failure	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	01/02/1990 11:50
Spill Date:	01/02/1990 11:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S102096326

Test method: Not reported Leak Rate: 0.00
Gross Leak/Fail: Not reported
Cleanup Ceased: 01/02/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/03/1990

231

GRUMMAN AEROSPACE CORPORATION
S. OYSTER BAY ROAD
BETHPAGE, NY 11714

AST

A100084358
N/A

CBS AST:

Facility ID: 1-000156
Owner: LAROCHE INDUSTRIES INC
PO BOX 1629
SOUTH HACKENSACK, NJ 07606
(201) 472-8008

Telephone: (516) 575-3195

Facility Status: Active
Tank ID: 1
Tank Status: In Service
Tank Location: ABOVEGROUND
Install Date: 08/78
Tank Type: Steel/carbon steel
Extnl Protection: PAINTED/ASPHALT COATING
Intrnl Protection: NONE
Tank Containment: NONE
Pipe Type: STEEL/IRON
Pipe Internal: NONE
Pipe External: NONE
Pipe Containment: NONE
Leak Detection: NONE

Total AST's: 1

Capacity (Gal): Not reported
Product Stored: LEADED GASOLINE

Overfill Protection: Product Level Gauge/Other
Chemical: Not reported
Tank Closed: Not reported
Capacity (Gals): 500
Case Number: 7664417
MOSF Number: Not reported
SPDES Number: Not reported
Operator: ROY FISHER
Emrgncy Contact: GEORGE COLLINS
Certified Date: 08/26/96
Owner type: Corporate/Commercial
Owner Sub Type: Not reported
Mail Name: LAROCHE INDUSTRIES INC.
Mail Contact: DONNA WHITTAKER
1260 IROQUOIS DRIVE, STE. 108
NAPERVILLE, IL 60563
Mail Phone: (404) 851-0325

Pipe Location: Aboveground

Haz Percent: 85

Region: STATE
PBS Number: Not reported
SWIS Code: 2824
ICS Number: 1-700328
Facility Town: OYSTER BAY
Emrgncy Phone: (516) 575-8033
Expiration Date: 07/07/97
Facility Type: Manufacturing

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

231

GRUMMAN AEROSPACE CORP
NEW SOUTH RD
BETHPAGE, NY 11714

FINDS
NY Spills
RCRIS-LQG

1000300851
NYD981182249

RCRIS:

Owner: GRUMMAN AEROSPACE CORP
(212) 555-1212

Contact: JOHN OHLMANN
(516) 575-2385

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	D002	0.000 (N)
F001	0.000 (N)	F002	0.000 (N)
F005	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

SPILLS:

Facility ID: 9414751
Facility Contact: Not reported
Investigator: AUSTIN
Caller Name: JOHN
Caller Phone: (516) 575-8176
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: MAIL STOP
BETHPAGE

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-8176

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: 20 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/09/1995 09:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 02/09/1995 10:18
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/10/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/10/1995

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	01-09-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/62	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	OTHER	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	12/84	Date Closed:	09/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
Legal Agent:	ATTN: JOHN COFMAN (516) 575-4680 OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	01-09-2
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/62	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	OTHER	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	12/84	Date Closed:	09/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	01-09-3
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	15000
Tank Status:	Closed-Removed	Tank Type:	Steel/carbon steel
Install Date:	12/62	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	OTHER	Dispenser:	Suction
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	04/90	Date Closed:	09/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	01-09-4
Applic Rcvd:	02/07/1996	Capacity (Gal):	15000
Tank Location:	UNDERGROUND	Tank Type:	Steel/carbon steel
Tank Status:	Closed-Removed	Tank Internal:	NONE
Install Date:	12/62	Pipe Type:	STEEL/IRON
CAS No:	Not reported	Dispenser:	Suction
Product:	OTHER		
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	11/85	Date Closed:	09/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	01-09-5
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	15000
Tank Status:	Closed-Removed	Tank Type:	Steel/carbon steel
Install Date:	12/62	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	OTHER	Dispenser:	Submersible
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	11/85	Date Closed:	09/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	01-09-6
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	15000
Install Date:	12/62	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	OTHER	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Submersible
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	11/85	Date Closed:	09/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	01-09-7
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/62	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	OTHER	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm		
Test Date:	Not reported	Date Closed:	09/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-01-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/41	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	Not reported
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	05/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-01-2
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/41	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	Not reported
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	05/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-01-3
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	15000
Install Date:	12/41	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	05/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-01-4
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	15000
Install Date:	12/41	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	05/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
Legal Agent:	ATTN: JOHN COFMAN (516) 575-4680 OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-01-5
Tank Location:	UNDERGROUND	Capacity (Gal):	275
Tank Status:	Closed-Removed	Tank Type:	Steel/carbon steel
Install Date:	12/76	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	UNLEADED GASOLINE	Dispenser:	Suction
Tank External:	NONE		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	05/93	Date Closed:	11/94
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-01-8
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/86	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	EXCAVATION LINER		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	Product Level Gauge		
Test Date:	04/91	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1991
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-22-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/41	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	12/89
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	02-27-1
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	1000
Tank Status:	Closed-Removed	Tank Type:	Steel/carbon steel
Install Date:	12/41	Tank Internal:	Not reported
CAS No:	Not reported	Pipe Type:	Not reported
Product:	NOS 1,2, OR 4 FUEL OIL	Dispenser:	Suction
Tank External:	Not reported		
Pipe Location:	Not reported		
Pipe Internal:	Not reported		
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	02-29-2
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/67	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	Not reported
Tank External:	Not reported		
Pipe Location:	Not reported	Pipe Type:	Not reported
Pipe Internal:	Not reported	Dispenser:	Suction
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	02-35-1
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	10000
Tank Status:	In Service	Tank Type:	Steel/carbon steel
Install Date:	12/78	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	NOS 1,2, OR 4 FUEL OIL	Dispenser:	Suction
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	09/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	03-01-4
Applic Rcvd:	02/07/1996	Capacity (Gal):	550
Tank Location:	UNDERGROUND	Tank Type:	Steel/carbon steel
Tank Status:	In Service	Tank Internal:	NONE
Install Date:	12/77	Pipe Type:	STEEL/IRON
CAS No:	Not reported	Dispenser:	Suction
Product:	DIESEL		
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-01-6
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/80	Capacity (Gal):	2500
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	OTHER	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	High Level Alarm		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-03-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/74	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	09/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-34-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/82	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-34-3
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/82	Capacity (Gal):	2000
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic (FRP)
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	01/93
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-34-4
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/82	Capacity (Gal):	4000
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic (FRP)
Product:	OTHER	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE/WAPPED [PIPING]		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
Legal Agent:	ATTN: JOHN COFMAN (516) 575-4680 OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1991
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	04-01-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/43	Capacity (Gal):	1000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	Not reported
Tank External:	Not reported		
Pipe Location:	Not reported	Pipe Type:	Not reported
Pipe Internal:	Not reported	Dispenser:	Suction
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1991
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	04-03-1
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	2000
Tank Status:	Closed-Removed	Tank Type:	Steel/carbon steel
Install Date:	12/65	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	NOS 1,2, OR 4 FUEL OIL	Dispenser:	Suction
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	05/89	Date Closed:	09/93
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	04-04-2
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/43	Capacity (Gal):	275
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	UNLEADED GASOLINE	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	06/92	Date Closed:	01/95
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	04-04-3
Applic Rcvd:	02/07/1996	Capacity (Gal):	275
Tank Location:	UNDERGROUND	Tank Type:	Steel/carbon steel
Tank Status:	Closed-Removed	Tank Internal:	NONE
Install Date:	12/43	Pipe Type:	STEEL/IRON
CAS No:	Not reported	Dispenser:	Suction
Product:	UNLEADED GASOLINE		
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None	Date Closed:	01/95
Test Date:	07/92		
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	05-01-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/44	Capacity (Gal):	1000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-C01 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	05-17-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	06/89	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	06/89	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	12-03-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/66	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	09/90	Date Closed:	07/96
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	12-03-2
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	15000
Tank Status:	Closed-Removed	Tank Type:	Steel/carbon steel
Install Date:	12/66	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	NOS 1,2, OR 4 FUEL OIL	Dispenser:	Suction
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	12/95	Date Closed:	07/96
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	12-05-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service	Capacity (Gal):	1000
Install Date:	12/68	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL		
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	06/93	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	14-01-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/60	Capacity (Gal):	10000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 5 OR 6 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	14-01-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service	Capacity (Gal):	10000
Install Date:	12/60	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 5 OR 6 FUEL OIL	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Suction
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	14-01-3
Tank Location:	UNDERGROUND		
Tank Status:	In Service	Capacity (Gal):	275
Install Date:	12/60	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1991
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	14-01-4
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/84	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	Product Level Gauge		
Test Date:	08/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	15-01-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	10000
Install Date:	12/58	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE/WAPPED [PIPING]		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	05/89	Date Closed:	11/94
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	17-20-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/44	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	NONE	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	09/91	Date Closed:	03/94
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714- (516) 575-2385		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	17-22-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	2500
Install Date:	12/44	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Tank External:	NONE	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	10/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
Legal Agent:	ATTN: JOHN COFMAN (516) 575-4680 OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	17-22-2
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/74	Capacity (Gal):	275
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	LEADED GASOLINE	Tank Internal:	Not reported
Tank External:	Not reported		
Pipe Location:	Not reported	Pipe Type:	Not reported
Pipe Internal:	Not reported	Dispenser:	Suction
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714- (516) 575-2385	Owner Type:	UNDEFINED
Owner Tel:	(516) 575-2385		
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	18-01-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	3000
Install Date:	12/51	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	Not reported
Tank External:	NONE	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	08/90
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/77	Capacity (Gal):	6000
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic (FRP)
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	GALVANIZED STEEL
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	12/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	20-01-2
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	4000
Tank Status:	In Service	Tank Type:	Fiberglass reinforced plastic [FRP]
Install Date:	12/77	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	GALVANIZED STEEL
Product:	UNLEADED GASOLINE	Dispenser:	Suction
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	09/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	20-01-3
Applic Rcvd:	02/07/1996	Capacity (Gal):	6000
Tank Location:	UNDERGROUND	Tank Type:	Fiberglass reinforced plastic [FRP]
Tank Status:	In Service	Tank Internal:	NONE
Install Date:	12/77	Pipe Type:	GALVANIZED STEEL
CAS No:	Not reported	Dispenser:	Suction
Product:	UNLEADED GASOLINE		
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	09/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-4
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/75	Capacity (Gal):	4000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	EMPTY	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	11/85	Date Closed:	08/90
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-5
Tank Location:	UNDERGROUND		
Tank Status:	Closed-In Place	Capacity (Gal):	5000
Install Date:	12/43	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	EMPTY		
Tank External:	NONE	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	11/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-7
Tank Location:	UNDERGROUND		
Tank Status:	Temporarily Out Of Service		
Install Date:	12/68	Capacity (Gal):	2000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	EMPTY	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	10/90	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-9
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/68	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	OTHER	Tank Internal:	EPOXY LINER
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	EPOXY LINER	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	10/90	Date Closed:	09/92
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714- (516) 575-2385	Owner Type:	UNDEFINED
Owner Tel:			
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	24-01-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	10000
Install Date:	12/66	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	08/90	Date Closed:	05/94
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	24-01-2
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	1000
Install Date:	12/66	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	OTHER		
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	07/92	Date Closed:	05/94
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	25-01-1
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	10000
Tank Status:	In Service	Tank Type:	Fiberglass coated steel
Install Date:	12/86	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	NOS 5 OR 6 FUEL OIL	Dispenser:	Suction
Tank External:	NONE		
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	EXCAVATION LINER		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	25-01-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/86	Capacity (Gal):	10000
CAS No:	Not reported	Tank Type:	Fiberglass coated steel
Product:	NOS 5 OR 6 FUEL OIL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	EXCAVATION LINER		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	05/94
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	25-01-3
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/63	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	COPPER
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	08/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	25-05-1
Applic Rcvd:	02/07/1996	Capacity (Gal):	275
Tank Location:	UNDERGROUND	Tank Type:	Steel/carbon steel
Tank Status:	Closed-Removed	Tank Internal:	NONE
Install Date:	12/45	Pipe Type:	STEEL/IRON
CAS No:	Not reported	Dispenser:	Suction
Product:	LEADED GASOLINE		
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	08/90
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	25-08-1
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	2000
Tank Status:	In Service	Tank Type:	Fiberglass reinforced plastic (FRP)
Install Date:	12/82	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	COPPER
Product:	NOS 1,2, OR 4 FUEL OIL	Dispenser:	Suction
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	26-01-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/84	Capacity (Gal):	20000
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic (FRP)
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	26-01-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/85	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	Product Level Gauge		
Test Date:	06/91	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	28-01-1
Applic Rcvd:	02/07/1996	Capacity (Gal):	4000
Tank Location:	UNDERGROUND	Tank Type:	Steel/carbon steel
Tank Status:	In Service	Tank Internal:	NONE
Install Date:	12/64	Pipe Type:	STEEL/IRON
CAS No:	Not reported	Dispenser:	Suction
Product:	NOS 1,2, OR 4 FUEL OIL		
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	09/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	30-01-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/64	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 5 C-6 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	30-01-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/64	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 5 OR 6 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	30-01-3
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	550
Tank Status:	In Service	Tank Type:	Steel/carbon steel
Install Date:	12/64	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	COPPER
Product:	DIESEL	Dispenser:	Suction
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	31-01-1
Applic Rcvd:	02/07/1996	Capacity (Gal):	12000
Tank Location:	UNDERGROUND	Tank Type:	Fiberglass reinforced plastic [FRP]
Tank Status:	In Service	Tank Internal:	NONE
Install Date:	12/85	Pipe Type:	GALVANIZED STEEL
CAS No:	Not reported	Dispenser:	Suction
Product:	NOS 1,2, OR 4 FUEL OIL		
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	DOUBLED-WALLED TANK		
Leak Detection:	Not reported		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	35-01-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/66	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 5 OR 6 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	35-01-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/66	Capacity (Gal):	15000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 5 OR 6 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	35-01-3
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/66	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	35-04-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/74	Capacity (Gal):	3000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	03-13-13
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	2000
Tank Status:	Closed-In Place	Tank Type:	Steel/carbon steel
Install Date:	12/65	Tank Internal:	Not reported
CAS No:	Not reported		
Product:	OTHER	Pipe Type:	Not reported
Tank External:	Not reported	Dispenser:	Suction
Pipe Location:	Not reported		
Pipe Internal:	Not reported		
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-13-14
Tank Location:	UNDERGROUND		
Tank Status:	Closed-In Place		
Install Date:	12/65	Capacity (Gal):	1000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	OTHER	Tank Internal:	Not reported
Tank External:	Not reported		
Pipe Location:	Not reported	Pipe Type:	Not reported
Pipe Internal:	Not reported	Dispenser:	Suction
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-13-15
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	2000
Install Date:	12/65	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Tank External:	PAINTED/ASPHALT COATING	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	05/90	Date Closed:	04/91
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	111-01-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/70	Capacity (Gal):	4000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/95	Date Closed:	10/95
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	111-01-2
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/70	Capacity (Gal):	4000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/95	Date Closed:	10/95
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1991
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	111-01-3
Tank Location:	UNDERGROUND		
Tank Status:	In Service	Capacity (Gal):	1000
Install Date:	12/70	Tank Type:	Steel/carbon steel
CAS No:	Not reported	Tank Internal:	NONE
Product:	DIESEL		
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	COPPER
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	08/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	20-01-10
Applic Rcvd:	02/07/1996	Capacity (Gal):	550
Tank Location:	UNDERGROUND	Tank Type:	Steel/carbon steel
Tank Status:	Closed-Removed	Tank Internal:	NONE
Install Date:	12/64	Pipe Type:	STEEL/IRON
CAS No:	Not reported	Dispenser:	Suction
Product:	DIESEL		
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	05/90	Date Closed:	09/92
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-11
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	02/79	Capacity (Gal):	20000
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	LEADED GASOLINE	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	GALVANIZED STEEL
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	None		
Test Date:	07/93	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	20-01-12
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	20000
Tank Status:	In Service	Tank Type:	Fiberglass reinforced plastic [FRP]
Install Date:	12/79	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	GALVANIZED STEEL
Product:	UNLEADED GASOLINE	Dispenser:	Suction
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	None		
Test Date:	07/93	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-	Owner Type:	UNDEFINED
Owner Tel:	(516) 575-2385		
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	20-01-13
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	10000
Tank Status:	In Service	Tank Type:	Fiberglass reinforced plastic [FRP]
Install Date:	12/79	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	GALVANIZED STEEL
Product:	DIESEL	Dispenser:	Suction
Tank External:	NONE		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	None		
Test Date:	12/95	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
	ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-14
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/79	Capacity (Gal):	6000
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic [FRP]
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	GALVANIZED STEEL
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	09/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-15
Tank Location:	UNDERGROUND		
Tank Status:	In Service	Capacity (Gal):	1000
Install Date:	12/85	Tank Type:	Fiberglass reinforced plastic [FRP]
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	GALVANIZED STEEL
Tank External:	NONE	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/VAPOR WELL		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-16
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	550
Install Date:	12/85	Tank Type:	Fiberglass reinforced plastic [FRP]
CAS No:	Not reported	Tank Internal:	NONE
Product:	OTHER		
Tank External:	NONE	Pipe Type:	GALVANIZED STEEL
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	08/90
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-17
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed	Capacity (Gal):	1000
Install Date:	12/85	Tank Type:	Fiberglass reinforced plastic [FRP]
CAS No:	Not reported	Tank Internal:	NONE
Product:	OTHER	Pipe Type:	GALVANIZED STEEL
Tank External:	NONE	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	08/90
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	20-01-19
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/82	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Fiberglass reinforced plastic (FRP)
Product:	OTHER	Tank Internal:	NONE
Tank External:	NONE		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None	Date Closed:	Not reported
Test Date:	09/94		
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	28A-01-1
Tank Location:	UNDERGROUND		
Tank Status:	Closed-Removed		
Install Date:	12/64	Capacity (Gal):	5000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	Not reported
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	02/90
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	01-04-3
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	12/45	Capacity (Gal):	1000
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING		
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	06/93	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714-		
Legal Agent:	ATTN: JOHN COFMAN (516) 575-4680 OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	03-07-1
Tank Location:	UNDERGROUND		
Tank Status:	In Service	Capacity (Gal):	4000
Install Date:	01/86	Tank Type:	Fiberglass reinforced plastic [FRP]
CAS No:	Not reported	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Tank External:	NONE	Dispenser:	Suction
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other	Tank ID:	02-01-9
Applic Rcvd:	02/07/1996		
Tank Location:	UNDERGROUND	Capacity (Gal):	10000
Tank Status:	In Service	Tank Type:	Fiberglass coated steel
Install Date:	06/91	Tank Internal:	NONE
CAS No:	Not reported	Pipe Type:	STEEL/IRON
Product:	DIESEL	Dispenser:	Suction
Tank External:	FIBERGLASS		
Pipe Location:	Underground		
Pipe Internal:	NONE		
Pipe External:	JACKETED/WRAPPED [PIPING]		
Second Contain:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	06/91	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680		
SPDES Num:	0-096792	Total Tanks:	88
Avg Throughpt:	2729	License Stat:	Issued
License Issued:	03/25/1996	Exp Date:	03/31/1901
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	25-05-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	09/90	Capacity (Gal):	550
CAS No:	Not reported	Tank Type:	Steel/carbon steel
Product:	DIESEL	Tank Internal:	NONE
Tank External:	SACRIFICIAL ANODE		
Pipe Location:	Underground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	JACKETED		
Second Contain:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	10/90	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Facility Status:	ACTIVE FACILITY
SWIS Code:	28	Facility Town:	OYSTER BAY
Contact:	JOHN COFMAN, (516) 575-4680		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714-		
Owner Tel:	(516) 575-2385	Owner Type:	UNDEFINED
Mail To:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714- ATTN: JOHN COFMAN (516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714-		
Date Filed:	Not reported	CBS Number:	1-000208
Emerg Contact:	JOHN COFMAN, (516) 575-4680	Total Tanks:	88
SPDES Num:	0-096792	License Stat:	Issued
Avg Throughpt:	2729	Exp Date:	03/31/1901
License Issued:	03/25/1996		
Facility Type:	Other		
Transfer Operation:	Tank Truck, Other		
Applic Rcvd:	02/07/1996	Tank ID:	17-20-2
Tank Location:	UNDERGROUND		
Tank Status:	In Service		
Install Date:	03/94	Capacity (Gal):	10000
CAS No:	Not reported	Tank Type:	Fiberglass coated steel
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Tank External:	FIBERGLASS		
Pipe Location:	Underground	Pipe Type:	FIBERGLASS [FRP]
Pipe Internal:	FIBERGLASS LINER [FRP]	Dispenser:	Suction
Pipe External:	FIBERGLASS		
Second Contain:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	03/94	Date Closed:	Not reported
Database Type:	Major Oil Storage		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

MOSF AST:

Facility ID: 1-1280 Telephone: (516) 575-4680
Facility Type: Other Facility Contact: JOHN COFMAN
Facility Status: ACTIVE FACILITY
Owner: GRUMMAN AEROSPACE CORP.

MAIL STOP D08-GHQ
BETHPAGE, NY 11714

Owner Tel: (516) 575-2385

Owner Type: Corporate/Commercial

CASNO: Not reported

Tank Status: In Service

Tank ID: 02-29-1

Total Tanks: 38

Daily Throughput 2729 Gal(s)

Tank Location: ABOVEGROUND

Capacity (Gal): Not reported

Install Date: 12/68

Tank Type: Steel/carbon steel

Tank External: NONE/JACKETED

Product: NOS 5 OR 6 FUEL OIL

Tank Internal: NONE

Pipe Location: Aboveground

Pipe Type: STEEL/IRON

Pipe Internal: NONE

Dispenser: Suction

Pipe External: NONE

Second Contain: PREFABRICATED STEEL DIKE/NATURAL LINER

Leak Detection: NONE/NONE

Overfill Protection: None

Test Date: Not reported

Date Closed: Not reported

Dispensing Mthd: Suction

SWIS Code: 28

Facility Town: OYSTER BAY

Mailing Name: GRUMMAN AEROSPACE CORP.

MAIL STOP D08-001
NY 11714

Mailing Contact: JOHN COFMAN

Mailing Phone: (516) 575-4680

Legal Agent: OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP
SOUTH OYSTER BAY ROAD
BETHPAGE, NY 11714

Date Legal Agent Filed with Secretary of State: Not reported

Name of Emergency Contact: JOHN COFMAN

Emergency Contact Telephone: (516) 575-4680

Chemical Bulk Storage Number: 1-000208

Pollution Discharge Elimination System Num: 0-096792

License Status: License Issued

Date License Application Received: 02/07/1996

Date License Issued: 03/25/1996

Date License Expires or Expired: 03/31/1901

Product Transfer Operation: Tank Truck

Other

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	20-03-22
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND	Capacity (Gal):	Not reported
Install Date:	02/92		
Tank Type:	Steel/carbon steel		
Tank External:	PAINTED/ASPHALT COATING		
Product:	OTHER	Tank Internal:	NONE
Pipe Location:	None	Pipe Type:	NONE
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	20-03-23
Tank Status:	In Service	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND		
Install Date:	02/92		
Tank Type:	Steel/carbon steel	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	NONE
Product:	OTHER	Dispenser:	Suction
Pipe Location:	None		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	DOUBLED-WALLED TANK		
Leak Detection:	INTERSTITIAL MONITORING		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	01-01-1
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/83		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	01-01-3
Tank Status:	In Service	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/83		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Gravity
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Gravity		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	01-04-2
Total Tanks:	38	Daily Throughput:	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/85		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	OTHER		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	02-01-7
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/41		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	OTHER		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	02-04-1
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/88		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	CONCRETE DIKE		
Leak Detection:	NONE/CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	03-01-7
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/77		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	03-01-8
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/43		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	04-04-1
Tank Status:	Closed-Removed	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/85		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	OTHER		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	04/93
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	05-05-1
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/85		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	OTHER		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	12-02-1
Total Tanks:	38	Daily Throughput:	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/80		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	None	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	12-03-3
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/45		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	12-03-4
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/45		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	15-01-2
Tank Status:	Closed-Removed	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/58		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	12/92
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	Closed-Removed	Tank ID:	15-01-3
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/54		
Tank Type:	Steel/carbon steel		
Tank External:	Not reported		
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Pipe Internal:	Not reported	Dispenser:	Suction
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	Closed-Removed	Tank ID:	15-01-4
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/78		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	08/94
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	17-22-3
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/87		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	CONCRETE DIKE		
Leak Detection:	NONE/CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	20-01-6
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/43		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	20-01-8
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/68		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	OTHER	Pipe Type:	NONE
Pipe Location:	None	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	Closed-Removed	Tank ID:	20-02-1
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/74		
Tank Type:	Steel/carbon steel		
Tank External:	Not reported	Tank Internal:	Not reported
Product:	OTHER	Pipe Type:	Not reported
Pipe Location:	Not reported	Dispenser:	Suction
Pipe Internal:	Not reported		
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	Closed-Removed	Tank ID:	20-02-2
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/41		
Tank Type:	Steel/carbon steel		
Tank External:	Not reported	Tank Internal:	Not reported
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	Not reported
Pipe Location:	Not reported	Dispenser:	Suction
Pipe Internal:	Not reported		
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	20-02-3
Tank Status:	Closed-Removed	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/41		
Tank Type:	Steel/carbon steel		
Tank External:	Not reported		
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	Not reported
Pipe Location:	Not reported	Pipe Type:	Not reported
Pipe Internal:	Not reported	Dispenser:	Suction
Pipe External:	Not reported		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	UNKWN
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	25-03-1
Tank Status:	In Service	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/45		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	NOS 1,2, OR 4 FUEL OIL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	111-01-4
Tank Status:	In Service	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/85		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	OTHER		
Leak Detection:	NONE/NONE		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	20-01-20
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/68		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	OTHER	Pipe Type:	STEEL/IRON
Pipe Location:	Underground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	20-01-21
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/68		
Tank Type:	Steel/carbon steel		
Tank External:	NONE		
Product:	OTHER	Tank Internal:	NONE
Pipe Location:	Underground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE/NONE		
Overfill Protection:	None		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	20-01-10
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	09/92		
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	COPPER
Pipe Location:	Aboveground	Dispenser:	Suction
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	03-01-9
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/92		
Tank Type:	Steel/carbon steel		
Tank External:	PAINTED/ASPHALT COATING		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	CONCRETE DIKE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMEN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714 (516) 575-2385		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	04-01-2
Tank Status:	Closed-Removed	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/43		
Tank Type:	Steel/carbon steel		
Tank External:	PAINTED/ASPHALT COATING		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	12/94
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	Closed-Removed	Tank ID:	04-01-3
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	12/43		
Tank Type:	Steel/carbon steel	Tank Internal:	NONE
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	STEEL/IRON
Product:	DIESEL	Dispenser:	Suction
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	12/94
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	03-13-15
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	04/91		
Tank Type:	Steel/carbon steel		
Tank External:	PAINTED/ASPHALT COATING		
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	COPPER
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	02-29-2
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	06/89		
Tank Type:	Steel/carbon steel		
Tank External:	PAINTED/ASPHALT COATING		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	02-01-10
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	04/93		
Tank Type:	Steel/carbon steel		
Tank External:	PAINTED/ASPHALT COATING		
Product:	DIESEL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	PAINTED/ASPHALT COATING		
Second Contain:	PREFABRICATED STEEL DIKE		
Leak Detection:	NONE		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385	CASNO:	Not reported
Owner Type:	Corporate/Commercial	Tank ID:	03-34-5(TEM
Tank Status:	In Service	Daily Throughput	2729 Gal(s)
Total Tanks:	38	Capacity (Gal):	Not reported
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	10/93		
Tank Type:	Steel/carbon steel	Tank Internal:	Not reported
Tank External:	PAINTED/ASPHALT COATING	Pipe Type:	COPPER
Product:	NOS 1,2, OR 4 FUEL OIL	Dispenser:	Suction
Pipe Location:	Aboveground		
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	15-01-5
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	08/94	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel		
Tank External:	NONE	Tank Internal:	NONE
Product:	DIESEL	Pipe Type:	STEEL/IRON
Pipe Location:	Aboveground	Dispenser:	Not reported
Pipe Internal:	NONE		
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge, High Level Alarm		
Test Date:	Not reported	Date Closed:	Not reported
Dispensing Mthd:	Not reported		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP. (Continued)

U003080110

Facility ID:	1-1280	Telephone:	(516) 575-4680
Facility Type:	Other	Facility Contact:	JOHN COFMAN
Facility Status:	ACTIVE FACILITY		
Owner:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-GHQ BETHPAGE, NY 11714		
Owner Tel:	(516) 575-2385		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	Closed-Removed	Tank ID:	111-01-5(T)
Total Tanks:	38	Daily Throughput	2729 Gal(s)
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE	Capacity (Gal):	Not reported
Install Date:	08/95		
Tank Type:	Steel/carbon steel		
Tank External:	PAINTED/ASPHALT COATING		
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	NONE
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Test Date:	Not reported	Date Closed:	08/95
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	GRUMMAN AEROSPACE CORP. MAIL STOP D08-001 NY 11714		
Mailing Contact:	JOHN COFMAN		
Mailing Phone:	(516) 575-4680		
Legal Agent:	OFFICE OF GENERAL COUNCIL, GRUMMAN AEROSPACE CORP SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714		
Date Legal Agent Filed with Secretary of State:	Not reported		
Name of Emergency Contact:	JOHN COFMAN		
Emergency Contact Telephone:	(516) 575-4680		
Chemical Bulk Storage Number:	1-000208		
Pollution Discharge Elimination System Num:	0-096792		
License Status:	License Issued		
Date License Application Received:	02/07/1996		
Date License Issued:	03/25/1996		
Date License Expires or Expired:	03/31/1901		
Product Transfer Operation:	Tank Truck Other		

231

GRUMMAN AEROSPACE CORPORATION
MAIL STOP:D08-GHQ
BETHPAGE, NY 11714

AST

A100084378
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

CBS AST:

Facility ID: 1-000208 Telephone: (516) 575-4680
Owner: GRUMMAN AEROSPACE CORPORATION

MAIL STOP:D08-GHQ
BETHPAGE, NY 11714
(516) 575-4680

Facility Status: Active

Tank ID: 10

Total AST's: 13

Tank Status: Closed-In Place

Tank Location: ABOVEGROUND

Install Date: 12/70

Capacity (Gal): Not reported

Tank Type: Steel/carbon steel

Product Stored: LEADED GASOLINE

Extrnl Protection: PAINTED/ASPHALT COATING

Intrnl Protection: NONE

Tank Containment: NONE

Pipe Type: GALVANIZED STEEL

Pipe Location: Aboveground

Pipe Internal: NONE

Pipe External: PAINTED/ASPHALT COATING

Pipe Containment: NONE

Haz Percent: 100

Leak Detection: NONE

Overfill Protection: Product Level Gauge

Chemical: Not reported

Tank Closed: 11/93

Capacity (Gals): 4000

Region: STATE

Case Number: 79016

PBS Number: Not reported

MOSF Number: 1-1280

SWIS Code: 2820

SPDES Number: 0-096792

ICS Number: 1-167380

Operator: JOHN COFMAN

Facility Town: HEMPSTEAD

Emrgncy Contact: JOHN INGENITO

Emrgncy Phone: (516) 575-3444

Certified Date: 08/03/95

Expiration Date: 08/08/97

Owner type: Corporate/Commercial

Facility Type: Other

Owner Sub Type: Not reported

Mail Name: GRUMMAN AEROSPACE CORPORATION

Mail Contact: JOHN COFMAN

MAIL STOP:D08-GHQ
BETHPAGE, NY 11714

Mail Phone: (516) 575-4680

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Facility Status:	Active		
Tank ID:	313	Total AST's:	13
Tank Status:	In Service		
Tank Location:	ABOVEGROUND		
Install Date:	12/84	Capacity (Gal):	Not reported
Tank Type:	Stainless steel alloy	Product Stored:	LEADED GASOLINE
Extrnl Protection:	JACKETED		
Intrnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	FIBERGLASS [FRP]	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	NONE		
Pipe Containment:	VAULT	Haz Percent:	93
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm/Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	5000	Region:	STATE
Case Number:	8014957	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN MAIL STOP:D08-GHQ BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
	(516) 575-4680		
Facility Status:	Active		
Tank ID:	329	Total AST's:	13
Tank Status:	In Service		
Tank Location:	ABOVEGROUND		
Install Date:	12/84	Capacity (Gal):	Not reported
Tank Type:	Fiberglass reinforced plastic [FRP]	Product Stored:	LEADED GASOLINE
Extrnl Protection:	FIBERGLASS		
Intrnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	FIBERGLASS [FRP]	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	JACKETED		
Pipe Containment:	VAULT	Haz Percent:	50
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm/Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	8000	Region:	STATE
Case Number:	1310732	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
	(516) 575-4680		
Facility Status:	Active		
Tank ID:	320	Total AST's:	13
Tank Status:	In Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/84	Capacity (Gal):	Not reported
Tank Type:	Other	Product Stored:	LEADED GASOLINE
Extrnl Protection:	NONE		
Intnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	FIBERGLASS [FRP]	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	JACKETED		
Pipe Containment:	VAULT	Haz Percent:	50
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm/Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	7000	Region:	STATE
Case Number:	7722841	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
	(516) 575-4680		
Facility Status:	Active		
Tank ID:	399	Total AST's:	13
Tank Status:	Temporarily Out Of Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	09/80	Capacity (Gal):	Not reported
Tank Type:	Fiberglass reinforced plastic [FRP]	Product Stored:	LEADED GASOLINE
Extrnl Protection:	NONE		
Intrnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	VAULT	Haz Percent:	50
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm/Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	4418	Region:	STATE
Case Number:	1310732	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Facility Status:	Active		
Tank ID:	400	Total AST's:	13
Tank Status:	Temporarily Out Of Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	09/80	Capacity (Gal):	Not reported
Tank Type:	Fiberglass reinforced plastic [FRP]	Product Stored:	LEADED GASOLINE
Extrnl Protection:	NONE		
Intnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	VAULT	Haz Percent:	50
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm/Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	4418	Region:	STATE
Case Number:	1310732	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Facility Status:	Active		
Tank ID:	941	Total AST's:	13
Tank Status:	Temporarily Out Of Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/62	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	PAINTED/ASPHALT COATING		
Intrnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	FIBERGLASS [FRP]	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	NONE		
Pipe Containment:	VAULT	Haz Percent:	100
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	500	Region:	STATE
Case Number:	71556	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN MAIL STOP:D08-GHQ BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Facility Status:	Active		
Tank ID:	1207	Total AST's:	13
Tank Status:	Temporarily Out Of Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	09/83	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	PAINTED/ASPHALT COATING		
Intnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	IMPERVIOUS UNDERLAYMENT	Haz Percent:	100
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	10000	Region:	STATE
Case Number:	127184	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN MAIL STOP:D08-GHQ BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Facility Status:	Active		
Tank ID:	1254	Total AST's:	13
Tank Status:	Temporarily Out Of Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/85	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	PAINTED/ASPHALT COATING		
Intrnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	IMPERVIOUS UNDERLAYMENT	Haz Percent:	100
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm/Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	6000	Region:	STATE
Case Number:	67561	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN MAIL STOP:D08-GHQ BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Facility Status:	Active		
Tank ID:	1303	Total AST's:	13
Tank Status:	Closed-Removed		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/88	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extnl Protection:	PAINTED/ASPHALT COATING		
Intnl Protection:	NONE		
Tank Containment:	NONE		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	NONE	Haz Percent:	100
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	04/94		
Capacity (Gals):	600	Region:	STATE
Case Number:	79016	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
	(516) 575-4680		
Facility Status:	Active	Total AST's:	13
Tank ID:	1271		
Tank Status:	Temporarily Out Of Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	09/87	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	PAINTED/ASPHALT COATING		
Intrnl Protection:	NONE		
Tank Containment:	VAULT		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	IMPERVIOUS UNDERLAYMENT	Haz Percent:	100
Leak Detection:	CONCRETE PAD WITH CHANNELS		
Overfill Protection:	High Level Alarm		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	10000	Region:	STATE
Case Number:	79016	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
	(516) 575-4680		
Facility Status:	Active		
Tank ID:	1304	Total AST's:	13
Tank Status:	In Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/69	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	PAINTED/ASPHALT COATING		
Intrnl Protection:	NONE		
Tank Containment:	NONE		
Pipe Type:	STEEL/IRON	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	NONE		
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	500	Region:	STATE
Case Number:	7664417	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN		
	MAIL STOP:D08-GHQ		
	BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORPORATION (Continued)

A100084378

Facility ID:	1-000208	Telephone:	(516) 575-4680
Owner:	GRUMMAN AEROSPACE CORPORATION MAIL STOP:D08-GHQ BETHPAGE, NY 11714 (516) 575-4680		
Facility Status:	Active		
Tank ID:	7002	Total AST's:	13
Tank Status:	Temporarily Out Of Service		
Tank Location:	ABOVEGROUND ON SADDLES LEGS, STILTS, RACK, OR CRADLE		
Install Date:	12/60	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel	Product Stored:	LEADED GASOLINE
Extrnl Protection:	PAINTED/ASPHALT COATING		
Intrnl Protection:	NONE		
Tank Containment:	NONE		
Pipe Type:	FIBERGLASS [FRP]	Pipe Location:	Aboveground
Pipe Internal:	NONE		
Pipe External:	PAINTED/ASPHALT COATING		
Pipe Containment:	NONE	Haz Percent:	100
Leak Detection:	NONE		
Overfill Protection:	Product Level Gauge		
Chemical:	Not reported		
Tank Closed:	Not reported		
Capacity (Gals):	4800	Region:	STATE
Case Number:	76131	PBS Number:	Not reported
MOSF Number:	1-1280	SWIS Code:	2820
SPDES Number:	0-096792	ICS Number:	1-167380
Operator:	JOHN COFMAN	Facility Town:	HEMPSTEAD
Emrgncy Contact:	JOHN INGENITO	Emrgncy Phone:	(516) 575-3444
Certified Date:	08/03/95	Expiration Date:	08/08/97
Owner type:	Corporate/Commercial	Facility Type:	Other
Owner Sub Type:	Not reported		
Mail Name:	GRUMMAN AEROSPACE CORPORATION		
Mail Contact:	JOHN COFMAN MAIL STOP:D08-GHQ BETHPAGE, NY 11714		
Mail Phone:	(516) 575-4680		

231

GRUMMAN
MULBERRY STREET BLDG 12
BETHPAGE, NY

LUST

S100664825
N/A

LUST:

Facility ID:	9208152	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPRT	Spill Type:	Facility
Caller Name:	JOHN COFMAN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-4680	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/26/1992		
Spill Cause:	Other	Resource Affected:	On Land

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S100664825

Water Affected: Not reported
Spill Notifier: Other
Spill Date: 10/14/1992 15:10
Cleanup Ceased: 10/26/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/29/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/16/1992

Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 10/14/1992 15:30

231

**GRUMMAN
PLANT #2 HANGER
BETHPAGE, NY**

LUST

**S100665943
N/A**

LUST:

Facility ID: 8909211
Facility Contact: Not reported
Investigator: NONE
Caller Name: JOHN OHLMANN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: Not reported
Spill Class: Not reported
Spill Closed Dt: 12/21/1989
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 12/19/1989 12:00
Cleanup Ceased: 12/21/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/04/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/21/1989

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN BETHPAGE
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: In Sewer
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 12/19/1989 14:15

231

**GRUMMAN AEROSPACE
SCALE HANGER PLANT #4
BETHPAGE, NY**

NY Spills

**S102098604
N/A**

SPILLS:

Facility ID: 9309624
Facility Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S102098604

Investigator:	KISPRT	Spill Type:	Facility
Caller Name:	JOHN SELVA	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AEROSPACE		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/02/1994		
Material Class:	Petroleum	Spilled Code:	0022
Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Housekeeping	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	11/08/1993 14:30	Reported to Dept:	11/09/1993 11:15
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/02/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/06/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	11/09/1993		

231

GRUMMAN PLANT 11
83 LUDY ST
HICKSVILLE, NY

LUST

S100493411
N/A

LUST:

Facility ID:	9200757	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	RICE	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN PLANT 11		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	11/05/1992		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	04/20/1992 15:30	Reported to Dept:	04/20/1992 16:02
Cleanup Ceased:	11/05/1992		
Last Inspection:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN PLANT 11 (Continued)

S100493411

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/09/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/22/1992

231

**GRUMMAN
PLANT #2, RECHARGE BASINS
BETHPAGE, NY**

NY Spills

**S102090600
N/A**

SPILLS:

Facility ID: 9108637
Facility Contact: Not reported
Investigator: PARISH
Caller Name: JOHN OHLMANN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 12/04/1991
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Unknown
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 11/13/1991 09:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/04/1991
Last Inspection: Not reported

Spilled Code: 0066
Quant Recovered: 0 gallons
Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 11/13/1991 09:35
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/10/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/13/1991

231

**GRUMMAN CORP
STEWART AVE - WHSE #8
BETHPAGE, NY**

LUST

**S101658229
N/A**

LUST:

Facility ID: 9506898
Facility Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN CORP (Continued)

S101658229

Investigator:	PARISH	Spill Type:	Facility
Caller Name:	JOHN SELVA	Caller Agency:	GRUMMAN CORP
Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-8176
Spiller:	GRUMMAN CORP		
Address:	STEWART AVE BETHPAGE, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Major Facility 400,000 gallons
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	09/06/1995 11:00	Reported to Dept:	09/06/1995 13:12
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/07/1995		

231

**NORTHROP GRUMMAN PLANT 20
SOUTH OYSTER BAY ROAD
BETHPAGE, NY**

NY Spills

**S102102599
N/A**

SPILLS:

Facility ID:	9509204	Region of Spill:	1
Facility Contact:	JOHN OHLMANN	Facility Tele:	(516) 575-2385
Investigator:	ACAMPORA	Spill Type:	UST
Caller Name:	JOHN OHLMANN	Caller Agency:	NORTHROP GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	SAME	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	JOHN OHLMANN	Spiller Phone:	(516) 575-2385
Spiller:	NORTHROP GRUMMAN PLANT 20		
Address:	SOUTH OYSTER BAY ROAD BETHPAGE		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/24/1996	Spilled Code:	0066
Material Class:	Petroleum	Quant Recovered:	Unknown gallons
Quantity Spilled:	Unknown gallons	Resource Affected:	On Land
Spill Cause:	Unknown	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	10/25/1995 13:30
Spill Date:	10/25/1995 14:18	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

NORTHROP GRUMMAN PLANT 20 (Continued)

S102102599

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/28/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/25/1995

Facility ID: 9608032
Facility Contact: JON INGENITO
Investigator: PARISH
Caller Name: JON INGENITO
Caller Phone: (516) 575-2029
Notifier Name: EMP
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: FORTUNATO AND SONS
Address: UNK

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: NORTHROP GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: 20 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 09/26/1996 17:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported

Spilled Code: 0008
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Commercial Vehicle
PBS Number: Not reported
Reported to Dept: 09/26/1996 18:38
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/30/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/26/1996

231

**GRUMMAN AEROSPACE
SO OYSTER BAY ROAD BLDG20
BETHPAGE, NY**

NY Spills

**S102097943
N/A**

SPILLS:

Facility ID: 9302356
Facility Contact: Not reported
Investigator: DECANDIA
Caller Name: JOHN SELVA
Caller Phone: (516) 575-8176
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-8176

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S102097943

Spiller:	GRUMMAN AEROSPACE		
Address	SO OYSTER BAY ROAD BETHPAGE, NY		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/31/1993	Spilled Code:	0008
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	5 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	05/20/1993 10:09
Spill Date:	05/20/1993 09:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/31/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/04/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/21/1993		

231

GRUMMAN PLANT #25 SO OYSTER BAY ROAD BETHPAGE, NY

NY Spills

S102098349
N/A

SPILLS:

Facility ID:	9306867	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPERT	Spill Type:	Facility
Caller Name:	JOHN OHLMAN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/28/1993	Spilled Code:	0066
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	3 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	09/03/1993 20:07
Spill Date:	09/03/1993 18:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/28/1993		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN PLANT #25 (Continued)

S102098349

Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/29/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/08/1993

231

**GRUMMAN
SO OYSTER BAY ROAD
BETHPAGE, NY**

NY Spills

**S102092506
N/A**

SPILLS:

Facility ID:	9206528	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PARISH	Spill Type:	Facility
Caller Name:	JOHN SALVA	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-2385
Spiller:	GRUMMAN		
Address:	Not reported		

Spill Class: Known release that creates potential for fire or hazard. (Highly improbable)

Spill Closed Dt:	09/16/1992	Spilled Code:	0098
Material Class:	Nonpetroleum/Nonhazardous	Quant Recovered:	0 gallons
Quantity Spilled:	30 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	09/04/1992 12:02
Spill Date:	09/04/1992 09:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		

Cleanup Ceased: 09/16/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/18/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/08/1992

Facility ID:	9303257	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S102092506

Spiller Contact:	Not reported	Spiller Phone:	(516) 575-2385
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/14/1993		
Material Class:	Petroleum	Spilled Code:	0016
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	06/10/1993 15:00	Reported to Dept:	06/10/1993 16:35
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	06/14/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/15/1993		

231

GRUMMAN AERO PLANT #3 BETHPAGE, NY

NY Spills

S102092503
N/A

SPILLS:

Facility ID:	9206477	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPRT	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AERO		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/08/1992		
Material Class:	Petroleum	Spilled Code:	0010
Quantity Spilled:	20 gallons	Quant Recovered:	0 gallons
Spill Cause:	Human Error	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	09/03/1992 12:00	Reported to Dept:	09/03/1992 14:20
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/08/1992		
Last Inspection:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AERO (Continued)

S102092503

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/10/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 09/04/1992

231

**NORTHROP GRUMMAN
STEWART AVENUE
BETHPAGE, NY**

LUST

**S101658189
N/A**

LUST:

Facility ID:	9506041	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	UST
Caller Name:	TOM DYKSTRA	Caller Agency:	NDE
Caller Phone:	(800) 964-7311	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NORTHROP GRUMMAN		
Address:	Not reported		

Spill Class: Known release that creates potential for fire or hazard. (Highly Improbable)

Spill Closed Dt: 04/09/1996

Spill Cause: Tank Test Failure

Water Affected: Not reported

Spill Notifier: Tank Tester

Spill Date: 08/16/1995 12:00

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 04/10/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 08/17/1995

Resource Affected: Groundwater

Spill Source: Other Commercial/Industrial

PBS Number: Not reported

Reported to Dept: 08/16/1995 12:20

231

**GRUMMAN CORP
PLANT 30,BETHPAGE COMPLEX
BETHPAGE, NY**

NY Spills

**S102100147
N/A**

SPILLS:

Facility ID:	9407147	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	JOHN SELVA	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN CORP (Continued)

S102100147

Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN CORP		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/29/1994		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	08/26/1994 10:00	Reported to Dept:	08/26/1994 12:07
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	08/29/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/30/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/29/1994		

231

GRUMMAN AEROSPACE PLANT #3 BETHPAGE, NY

NY Spills

S102096318
N/A

SPILLS:

Facility ID:	8909417	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ACAMPORA	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN AEROSPACE
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 575-2385
Spiller:	GRUMMAN AEROSPACE		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	01/11/1990	Spilled Code:	0038
Material Class:	Nonpetroleum/Nonhazardous	Quant Recovered:	0 gallons
Quantity Spilled:	20 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	12/28/1989 21:59
Spill Date:	12/28/1989 14:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	01/11/1990		
Last Inspection:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S102096318

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/04/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/02/1990

Facility ID: 9109374
Facility Contact: Not reported
Investigator: PARISH
Caller Name: JOHN OLHMANN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported
Material Class: Nonpetroleum/Nonhazardous
Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 12/04/1991 07:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/25/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/05/1991

Spilled Code: 1695
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 12/04/1991 08:50
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Facility ID: 9312502
Facility Contact: Not reported
Investigator: PARISH
Caller Name: JOHN OHLMANN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE (Continued)

S102096318

Spill Closed Dt:	04/07/1994	Spilled Code:	0039
Material Class:	Nonpetroleum/Nonhazardous	Quant Recovered:	0 gallons
Quantity Spilled:	5 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Commercial Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	01/24/1994 15:10
Spill Date:	01/24/1994 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	04/07/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/08/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/26/1994		

231

GRUMMAN AEROSPACE CORP
S OYSTER BAY RD
BETHPAGE, NY 11714

CORRACTS 1000300847
CERC-NFRAP NYD002047967
PADS
FINDS
LUST
RCRIS-LQG
TRIS
RCRIS-TSD

CERCLIS-NFRAP Classification Data:

Site Incident Category: Not reported
Ownership Status: OTHER
EPA Notes: Not reported

Federal Facility: NO
NPL Status: NOT ON NPL

CERCLIS-NFRAP Assessment History:

Assessment: DISCOVERY
Assessment: PRELIMINARY ASSESSMENT

Completed: 12/01/79
Completed: 01/01/80

CERCLIS-NFRAP Alias Name(s):

GRUMMAN AEROSPACE
GRUMMAN A/C-NAVWEPS IND RESERVE PLANT
GRUMMAN AEROSPACE CORP

CORRACTS Data:

Prioritization: High
Status: RCRA Facility Investigation Completed, Determination of Need for a RCRA Facility Investigation, RFI Imposition, RFI Workplan Approved, RCRA Facility Investigation Approved, CMS Workplan Approved, Corrective Measure Study Approved, Corrective Measures Investigation Workplan Approved, Stabilization Measures Implemented

RCRIS Corrective Action Summary:

Effective Date: 03/25/92
Legal Authority: RCRA 3004(u) or equivalent
Effective Date: 05/11/92
Legal Authority: RCRA 3004(u) or equivalent

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP (Continued)

1000300847

RCRIS:

Owner: GRUMMAN AEROSPACE CORP
(516) 575-2385

Contact: JOHN OHLMANN
(516) 575-2385

Classification: Large Quantity Generator, TSDF, Hazardous Waste Transporter

Waste	Quantity	Waste	Quantity
D001	145.000 (T)	D001	100.000 (T)
D001	50.000 (T)	D001	15.000 (T)
D001	120.000 (T)	D001	225.000 (T)
D001	25.000 (T)	D002	0.000 (N)
D002	15.000 (T)	D002	120.000 (T)
D003	120.000 (T)	D004	145.000 (T)
D004	120.000 (T)	D005	120.000 (T)
D006	0.000 (N)	D006	100.000 (T)
D006	145.000 (T)	D006	40.000 (T)
D006	120.000 (T)	D006	15.000 (T)
D006	225.000 (T)	D006	25.000 (T)
D006	3.000 (T)	D007	0.000 (N)
D007	145.000 (T)	D007	25.000 (T)
D007	225.000 (T)	D007	100.000 (T)
D007	120.000 (T)	D007	15.000 (T)
D007	40.000 (T)	D008	145.000 (T)
D008	225.000 (T)	D008	120.000 (T)
D008	25.000 (T)	D008	100.000 (T)
D009	120.000 (T)	D011	15.000 (T)
D011	120.000 (T)	D018	225.000 (T)
D018	120.000 (T)	D019	225.000 (T)
D019	120.000 (T)	D022	145.000 (T)
D022	120.000 (T)	D022	225.000 (T)
D027	120.000 (T)	D028	145.000 (T)
D028	100.000 (T)	D028	225.000 (T)
D029	100.000 (T)	D029	225.000 (T)
D029	15.000 (T)	D030	120.000 (T)
D035	145.000 (T)	D035	225.000 (T)
D035	120.000 (T)	D035	15.000 (T)
D035	100.000 (T)	D035	25.000 (T)
D039	145.000 (T)	D039	120.000 (T)
D039	225.000 (T)	D039	100.000 (T)
D040	145.000 (T)	D040	120.000 (T)
D040	225.000 (T)	D040	100.000 (T)
F001	0.000 (N)	F001	120.000 (T)
F001	145.000 (T)	F002	0.000 (N)
F002	25.000 (T)	F002	225.000 (T)
F002	120.000 (T)	F002	15.000 (T)
F002	100.000 (T)	F002	145.000 (T)
F003	0.000 (N)	F003	225.000 (T)
F003	25.000 (T)	F003	120.000 (T)
F003	145.000 (T)	F003	100.000 (T)
F005	0.000 (N)	F005	225.000 (T)
F005	120.000 (T)	F005	15.000 (T)
F005	25.000 (T)	F005	100.000 (T)

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP (Continued)

1000300847

F005	145.000 (T)	F006	0.000 (N)
F006	120.000 (T)	F007	0.000 (N)
F008	0.000 (N)	F009	0.000 (N)
F010	0.000 (N)	F011	0.000 (N)
F012	0.000 (N)	F017	0.000 (N)
F018	0.000 (N)	F019	0.000 (N)
F019	120.000 (T)	P003	120.000 (T)
P030	120.000 (T)	P064	120.000 (T)
P104	120.000 (T)	P106	120.000 (T)
U002	120.000 (T)	U003	0.000 (N)
U036	120.000 (T)	U061	120.000 (T)
U072	120.000 (T)	U080	120.000 (T)
U105	120.000 (T)	U106	120.000 (T)
U117	120.000 (T)	U133	0.000 (N)
U133	120.000 (T)	U134	0.000 (N)
U151	0.000 (N)	U151	120.000 (T)
U154	0.000 (N)	U159	0.000 (N)
U160	0.000 (N)	U161	0.000 (N)
U161	120.000 (T)	U165	120.000 (T)
U188	0.000 (N)	U188	120.000 (T)
U190	120.000 (T)	U197	0.000 (N)
U210	0.000 (N)	U210	120.000 (T)
U213	0.000 (N)	U220	0.000 (N)
U223	0.000 (N)	U226	0.000 (N)
U226	120.000 (T)	U228	0.000 (N)
U238	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Facility is a PCB generator, storer, transporter or permitted disposer (under PADS)

LUST:

Facility ID:	8901927	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	DAN NEILEY	Caller Agency:	GEN. UTILITIES
Caller Phone:	(516) 349-8989	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	06/09/1989		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	05/25/1989 12:00	Reported to Dept:	05/25/1989 14:10
Cleanup Ceased:	06/09/1989		
Last Inspection:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP (Continued)

1000300847

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 06/12/1989
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/29/1989

Facility ID: 9304538
Facility Contact: Not reported
Investigator: GIBBONS
Caller Name: JOHN SELVA
Caller Phone: (516) 575-8176
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AERO
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 07/27/1993
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 07/12/1993 08:00
Cleanup Ceased: 07/27/1993
Last Inspection: Not reported

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 07/12/1993 09:25

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: True
Spill Record Last Update: 07/28/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/15/1993

Facility ID: 9100585
Facility Contact: Not reported
Investigator: PARISH
Caller Name: JOHN AULMAN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported
Spill Cause: Tank Failure
Water Affected: Not reported
Spill Notifier: Responsible Party

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AEROSPACE CORP (Continued)

1000300847

Spill Date: 04/16/1991 09:00 Reported to Dept: 04/16/1991 09:35
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/25/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/17/1991

231

**NORTHROP GRUMMAN CORP
B12 NEW SOUTH STREET
BETHPAGE, NY**

LUST

S102232614
N/A

LUST:

Facility ID: 9602153	Region of Spill: 1
Facility Contact: RON PATEK	Facility Tele: (000) 000-0000
Investigator: T/T/F	Spill Type: UST
Caller Name: FRED LAUHARN	Caller Agency: DRY AS A BONE TANK TESTIN
Caller Phone: (516) 678-5115	Caller Extension: Not reported
Notifier Name: FRED LAUHARN	Notifier Agency: DRY AS A BONE INC
Notifier Phone: (516) 678-5115	Notifier Extension: Not reported
Spiller Contact: RON PATEK	Spiller Phone: (000) 000-0000
Spiller: NORTHROP GRUMMAN CORP	
Address: B12 NEW SOUTH STREET BETHPAGE	
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: 07/25/1996	
Spill Cause: Tank Test Failure	Resource Affected: On Land
Water Affected: Not reported	Spill Source: Other Commercial/Industrial
Spill Notifier: Tank Tester	PBS Number: 0-00000
Spill Date: 05/14/1996 17:04	Reported to Dept: 05/14/1996 18:07
Cleanup Ceased: Not reported	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 07/25/1996	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 05/14/1996	

231

**GRUMMAN AERO
GRUMMAN AERO
BETHPAGE, NY**

NY Spills

S102093710
N/A

SPILLS:

Facility ID: 8605970	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: O'BRIEN	Spill Type: Facility

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN AERO (Continued)

S102093710

Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN AERO		
Address:	Not reported		
	BETHPAGE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	12/22/1986	Spilled Code:	0008
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	25 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Commercial Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	12/19/1986 19:00
Spill Date:	12/19/1986 16:45	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/22/1986		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/28/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/23/1986		

231

GRUMMAN CORP
PLANT #14
BETHPAGE, NY

NY Spills

S102098304
N/A

SPILLS:

Facility ID:	9306232	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	JOHN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-4680	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN CORP		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	02/27/1995	Spilled Code:	0022
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	2 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	08/20/1993 14:30
Spill Date:	08/20/1993 11:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN CORP (Continued)

S102098304

Gross Leak/Fail: Not reported
Cleanup Ceased: 02/27/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/27/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/23/1993

231

**GRUMMAN
STEWART AVENUE
BETHPAGE, NY**

**LUST
NY Spills**

**S101276355
N/A**

LUST:

Facility ID: 9302538
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: SCOTT MATZEN
Caller Phone: (516) 586-4900
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN PLANT #1
Address: Not reported
Spill Class: No spill occurred. (Not Possible)
Spill Closed Dt: 07/27/1993
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 05/25/1993 12:00
Cleanup Ceased: 07/27/1993
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/28/1993
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/26/1993

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: F&N
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: Groundwater
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 05/25/1993 12:50

Facility ID: 9302825
Facility Contact: Not reported
Investigator: RMS
Caller Name: SCOTT
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN AEROSPACE
Address: Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: F&N
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 575-1529

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S101276355

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.
Spill Closed Dt: Not reported
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 06/02/1993 09:30
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/01/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/03/1993

Resource Affected: Groundwater
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 06/02/1993 10:45

SPILLS:

Facility ID: 9004904
Facility Contact: Not reported
Investigator: NONE
Caller Name: JOHN COFMAN
Caller Phone: (516) 575-2385
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GRUMMAN
Address: MAIL STOP B08-30 PLANT 30
BETHPAGE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GRUMMAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 08/03/1990
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Unknown
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 08/02/1990 09:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 08/03/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/03/1990

Spilled Code: 0066
Quant Recovered: 0 gallons
Resource Affected: In Sewer
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 08/02/1990 12:15
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Facility ID: 9211482
Facility Contact: Not reported
Investigator: KISPERT

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GRUMMAN (Continued)

S101276355

Caller Name:	JOHN SELVA	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-8176	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	02/27/1995		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	01/06/1993 14:00	Reported to Dept:	01/06/1993 14:40
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/27/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/28/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	01/07/1993		

231

GRUMMAN GRUMMANS GARAGE BETHPAGE, NY

NY Spills

S102096306
N/A

SPILLS:

Facility ID:	8909235	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	JOHN OHLMANN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	12/21/1989	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	20 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Other Non Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Affected Persons	Reported to Dept:	12/20/1989 15:30
Spill Date:	12/20/1989 09:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

GRUMMAN (Continued)

S102096306

Gross Leak/Fail: Not reported
 Cleanup Ceased: 12/21/1989
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: Not reported
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 12/21/1989

231

**GRUMMAN CORP
 STEWART AVE BLDG 30
 BETHPAGE, NY**

NY Spills

**S102089920
 N/A**

SPILLS:

Facility ID: 9100911
 Facility Contact: Not reported
 Investigator: WALSH
 Caller Name: BOB AGEE
 Caller Phone: (516) 575-6196
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: GRUMMAN CORP
 Address: Not reported
 Not reported

Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: GRUMMAN
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: (516) 575-2385

Spill Class: Not reported
 Spill Closed Dt: 06/17/1991
 Material Class: Petroleum
 Quantity Spilled: 10 gallons
 Spill Cause: Equipment Failure
 Water Affected: Not reported
 Spill Notifier: Responsible Party
 Spill Date: 04/23/1991 08:30
 Tank Number: Not reported
 Test method: Not reported
 Gross Leak/Fail: Not reported
 Cleanup Ceased: 06/17/1991
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 06/17/1991
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 04/24/1991

Spilled Code: 0022
 Quant Recovered: 0 gallons
 Resource Affected: On Land
 Spill Source: Other Commercial/Industrial
 PBS Number: Not reported
 Reported to Dept: 04/23/1991 09:00
 Tank Capacity: 0 Gallons
 Leak Rate: 0.00

232

**UNK
 3529 CORTNEY LANE
 BETHPAGE, NY**

LUST

**S100173586
 N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNK (Continued)

S100173586

LUST:

Facility ID:	9003089	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	HOFMANN	Spill Type:	Facility
Caller Name:	DOROTHY GALAN	Caller Agency:	CITIZEN
Caller Phone:	(516) 938-3720	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	12/17/1990	Resource Affected:	On Land
Spill Cause:	Tank Overfill	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Affected Persons	Reported to Dept:	06/18/1990 12:00
Spill Date:	06/14/1990 12:00		
Cleanup Ceased:	12/17/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/19/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/19/1990		

233

**S & S SUNOCO SERVICE
489 STEWART AVE
BETHPAGE, NY 11714**

**FINDS 1000328751
RCRIS-LQG NYD000701599**

RCRIS:

Owner: LVF CONT
(212) 555-1212

Contact: L MANZO
(516) 931-9244

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

FINDS:

Other Pertinent Environmental Activity Identified at Site:
- Civil judicial and administrative enforcement case against facility (under DOCKET)

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

233

SUNOCO
489 STEWART AVENUE
BETHPAGE, NY

LUST

S100169300
N/A

LUST:

Facility ID:	8902244	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	TONY LEUNG	Caller Agency:	DEC
Caller Phone:	(516) 751-7900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 931-9244
Spiller:	SUNOCO		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	06/09/1989	Spill Source:	Gas Station
Spill Cause:	Tank Failure	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	06/02/1989 11:00
Spill Notifier:	DEC		
Spill Date:	06/02/1989 11:00		
Cleanup Ceased:	06/09/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/12/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/07/1989		

233

SUNOCO S/S
489 STEWART AVENUE
BETHPAGE, NY

NY Spills

S102094187
N/A

SPILLS:

Facility ID:	8701169	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	WALEK	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SUNOCO S/S		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported	Spilled Code:	0022
Spill Closed Dt:	05/13/1987	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	On Land
Quantity Spilled:	0 gallons	Spill Source:	Gas Station
Spill Cause:	Housekeeping	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	05/12/1987 09:49
Spill Notifier:	Fire Department	Tank Capacity:	0 Gallons
Spill Date:	05/12/1987 12:00	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

SUNOCO S/S (Continued)

S102094187

Gross Leak/Fail: Not reported
Cleanup Ceased: 05/13/1987
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/17/1987
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/14/1987

Facility ID:	9107380	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	CAMPBELL	Spill Type:	Facility
Caller Name:	CARL BARKLAND	Caller Agency:	SUNOCO
Caller Phone:	(401) 461-9105	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	SUNOCO S/S		
Address:	Not reported		
	Not reported		

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	Not reported	Spilled Code:	0009
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	0 gallons	Resource Affected:	Groundwater
Spill Cause:	Unknown	Spill Source:	Gas Station
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	10/09/1991 14:00
Spill Date:	10/08/1991 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	07/21/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/11/1991		

233

PAGE SERVICE STATION
497 STEWART AVE
BETHPAGE, NY

AST

A100090642
N/A

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

PAGE SERVICE STATION (Continued)

A100090642

Nassau County AST:

Facility ID:	055611	Tank ID:	0002
Tank Location:	Indoors, Aboveground	Capacity (Gal):	250
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	NONE		
Piping Type:	Other	Material Type:	Waste
Description:	WASTE OIL		
Leak Detect:	NONE	Containment:	NONE
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	1255
Total Tanks:	Not reported		

233

NY Spills

S102400935
N/A

497 STEWART AVENUE BETHPAGE, NY

SPILLS:

Facility ID:	9608210	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	RBC	Spill Type:	UST
Caller Name:	BEATRICE PACKMOHR	Caller Agency:	AMERICAN ENVIRON. ASSESSM
Caller Phone:	(516) 454-6100	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	Not reported		
Address:	497 STEWART AVENUE BETHPAGE -		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0009
Quantity Spilled:	Unknown gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Local Agency	PBS Number:	Not reported
Spill Date:	10/01/1996 15:30	Reported to Dept:	10/01/1996 16:35
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	10/07/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/01/1996		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

234

LEVITTOWN, NY

NY Spills

S102101704
N/A

SPILLS:

Facility ID:	9501382	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	NCFM
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	05/03/1995		
Material Class:	Petroleum	Spilled Code:	0009
Quantity Spilled:	5 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department	PBS Number:	Not reported
Spill Date:	05/02/1995 22:44	Reported to Dept:	05/03/1995 00:14
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/03/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	05/04/1995		

Exemption 6

234

LEVITTOWN, NY

LUST

S101658099
N/A

LUST:

Facility ID:	9504460	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DECANDIA	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	EX-RESIDENT
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	[REDACTED]
Spiller:	[REDACTED]		
Address:	[REDACTED]		
	PLAINVIEW, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	On Land

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S101658099

Exemption 6

Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	07/13/1995 12:00	Reported to Dept:	07/13/1995 15:57
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/14/1995		

235

UNK
322 BROADWAY
BETHPAGE, NY

NY Spills

S102093794
N/A

SPILLS:

Facility ID:	8607163	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	RAYMOND	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 334-6722
Spiller:	326 CORP		
Address	115 S.SERVICE ROAD WESTBURY, NY		
Spill Class:	Not reported	Spilled Code:	0066
Spill Closed Dt:	05/04/1987	Quant Recovered:	0 gallons
Material Class:	Petroleum	Resource Affected:	Groundwater
Quantity Spilled:	169 gallons	Spill Source:	Other Commercial/Industrial
Spill Cause:	Unknown	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	02/24/1987 14:57
Spill Notifier:	Police Department	Tank Capacity:	0 Gallons
Spill Date:	02/24/1987 12:00	Leak Rate:	0.00
Tank Number:	Not reported		
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/04/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/30/1988		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/02/1987		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

235

WASHINGTON ST / BROADWAY
BETHPAGE, NY

NY Spills

S102236622
N/A

SPILLS:

Facility ID:	9512891	Region of Spill:	1
Facility Contact:	INSPECTOR DUBIN	Facility Tele:	(516) 659-1917
Investigator:	DECANDIA	Spill Type:	UST
Caller Name:	INSPECTOR DUBIN	Caller Agency:	NASSAU CO FIRE MARSHALL
Caller Phone:	(516) 659-1917	Caller Extension:	Not reported
Notifier Name:	FIRE DISPATCHER	Notifier Agency:	NASSAU COUNTY FIRE CONTRO
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNKNOWN		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0010
Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Unknown	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Unknown
Spill Notifier:	Fire Department	PBS Number:	Not reported
Spill Date:	01/17/1996 07:10	Reported to Dept:	01/17/1996 07:15
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/18/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/17/1996		

235

EASTERN EXTERMINATING CO INC
326 BROADWAY
BETHPAGE, NY 11714

FINDS

RCRIS-LQG

1000402157

NYD049202088

RCRIS:

Owner: Not reported
Contact: CHARLES KEATING
(517) 735-4142
Classification: Large Quantity Generator

Waste	Quantity
P122	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EASTERN EXTERMINATING CO INC (Continued)

1000402157

Used Oil Recyc: No

Violation Status: No violations found

235

**BETHPAGE STRIP SHOPPING
326-360 BROADWAY
BETHPAGE, NY**

**AST
UST**

**U003112050
N/A**

Nassau County UST:

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0328
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0330
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0332
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0334
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BETHPAGE STRIP SHOPPING (Continued)

U003112050

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0336
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0338
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0340
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0342
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BETHPAGE STRIP SHOPPING (Continued)

U003112050

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0344
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0352
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0354
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0356
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BETHPAGE STRIP SHOPPING (Continued)

U003112050

Facility ID: 057141
Tank Location: Indoors, Belowground
Tank Status: 6
Piping Type: Steel/Iron
Int Protection: Unknown
Ext Protection: UNKNOWN
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: 13

Tank ID: 0358
Capacity: 00000550
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 1255

Nassau County AST:

Facility ID: 057141
Tank Location: Outdoors, Aboveground
Tank Status: In Service
Int Protection: Unknown
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, FUEL #2
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0326
Capacity (Gal): 275
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: Yes
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Aboveground
Tank Status: 6
Int Protection: Unknown
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, FUEL #2
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0346
Capacity (Gal): 275
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: Yes
Install Date: 1255

Facility ID: 057141
Tank Location: Indoors, Aboveground
Tank Status: 6
Int Protection: Unknown
Ext Protection: PAINTED [e.g. asphaltic]
Piping Type: Steel/Iron
Description: OIL, FUEL #2
Leak Detect: NONE
Dispense Method: Gravity
Fill Type: Gravity
Total Tanks: Not reported

Tank ID: 0348
Capacity (Gal): 275
Tank Material: STEEL

Material Type: Fresh/Product
Containment: NONE
Product Gauge: Yes
Install Date: 1255

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

BETHPAGE STRIP SHOPPING (Continued)

U003112050

Facility ID:	057141	Tank ID:	0350
Tank Location:	Indoors, Aboveground	Capacity (Gal):	275
Tank Status:	6	Tank Material:	STEEL
Int Protection:	Unknown		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	OIL, FUEL #2	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	Yes
Dispense Method:	Gravity	Install Date:	1255
Fill Type:	Gravity		
Total Tanks:	Not reported		
Facility ID:	057141	Tank ID:	0360
Tank Location:	Outdoors, Aboveground	Capacity (Gal):	275
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	Unknown		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Steel/Iron		
Description:	OIL, FUEL #2	Containment:	NONE
Leak Detect:	NONE	Product Gauge:	Yes
Dispense Method:	Gravity	Install Date:	1255
Fill Type:	Gravity		
Total Tanks:	Not reported		

236

NY Spills

S102102300
N/A

LEVITTOWN, NY

SPILLS:

Facility ID:	9506521	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	GIFFORDS
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/28/1995	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	6 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	08/27/1995 23:12
Spill Date:	08/27/1995 22:12	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	08/28/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102102300

Exemption 6

Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/29/1995

237

LILCO
3585 COURTNEY LANE
BETHPAGE, NY

NY Spills

S102094135
N/A

SPILLS:

Facility ID: 8700561
Facility Contact: Not reported
Investigator: WALEK
Caller Name: Not reported
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: LILCO
Address: 175 EAST O.C.R.
HICKSVILLE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 420-6058

Spill Class: Not reported
Spill Closed Dt: 04/21/1987
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Traffic Accident
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 04/20/1987 13:45
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 04/21/1987
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 06/17/1987
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/22/1987

Spilled Code: 0017
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Other Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 04/20/1987 14:17
Tank Capacity: 0 Gallons
Leak Rate: 0.00

238

VACANT COMMERCIAL BLDG
1 LEXINGTON AVENUE
BETHPAGE, NY

NY Spills

S102446313
N/A

239

GIFFORD OIL
24 HUNTER LANE
LEVITTOWN, NY

LUST

S100173351
N/A

LUST:

Facility ID: 9000830

Region of Spill: 1

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

GIFFORD OIL (Continued)

S100173351

Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ANDERSON	Spill Type:	Facility
Caller Name:	HARRY LYNK	Caller Agency:	GIFFORD OIL
Caller Phone:	(516) 576-3000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GIFFORD OIL		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	04/27/1990	Resource Affected:	On Land
Spill Cause:	Tank Overfill	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Affected Persons	Reported to Dept:	04/23/1990 18:53
Spill Date:	04/23/1990 16:53		
Cleanup Ceased:	04/27/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/30/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/26/1990		

240

64 BARRISTER ROAD LEVITTOWN, NY

NY Spills

S102237688
N/A

SPILLS:

Facility ID:	9602072	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	UST
Caller Name:	TERRY CARBONE	Caller Agency:	HEMPSTEAD SANITATION DEPA
Caller Phone:	(516) 378-4210	Caller Extension:	326
Notifier Name:	MR JOHN GURERRA	Notifier Agency:	HEMPSTEAD SANITATION
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	TERRY CARBONE	Spiller Phone:	(516) 378-4210
Spiller:	HEMPSTEAD SANITATION		
Address:	1600 MERRICK ROAD MERRICK, NY 11566-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	05/14/1996	Spilled Code:	0010
Material Class:	Petroleum	Quant Recovered:	1 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Commercial Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	05/13/1996 10:12
Spill Date:	05/10/1996 09:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102237688

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/15/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/13/1996

241

**TRANSMISSION TECHNICIANS
305 BROADWAY
BETHPAGE, NY 11714**

**RCRIS-SQG
FINDS**

**1000791672
NYD987031895**

RCRIS:

Owner: TRANSMISSION TECHNICIANS INC
(516) 938-8139

Contact: WALTER LAUT
(516) 938-8139

Classification: Small Quantity Generator

Waste	Quantity
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

241

**BETHPAGE AUTO BODY
309 BROADWAY
BETHPAGE, NY 11714**

**RCRIS-SQG
FINDS**

**1000243982
NYD981085764**

RCRIS:

Owner: BOB SCHOPPMANN
(516) 796-4789

Contact: ROBERT SCHOPPMANN
(516) 822-5093

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	F001	0.000 (N)
F002	0.000 (N)	F003	0.000 (N)
F005	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

242

**PRENTICE ROAD/FIDDLER
LEVITTOWN, NY**

NY Spills

**S102236135
N/A**

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236135

SPILLS:

Facility ID:	9510364	Region of Spill:	1
Facility Contact:	CALLER	Facility Tele:	Not reported
Investigator:	SCHULZ	Spill Type:	UST
Caller Name:	TERRY CARBONE	Caller Agency:	TOWN OF HEMPSTEAD SANITAT
Caller Phone:	(516) 378-4210	Caller Extension:	326
Notifier Name:	PAUL POLSTER	Notifier Agency:	SUPERVISOR
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	HEMPSTEAD SANITATION		
Address:	1600 MERRICK ROAD MERRICK, NY 11566-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	11/27/1995		
Material Class:	Petroleum	Spilled Code:	0010
Quantity Spilled:	3 gallons	Quant Recovered:	3 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	11/17/1995 08:30	Reported to Dept:	11/17/1995 13:59
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	11/27/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/27/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/17/1995		

243

BETHPAGE, NY

LUST

S100148412
N/A

LUST:

Facility ID:	8912328	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	NCDH
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	[REDACTED]		
	BETHPAGE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	03/29/1990	Resource Affected:	On Land
Spill Cause:	Tank Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Health Department		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S100148412

Spill Date: 03/26/1990 12:00
Cleanup Ceased: 03/29/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/30/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/28/1990

Reported to Dept: 03/27/1990 15:00

244

LVF CONTRACTING
STEWART AVE & LAFAYETTE AVE
BETHPAGE, NY 11714

FINDS
RCRIS-LQG

1000108433
NYD982742934

RCRIS:

Owner: LVF CONTRACTING
(212) 555-1212

Contact: LENNY MANZO
(516) 546-3475

Classification: Large Quantity Generator

Waste	Quantity
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

245

BETHPAGE, NY

NY Spills

S102446485
N/A

246

LEVITTOWN, NY

NY Spills

S102137931
N/A

SPILLS:

Facility ID: 8904440
Facility Contact: Not reported
Investigator: GOERTZ
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MEENAN
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

LEVITTOWN, NY
Spill Class: Not reported
Spill Closed Dt: 08/17/1989
Material Class: Petroleum

Spilled Code: 0001

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102137931

Exemption 6

Quantity Spilled:	0 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	08/03/1989 12:00	Reported to Dept:	08/03/1989 15:15
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	08/17/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/18/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/04/1989		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

247

LEVITTOWN, NY

NY Spills

S102236331
N/A

SPILLS:

Facility ID: 9511366
Facility Contact: [REDACTED]
Investigator: Not reported
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: FRANK HOERAUF
Notifier Phone: (516) 783-1000
Spiller Contact: [REDACTED]
Spiller: MEENAN OIL
Address: 3020 BURNS AVE
WANTAGH, NY

Region of Spill: 1
Facility Tele: [REDACTED]
Spill Type: UST
Caller Agency: MEENAN OIL CO
Caller Extension: Not reported
Notifier Agency: MEENAN OIL CO
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Spill Class: Not reported
Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: 2 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 12/08/1995 13:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/08/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/08/1995

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 12/08/1995 14:40
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

248

BETHPAGE, NY

LUST
NY Spills

S100150512
N/A

LUST:

Facility ID: 9000164
Facility Contact: Not reported
Investigator: HAAS
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RESPONSIBLE PARTY
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY 11714
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. (Highly Improbable)
Spill Closed Dt: 01/28/1992
Spill Cause: Tank Failure
Water Affected: Not reported

Resource Affected: Groundwater
Spill Source: Private Dwelling

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100150512

Spill Notifier: Responsible Party
Spill Date: 04/01/1990 12:00
Cleanup Ceased: 01/28/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/18/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/10/1990
PBS Number: Not reported
Reported to Dept: 04/05/1990 16:40

SPILLS:

Facility ID: 9605606
Facility Contact: Not reported
Investigator: DECANDIA
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: UNKNOWN
Address: Not reported
Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: Not reported
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Unable/unwilling Responsible Party. Corrective action taken. (ISR)

Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Abandoned Drums
Water Affected: Not reported
Spill Notifier: Affected Persons
Spill Date: 07/31/1996 10:45
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/02/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/31/1996
Spilled Code: 0022
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Unknown
PBS Number: Not reported
Reported to Dept: 07/31/1996 16:30
Tank Capacity: 0 Gallons
Leak Rate: 0.00

248

BETHPAGE, NY

NY Spills

S102091533
N/A

SPILLS:

Facility ID: 9109846
Facility Contact: Not reported
Region of Spill: 1
Facility Tele: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102091533

Exemption 6

Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	GIFFORD OIL
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	
Spiller:			
Address:	BETHPAGE, NY		
Spill Class:	Not reported		
Spill Closed Dt:	12/15/1991		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	12/15/1991 13:30	Reported to Dept:	12/15/1991 16:24
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	12/15/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/18/1991		

249

EAGLES NEST
500 CENTRAL AVENUE
BETHPAGE, NY

NY Spills

S102400933
N/A

SPILLS:

Facility ID:	9608183	Region of Spill:	1
Facility Contact:	JOHN OHLMANN	Facility Tele:	(516) 575-2385
Investigator:	PARISH	Spill Type:	UST
Caller Name:	JOHN OHLMANN	Caller Agency:	NORTHUP GRUMMAN CORP
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	JOHN OHLMANN	Notifier Agency:	NORTHUP GRUMMAN CORP
Notifier Phone:	(516) 575-2385	Notifier Extension:	Not reported
Spiller Contact:	JOHN OHLMANN	Spiller Phone:	(516) 575-2385
Spiller:	EAGLES NEST		
Address:	500 CENTRAL AVENUE BETHPAGE		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0015
Quantity Spilled:	Unknown gallons	Quant Recovered:	0 gallons
Spill Cause:	Unknown	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Affected Persons	PBS Number:	Not reported
Spill Date:	09/24/1996 12:00	Reported to Dept:	10/01/1996 10:24
Tank Number:	Not reported	Tank Capacity:	0 Gallons

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

EAGLES NEST (Continued)

S102400933

Test method: Not reported Leak Rate: 0.00
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/02/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/01/1996

249

**EAGAL NEST
500 CENTRAL AVE
BETHPAGE, NY 11714**

**RCRIS-SQG 1000553989
FINDS NYD986964278**

RCRIS:

Owner: EAGELS NEST MOTOR SPORT INC
(516) 822-9494

Contact: JOSEPH PARISI
(516) 877-9494

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)
D008	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: Violations exist, high priority violator

There are 1 compliance/violation record(s) reported at this site:

Evaluation
Non-Financial Record Review

Area of Violation
Generator-All Requirements

Date of Compliance
07/29/1994

250

**10 COLLECTOR LANE
LEVITTOWN, NY**

**NY Spills S102236690
N/A**

SPILLS:

Facility ID:	9513370	Region of Spill:	1
Facility Contact:	HENDAWI	Facility Tele:	(516) 921-8253
Investigator:	NONE	Spill Type:	UST
Caller Name:	JIM CLEMENTE	Caller Agency:	SLOMINS OIL
Caller Phone:	(516) 932-7000	Caller Extension:	Not reported
Notifier Name:	JAMES BRUNGESS	Notifier Agency:	SLOMINS OIL
Notifier Phone:	(516) 932-7000	Notifier Extension:	Not reported
Spiller Contact:	JIM CLEMENTE	Spiller Phone:	(516) 932-7000
Spiller:	SLOMINS OIL		
Address:	125 LAUMAN LANE HICKSVILLE, NY 11801-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236690

Spill Closed Dt:	01/23/1996	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	1 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Commercial Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	01/23/1996 14:43
Spill Date:	01/23/1996 14:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/24/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/23/1996		

250

ON PAVEMENT IFO
10 COLLECTOR LANE
LEVITTOWN, NY

NY Spills

S102237570
N/A

SPILLS:

Facility ID:	9601247	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	UST
Caller Name:	JAMES KANE	Caller Agency:	SOLMANS OIL CO
Caller Phone:	(516) 932-7000	Caller Extension:	Not reported
Notifier Name:	DON SPRINGER	Notifier Agency:	SOLMANS OIL CO
Notifier Phone:	(516) 932-7000	Notifier Extension:	Not reported
Spiller Contact:	JAMES KANE	Spiller Phone:	(516) 932-7000
Spiller:	SLOMINS OIL CO		
Address:	125 LAUMAN LANE HICKSVILLE, NY 11810-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/25/1996	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	1 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	04/24/1996 17:37
Spill Date:	04/24/1996 17:20	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

ON PAVEMENT IFO (Continued)

S102237570

Spill Record Last Update: 04/26/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/24/1996

251

3697 COLLECTOR LANE
BETHPAGE, NY

LUST

S102234332
N/A

LUST:

Facility ID:	9600766	Region of Spill:	1
Facility Contact:	RICHARD DEISLER	Facility Tele:	(516) 935-0632
Investigator:	LAMANNO	Spill Type:	UST
Caller Name:	FRAN PAUL	Caller Agency:	GIFFORDS ENERGY
Caller Phone:	(516) 576-3000	Caller Extension:	Not reported
Notifier Name:	BILL HOBERG	Notifier Agency:	DRIVER
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 576-3100
Spiller:	GIFFORDS ENERGY		
Address:	171 EAST AMES COURT PLAINVIEW, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported	Resource Affected:	On Land
Spill Cause:	Tank Overfill	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	04/16/1996 15:35
Spill Date:	04/16/1996 15:20		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	04/17/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/16/1996		

252

BETHPAGE, NY

NY Spills

S102100120
N/A

SPILLS:

Facility ID:	9406845	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	GIFFORDS
Caller Phone:		Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:			
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102100120

Exemption 6

Spill Closed Dt:	08/22/1994	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	5 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	08/20/1994 15:54
Spill Date:	08/20/1994 15:40	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	08/22/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	08/22/1994		

253

TOWN OF HEMPSTEAD
GLENER / STONECUTTER RD
LEVITTOWN, NY

NY Spills

S102101729
N/A

SPILLS:

Facility ID:	9501581	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	THERESA CARBONE	Caller Agency:	TOWN OF HEMPSTEAD
Caller Phone:	(516) 378-4210	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	TOWN OF HEMPSTEAD		
Address:	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	05/08/1995	Spilled Code:	0022
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Commercial Vehicle
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	05/08/1995 11:25
Spill Date:	05/03/1995 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	05/08/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

TOWN OF HEMPSTEAD (Continued)

S102101729

UST Involvement: Fale
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/09/1995

254

STRIP STORES AT 419-429 CENTRAL AVE. BETHPAGE, NY

UST

U003138984
N/A

Nassau County UST:

Facility ID: 057176
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Steel/Iron
Int Protection: None
Ext Protection: NONE
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 6

Tank ID: 0001
Capacity: 00000275
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 0174

Facility ID: 057176
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Steel/Iron
Int Protection: None
Ext Protection: NONE
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 6

Tank ID: 0002
Capacity: 00000275
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 0174

Facility ID: 057176
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Steel/Iron
Int Protection: None
Ext Protection: NONE
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 6

Tank ID: 0003
Capacity: 00000275
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 0174

Facility ID: 057176
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Steel/Iron
Int Protection: None
Ext Protection: NONE
Description: OIL, FUEL #2
Leak Detect: OTHER
Dispense Method: Suction
Fill Type: Pumped
Total Tanks: 6

Tank ID: 0004
Capacity: 00000275
Tank Material: STEEL
Material Type: Fresh/Product

Containment: Other
Product Gauge: No
Install Date: 0174

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

STRIP STORES AT (Continued)

U003138984

Facility ID:	057176	Tank ID:	0005
Tank Location:	Indoors, Belowground	Capacity:	00000275
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	NONE		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0174
Total Tanks:	6		

Facility ID:	057176	Tank ID:	0006
Tank Location:	Indoors, Belowground	Capacity:	00000275
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Steel/Iron	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	NONE		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0174
Total Tanks:	6		

255

CITGO S/S
486 WANTAGH AVENUE
BETHPAGE, NY

NY Spills

S102400932
N/A

SPILLS:

Facility ID:	9608174	Region of Spill:	1
Facility Contact:	ED CUCCURULLO	Facility Tele:	(914) 561-4000
Investigator:	NONE	Spill Type:	UST
Caller Name:	LARRY FARIA	Caller Agency:	TYREE
Caller Phone:	(516) 249-3150	Caller Extension:	Not reported
Notifier Name:	BILL WATSON	Notifier Agency:	TYREE
Notifier Phone:	(516) 249-3150	Notifier Extension:	Not reported
Spiller Contact:	ED CUCCURULLO	Spiller Phone:	(914) 561-4000
Spiller:	CITGO S/S		
Address:	486 WANTAGH AVENUE BETHPAGE, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/01/1996	Spilled Code:	0009
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	Unknown gallons	Resource Affected:	On Land
Spill Cause:	Unknown	Spill Source:	Gas Station
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Other	Reported to Dept:	10/01/1996 07:39
Spill Date:	10/01/1996 06:30	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

CITGO S/S (Continued)

S102400932

Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/02/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/01/1996

256

BETHPAGE, NY

NY Spills

S102100810
N/A

SPILLS:

Facility ID: 9411764
Facility Contact: Not reported
Investigator: SCHULZ
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GIFFORDS
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 12/09/1994
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 12/03/1994 11:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/09/1994
Last Inspection: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 12/03/1994 12:23
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/12/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/06/1994

Exemption 6

257

LEVITTOWN, NY

NY Spills

S102092081
N/A

SPILLS:

Facility ID: 9202198
Facility Contact: Not reported
Investigator: DECANDIA
Caller Name: [REDACTED]
Caller Phone: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: CITIZEN
Caller Extension: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102092081

Exemption 6

Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: RESIDENCE
 Address: Not reported
 Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. (Highly Improbable)
 Spill Closed Dt: 07/27/1992
 Material Class: Petroleum
 Quantity Spilled: 0 gallons
 Spill Cause: Unknown
 Water Affected: Not reported
 Spill Notifier: Citizen
 Spill Date: 05/21/1992 16:00
 Tank Number: Not reported
 Test method: Not reported
 Gross Leak/Fail: Not reported
 Cleanup Ceased: 07/27/1992
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 07/25/1992
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 05/27/1992

Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported
 Spilled Code: 0022
 Quant Recovered: 0 gallons
 Resource Affected: On Land
 Spill Source: Passenger Vehicle
 PBS Number: Not reported
 Reported to Dept: 05/21/1992 16:25
 Tank Capacity: 0 Gallons
 Leak Rate: 0.00

258

NY Spills

S102099578
N/A

BETHPAGE, NY

SPILLS:

Facility ID: 9402618
 Facility Contact: Not reported
 Investigator: AUSTIN
 Caller Name: UNK
 Caller Phone: Not reported
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: [REDACTED]
 Address: [REDACTED]
 Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.
 Spill Closed Dt: Not reported
 Material Class: Petroleum
 Quantity Spilled: 1 gallons
 Spill Cause: Deliberate
 Water Affected: Not reported
 Spill Notifier: Local Agency
 Spill Date: 05/22/1994 12:00
 Tank Number: Not reported
 Test method: Not reported
 Gross Leak/Fail: Not reported

Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: Not reported
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported
 Spilled Code: 0022
 Quant Recovered: 0 gallons
 Resource Affected: On Land
 Spill Source: Passenger Vehicle
 PBS Number: Not reported
 Reported to Dept: 05/23/1994 13:50
 Tank Capacity: 0 Gallons
 Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102099578

Exemption 6

Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/24/1994
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/24/1994

259

MEENAN OIL CO
89 CONSTABLE LA
LEVITTOWN, NY

LUST

S101340067
N/A

LUST:

Facility ID:	9411241	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	MATTHEWS DRO	Spill Type:	Facility
Caller Name:	FRAN	Caller Agency:	MEENAN OIL CO
Caller Phone:	(516) 783-1000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 783-1000
Spiller:	MEENAN OIL CO		
Address:	3020 BURNS AVE WANTAGH, NY 11793		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/02/1995		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	11/22/1994 12:15	Reported to Dept:	11/22/1994 14:04
Cleanup Ceased:	08/02/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/04/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/23/1994		

260

LEVITTOWN, NY

LUST

S101508869
N/A

LUST:

Facility ID:	9415349	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LAMANNO	Spill Type:	Facility
Caller Name:		Caller Agency:	GIFFORDS

MAP FINDINGS

SiteEDR ID Number
EPA ID Number

S101508869

Exemption 6

S102237349
N/A

SPILLS:

TC172329.1s Page 501 of 520

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102237349

Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/15/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/01/1996

261

BETHPAGE, NY

NY Spills

S102097602
N/A

SPILLS:

Facility ID: 9012743
Facility Contact: Not reported
Investigator: KISPERT
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: COMMANDER OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

BETHPAGE, NY
Spill Class: Not reported
Spill Closed Dt: 05/09/1991
Material Class: Petroleum
Quantity Spilled: 35 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 03/12/1991 21:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 05/09/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/13/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/13/1991

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 03/12/1991 22:18
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

262

LEVITTOWN, NY

NY Spills

S102091633
N/A

SPILLS:

Facility ID: 9110749
Facility Contact: Not reported
Investigator: NONE
Caller Name: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: BENNETT FUEL CO

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102091633

Exemption 6

Caller Phone: [REDACTED]
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: [REDACTED]
 Address: Not reported
 Spill Class: Not reported
 Spill Closed Dt: 01/16/1992
 Material Class: Petroleum
 Quantity Spilled: 2 gallons
 Spill Cause: Equipment Failure
 Water Affected: Not reported
 Spill Notifier: Other
 Spill Date: 01/15/1992 08:30
 Tank Number: Not reported
 Test method: Not reported
 Gross Leak/Fail: Not reported
 Cleanup Ceased: 01/16/1992
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 01/16/1992
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered in Computer Data File: 01/16/1992

Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported
 Spilled Code: 0009
 Quant Recovered: 0 gallons
 Resource Affected: On Land
 Spill Source: Private Dwelling
 PBS Number: Not reported
 Reported to Dept: 01/15/1992 13:51
 Tank Capacity: 0 Gallons
 Leak Rate: 0.00

263

LUST

S100148406
N/A

LEVITTOWN, NY

LUST:

Facility ID: 8912267
 Facility Contact: Not reported
 Investigator: GOMEZ
 Caller Name: [REDACTED]
 Caller Phone: [REDACTED]
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: [REDACTED]
 Address: [REDACTED]
 Spill Class: Not reported
 Spill Closed Dt: 10/29/1990
 Spill Cause: Tank Failure
 Water Affected: Not reported
 Spill Notifier: Health Department
 Spill Date: 03/26/1990 12:15
 Cleanup Ceased: 10/29/1990
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported

Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: NCDH
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: [REDACTED]
 Resource Affected: Groundwater
 Spill Source: Private Dwelling
 PBS Number: Not reported
 Reported to Dept: 03/26/1990 12:45

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S100148406

Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/30/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/28/1990

264

RELiance
12 FARMEDGE ROAD
BETHPAGE, NY

NY Spills

S102101945
N/A

SPILLS:

Facility ID:	9503364	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LAMANNO	Spill Type:	Facility
Caller Name:	MIKE EMANUELO	Caller Agency:	RELiance
Caller Phone:	(516) 338-1180	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	RELiance		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	06/19/1995 09:00	Reported to Dept:	06/19/1995 09:44
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	06/20/1995		

265

BETHPAGE, NY

LUST

S100780906
N/A

LUST:

Facility ID:	9307110	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:		Caller Agency:	COMMANDER
Caller Phone:		Caller Extension:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

RESIDENCE (Continued)

S100780906

Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	RESIDENCE		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/13/1993		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	09/10/1993 15:00	Reported to Dept:	09/10/1993 16:31
Cleanup Ceased:	09/13/1993		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/14/1993		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/13/1993		

266

UNK
26 SILVERSMITH LANE
LEVITTOWN, NY

NY Spills

S102094413
N/A

SPILLS:

Facility ID:	8704339	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	ACAMPORA	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	09/01/1987	Spilled Code:	0066
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	0 gallons	Resource Affected:	On Land
Spill Cause:	Unknown	Spill Source:	Unknown
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Health Department	Reported to Dept:	08/25/1987 16:10
Spill Date:	08/25/1987 16:10	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	09/01/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

UNK (Continued)

S102094413

Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 09/03/1987
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/28/1987

267

TAHOE CLEANERS
436 N WANTAUGH AVE
BETHPAGE, NY 11714

FINDS 1000332269
RCRIS-LQG NYD981133705

RCRIS:

Owner: SANG CHONG
(516) 822-7103

Contact: CHONG SON
(516) 822-7103

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D039	0.000 (N)	F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

268

LEVITTOWN, NY

NY Spills S102099213
N/A

SPILLS:

Facility ID: 9314967
Facility Contact: Not reported
Investigator: AUSTIN
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: GIFFORDS
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Unknown Responsible Party. Corrective action taken. (ISR)

Spill Closed Dt: 02/23/1995
Material Class: Petroleum
Quantity Spilled: 0 gallons
Spill Cause: Unknown
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 03/22/1994 14:15
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 02/23/1995
Last Inspection: Not reported
Cleanup Meets Standard: True

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 03/22/1994 14:21
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

Exemption 6

(Continued)

S102099213

Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/24/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/23/1994

269

MEENAN OIL
20 TRAPPER LANE
LEVITTOWN, NY

LUST

S101173961
N/A

LUST:

Facility ID:	9404791	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	CAROLYN	Caller Agency:	MEENAN
Caller Phone:	(516) 781-1200	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 781-1200
Spiller:	MEENAN OIL		
Address:	Not reported		

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt:	07/08/1994	Resource Affected:	On Land
Spill Cause:	Tank Overfill	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	07/07/1994 16:15
Spill Date:	07/07/1994 15:30		
Cleanup Ceased:	07/08/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/08/1994		

270

COMMANDER
72 CONSTELLATION ROAD
LEVITTOWN, NY

LUST

S101508021
N/A

LUST:

Facility ID:	9414871	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	ELENA ZAZZERA	Caller Agency:	COMMANDER
Caller Phone:	(516) 922-7000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

COMMANDER (Continued)

S101508021

Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	COMMANDER		
Address	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	02/13/1995		
Spill Cause:	Tank Overfill	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	02/12/1995 13:00	Reported to Dept:	02/12/1995 13:27
Cleanup Ceased:	02/13/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/13/1995		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

271

BETHPAGE, NY

LUST

S101508878
N/A

Exemption 6

LUST:

Facility ID: 9415625

Facility Contact: Not reported

Investigator: Not reported

Caller Name: [REDACTED]

Caller Phone: [REDACTED]

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Spiller: [REDACTED]

Address

PLAINVIEW

Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported

Spill Cause: Tank Failure

Water Affected: Not reported

Spill Notifier: Affected Persons

Spill Date: 03/02/1995 11:13

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: False

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: Not reported

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 03/03/1995

Region of Spill: 1

Facility Tele: Not reported

Spill Type: Facility

Caller Agency: RESIDENCE

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone: [REDACTED]

Resources Affected: On Land

Spill Source: Private Dwelling

PBS Number: Not reported

Reported to Dept: 03/02/1995 11:13

272

LEVITTOWN, NY

NY Spills

S102236436
N/A

SPILLS:

Facility ID: 9511861

Facility Contact: [REDACTED]

Investigator: SCHULZ

Caller Name: [REDACTED]

Caller Phone: [REDACTED]

Notifier Name: [REDACTED]

Notifier Phone: [REDACTED]

Spiller Contact: Not reported

Spiller: UNK

Address: Not reported

Not reported

Spill Class: Known release that creates potential for fire or hazard. DEC Response. Unknown Responsible Party. Corrective action taken. (ISR)

Spill Closed Dt: Not reported

Material Class: Raw Sewage

Quantity Spilled: 0 gallons

Spill Cause: Abandoned Drums

Water Affected: Not reported

Spill Notifier: Affected Persons

Region of Spill: 1

Facility Tele: [REDACTED]

Spill Type: UST

Caller Agency: NYS DEC DHWR

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone: Not reported

Spilled Code: 0064

Quant Recovered: 0 gallons

Resource Affected: On Land

Spill Source: Unknown

PBS Number: Not reported

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236436

Spill Date:	12/19/1995 08:00	Reported to Dept:	12/19/1995 09:25
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/12/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/19/1995		

273

LEVITTOWN, NY

NY Spills

S102102041
N/A

Exemption 6

SPILLS:

Facility ID:	9504164	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	SCHULZ	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	LEVITTOWN, NY		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	07/14/1995	Spilled Code:	0022
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	0 gallons	Resource Affected:	Groundwater
Spill Cause:	Deliberate	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Citizen	Reported to Dept:	07/06/1995 16:13
Spill Date:	07/06/1995 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	07/14/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	07/22/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	07/11/1995		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

274

BETHPAGE, NY

NY Spills

S102101186
N/A

SPILLS:

Facility ID:	9414291	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORDS
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	01/30/1995		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	1 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	01/28/1995 13:15	Reported to Dept:	01/28/1995 13:15
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	01/30/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/31/1995		

Exemption 6

275

LEVITTOWN, NY

NY Spills

S102097687
N/A

SPILLS:

Facility ID:	9213999	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DECANDIA	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	GIFFORDS
Caller Phone:	[REDACTED]	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	[REDACTED]		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	03/02/1995		
Material Class:	Petroleum	Spilled Code:	0001

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102097687

Exemption 6

Quantity Spilled: 0 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 03/22/1993 10:00
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 03/02/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/02/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/22/1993

Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 03/22/1993 13:07
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

275

16 COMET LANE
LEVITTOWN, NY

NY Spills

S102236336
N/A

SPILLS:

Facility ID: 9511398
Facility Contact: SCANLON
Investigator: Not reported
Caller Name: SANTORO
Caller Phone: (516) 576-3000
Notifier Name: EMPLOYEE
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: GIFFORDS OIL
Address: 171 EAST AMES CT
PLAINVIEW, NY 11803-

Region of Spill: 1
Facility Tele: (516) 579-2877
Spill Type: UST
Caller Agency: GIFFORDS OIL
Caller Extension: Not reported
Notifier Agency: TIM SPRINGER
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: Not reported
Material Class: Petroleum
Quantity Spilled: 1 gallons
Spill Cause: Human Error
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 12/09/1995 14:25
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False

Spilled Code: 0001
Quant Recovered: 1 gallons
Resource Affected: On Land
Spill Source: Tank Truck
PBS Number: Not reported
Reported to Dept: 12/09/1995 14:57
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Spill Record Last Update: 12/09/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/09/1995

276

LEVITTOWN, NY

NY Spills

S102236255
N/A

SPILLS:

Facility ID: 9510957
Facility Contact: [REDACTED]
Investigator: NONE
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: SVC -DOUG WILLIAMS
Notifier Phone: (516) 576-3000
Spiller Contact: [REDACTED]
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: [REDACTED]
Spill Type: UST
Caller Agency: GIFFORDS ENERGY
Caller Extension: Not reported
Notifier Agency: GIFFORDS ENERGY
Notifier Extension: Not reported
Spiller Phone: [REDACTED]

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 12/01/1995
Material Class: Petroleum
Quantity Spilled: 1 gallons

Spilled Code: 0001
Quant Recovered: Unknown gallons

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102236255

Exemption 6

Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 11/30/1995 19:36
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 12/01/1995
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 12/04/1995
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 11/30/1995

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 11/30/1995 19:55
Tank Capacity: 0 Gallons
Leak Rate: 0.00

277

RELIANCE
46 EDNA LANE
BETHPAGE, NY

NY Spills

S102096646
N/A

SPILLS:

Facility ID: 9001156
Facility Contact: Not reported
Investigator: HAAS
Caller Name: DAVE WAGNER
Caller Phone: (516) 931-6800
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: RELIANCE
Address: 477 WEST JOHN STREET
HICKSVILLE, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: RELIANCE UTILITIES
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 913-1131

Spill Class: Not reported
Spill Closed Dt: 05/03/1990
Material Class: Petroleum
Quantity Spilled: 2 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 05/01/1990 08:30
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 05/03/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 05/04/1990
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 05/03/1990

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 05/01/1990 08:37
Tank Capacity: 0 Gallons
Leak Rate: 0.00

MAP FINDINGS

Map ID Direction Distance	Site	Database(s)	EDR ID Number EPA ID Number
---------------------------------	------	-------------	--------------------------------

278	GIFFORDS OIL 20 CELESTIAL LANE LEVITTOWN, NY	NY Spills	S102097522 N/A
-----	---	-----------	-------------------

SPILLS:

Facility ID:	9011908	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	CARL KAMPFER	Caller Agency:	GIFFORDS
Caller Phone:	(516) 576-3000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 576-3000
Spiller:	GIFFORDS OIL		
Address	171 EAST AMES COURT PLAINVIEW, NY		
Spill Class:	Not reported		
Spill Closed Dt:	02/14/1991	Spilled Code:	0001
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	5 gallons	Resource Affected:	On Land
Spill Cause:	Human Error	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	02/13/1991 12:05
Spill Date:	02/13/1991 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	02/14/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	02/14/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	02/14/1991		

279	MEENAN OIL 4 SATELITE LANE LEVITTOWN, NY	LUST	S100490580 N/A
-----	---	------	-------------------

LUST:

Facility ID:	9102685	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	LARRY TREFCER	Caller Agency:	MEENAN OIL
Caller Phone:	(516) 783-1000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 783-1000
Spiller:	MEENAN OIL		
Address	3020 BURNS AVENUE WANTAGH, NY		
Spill Class:	Not reported		
Spill Closed Dt:	06/07/1991	Resource Affected:	On Land
Spill Cause:	Tank Overfill	Spill Source:	Tank Truck
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MEENAN OIL (Continued)

S100490580

Spill Date: 06/06/1991 11:30
Cleanup Ceased: 06/07/1991
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 06/11/1991
Reported to Dept: 06/06/1991 12:35

279

MEENAN OIL
4 SATELLITE LANE
LEVITTOWN, NY

LUST

S100169037
N/A

LUST:

Facility ID: 8808861
Facility Contact: Not reported
Investigator: NONE
Caller Name: LARRY TREFEER
Caller Phone: (516) 783-1000
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: MEENAN OIL
Address: 3020 BURNS AVENUE
WANTAGH, NY
Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MEENAN OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 783-1000
Spill Class: Not reported
Spill Closed Dt: 02/13/1989
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 02/11/1989 14:00
Cleanup Ceased: 02/13/1989
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 02/14/1989
Resource Affected: On Land
Spill Source: Tank Truck
PBS Number: Not reported
Reported to Dept: 02/13/1989 14:50

280

LEVITTOWN, NY

LUST

S100147632
N/A

LUST:

Facility ID: 8900767
Facility Contact: Not reported
Investigator: WALEK
Caller Name: [REDACTED]
Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MILRO SERVICES

Exemption 6

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S100147632

Exemption 6

Caller Phone: [REDACTED]
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: [REDACTED]
 Address: [REDACTED]
 LEVITTOWN, NY
 Spill Class: Not reported
 Spill Closed Dt: 04/28/1989
 Spill Cause: Tank Failure
 Water Affected: Not reported
 Spill Notifier: Other
 Spill Date: 04/21/1989 12:00
 Cleanup Ceased: 04/28/1989
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 05/01/1989
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 04/26/1989
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported
 Resource Affected: On Land
 Spill Source: Private Dwelling
 PBS Number: Not reported
 Reported to Dept: 04/25/1989 10:56

281

NY Spills

S102400764
N/A

BETHPAGE, NY

SPILLS:

Facility ID: 9605604
 Facility Contact: [REDACTED]
 Investigator: [REDACTED]
 Caller Name: [REDACTED]
 Caller Phone: [REDACTED]
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: UNKNOWN
 Address: Not reported
 Not reported
 Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)
 Spill Closed Dt: 10/07/1996
 Material Class: Petroleum
 Quantity Spilled: Unknown gallons
 Spill Cause: Unknown
 Water Affected: Not reported
 Spill Notifier: Citizen
 Spill Date: 07/31/1996 12:00
 Tank Number: Not reported
 Test method: Not reported
 Gross Leak/Fail: Not reported
 Cleanup Ceased: Not reported
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Region of Spill: 1
 Facility Tele: [REDACTED]
 Spill Type: UST
 Caller Agency: Not reported
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported
 Spilled Code: 0066
 Quant Recovered: 0 gallons
 Resource Affected: On Land
 Spill Source: Unknown
 PBS Number: Not reported
 Reported to Dept: 07/31/1996 16:30
 Tank Capacity: 0 Gallons
 Leak Rate: 0.00

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

(Continued)

S102400764

Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 10/07/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/31/1996

282

LEVITTOWN, NY

NY Spills

S102091580
N/A

SPILLS:

Facility ID: 9110293
Facility Contact: Not reported
Investigator: DEROSA
Caller Name: [REDACTED]
Caller Phone: [REDACTED]
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: [REDACTED]

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MEENAN OIL
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

LEVITTOWN, NY

Spill Class: Known release with minimal potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 07/21/1992
Material Class: Petroleum
Quantity Spilled: 200 gallons
Spill Cause: Equipment Failure
Water Affected: Not reported
Spill Notifier: Other
Spill Date: 12/31/1991 13:45
Tank Number: Not reported
Test method: Not reported
Gross Leak/Fail: Not reported
Cleanup Ceased: 07/21/1992
Last Inspection: Not reported

Spilled Code: 0001
Quant Recovered: 0 gallons
Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 12/31/1991 14:52
Tank Capacity: 0 Gallons
Leak Rate: 0.00

Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/27/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/02/1992

Exemption 6

283

MEENAN OIL
29 CELESTIAL LANE
LEVITTOWN, NY

NY Spills

S102097538
N/A

SPILLS:

Facility ID: 9012061
Facility Contact: Not reported
Investigator: KISPERT
Caller Name: LARRY TREFIER

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: MEENAN OIL

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

MEENAN OIL (Continued)

S102097538

Caller Phone:	(516) 783-1000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	MEENAN OIL		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	03/12/1991		
Material Class:	Petroleum	Spilled Code:	0001
Quantity Spilled:	3 gallons	Quant Recovered:	0 gallons
Spill Cause:	Equipment Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Tank Truck
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	02/19/1991 12:00	Reported to Dept:	02/19/1991 14:10
Tank Number:	Not reported	Tank Capacity:	0 Gallons
Test method:	Not reported	Leak Rate:	0.00
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	03/12/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	03/13/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/20/1991		

284

LILCO
3675 STOKES AVENUE
BETHPAGE, NY

NY Spills

S102090296
N/A

SPILLS:

Facility ID:	9105691	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	DAVE BURGER	Caller Agency:	LILCO
Caller Phone:	(516) 391-6142	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	LILCO		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	08/27/1991	Spilled Code:	0016
Material Class:	Petroleum	Quant Recovered:	0 gallons
Quantity Spilled:	1 gallons	Resource Affected:	On Land
Spill Cause:	Equipment Failure	Spill Source:	Other Non Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	08/26/1991 11:31
Spill Date:	08/19/1991 12:00	Tank Capacity:	0 Gallons
Tank Number:	Not reported	Leak Rate:	0.00
Test method:	Not reported		
Gross Leak/Fail:	Not reported		
Cleanup Ceased:	08/27/1991		

MAP FINDINGS

Map ID
Direction
Distance

Site

Database(s)

EDR ID Number
EPA ID Number

LILCO (Continued)

S102090296

Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 08/28/1991
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 08/28/1991

285

LUST

S100666433
N/A

LEVITTOWN, NY

LUST:

Exemption 6

Facility ID: 9003727
Facility Contact: Not reported
Investigator: NCDH
Caller Name: [REDACTED]
Caller Phone: Not reported
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: [REDACTED]
Address: Not reported
Not reported
Spill Class: Not reported
Spill Closed Dt: 07/03/1990
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Health Department
Spill Date: 07/02/1990 13:00
Cleanup Ceased: 07/03/1990
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: Not reported
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 07/06/1990

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCDH
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 07/03/1990 09:28

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
BETHPAGE	1000178350	LILCO-LEVITTOWN SUBSTATION	RT 107 N/O HEMPSTEAD TPK	11714	FINDS, RCRIS-LQG	
BETHPAGE	S100491639	NORTHVILLE GAS STATION	RTE 107 WANTAGH AVENUE	11714	LUST	9206489
BETHPAGE	1000556023	NYS DOT BIN 1037909	RTE 135 OVER HAYPATH RD	11714	FINDS, RCRIS-LQG	
BETHPAGE	1000556026	NYS DOT BIN 1037860	RTE 135 UNDER CENTRAL AVE	11714	FINDS, RCRIS-LQG	
BETHPAGE	1000890356	NYS DOT BIN 1037859	RTE 135 OVER BOUNDARY AVE	11714	FINDS, RCRIS-LQG	
BETHPAGE	1000890357	NYS DOT BIN 1037899	RTE 135 OVER BROADWAY	11714	FINDS, RCRIS-LQG	
BETHPAGE	S100149985	OGS/NYS	BETHPAGE STATE PARK	11714	LUST	8803698
BETHPAGE	S101657986	BETHPAGE STATE PARK	BETHPAGE STATE PARK	11714	LUST	8807183
BETHPAGE	A100090114	BETHPAGE W.D. PLANT 5	BROADWAY	11714	AST	
BETHPAGE	A100090457	BETHPAGE SCH.BUS GARAGE	BROADWAY	11714	AST	
BETHPAGE	U002264560	JOHN F. KENNEDY J.H.S.	BROADWAY	11714	UST	052343
BETHPAGE	S100491423	UNK	339 BROADWAY / WASHINGTON	11714	LUST	9204651
BETHPAGE	U002264561	CENTRAL BLVD SCHOOL	CENTRAL AVE.	11714	UST	052345
BETHPAGE	S100664204		1 FAMS CT / HAYPATH ROAD	11714	LUST	8604091
BETHPAGE	1000144478	TEXACO SVC STA	HEMPSTEAD TPK & STEWART	11714	FINDS, RCRIS-LQG	
BETHPAGE	S101508890	OCEAN PETROLEUM	HEMPSTEAD TPK / RTE 107	11714	LUST	9416174
BETHPAGE	1000244487	BETHVIEW WHEEL ALIGNMENT INC	HICKSVILLE RD & CENTRAL AVE	11714	FINDS, RCRIS-LQG	
BETHPAGE	S102234297	BETHPAGE TOWNHOUSES	KENSINGTON LANE / RTE 107	11714	LUST	9515468
BETHPAGE	S100665895	UNK	MANCHESTER DR/PLAINVIEW R	11714	LUST	8906174
BETHPAGE	S100664230	MR.BAR-B-QUE	NIBBE LANE / LEXINGTON AV	11714	LUST	8706872
BETHPAGE	1000148518	NAVAL WEAPONS INDUSTRIAL RESERVE PLANT	SOUTH OYSTER BAY ROAD	11714	CERCLIS, FINDS	
BETHPAGE	S100169909	MOBIL OIL	SO OYSTER BAY / STEWART A	11714	LUST	8908752
BETHPAGE	U002096782	BETHPAGE W.D. PLANT 6	PARK LANE	11714	UST	001190
BETHPAGE	1000407948	NORTHERN ALLOYS INC	PLAINVIEW RD & MANCHESTER	11714	RCRIS-SQG, FINDS	
BETHPAGE	U001446275	CHARLES CAMPAGNE SCHOOL	PLAINVIEW RD.	11714	UST	052346
BETHPAGE	1001028645	NYS DOT BIN 1037880	POWELL AVE OVER RTE 135	11714	RCRIS-LQG	
BETHPAGE	1001079769	NORTHVILLE STATION	STATE RD 107 & WANTAGH AVE	11714	RCRIS-SQG	
BETHPAGE	1000432425	SERVICE STATION	N/S STEWART & CHERRY AVES	11714	FINDS, RCRIS-LQG	
BETHPAGE	U001854915	A & D SHELL	STEWART & FARMERS AVENUES	11714	UST	041021
BETHPAGE	U002264557	NORTHEdge SCHOOL	STEWART AVE.	11714	UST	052270
BETHPAGE	U002264558	JOHN H. WEST SCHOOL	STEWART & BOUNDARY AVES.	11714	UST	052272
BETHPAGE	1000243981	BETHPAGE COMMUNITY PARK	STEWART AVE	11714	RCRIS-SQG, FINDS, LUST, UST	9110161
BETHPAGE	S100521004	NAVAL WEAPONS IND. RESERVE PLANT	STEWART AVENUE	11714	SHWS	
BETHPAGE	S101173536	TOWN OF OYSTER BAY	STEWART AVENUE	11714	LUST	9409098
BETHPAGE	S101340109	DIFAZIO ELECTRIC (G.C.)	STEWART AVE	11714	LUST	9411984
BETHPAGE	S102235111		STEWART AVE/PLANT #3	11714	LUST	9603860
BETHPAGE	S100490592	ISLAND TRANSPORT CORP	SOUTH WAREHOUSE AT GRUMMA	11714	LUST	9105673
BETHPAGE	S100560179	NCDPW	WINDING ROAD	11714	LUST	9303993
BETHPAGE	S100666848	NCDPW HAZ WASTE	WINDING ROAD	11714	LUST	9300577
BETHPAGE	S100666850	NCDWP HAZ WASTE	WINDING ROAD	11714	LUST	9300626
BETHPAGE	S102234974	FIREMENS TRAINING CENTER	WINDING RD / ROUND SWAMP	11714	LUST	9105485
FARMINGDALE	1000243984	BETHPAGE STATE PARK	BETHPAGE PKY	11714	RCRIS-SQG, FINDS, LUST	8807195
GARDEN CITY	1000105580	MTA BUS GARGE FORMERLY PUREX IND INC	COMMERCIAL AVE MITCHELL FIELD	11756	RCRIS-LQG	

Exemption 6

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
HICKSVILLE	1000335584	EXXON CO USA - HICKSVILLE	RTE 106 & 107	11801	FINDS, RCRIS-LQG	
HICKSVILLE	1000144487	TEXACO SERVICE STATION - 13-006-0196	RTE 107 & BETHPAGE RD	11801	FINDS, RCRIS-LQG	
HICKSVILLE	1000556708	NEWBAR SERVICE CENTER	1 BARTEL LANE	11801	RCRIS-SQG, FINDS	
HICKSVILLE	1000555555	M G M TOWING & AUTOMOTIVE	870 S BROADWAY - FRONT OF BLDG	11801	RCRIS-SQG, FINDS	
HICKSVILLE	1000872226	WHOLE SALE TIRE CO	358 B BROADWAY MALL	11801	RCRIS-SQG	
HICKSVILLE	1000335580	EXXON CO	BROADWAY & RTE 106	11801	RCRIS-SQG, FINDS	
HICKSVILLE	U003080080	SLOMINS INC.	75 LAUMAN LANE	11801	AST, UST	1-3240
HICKSVILLE	S102232601	HICKSVILLE POST OFFICE	109 LUDY ST	11801	LUST	9515845
HICKSVILLE	1000140663	S S PREMISES C/O SHELL OIL CO	500 OLD CO RD & LEVITTOWN RD	11801	FINDS, RCRIS-LQG	
HICKSVILLE	1000144528	TEXACO SVC STA	180 OLD COUNTRY RD	11801	FINDS, RCRIS-LQG	
HICKSVILLE	1000381240	FRESH START CLEANERS	212 OLD COUNTRY RD	11801	FINDS, RCRIS-LQG	
HICKSVILLE	1000402170	WESTERN AUTO REPAIR	67 OLD COUNTRY RD	11801	RCRIS-SQG	
HICKSVILLE	1000789398	GETTY SVC STA	178 OLD COUNTRY RD	11801	RCRIS-SQG, FINDS	
HICKSVILLE	1000990180	SUNRISE PROFESSIONAL SERVICE INC	73A OLD COUNTRY RD	11801	RCRIS-SQG	
HICKSVILLE	1000457594	HICKSVILLE FIRE DIST	STRONG ST FIRE STATION	11801	FINDS, RCRIS-LQG	
JERUSALEM	S101102772	KEUKA LAKE STATE PARK	ROUTE 54A CAMP COMFORT ST	11714	LUST	9400514
JERUSALEM	S102234040			11714	LUST	9515023
JERUSALEM	S101340786	KEUKA COLLEGE	KEUKA PARK KEUKA COLLEGE	11714	LUST	9413939
LEVITTOWN	S100666417			11756	LUST	9002819
LEVITTOWN	U001446252	GENEVA N. GALLOW SCHOOL	FARMEDGE RD & CARPENTER	11756	UST	052323
LEVITTOWN	U001855031	STEVEN KAROPCZYK SCHL	FARMEDGE ROAD	11756	UST	052322
LEVITTOWN	U001445718	D&J CIRCLE SALES 120379	3285 HEMP TPK & JERUSALEM	11756	UST	040142
LEVITTOWN	S100147448	MAJOR FUEL OIL CO	LAUREL LA / ORCHARD ST	11756	LUST	8807549
LEVITTOWN	U001446126	LEE ROAD SCHOOL	LEE ROAD	11756	UST	052219
LEVITTOWN	S100168939	MEENAN OIL	36 OAK TREE LANE	11756	LUST	8807457
LEVITTOWN	U001446132	SALK MIDDLE SCHOOL	OLD JERUSALEM ROAD	11756	UST	052225
LEVITTOWN	U001855009	MACARTHUR HIGH SCHOOL	OLD JERUSALEM ROAD	11756	UST	052220
LEVITTOWN	U001855052	RED SCHOOL HOUSE	OLD JERUSALEM ROAD	11756	UST	052384
LEVITTOWN	S102232956			11756	LUST	8603980
LEVITTOWN	S101508043	MEENAN OIL	17 SHELTA LANE	11756	LUST	9415247
LEVITTOWN	S100174807	RELIANCE UTILITIES	10 SHERPARD LANE	11756	LUST	9101321
LEVITTOWN	S100174580	RELIANCE	29 SPRINGTIME LANE EAST	11756	LUST	9012363
LEVITTOWN	S100148673	CASTEL COAL & OIL CO.	STOKES SCHOOL/CONDOR RD	11756	LUST	8607293
LEVITTOWN	U001855032	ISLAND TREES HIGH SCHOOL	STRAIGHT LANE	11756	UST	052324
LEVITTOWN	S100666484	UFI INC	STRAIGHT LANE	11756	LUST	9006235
LEVITTOWN	1000300430	SUMMIT LANE SCHOOL	SUMMIT LANE	11756	FINDS, RCRIS-LQG, UST	052226
LEVITTOWN	S100177590	NCDPW	NO WANTAGH AVENUE	11756	LUST	9111735
LEVITTOWN	S100665851			11756	LUST	8903731
NASSAU COUNTY	1000125395	HEMPSTEAD TOWNSHIP OF DEPT OF SANIT	1600 MERRICK RD		RCRIS-SQG, FINDS, SWF/LF	
NASSAU COUNTY	1000231519	LONG BEACH WATER POLLUTION CONTROL	NATIONAL BLVD AT BAY		FINDS, SWF/LF, RCRIS-LQG	
OLD BETHPAGE	S101008281	NASSAU COUNTY FIRE TRAINING CENTER	WINDING ROAD	11714	SHWS	
PLAINEDGE	1000556022	NYS DOT BIN 108119	RTE 135 OVER RTE 24	11714	FINDS, RCRIS-LQG	
PLAINEDGE	U001447244	TOB-SR CITIZ HOUSNG-PLNVW	50 HICKSVILLE RD	11756	UST	055974
PLAINVIEW	S100664144	UNK	RTE 135	11803	LUST, NY Spills	8902553
PLAINVIEW	S101658263	VEHICLE	RTE 495 WB / EXIT 42	11803	LUST	9507635
PLAINVIEW	S100665795	ENVIRONMENTAL DRILLING	AMES CT / COMMERCIAL DR	11803	LUST	8809881
PLAINVIEW	1000258693	STRATFORD ROAD SCHOOL	BEDFORD RD-ESSEX RD	11803	FINDS, RCRIS-LQG	

ORPHAN SUMMARY

City	EDR ID	Site Name	Site Address	Zip	Database(s)	Facility ID
PLAINVIEW	S100664054	JLD BETHPAGE HIGH SCHOOL	CENTRAL PARK ROAD	11803	LUST	9007474
PLAINVIEW	U001855029	FERN PLACE ELEMENTARY SCH	FERN PLACE AND ORCHARD ST	11803	UST	052316
PLAINVIEW	U002264562	KRAMER LANE SCHOOL	KRAMER LA.	11803	UST	052347
PLAINVIEW	1000273053	PARKWAY ELEMENTARY SCHOOL	MANETTO HILL RD-CENTRAL PK RD	11803	FINDS, RCRIS-LQG	
PLAINVIEW	1000241638	MACHINE COMPONENTS CORP	70 NEW RD	11803	FINDS, RCRIS-LQG	
PLAINVIEW	1000258696	PLAINVIEW OFFICE COMPLEX	OLD COUNTRY RD	11803	FINDS, RCRIS-LQG	
PLAINVIEW	1001028650	NYS DOT BIN 1037910	OLD COUNTRY RD OVER RTE 135	11803	RCRIS-LQG	
PLAINVIEW	S100148690	NY TELEPHONE CO.	OLD COUNTRY ROAD	11803	LUST	8607478
PLAINVIEW	S100171919	SHELL S/S	OLD COUNTRY ROAD	11803	LUST	8706265
PLAINVIEW	S100177607	SHELL OIL	OLD COUNTRY ROAD	11803	LUST	9111978
PLAINVIEW	S100664874	JAMAICA ASH	OLD COUNTRY ROAD	11803	LUST	9209403
PLAINVIEW	S100665941	ISLAND TRANSPORTATION	OLD CTRY RD/RD SWAMP ROAD	11803	LUST	8909030
PLAINVIEW	U001855084	N.C. SHATTUCK ESTATE	960 PLAINVIEW RD.	11803	UST	053148
PLAINVIEW	S100492056	SHELL S/S	PLAINVIEW / OLD CTRY ROAD	11803	LUST	9209688
PLAINVIEW	1000145403	PASADENA DRIVE ELEMENTARY SCHOOL	RICHARD CT-BENMUR ST	11803	FINDS, RCRIS-LQG	
PLAINVIEW	S100149233	PLAINVIEW FIRE DISTRICT	ROUND SWAMP / OLD BETHPAG	11803	LUST	8707415
PLAINVIEW	S102235074		SEAFORD OYSTER BAY EXPRES	11803	LUST	9516654
PLAINVIEW	S101658198	OLD BETHPAGE SCHOOL	STADFORD ROAD SCHOOL	11803	LUST	9506301
PLAINVIEW	U001446580	NYS DOT-PLAINVIEW	SUNNYSIDE BLVD. & RTE 495	11803	LUST, UST	8602110
PLAINVIEW	U001446001	H.B.MATTLIN MIDDLE SCHOOL	WASHINGTON STREET	11803	UST	052061
PLAINVIEW	U001855097	PLAINVIEW-OLD BETHPAGE PK	WASHINGTON AVENUE	11803	UST	053203
PLAINVIEW	S100177523	PLAINVIEW COMM PARK	WASHINGTON BLVD	11803	LUST	9110559
STUART	1000698804	GRUMMAN AEROSPACE CORP #77	SR A1A 1 MI S OF STUART	11714	CORRACTS, RCRIS-LQG, RCRIS-TSI RAATS	



DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
LILCO-LEVITTOWN SUBSTATION RT 107 N/O HEMPSTEAD TPK BETHPAGE, NY 11714	FINDS RCRIS-LQG	1000178350 NYD981181902

RCRIS:

Owner: LONG ISLAND LIGHTING COMPANY
(212) 555-1212

Contact: MADISON MILHOUS
(516) 420-6133

Classification: Large Quantity Generator

Waste	Quantity
X002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

NORTHVILLE GAS STATION RTE 107 WANTAGH AVENUE BETHPAGE, NY 11714	LUST	S100491639 N/A
---	-------------	---------------------------------

LUST:

Facility ID: 9206489	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: MIRZA	Spill Type: Facility
Caller Name: BOB MENNIGHE	Caller Agency: GASOLINE INSTALLATION
Caller Phone: (516) 371-2743	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: NORTHVILLE GAS STATION	
Address: Not reported	
Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: 06/22/1995	
Spill Cause: Tank Test Failure	Resource Affected: Groundwater
Water Affected: Not reported	Spill Source: Gas Station
Spill Notifier: Tank Tester	PBS Number: Not reported
Spill Date: 09/03/1992 15:00	Reported to Dept: 09/03/1992 17:21
Cleanup Ceased: 06/22/1995	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: True	
Spill Record Last Update: 06/26/1995	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 09/08/1992	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
NYSDOT BIN 1037909 RTE 135 OVER HAYPATH RD BETHPAGE, NY 11714	FINDS RCRIS-LQG	1000556023 NYD986985729

RCRIS:

Owner: NYSDOT
(212) 555-1212

Contact: BRUCE OGUREK
(516) 360-6050

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

NYSDOT BIN 1037860 RTE 135 UNDER CENTRAL AVE BETHPAGE, NY 11714	FINDS RCRIS-LQG	1000556026 NYD986985752
--	----------------------------------	--

RCRIS:

Owner: NYSDOT
(212) 555-1212

Contact: BRUCE OGUREK
(516) 360-6050

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D008	0.000 (N)
NONE	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

NYSDOT BIN 1037859 RTE 135 OVER BOUNDARY AVE BETHPAGE, NY 11714	FINDS RCRIS-LQG	1000890356 NY0000348458
--	----------------------------------	--

RCRIS:

Owner: NYSDOT
(516) 471-6253

Contact: BERNARD ESPOSITO
(516) 471-6253

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>
D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

NYSDOT BIN 1037859 (Continued)

1000890356

Used Oil Recyc: No

Violation Status: No violations found

NYSDOT BIN 1037899
RTE 135 OVER BROADWAY
BETHPAGE, NY 11714

FINDS 1000890357
RCRIS-LQG NY0000348466

RCRIS:

Owner: NYSDOT
(516) 471-6253

Contact: BERNARD ESPOSITO
(516) 471-6253

Classification: Large Quantity Generator

Waste	Quantity
D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

OGS/NYS
BETHPAGE STATE PARK
BETHPAGE, NY 11714

LUST S100149985
N/A

LUST:

Facility ID: 8803698
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: DICK WILBER
Caller Phone: (518) 374-5571
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: OGS/NYS
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: VALLEY EQUIP
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 249-0701

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: Not reported
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 07/28/1988 14:00
Cleanup Ceased: Not reported
Last Inspection: Not reported
Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 07/13/1992
Corrective Action Plan Submitted: Not reported

Resource Affected: Groundwater
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 07/28/1988 14:35

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

OGS/NYS (Continued)

S100149985

Date Spill Entered In Computer Data File: 07/29/1988

BETHPAGE STATE PARK
BETHPAGE STATE PARK
BETHPAGE, NY 11714

LUST

S101657986
N/A

LUST:

Facility ID:	8807183	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	JOE MCDONALD	Caller Agency:	CENTRAL TESTING
Caller Phone:	(607) 692-4688	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 669-1000
Spiller:	BETHPAGE STATE PARK		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	11/30/1988 13:00	Reported to Dept:	11/30/1988 14:27
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	Fale		
Spill Record Last Update:	07/25/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/02/1988		

BETHPAGE W.D. PLANT 5
BROADWAY
BETHPAGE, NY 11714

AST

A100090114
N/A

Nassau County AST:

Facility ID:	001045	Tank ID:	0001
Tank Location:	Indoors, Aboveground	Capacity (Gal):	1500
Tank Status:	In Service	Tank Material:	STEEL
Int Protection:	None		
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type:	Fresh/Product
Piping Type:	Steel/Iron	Containment:	DOUBLE WALL TANK
Description:	SODIUM HYDROXIDE	Product Gauge:	Yes
Leak Detect:	OTHER	Install Date:	0792
Dispense Method:	Suction		
Fill Type:	Pumped		
Total Tanks:	Not reported		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
BETHPAGE SCH.BUS GARAGE BROADWAY BETHPAGE, NY 11714	AST	A100090457 N/A
Nassau County AST:		
Facility ID:	052344	Tank ID: 0603
Tank Location:	Outdoors, Aboveground	Capacity (Gal): 1000
Tank Status:	In Service	Tank Material: STEEL
Int Protection:	Other	
Ext Protection:	PAINTED [e.g. asphaltic]	Material Type: Fresh/Product
Piping Type:	Galvanized Steel	
Description:	OIL, FUEL #2	Containment: DOUBLE WALL TANK
Leak Detect:	ELECTRONIC	Product Gauge: Yes
Dispense Method:	Suction	Install Date: 0792
Fill Type:	Gravity	
Total Tanks:	Not reported	
JOHN F. KENNEDY J.H.S. BROADWAY BETHPAGE, NY 11714	UST	U002264560 N/A
Nassau County UST:		
Facility ID:	052343	Tank ID: 0203
Tank Location:	Indoors, Belowground	Capacity: 00010000
Tank Status:	In Service	Tank Material: Fiberglass Reinforced Plastic
Piping Type:	Double Walled Fiberglass	Material Type: Fresh/Product
Int Protection:	None	
Ext Protection:	FIBERGLASS REINFORCED PLASTIC	
Description:	OIL, FUEL #2	Containment: Double Wall Tank
Leak Detect:	IN-TANK SYSTEM	Product Gauge: Yes
Dispense Method:	Suction	Install Date: 1289
Fill Type:	Gravity	
Total Tanks:	2	
Facility ID:	052343	Tank ID: 0204
Tank Location:	Indoors, Belowground	Capacity: 00015000
Tank Status:	In Service	Tank Material: Fiberglass Reinforced Plastic
Piping Type:	Double Walled Fiberglass	Material Type: Fresh/Product
Int Protection:	None	
Ext Protection:	FIBERGLASS REINFORCED PLASTIC	
Description:	OIL, FUEL #2	Containment: Double Wall Tank
Leak Detect:	IN-TANK SYSTEM	Product Gauge: Yes
Dispense Method:	Suction	Install Date: 1289
Fill Type:	Gravity	
Total Tanks:	2	
UNK 339 BROADWAY / WASHINGTON BETHPAGE, NY 11714	LUST	S100491423 N/A
LUST:		
Facility ID:	9204651	Region of Spill: 1
Facility Contact:	Not reported	Facility Tele: Not reported
Investigator:	DECANDIA	Spill Type: Facility
Caller Name:	INSPECTOR SMITHING	Caller Agency: NCFM
Caller Phone:	(516) 689-1917	Caller Extension: Not reported
Notifier Name:	Not reported	Notifier Agency: Not reported
Notifier Phone:	Not reported	Notifier Extension: Not reported
Spiller Contact:	Not reported	Spiller Phone: Not reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
UNK (Continued)		S100491423
<p>Spiller: UNK</p> <p>Address: Not reported</p> <p>Spill Class: Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.</p> <p>Spill Closed Dt: 09/20/1992</p> <p>Spill Cause: Tank Overfill Resource Affected: On Land</p> <p>Water Affected: Not reported Spill Source: Tank Truck</p> <p>Spill Notifier: Fire Department PBS Number: Not reported</p> <p>Spill Date: 07/22/1992 18:00 Reported to Dept: 07/23/1992 00:01</p> <p>Cleanup Ceased: 09/20/1992</p> <p>Last Inspection: Not reported</p> <p>Cleanup Meets Standard: True</p> <p>Recommended Penalty: No Penalty</p> <p>Spiller Cleanup Date: Not reported</p> <p>Enforcement Date: Not reported</p> <p>Investigation Complete: Not reported</p> <p>UST Involvement: False</p> <p>Spill Record Last Update: 11/10/1992</p> <p>Corrective Action Plan Submitted: Not reported</p> <p>Date Spill Entered In Computer Data File: 07/24/1992</p>		

CENTRAL BLVD SCHOOL **CENTRAL AVE.** **BETHPAGE, NY 11714**

UST U002264561
N/A

Nassau County UST:

Facility ID:	052345	Tank ID:	0303
Tank Location:	Indoors, Belowground	Capacity:	00020000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Double Walled Fiberglass	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	IN-TANK SYSTEM	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1289
Total Tanks:	2		
Facility ID:	052345	Tank ID:	0304
Tank Location:	Indoors, Belowground	Capacity:	00002500
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #4		
Leak Detect:	IN-TANK SYSTEM	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1289
Total Tanks:	2		

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

BETHPAGE, NY 11714	LUST	S100664204 N/A
---------------------------	-------------	---------------------------

LUST:

Facility ID:	8604091	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	Parish	Spill Type:	UST
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	Not reported		
Address:	Not reported		
Spill Class:	Known release that creates a file or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported	Resource Affected:	On Land
Spill Cause:	Other	Spill Source:	Private Dwelling
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Fire Department	Reported to Dept:	09/24/1986 21:54
Spill Date:	09/24/1986 19:48		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	11/14/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/04/1986		

**TEXACO SVC STA
HEMPSTEAD TNP & STEWART
BETHPAGE, NY 11714**

**FINDS 1000144478
RCRIS-LQG NYD982791527**

RCRIS:

Owner: STAR ENTERPRISE
(212) 555-1212

Contact: J F LOVE
(609) 866-3233

Classification: Large Quantity Generator, Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
NONE	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
<hr/>		
TEXACO SVC STA (Continued)		1000144478
Used Oil Recyc: No		
Violation Status: No violations found		

OCEAN PETROLEUM	LUST	S101508890
HEMPSTEAD TPKE / RTE 107		N/A
BETHPAGE, NY 11714		

LUST:

Facility ID:	9416174	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	ROBERT NEDWICK	Caller Agency:	ISLAND PUMP & TANK
Caller Phone:	(516) 261-1590	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 520-2057
Spiller:	OCEANS PETROLEUMS		
Address	1320 STONYBROOK ROAD		
	STONYBROOK		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	04/28/1995		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	03/14/1995 16:40	Reported to Dept:	03/14/1995 18:15
Cleanup Ceased:	04/28/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	05/01/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/15/1995		

BETHVIEW WHEEL ALIGNMENT INC	FINDS	1000244487
HICKSVILLE RD & CENTRAL AVE	RCRIS-LQG	NYD077387165
BETHPAGE, NY 11714		

RCRIS:

Owner: KEVIN HUTTENLOCHER
(212) 555-1212

Contact: KEVIN HUTTENLOCHER
(516) 938-4114

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

BETHVIEW WHEEL ALIGNMENT INC (Continued)

1000244487

Used Oil Recyc: No

Violation Status: No violations found

BETHPAGE TOWNHOUSES
KENSINGTON LANE / RTE 107
BETHPAGE, NY 11714

LUST

S102234297
N/A

LUST:

Facility ID: 9515468
Facility Contact: Not reported
Investigator: Not reported
Caller Name: FRAN DAMANTI
Caller Phone: (516) 783-1000
Notifier Name: FRAN DAMANTI
Notifier Phone: (516) 783-1000
Spiller Contact: WARREN BEALE
Spiller: MEENAN OIL CO
Address: 3020 BURNS AVE
WANTAGH, NY 11793-

Region of Spill: 1
Facility Tele: Not reported
Spill Type: UST
Caller Agency: MEENAN OIL CO
Caller Extension: Not reported
Notifier Agency: MEENAN OIL CO
Notifier Extension: Not reported
Spiller Phone: (516) 783-1100

Spill Class: Not reported
Spill Closed Dt: Not reported
Spill Cause: Tank Overfill
Water Affected: Not reported
Spill Notifier: Responsible Party
Spill Date: 03/01/1996 12:50
Cleanup Ceased: Not reported
Last Inspection: Not reported

Resource Affected: On Land
Spill Source: Private Dwelling
PBS Number: Not reported
Reported to Dept: 03/01/1996 14:03

Cleanup Meets Standard: False
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 03/01/1996
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 03/01/1996

UNK
MANCHESTER DR/PLAINVIEW R
BETHPAGE, NY 11714

LUST

S100665895
N/A

LUST:

Facility ID: 8906174
Facility Contact: Not reported
Investigator: NONE
Caller Name: PHIL STEIN
Caller Phone: (516) 521-3751
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: UNK
Address: Not reported
Not reported
Spill Class: Not reported
Spill Closed Dt: 09/25/1989

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
UNK (Continued)		S100665895
Spill Cause: Other	Resource Affected: In Sewer	
Water Affected: Not reported	Spill Source: Passenger Vehicle	
Spill Notifier: Fire Department	PBS Number: Not reported	
Spill Date: 09/22/1989 09:30	Reported to Dept: 09/22/1989 10:40	
Cleanup Ceased: 09/25/1989		
Last Inspection: Not reported		
Cleanup Meets Standard: True		
Recommended Penalty: No Penalty		
Spiller Cleanup Date: Not reported		
Enforcement Date: Not reported		
Investigation Complete: Not reported		
UST Involvement: False		
Spill Record Last Update: 09/27/1989		
Corrective Action Plan Submitted: Not reported		
Date Spill Entered In Computer Data File: 09/25/1989		

<div style="background-color: black; width: 200px; height: 20px;"></div>	LUST	S100664230 N/A
--	------	-------------------

BETHPAGE, NY 11714

LUST:

Exemption 6

Facility ID: 8706872	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: RAYMOND	Spill Type: Facility
Caller Name: Not reported	Caller Agency: Not reported
Caller Phone: Not reported	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: <div style="background-color: black; width: 100px; height: 1em;"></div>	
Address: Not reported	
Spill Class: Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: Not reported	
Spill Cause: Other	Resource Affected: In Sewer
Water Affected: Not reported	Spill Source: Other Commercial/Industrial
Spill Notifier: Health Department	PBS Number: Not reported
Spill Date: 11/13/1987 02:50	Reported to Dept: 11/13/1987 05:55
Cleanup Ceased: Not reported	
Last Inspection: Not reported	
Cleanup Meets Standard: False	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 07/23/1992	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 11/13/1987	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
NAVAL WEAPONS INDUSTRIAL RESERVE PLANT SOUTH OYSTER BAY ROAD BETHPAGE, NY 11714	CERCLIS FINDS	1000148518 NY2170022162

CERCLIS Classification Data:

Site Incident Category:	Not reported	Federal Facility:	YES
Ownership Status:	FEDERALLY OWNED	NPL Status:	NOT ON NPL
EPA Notes:	THERE ARE POTENTIAL HAZARDOUS WASTE AREAS AT THIS SITE; SUCH AS WASTES GENERATED PERMARILY FROM AIRCRAFT PRODUCTIONS.		

CERCLIS Assessment History:

Assessment:	DISCOVERY	Completed:	02/17/1987
Assessment:	PRELIMINARY ASSESSMENT	Completed:	12/29/1988
Assessment:	SCREENING SITE INSPECTION	Completed:	09/30/1992
Assessment:	COMBINED RI/FS	Completed:	Not reported

CERCLIS Site Status:

This site is currently under investigation by the government to assess the extent of further action

FINDS:

Other Pertinent Environmental Activity Identified at Site:

- Facility has an active water discharge permit (under PCS)
- Facility is monitored or permitted for air emissions under the Clean Air Act (under AFS/AIRS)
- Civil judicial and administrative enforcement case against facility (under DOCKET)
- Federal facility has submitted specific environmental project budget plans (under FFIS)

**MOBIL OIL
SO OYSTER BAY / STEWART A
BETHPAGE, NY 11714**

LUST

**S100169909
N/A**

LUST:

Facility ID:	8908752	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	DOUG SCHRIMPS	Caller Agency:	ISLAND PUMP AND TANK
Caller Phone:	(516) 261-1590	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	MOBIL OIL		
Address:	Not reported		
	Not reported		
Spill Class:	Not reported		
Spill Closed Dt:	09/07/1990		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	12/05/1989 11:30	Reported to Dept:	12/05/1989 13:40
Cleanup Ceased:	09/07/1990		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/11/1990		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/06/1989		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
BETHPAGE W.D. PLANT 6 PARK LANE BETHPAGE, NY 11714	UST	U002096782 N/A
Nassau County UST:		
Facility ID: 001190	Tank ID: 0001	
Tank Location: Indoors, Belowground	Capacity: 00004000	
Tank Status: In Service	Tank Material: STEEL	
Piping Type: Steel/Iron	Material Type: Fresh/Product	
Int Protection: Other		
Ext Protection: OTHER		
Description: SODIUM HYDROXIDE		
Leak Detect: ELECTRONIC	Containment: Double Wall Tank	
Dispense Method: Submersible	Product Gauge: Yes	
Fill Type: Gravity	Install Date: 0689	
Total Tanks: 1		

NORTHERN ALLOYS INC PLAINVIEW RD & MANCHESTER BETHPAGE, NY 11714	RCRIS-SQG FINDS	1000407948 NYD982797938
---	----------------------------------	--

RCRIS:

Owner: NORTHERN ALLOYS INC
(212) 555-1212

Contact: TOM MILONE
(516) 225-1000

Classification: Small Quantity Generator

Waste	Quantity
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

CHARLES CAMPAGNE SCHOOL PLAINVIEW RD. BETHPAGE, NY 11714	UST	U001446275 N/A
---	------------	---------------------------------

Nassau County UST:

Facility ID: 052346	Tank ID: 0002
Tank Location: Indoors, Belowground	Capacity: 00015000
Tank Status: In Service	Tank Material: Fiberglass Reinforced Plastic
Piping Type: Double Walled Fiberglass	Material Type: Fresh/Product
Int Protection: None	
Ext Protection: FIBERGLASS REINFORCED PLASTIC	
Description: OIL, FUEL #4	
Leak Detect: ELECTRONIC	Containment: Other
Dispense Method: Suction	Product Gauge: Yes
Fill Type: Gravity	Install Date: 1089
Total Tanks: 1	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
NYSDOT BIN 1037880 POWELL AVE OVER RTE 135 BETHPAGE, NY 11714	RCRIS-LQG	1001028645 NYR000008771

RCRIS:

Owner: NYSDOT
(516) 952-6053

Contact: KARL DRECHSLER
(516) 864-4351

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	X003	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

NORTHVILLE STATION STATE RD 107 & WANTAGH AVE BETHPAGE, NY 11714	RCRIS-SQG	1001079769 NYR000014761
---	------------------	--

RCRIS:

Owner: NORTHVILLE INDUSTRIES CORP
(516) 293-4700

Contact: THOMAS MAUS
(516) 293-4700

Classification: Small Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)	D018	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

SERVICE STATION N/S STEWART & CHERRY AVES BETHPAGE, NY 11714	FINDS RCRIS-LQG	1000432425 NYD000697961
---	----------------------------------	--

RCRIS:

Owner: BARTOLOMEO NICHOLAS & BUCCELLATO GENE
(212) 555-1212

Contact: NICHOLAS BARTOLOMEO
(212) 555-1212

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
SERVICE STATION (Continued)		1000432425
Used Oil Recyc: No		
Violation Status: No violations found		
<hr/>		
A & D SHELL	UST	U001854915
STEWART & FARMERS AVENUES		N/A
BETHPAGE, NY 11714		
Nassau County UST:		
Facility ID: 041021	Tank ID: 0009	
Tank Location: Indoors, Belowground	Capacity: 00001000	
Tank Status: 6	Tank Material: STEEL	
Piping Type: Galvanized Steel	Material Type: Fresh/Product	
Int Protection: Unknown		
Ext Protection: PAINTED [e.g. asphaltic]		
Description: OIL, FUEL #2		
Leak Detect: OTHER	Containment: Other	
Dispense Method: Suction	Product Gauge: Yes	
Fill Type: Gravity	Install Date: 1255	
Total Tanks: 1		
<hr/>		
NORTHEdge SCHOOL	UST	U002264557
STEWART AVE.		N/A
BETHPAGE, NY 11714		
Nassau County UST:		
Facility ID: 052270	Tank ID: 0003	
Tank Location: Indoors, Belowground	Capacity: 00010000	
Tank Status: In Service	Tank Material: Fiberglass Reinforced Plastic	
Piping Type: Double Walled Fiberglass	Material Type: Fresh/Product	
Int Protection: Internal Lining		
Ext Protection: FIBERGLASS REINFORCED PLASTIC		
Description: OIL, FUEL #2		
Leak Detect: ELECTRONIC	Containment: Double Wall Tank	
Dispense Method: Not reported	Product Gauge: Yes	
Fill Type: Pumped	Install Date: 0988	
Total Tanks: 1		
<hr/>		
JOHN H. WEST SCHOOL	UST	U002264558
STEWART & BOUNDARY AVES.		N/A
BETHPAGE, NY 11714		
Nassau County UST:		
Facility ID: 052272	Tank ID: 0003	
Tank Location: Indoors, Belowground	Capacity: 00015000	
Tank Status: In Service	Tank Material: Fiberglass Reinforced Plastic	
Piping Type: Double Walled Fiberglass	Material Type: Fresh/Product	
Int Protection: Internal Lining		
Ext Protection: FIBERGLASS REINFORCED PLASTIC		
Description: OIL, FUEL #2		
Leak Detect: ELECTRONIC	Containment: Double Wall Tank	
Dispense Method: Not reported	Product Gauge: Yes	
Fill Type: Pumped	Install Date: 0988	
Total Tanks: 1		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
BETHPAGE COMMUNITY PARK STEWART AVE BETHPAGE, NY 11714	RCRIS-SQG FINDS LUST UST	1000243981 NYD980785612

RCRIS:

Owner: Not reported
Contact: FRANK ANTETOMASO
(516) 921-7347

Classification: Not reported

Waste	Quantity	Waste	Quantity
D002	0.000 (N)	X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

LUST:

Facility ID: 9110161
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: PAT VOLINO
Caller Phone: (516) 634-0414
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: BETHPAGE COMM PARK
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: A. VOLINO & SONS
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 349-1010

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 04/16/1992
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 12/26/1991 16:00

Resource Affected: Groundwater
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 12/26/1991 21:59

Cleanup Ceased: 04/16/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 11/09/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 12/30/1991

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
BETHPAGE COMMUNITY PARK (Continued)		1000243981
Nassau County UST:		
Facility ID:	053202	Tank ID: 0002
Tank Location:	Indoors, Belowground	Capacity: 00000500
Tank Status:	In Service	Tank Material: Fiberglass Reinforced Plastic
Piping Type:	Unknown	Material Type: Fresh/Product
Int Protection:	Unknown	
Ext Protection:	UNKNOWN	
Description:	ACIDS, NOS	
Leak Detect:	OTHER	Containment: Double Wall Tank
Dispense Method:	Suction	Product Gauge: Yes
Fill Type:	Gravity	Install Date: 1255
Total Tanks:	1	
NAVAL WEAPONS IND. RESERVE PLANT STEWART AVENUE BETHPAGE, NY 11714		SHWS S100521004 N/A
SHWS:		
Facility ID:	130003B	EPA ID: NYD602047967
Owner:	U.S. Navy Grumman Corp., Stewart Ave Bethpage, NY 11714	
Owner Telephone:	Not reported	
Operator:	Grumman Aerospace Corp Stewart Ave Bethpage, NY 11714	
Contact:	Not reported	Telephone Not reported
Site Classification:	Significant threat to the public health or environment - action required.	
Region:	1	
Site Type:	Lagoon, Landfill	
Acres:	105	User: Grumman Aerospace - US Navy
HW Started:	1943	HW Ended: 1987
HW Disposed:	Trichlorethylene (F001), Tetrachloroethene ((PCE or "perc.") F002), 1,1,1-Trichloroethane, Cyanide (F007), Lead (D008)	
Units:	unknown, unknown, unknown, unknown, unknown	
Air Data:	Unavailable	Surf. Water Data: Unavailable
Gmd. Water Data:	Available	Soil Data: Available
Sediment Data:	Available	
Ground Water Standards Contravention:	Yes	
Drinking Water Standards Contravention:	Yes	
Surface Water Standards Contravention:	No	
Air Standards Contravention:	No	
Enforcement Status:	Order Has Been Signed	Legal Action: No
State Action:	Yes	Fed Action: Yes
Remedial Action:	Under Design, In Progress	
Remed action type:	Final on-site soils remedy	
Soil Type:	Sand	
Gmd Water Depth:	Approximately 55 feet	

DETAILED ORPHAN LISTING

Site

Database(s)

ER ID Number
EPA ID Number

NAVAL WEAPONS IND. RESERVE PLANT (Continued)

S100521004

Assessment of Environmental Problems:

Two municipal downgradient water supplies have been impacted, and others are being threatened.

Assessment of Health Problems:

Groundwater on-site is contaminated but is not used as potable water supply. The Bethpage Water District operates 3 well fields approximately 2500 feet downgradient of the Grumman/Navy sites. Contamination was detected at Bethpage Water District (BWD) Plants 4 and 6 and treatment systems are in operation at each of these two plants. Plans are being developed to install treatment at the BWD Plant 5. Grumman is funding treatment for BWD Plant 4 & 6 and Navy will fund treatment for plant 5 in anticipation that this plant will become contaminated, although no contamination was been detected in BWD Plant 5 to date. The Navy sampled surface soils in residential yards to the south east of the site in November 1994 in response to residents concerns. These samples were to be tested for PCBs. The results of this sampling are still pending.

TOWN OF OYSTER BAY
STEWART AVENUE
BETHPAGE, NY 11714

LUST

S101173536
N/A

LUST:

Facility ID: 9409098

Facility Contact: Not reported

Investigator: T/T/F

Caller Name: PAT VOLINO

Caller Phone: (516) 334-0414

Notifier Name: Not reported

Notifier Phone: Not reported

Spiller Contact: Not reported

Spiller: TOWN OF OYSTER BAY

Address: 150 MILLER PLACE ROAD
SYOSSET, NY

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 07/23/1996

Spill Cause: Tank Test Failure

Water Affected: Not reported

Spill Notifier: Tank Tester

Spill Date: 10/07/1994 11:45

Cleanup Ceased: Not reported

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 07/24/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 10/11/1994

Region of Spill: 1

Facility Tele: Not reported

Spill Type: UST

Caller Agency: VOLINO & SONS

Caller Extension: Not reported

Notifier Agency: Not reported

Notifier Extension: Not reported

Spiller Phone: Not reported

Resource Affected: Groundwater

Spill Source: Other Non Commercial/Industrial

PBS Number: Not reported

Reported to Dept: 10/07/1994 12:25

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
DIFAZIO ELECTRIC (G.C.) STEWART AVE BETHPAGE, NY 11714	LUST	S101340109 N/A

LUST:

Facility ID:	9411984	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	NONE	Spill Type:	Facility
Caller Name:	JOHN OHLMAN	Caller Agency:	NORTHROP/GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 667-2200
Spiller:	DIFAZIO ELECTRIC (G.C.)		
Address:	Not reported		
	Not reported		
Spill Class:	Possible release with minimal potential for fire or hazard or Known release with no damage. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/08/1994		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	12/08/1994 08:00	Reported to Dept:	12/08/1994 08:40
Cleanup Ceased:	12/08/1994		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/12/1994		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/09/1994		

STEWART AVE/PLANT #3 BETHPAGE, NY 11714	LUST	S102235111 N/A
--	-------------	---------------------------

LUST:

Facility ID:	9603860	Region of Spill:	1
Facility Contact:	JOHN SELVA	Facility Tele:	(516) 575-8176
Investigator:	LAMANNO	Spill Type:	UST
Caller Name:	JOHN UHLMAN	Caller Agency:	GRUMMAN
Caller Phone:	(516) 575-2385	Caller Extension:	Not reported
Notifier Name:	JOHN INGENITO	Notifier Agency:	GRUMMAN
Notifier Phone:	(516) 575-2029	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	GRUMMAN		
Address:	Not reported		
	Not reported		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	In Sewer
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	06/19/1996 12:00	Reported to Dept:	06/20/1996 16:06

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

(Continued)

S102235111

Cleanup Ceased: Not reported
 Last Inspection: Not reported
 Cleanup Meets Standard: False
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 06/24/1996
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 06/20/1996

**ISLAND TRANSPORT CORP
 SOUTH WAREHOUSE AT GRUMMA
 BETHPAGE, NY 11714**

LUST

**S100490592
 N/A**

LUST:

Facility ID: 9105673
 Facility Contact: Not reported
 Investigator: PARISH
 Caller Name: JOHN OHLMANN
 Caller Phone: (516) 575-2385
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: ISLAND TRANSPORT CORP
 Address: Not reported
 Not reported

Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: GRUMMAN
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported

Spill Class: Not reported
 Spill Closed Dt: 10/03/1991
 Spill Cause: Tank Overfill
 Water Affected: Not reported
 Spill Notifier: Affected Persons
 Spill Date: 08/26/1991 08:00
 Cleanup Ceased: 10/03/1991
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 10/07/1991
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 08/28/1991

Resource Affected: On Land
 Spill Source: Tank Truck
 PBS Number: Not reported
 Reported to Dept: 08/26/1991 09:10

**NCDPW
 WINDING ROAD
 BETHPAGE, NY 11714**

LUST

**S100560179
 N/A**

LUST:

Facility ID: 9303993
 Facility Contact: Not reported
 Investigator: PARISH
 Caller Name: LENNY
 Caller Phone: (516) 249-3150

Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: LARRY TYREE
 Caller Extension: Not reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
NCDPW (Continued)		S100560179
Notifier Name:	Not reported	Notifier Agency: Not reported
Notifier Phone:	Not reported	Notifier Extension: Not reported
Spiller Contact:	Not reported	Spiller Phone: Not reported
Spiller:	NCDPW	
Address:	Not reported	
	Not reported	
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt:	Not reported	
Spill Cause:	Tank Failure	Resource Affected: Groundwater
Water Affected:	Not reported	Spill Source: Other Non Commercial/Industrial
Spill Notifier:	Other	PBS Number: Not reported
Spill Date:	06/28/1993 13:00	Reported to Dept: 06/29/1993 09:15
Cleanup Ceased:	Not reported	
Last Inspection:	Not reported	
Cleanup Meets Standard:	False	
Recommended Penalty:	No Penalty	
Spiller Cleanup Date:	Not reported	
Enforcement Date:	Not reported	
Investigation Complete:	Not reported	
UST Involvement:	False	
Spill Record Last Update:	Not reported	
Corrective Action Plan Submitted:	Not reported	
Date Spill Entered In Computer Data File:	07/01/1993	

NCDPW HAZ WASTE
WINDING ROAD
BETHPAGE, NY 11714

LUST

S10066848
N/A

LUST:

Facility ID:	9300577	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPERT DRO	Spill Type:	Facility
Caller Name:	KEVIN KISPERT	Caller Agency:	DEC
Caller Phone:	(516) 751-7900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NCDPW HAZ WASTE		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/01/1995		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	DEC	PBS Number:	Not reported
Spill Date:	04/12/1993 12:00	Reported to Dept:	04/12/1993 12:45
Cleanup Ceased:	08/01/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/02/1995		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

NCDPW HAZ WASTE (Continued)

S100666848

Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 04/14/1993

NCDWP HAZ WASTE WINDING ROAD BETHPAGE, NY 11714

LUST

S100666850
N/A

LUST:

Facility ID:	9300626	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	KISPERS DRO	Spill Type:	Facility
Caller Name:	KEVIN KISPERS	Caller Agency:	DEC
Caller Phone:	(516) 751-7900	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	NCDPW HAZ WASTE		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	08/01/1995		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	DEC	PBS Number:	Not reported
Spill Date:	04/06/1993 12:00	Reported to Dept:	04/06/1993 13:00
Cleanup Ceased:	08/01/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	08/02/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/14/1993		

FIREMENS TRAINING CENTER WINDING RD / ROUND SWAMP BETHPAGE, NY 11714

LUST

S102234974
N/A

LUST:

Facility ID:	9105485	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PARISH	Spill Type:	UST
Caller Name:	PETER WILTOWSKI	Caller Agency:	NCDPW HAZ WASTE
Caller Phone:	(516) 997-8282	Caller Extension:	Not reported
Notifier Name:	PETER WILTOWSKI	Notifier Agency:	NCDPW HAZ WASTE
Notifier Phone:	(516) 997-8282	Notifier Extension:	Not reported
Spiller Contact:	TIM KELLY	Spiller Phone:	(516) 997-8282
Spiller:	NASSAU COUNTY DPW		
Address:	170 CANTIAGUE ROCK RD HICKSVILLE, NY 11801-		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

FIREMENS TRAINING CENTER (Continued)

S102234974

Spill Closed Dt:	Not reported	Resource Affected:	Surface Water
Spill Cause:	Other	Spill Source:	Other Non Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	08/21/1991 10:45
Spill Date:	08/20/1991 12:00		
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/04/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered in Computer Data File:	08/26/1991		

BETHPAGE STATE PARK BETHPAGE PKY FARMINGDALE, NY 11714

RCRIS-SQG 1000243984
FINDS NYD981875362
LUST

RCRIS:

Owner: LI STATE PARK COMM
(212) 555-1212

Contact: JAMES EVANS
(516) 249-0701

Classification: Small Quantity Generator

Waste	Quantity
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

LUST:

Facility ID:	8807195	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	JOE MCDONALD	Caller Agency:	CENTRAL TESTING
Caller Phone:	(607) 692-4688	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 669-1000
Spiller:	BETHPAGE STATE PARK		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	11/30/1988 16:15	Reported to Dept:	11/30/1988 17:31
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		

DETAILED ORPHAN LISTING

<u>Site</u>	<u>Database(s)</u>	<u>EDR ID Number</u> <u>EPA ID Number</u>
-------------	--------------------	--

BETHPAGE STATE PARK (Continued)

1000243984

Cleanup Meets Standard: False
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 07/14/1992
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 12/02/1988

MTA BUS GARGE FORMERLY PUREX IND INC
COMMERCIAL AVE MITCHELL FIELD
GARDEN CITY, NY 11756

RCRIS-LQG **1000105580**
NYD980760425

RCRIS:

Owner: NASSAU COUNTY
(212) 555-1212

Contact: DOUGLAS GARFIELD
(213) 630-7585

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
U037	0.000 (N)	U070	0.000 (N)
U071	0.000 (N)	U072	0.000 (N)
U076	0.000 (N)	U080	0.000 (N)
U210	0.000 (N)	U211	0.000 (N)
U220	0.000 (N)	U226	0.000 (N)
U228	0.000 (N)	U239	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

EXXON CO USA - HICKSVILLE
RTE 106 & 107
HICKSVILLE, NY 11801

FINDS **1000335584**
RCRIS-LQG **NYD982796542**

RCRIS:

Owner: EXXON CO USA
(212) 555-1212

Contact: LARRY WESTON
(516) 794-5436

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

<u>Site</u>	<u>Database(s)</u>	<u>EDR ID Number</u> <u>EPA ID Number</u>												
<hr/>														
EXXON CO USA - HICKSVILLE (Continued) Used Oil Recyc: No Violation Status: No violations found		1000335584												
<hr/>														
TEXACO SERVICE STATION - 13-006-0196 RTE 107 & BETHPAGE RD HICKSVILLE, NY 11801	FINDS RCRIS-LQG	1000144487 NYD982792913												
RCRIS: Owner: STAR ENTERPRISE (212) 555-1212 Contact: JOHN F LOVE (609) 866-3233 Classification: Large Quantity Generator <table border="0"> <tr> <td><u>Waste</u></td> <td><u>Quantity</u></td> <td><u>Waste</u></td> <td><u>Quantity</u></td> </tr> <tr> <td>D001</td> <td>0.000 (N)</td> <td>F001</td> <td>0.000 (N)</td> </tr> </table> <p align="center">(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported</p> Used Oil Recyc: No Violation Status: No violations found			<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>	D001	0.000 (N)	F001	0.000 (N)				
<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>											
D001	0.000 (N)	F001	0.000 (N)											
<hr/>														
NEWBAR SERVICE CENTER 1 BARTEL LANE HICKSVILLE, NY 11801	RCRIS-SQG FINDS	1000556708 NYD986992832												
RCRIS: Owner: BILL HARTINGER (516) 931-9654 Contact: BILL HARTINGER (516) 931-9654 Classification: Small Quantity Generator <table border="0"> <tr> <td><u>Waste</u></td> <td><u>Quantity</u></td> <td><u>Waste</u></td> <td><u>Quantity</u></td> </tr> <tr> <td>D001</td> <td>0.000 (N)</td> <td>D008</td> <td>0.000 (N)</td> </tr> <tr> <td>D018</td> <td>0.000 (N)</td> <td>D039</td> <td>0.000 (N)</td> </tr> </table> <p align="center">(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported</p> Used Oil Recyc: No Violation Status: No violations found			<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>	D001	0.000 (N)	D008	0.000 (N)	D018	0.000 (N)	D039	0.000 (N)
<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>											
D001	0.000 (N)	D008	0.000 (N)											
D018	0.000 (N)	D039	0.000 (N)											
<hr/>														
M G M TOWING & AUTOMOTIVE 870 S BROADWAY - FRONT OF BLDG HICKSVILLE, NY 11801	RCRIS-SQG FINDS	1000555555 NYD986980936												

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

M G M TOWING & AUTOMOTIVE (Continued)

1000555555

RCRIS:

Owner: M G M TOWING & AUTOMOTIVE
(516) 822-2857

Contact: MICHAEL KENJESKY
(516) 822-7857

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D008	0.000 (N)	D018	0.000 (N)
D039	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

WHOLE SALE TIRE CO
358 B BROADWAY MALL
HICKSVILLE, NY 11801

RCRIS-SQG 1000872226
NYD987034352

RCRIS:

Owner: BROADWAY MILL CORP
(516) 942-8800

Contact: SCOTT STANTON
(516) 942-8800

Classification: Conditionally Exempt Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
D008	0.000 (N)	D018	0.000 (N)
D039	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

EXXON CO
BROADWAY & RTE 106
HICKSVILLE, NY 11801

RCRIS-SQG 1000335580
FINDS NYD982743114

RCRIS:

Owner: EXXON COMPANY
(212) 555-1212

Contact: LARRY WESTON
(516) 794-5436

Classification: Not reported

Waste	Quantity
D001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
EXXON CO (Continued) Used Oil Recyc: No Violation Status: No violations found		1000335580
SLOMINS INC. 75 LAUMAN LANE HICKSVILLE, NY 11801	AST UST	U003080080 N/A
MOSF AST: Facility ID: 1-3240 Telephone: (516) 932-7000 Facility Type: Storage Terminal Facility Contact: HOWARD SELDES Facility Status: ACTIVE FACILITY Owner: SLOMINS INC. 125 LAUMAN LANE HICKSVILLE, NY 11801 Owner Tel: (516) 932-7000 Owner Type: Corporate/Commercial CASNO: Not reported Tank Status: In Service Tank ID: 1 Total Tanks: 2 Daily Throughput 60000 Gal(s) Tank Location: ABOVEGROUND Install Date: 12/57 Capacity (Gal): Not reported Tank Type: Steel/carbon steel Tank External: OTHER Product: NOS 1,2, OR 4 FUEL OIL Tank Internal: EPOXY LINER Pipe Location: Aboveground Pipe Type: STEEL/IRON Pipe Internal: NONE Dispenser: Suction Pipe External: NONE Second Contain: PREFABRICATED STEEL DIKE Leak Detection: NONE/GROUNDWATER WELL Overfill Protection: High Level Alarm, Product Level Gauge Test Date: 06/91 Date Closed: Not reported Dispensing Mthd: Suction Facility Town: OYSTER BAY SWIS Code: 28 Mailing Name: SLOMINS INC. 125 LAUMAN LANE NY 11801 Mailing Contact: HOWARD SELDES Mailing Phone: (516) 932-7000 Legal Agent: RAYMOND SLOMIN 125 LAUMAN LANE HICKSVILLE, NY 11801 Date Legal Agent Filed with Secretary of State: 03/42 Name of Emergency Contact: HOWARD SELDES Emergency Contact Telephone: (516) 932-7000 Chemical Bulk Storage Number: Not reported Pollution Discharge Elimination System Num: 0-110591 License Status: License Issued Date License Application Received: 01/04/1994 Date License Issued: 04/01/1994 Date License Expires or Expired: 03/31/1999 Product Transfer Operation: Tank Truck		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

SLOMINS INC. (Continued)

U003080080

Facility ID:	1-3240	Telephone:	(516) 932-7000
Facility Type:	Storage Terminal	Facility Contact:	HOWARD SELDES
Facility Status:	ACTIVE FACILITY		
Owner:	SLOMINS INC.		
	125 LAUMAN LANE		
	HICKSVILLE, NY 11801		
Owner Tel:	(516) 932-7000		
Owner Type:	Corporate/Commercial	CASNO:	Not reported
Tank Status:	In Service	Tank ID:	2
Total Tanks:	2	Daily Throughput	60000 Gal(s)
Tank Location:	ABOVEGROUND		
Install Date:	11/82	Capacity (Gal):	Not reported
Tank Type:	Steel/carbon steel		
Tank External:	OTHER		
Product:	NOS 1,2, OR 4 FUEL OIL	Tank Internal:	EPOXY LINER
Pipe Location:	Aboveground	Pipe Type:	STEEL/IRON
Pipe Internal:	NONE	Dispenser:	Suction
Pipe External:	NONE		
Second Contain:	PREFABRICATED STEEL DIKE		
Leak Detection:	NONE/GROUNDWATER WELL		
Overfill Protection:	High Level Alarm, Product Level Gauge		
Test Date:	04/92	Date Closed:	Not reported
Dispensing Mthd:	Suction		
SWIS Code:	28	Facility Town:	OYSTER BAY
Mailing Name:	SLOMINS INC.		
	125 LAUMAN LANE		
	NY 11801		
Mailing Contact:	HOWARD SELDES		
Mailing Phone:	(516) 932-7000		
Legal Agent:	RAYMOND SLOMIN		
	125 LAUMAN LANE		
	HICKSVILLE, NY 11801		
Date Legal Agent Filed with Secretary of State:	03/42		
Name of Emergency Contact:	HOWARD SELDES		
Emergency Contact Telephone:	(516) 932-7000		
Chemical Bulk Storage Number:	Not reported		
Pollution Discharge Elimination System Num:	0-110591		
License Status:	License Issued		
Date License Application Received:	01/04/1994		
Date License Issued:	04/01/1994		
Date License Expires or Expired:	03/31/1999		
Product Transfer Operation:	Tank Truck		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
SLOMINS INC. (Continued)		U003080080
<p>MOSF UST:</p> <p>Facility ID: 1-3240 Facility Status: ACTIVE FACILITY</p> <p>SWIS Code: 28 Facility Town: OYSTER BAY</p> <p>Contact: HOWARD SELDES, (516) 932-7000</p> <p>Owner: SLOMINS INC.</p> <p>125 LAUMAN LANE</p> <p>HICKSVILLE, NY 11801-</p> <p>Owner Tel: (516) 932-7000 Owner Type: UNDEFINED</p> <p>Mail To: SLOMINS INC.</p> <p>125 LAUMAN LANE</p> <p>NY 11801-</p> <p>ATTN: HOWARD SELDES</p> <p>(516) 932-7000</p> <p>Legal Agent: RAYMOND SLOMIN</p> <p>125 LAUMAN LANE</p> <p>HICKSVILLE, NY 11801-</p> <p>Date Filed: 03/42 CBS Number: Not reported</p> <p>Emerg Contact: HOWARD SELDES, (516) 932-7000</p> <p>SPDES Num: 0-110591 Total Tanks: 1</p> <p>Avg Throughpt: 60000 License Stat: Issued</p> <p>License Issued: 04/01/1994 Exp Date: 03/31/1999</p> <p>Facility Type: Storage Terminal</p> <p>Transfer Operation: Tank Truck</p> <p>Applic Rcvd: 01/04/1994 Tank ID: 3</p> <p>Tank Location: UNDERGROUND</p> <p>Tank Status: In Service</p> <p>Install Date: 10/82 Capacity (Gal): 3600</p> <p>CAS No: Not reported Tank Type: Steel/carbon steel</p> <p>Product: OTHER Tank Internal: EPOXY LINER</p> <p>Tank External: PAINTED/ASPHALT COATING</p> <p>Pipe Location: Underground Pipe Type: OTHER</p> <p>Pipe Internal: NONE Dispenser: Gravity</p> <p>Pipe External: NONE</p> <p>Second Contain: NONE</p> <p>Leak Detection: NONE/GROUNDWATER WELL</p> <p>Overfill Protection: None</p> <p>Test Date: 11/92 Date Closed: Not reported</p> <p>Database Type: Major Oil Storage</p>		

HICKSVILLE POST OFFICE
109 LUDY ST
HICKSVILLE, NY 11801

LUST

S102232601
N/A

LUST:

Facility ID: 9515845	Region of Spill: 1
Facility Contact: BRIAN RUFFLEY	Facility Tele: (516) 433-9188
Investigator: T/T/F	Spill Type: UST
Caller Name: STEVE BRANCIFORTE	Caller Agency: NEC
Caller Phone: (516) 433-2675	Caller Extension: Not reported
Notifier Name: SAME	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: BRIAN RUFFLEY	Spiller Phone: (516) 433-9188
Spiller: HICKSVILLE POST OFFICE	
Address: 109 LUDY STREET	
HICKSVILLE, NY 11802-	
Spill Class: Known release that creates potential for fire or hazard. DEC Response.	
Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: 06/18/1996	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

HICKSVILLE POST OFFICE (Continued)

S102232601

Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	03/11/1996 16:00	Reported to Dept:	03/11/1996 17:01
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	06/20/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/11/1996		

S S PREMISES C/O SHELL OIL CO 500 OLD CO RD & LEVITTOWN RD HICKSVILLE, NY 11801

FINDS 1000140663
RCRIS-LQG NYD981133325

RCRIS:

Owner: SHELL OIL CO
(212) 555-1212

Contact: JOHN SPINELLE
(800) 431-5566

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	K052	0.000 (N)
X001	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

TEXACO SVC STA 180 OLD COUNTRY RD HICKSVILLE, NY 11801

FINDS 1000144528
RCRIS-LQG NYD986901726

RCRIS:

Owner: STAR ENTERPRISE
(212) 555-1212

Contact: JOHN YOUNG
(609) 866-3233

Classification: Large Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	D001	0.000 (N)
NONE	0.000 (N)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number				
TEXACO SVC STA (Continued) Used Oil Recyc: No Violation Status: No violations found		1000144528				
<hr/>						
FRESH START CLEANERS 212 OLD COUNTRY RD HICKSVILLE, NY 11801	FINDS RCRIS-LQG	1000381240 NYD981131444				
RCRIS: Owner: Not reported Contact: JEROME KANE (516) 935-5619 Classification: Large Quantity Generator <table><tr><td><u>Waste</u></td><td><u>Quantity</u></td></tr><tr><td>F002</td><td>0.000 (N)</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported Used Oil Recyc: No Violation Status: No violations found			<u>Waste</u>	<u>Quantity</u>	F002	0.000 (N)
<u>Waste</u>	<u>Quantity</u>					
F002	0.000 (N)					
<hr/>						
WESTERN AUTO REPAIR 67 OLD COUNTRY RD HICKSVILLE, NY 11801	RCRIS-SQG	1000402170 NYD986890564				
RCRIS: Owner: WESTERN AUTO REPAIR (212) 555-1212 Contact: HERB BROWER (516) 931-9563 Classification: Small Quantity Generator <table><tr><td><u>Waste</u></td><td><u>Quantity</u></td></tr><tr><td>D001</td><td>0.000 (N)</td></tr></table> (P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported Used Oil Recyc: No Violation Status: No violations found			<u>Waste</u>	<u>Quantity</u>	D001	0.000 (N)
<u>Waste</u>	<u>Quantity</u>					
D001	0.000 (N)					
<hr/>						
GETTY SVC STA 178 OLD COUNTRY RD HICKSVILLE, NY 11801	RCRIS-SQG FINDS	1000789398 NYD987008596				

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

GETTY SVC STA (Continued)

1000789398

RCRIS:

Owner: GETTY PETROLEUM CORP
(718) 729-6500

Contact: JOHN CATAPANO
(718) 729-6500

Classification: Conditionally Exempt Small Quantity Generator, Hazardous Waste Transporter

Waste	Quantity	Waste	Quantity
D001	0.000 (N)	D018	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: Violations exist, high priority violator

There are 1 compliance/violation record(s) reported at this site:

Evaluation
Non-Financial Record Review

Area of Violation
Generator-All Requirements

Date of Compliance
08/04/1993

SUNRISE PROFESSIONAL SERVICE INC
73A OLD COUNTRY RD
HICKSVILLE, NY 11801

RCRIS-SQG 1000990180
NYR000001396

RCRIS:

Owner: SUNNY CHEN
(516) 681-6081

Contact: SUNNY J CHEN
(516) 681-6081

Classification: Small Quantity Generator

Waste	Quantity	Waste	Quantity
D000	0.000 (N)	F002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

HICKSVILLE FIRE DIST
STRONG ST FIRE STATION
HICKSVILLE, NY 11801

FINDS 1000457594
RCRIS-LQG NYD986928554

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
-------------	--------------------	--

HICKSVILLE FIRE DIST (Continued)

1000457594

RCRIS:

Owner: HICKSVILLE FIRE DIST
(212) 555-1212

Contact: OWEN MAGEE
(516) 933-6445

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
NONE	0.000 (N)	NONE	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

KEUKA LAKE STATE PARK
ROUTE 54A CAMP COMFORT ST
JERUSALEM, NY 11714

LUST

S101102772
N/A

LUST:

Facility ID: 9400514
Facility Contact: Not reported
Investigator: PL
Caller Name: JIM TERRY
Caller Phone: (607) 387-7041
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: NYS PARKS & RECREATION
Address: Not reported
Not reported

Region of Spill: 8
Facility Tele: Not reported
Spill Type: UST
Caller Agency: FINGER LAKES STATE PARKS
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (607) 387-7041

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 05/29/1996

Spill Cause: Other

Resource Affected: Groundwater

Water Affected: Not reported

Spill Source: Other Non Commercial/Industrial

Spill Notifier: Responsible Party

PBS Number: Not reported

Spill Date: 04/12/1994 11:50

Reported to Dept: 04/12/1994 11:57

Cleanup Ceased: 05/29/1996

Last Inspection: Not reported

Cleanup Meets Standard: True

Recommended Penalty: No Penalty

Spiller Cleanup Date: Not reported

Enforcement Date: Not reported

Investigation Complete: Not reported

UST Involvement: False

Spill Record Last Update: 05/30/1996

Corrective Action Plan Submitted: Not reported

Date Spill Entered In Computer Data File: 04/13/1994

Facility ID: 9400525
Facility Contact: Not reported
Investigator: PL
Caller Name: JIM TERRY
Caller Phone: (607) 387-7041
Notifier Name: Not reported
Notifier Phone: Not reported

Region of Spill: 8
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: FINGER LAKES STATE PARK
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

KEUKA LAKE STATE PARK (Continued)

S101102772

Spiller Contact:	Not reported	Spiller Phone:	(607) 387-7041
Spiller:	NYS PARKS & RECREATION		
Address:	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	01/23/1995		
Spill Cause:	Other	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	04/12/1994 15:00	Reported to Dept:	04/12/1994 15:27
Cleanup Ceased:	01/23/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/23/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	04/13/1994		

██████████
JERUSALEM, NY 11714

LUST

S102234040
N/A

LUST:

Exemption 6

Facility ID:	9515023	Region of Spill:	8
Facility Contact:	DALE BERGSTRESSER	Facility Tele:	██████████
Investigator:	PL	Spill Type:	UST
Caller Name:	██████████	Caller Agency:	IRA WYMAN OIL CO
Caller Phone:	██████████	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	██████████	Spiller Phone:	██████████
Spiller:	██████████		
Address:	██████████		
	JERUSALEM, NY		
Spill Class:	Known release that creates a file or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Tank Failure	Resource Affected:	Surface Water
Water Affected:	KEUKA LAKE	Spill Source:	Private Dwelling
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	02/21/1996 10:00	Reported to Dept:	02/21/1996 11:00
Cleanup Ceased:	Not reported		
Last Inspection:	02/21/1996		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	03/08/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/22/1996		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
KEUKA COLLEGE KEUKA PARK KEUKA COLLEGE JERUSALEM, NY 11714	LUST	S101340786 N/A

LUST:

Facility ID:	9413939	Region of Spill:	8
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PL	Spill Type:	Facility
Caller Name:	GEORGE BAUESCHNMIDT	Caller Agency:	PRO TESTING SERVICE
Caller Phone:	(716) 732-5312	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(716) 536-5251
Spiller:	KEUKA COLLEGE		
Address:	Not reported KEUKA PARK 14478		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Non Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	01/19/1995 11:00	Reported to Dept:	01/19/1995 12:05
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	False		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/20/1995		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	01/20/1995		

[REDACTED]	LUST	S100666417 N/A
LEVITTOWN, NY 11756		

LUST:

Facility ID:	9002819	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	LEUNG	Spill Type:	Facility
Caller Name:	[REDACTED]	Caller Agency:	NCDH
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	RESIDENCE		
Address:	Not reported Not reported		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	07/11/1990	Spill Source:	Private Dwelling
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	06/11/1990 16:35
Spill Notifier:	Health Department		
Spill Date:	06/08/1990 10:35		
Cleanup Ceased:	07/11/1990		
Last Inspection:	Not reported		

Exemption 6

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

RESIDENCE (Continued)

S100666417

Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 07/12/1990
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 06/13/1990

GENEVA N. GALLOW SCHOOL FARMEDGE RD & CARPENTER LEVITTOWN, NY 11756

UST

U001446252
N/A

Nassau County UST:

Facility ID:	052323	Tank ID:	0002
Tank Location:	Indoors, Belowground	Capacity:	00010000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	IN-TANK SYSTEM	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1087
Total Tanks:	1		

STEVEN KAROPCZYK SCHL FARMEDGE ROAD LEVITTOWN, NY 11756

UST

U001855031
N/A

Nassau County UST:

Facility ID:	052322	Tank ID:	0002
Tank Location:	Indoors, Belowground	Capacity:	00006000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #4		
Leak Detect:	IN-TANK SYSTEM	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1087
Total Tanks:	1		

D&J CIRCLE SALES 120379 3285 HEMP TPK & JERUSALEM LEVITTOWN, NY 11756

UST

U001445718
N/A

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
<hr/>		
D&J CIRCLE SALES 120379 (Continued)		U001445718
Nassau County UST:		
Facility ID:	040142	Tank ID: 0005
Tank Location:	Indoors, Belowground	Capacity: 00000550
Tank Status:	In Service	Tank Material: OTHER
Piping Type:	Other	Material Type: Fresh/Product
Int Protection:	Internal Lining	
Ext Protection:	PAINTED [e.g. asphaltic]	
Description:	OIL, FUEL #2	
Leak Detect:	ELECTRONIC	Containment: Double Wall Tank
Dispense Method:	Suction	Product Gauge: Yes
Fill Type:	Pumped	Install Date: 1291
Total Tanks:	1	
<hr/>		
MAJOR FUEL OIL CO	LUST	S100147448
LAUREL LA / ORCHARD ST		N/A
LEVITTOWN, NY 11756		
LUST:		
Facility ID:	8807549	Region of Spill: 1
Facility Contact:	Not reported	Facility Tele: Not reported
Investigator:	ACAMPORA	Spill Type: Facility
Caller Name:	MATT	Caller Agency: TYREE
Caller Phone:	(516) 249-3150	Caller Extension: Not reported
Notifier Name:	Not reported	Notifier Agency: Not reported
Notifier Phone:	Not reported	Notifier Extension: Not reported
Spiller Contact:	Not reported	Spiller Phone: (516) 588-9276
Spiller:	MAJOR FUEL OIL CO	
Address:	900 PORTION ROAD LAKE RONKONKOMA, NY 11779	
Spill Class:	Not reported	
Spill Closed Dt:	02/12/1989	
Spill Cause:	Tank Overfill	Resource Affected: On Land
Water Affected:	Not reported	Spill Source: Tank Truck
Spill Notifier:	Other	PBS Number: Not reported
Spill Date:	12/14/1988 13:30	Reported to Dept: 12/14/1988 13:42
Cleanup Ceased:	02/12/1989	
Last Inspection:	Not reported	
Cleanup Meets Standard:	True	
Recommended Penalty:	No Penalty	
Spiller Cleanup Date:	Not reported	
Enforcement Date:	Not reported	
Investigation Complete:	Not reported	
UST Involvement:	Fale	
Spill Record Last Update:	02/14/1989	
Corrective Action Plan Submitted:	Not reported	
Date Spill Entered In Computer Data File:	12/15/1988	
<hr/>		
LEE ROAD SCHOOL	UST	U001446126
LEE ROAD		N/A
LEVITTOWN, NY 11756		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number																																												
LEE ROAD SCHOOL (Continued)		U001446126																																												
<p>Nassau County UST:</p> <table border="0"> <tr> <td>Facility ID:</td> <td>052219</td> <td>Tank ID:</td> <td>0001</td> </tr> <tr> <td>Tank Location:</td> <td>Indoors, Belowground</td> <td>Capacity:</td> <td>00010000</td> </tr> <tr> <td>Tank Status:</td> <td>In Service</td> <td>Tank Material:</td> <td>Fiberglass Reinforced Plastic</td> </tr> <tr> <td>Piping Type:</td> <td>Double Walled Fiberglass</td> <td>Material Type:</td> <td>Fresh/Product</td> </tr> <tr> <td>Int Protection:</td> <td>None</td> <td></td> <td></td> </tr> <tr> <td>Ext Protection:</td> <td>NONE</td> <td></td> <td></td> </tr> <tr> <td>Description:</td> <td>OIL, FUEL #2</td> <td></td> <td></td> </tr> <tr> <td>Leak Detect:</td> <td>OTHER</td> <td>Containment:</td> <td>Double Wall Tank</td> </tr> <tr> <td>Dispense Method:</td> <td>Suction</td> <td>Product Gauge:</td> <td>Yes</td> </tr> <tr> <td>Fill Type:</td> <td>Gravity</td> <td>Install Date:</td> <td>0288</td> </tr> <tr> <td>Total Tanks:</td> <td>1</td> <td></td> <td></td> </tr> </table>			Facility ID:	052219	Tank ID:	0001	Tank Location:	Indoors, Belowground	Capacity:	00010000	Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic	Piping Type:	Double Walled Fiberglass	Material Type:	Fresh/Product	Int Protection:	None			Ext Protection:	NONE			Description:	OIL, FUEL #2			Leak Detect:	OTHER	Containment:	Double Wall Tank	Dispense Method:	Suction	Product Gauge:	Yes	Fill Type:	Gravity	Install Date:	0288	Total Tanks:	1		
Facility ID:	052219	Tank ID:	0001																																											
Tank Location:	Indoors, Belowground	Capacity:	00010000																																											
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic																																											
Piping Type:	Double Walled Fiberglass	Material Type:	Fresh/Product																																											
Int Protection:	None																																													
Ext Protection:	NONE																																													
Description:	OIL, FUEL #2																																													
Leak Detect:	OTHER	Containment:	Double Wall Tank																																											
Dispense Method:	Suction	Product Gauge:	Yes																																											
Fill Type:	Gravity	Install Date:	0288																																											
Total Tanks:	1																																													

MEENAN OIL 36 OAK TREE LANE LEVITTOWN, NY 11756	LUST	S100168939 N/A
---	------	-------------------

LUST:

Facility ID:	8807457	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	WALEKK	Spill Type:	Facility
Caller Name:	MR.KUNNMANN	Caller Agency:	MEENAN
Caller Phone:	(516) 783-1000	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	MEENAN OIL		
Address	3020 BURNS AVENUE WANTAGH, NY		
Spill Class:	Not reported		
Spill Closed Dt:	01/24/1989	Resource Affected:	On Land
Spill Cause:	Tank Overfill	Spill Source:	Other Commercial/Industrial
Water Affected:	Not reported	PBS Number:	Not reported
Spill Notifier:	Responsible Party	Reported to Dept:	12/09/1988 10:03
Spill Date:	12/08/1988 11:30		
Cleanup Ceased:	01/24/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	01/25/1989		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	12/13/1988		

SALK MIDDLE SCHOOL OLD JERUSALEM ROAD LEVITTOWN, NY 11756	UST	U001446132 N/A
---	-----	-------------------

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
SALK MIDDLE SCHOOL (Continued)		U001446132
Nassau County UST: Facility ID: 052225 Tank Location: Indoors, Belowground Tank Status: In Service Piping Type: Double Walled Fiberglass Int Protection: None Ext Protection: NONE Description: OIL, FUEL #2 Leak Detect: ELECTRONIC Dispense Method: Suction Fill Type: Gravity Total Tanks: 1	Tank ID: 0001 Capacity: 00015000 Tank Material: Fiberglass Reinforced Plastic Material Type: Fresh/Product Containment: Double Wall Tank Product Gauge: Yes Install Date: 0887	
MACARTHUR HIGH SCHOOL OLD JERUSALEM ROAD LEVITTOWN, NY 11756	UST	U001855009 N/A
Nassau County UST: Facility ID: 052220 Tank Location: Indoors, Belowground Tank Status: In Service Piping Type: Double Walled Fiberglass Int Protection: None Ext Protection: NONE Description: OIL, FUEL #2 Leak Detect: ELECTRONIC Dispense Method: Suction Fill Type: Gravity Total Tanks: 1	Tank ID: 0001 Capacity: 00020000 Tank Material: Fiberglass Reinforced Plastic Material Type: Fresh/Product Containment: Double Wall Tank Product Gauge: Yes Install Date: 0787	
RED SCHOOL HOUSE OLD JERUSALEM ROAD LEVITTOWN, NY 11756	UST	U001855052 N/A
Nassau County UST: Facility ID: 052384 Tank Location: Indoors, Belowground Tank Status: In Service Piping Type: Other Int Protection: None Ext Protection: FIBERGLASS REINFORCED PLASTIC Description: OIL, FUEL #2 Leak Detect: ELECTRONIC Dispense Method: Suction Fill Type: Gravity Total Tanks: 1	Tank ID: 0002 Capacity: 00000550 Tank Material: Fiberglass Reinforced Plastic Material Type: Fresh/Product Containment: Double Wall Tank Product Gauge: No Install Date: 0390	
<div style="background-color: black; width: 100px; height: 20px; margin-bottom: 5px;"></div> LEVITTOWN, NY 11756	LUST	S102232956 N/A
LUST: Facility ID: 8603980 Facility Contact: Not reported Investigator: Not reported Caller Name: Not reported Caller Phone: Not reported	Region of Spill: 1 Facility Tele: Not reported Spill Type: UST Caller Agency: Not reported Caller Extension: Not reported	

Exemption 6

Exemption 6

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
(Continued)		
<p>Notifier Name: Not reported Notifier Phone: Not reported Spiller Contact: Not reported Spiller: [REDACTED] Address: [REDACTED] LEVITTOWN Spill Class: Not reported Spill Closed Dt: 02/09/1987 Spill Cause: Tank Failure Water Affected: Not reported Spill Notifier: Other Spill Date: 09/18/1986 Cleanup Ceased: 02/09/1987 Last Inspection: Not reported Cleanup Meets Standard: True Recommended Penalty: No Penalty Spiller Cleanup Date: Not reported Enforcement Date: Not reported Investigation Complete: Not reported UST Involvement: False Spill Record Last Update: 11/14/1995 Corrective Action Plan Submitted: Not reported Date Spill Entered In Computer Data File: 09/27/1986</p>	<p>Notifier Agency: Not reported Notifier Extension: Not reported Spiller Phone: Not reported Resource Affected: Groundwater Spill Source: Private Dwelling PBS Number: Not reported Reported to Dept: 09/18/1986 16:30</p>	S102232956

MEENAN OIL
17 SHELTA LANE
LEVITTOWN, NY 11756

LUST

S101508043
 N/A

LUST:

Facility ID: 9415247	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: SCHULZ	Spill Type: Facility
Caller Name: JIM WATERS	Caller Agency: MEENAN
Caller Phone: (516) 783-1299	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: MEENAN OIL	
Address: Not reported	
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: 03/08/1995	Resource Affected: On Land
Spill Cause: Tank Overfill	Spill Source: Private Dwelling
Water Affected: Not reported	PBS Number: Not reported
Spill Notifier: Responsible Party	Reported to Dept: 02/21/1995 15:29
Spill Date: 02/21/1995 15:09	
Cleanup Ceased: 03/08/1995	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 03/08/1995	
Corrective Action Plan Submitted: Not reported	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
<hr/>		
MEENAN OIL (Continued)		S101508043
Date Spill Entered In Computer Data File: 02/22/1995		
<hr/>		
RELIANCE UTILITIES 10 SHERPARD LANE LEVITTOWN, NY 11756	LUST	S100174807 N/A
LUST:		
Facility ID: 9101321	Region of Spill: 1	
Facility Contact: Not reported	Facility Tele: Not reported	
Investigator: PARISH	Spill Type: Facility	
Caller Name: KEN NELSON	Caller Agency: RELIANCE UTILITIES	
Caller Phone: (516) 931-6800	Caller Extension: Not reported	
Notifier Name: Not reported	Notifier Agency: Not reported	
Notifier Phone: Not reported	Notifier Extension: Not reported	
Spiller Contact: Not reported	Spiller Phone: (516) 931-6800	
Spiller: RELIANCE UTILITIES		
Address: Not reported		
Not reported		
Spill Class: Not reported		
Spill Closed Dt: 01/21/1992		
Spill Cause: Tank Overfill	Resource Affected: On Land	
Water Affected: Not reported	Spill Source: Tank Truck	
Spill Notifier: Responsible Party	PBS Number: Not reported	
Spill Date: 05/02/1991 09:30	Reported to Dept: 05/02/1991 09:39	
Cleanup Ceased: 01/21/1992		
Last Inspection: Not reported		
Cleanup Meets Standard: True		
Recommended Penalty: No Penalty		
Spiller Cleanup Date: Not reported		
Enforcement Date: Not reported		
Investigation Complete: Not reported		
UST Involvement: False		
Spill Record Last Update: 01/22/1992		
Corrective Action Plan Submitted: Not reported		
Date Spill Entered In Computer Data File: 05/03/1991		

RELIANCE 29 SPRINGTIME LANE EAST LEVITTOWN, NY 11756	LUST	S100174580 N/A
LUST:		
Facility ID: 9012363	Region of Spill: 1	
Facility Contact: Not reported	Facility Tele: Not reported	
Investigator: KISPRT	Spill Type: Facility	
Caller Name: KEN RENN	Caller Agency: RELIANCE	
Caller Phone: (516) 931-6800	Caller Extension: Not reported	
Notifier Name: Not reported	Notifier Agency: Not reported	
Notifier Phone: Not reported	Notifier Extension: Not reported	
Spiller Contact: Not reported	Spiller Phone: Not reported	
Spiller: RELIANCE		
Address: 477 WEST JOHN STREET		
HICKSVILLE, NY		
Spill Class: Not reported		
Spill Closed Dt: 05/09/1991		
Spill Cause: Tank Overfill	Resource Affected: On Land	
Water Affected: Not reported	Spill Source: Tank Truck	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

RELIANCE (Continued)

S100174580

Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	03/01/1991 13:00	Reported to Dept:	03/01/1991 14:38
Cleanup Ceased:	05/09/1991		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	05/13/1991		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/04/1991		

CASTEL COAL & OIL CO. STOKES SCHOOL/CONDOR RD LEVITTOWN, NY 11756

LUST

S100148673
N/A

LUST:

Facility ID:	8607293	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	WALEK	Spill Type:	Facility
Caller Name:	Not reported	Caller Agency:	Not reported
Caller Phone:	Not reported	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(212) 823-8800
Spiller:	CASTEL COAL & OIL CO.		
Address	1724 EAST CHESTER ROAD BRONX, NY 14061		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	03/05/1987	Spill Source:	Other Commercial/Industrial
Spill Cause:	Tank Overfill	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	03/02/1987 11:30
Spill Notifier:	Health Department		
Spill Date:	02/27/1987 11:30		
Cleanup Ceased:	03/05/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/08/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/05/1987		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
ISLAND TREES HIGH SCHOOL STRAIGHT LANE LEVITTOWN, NY 11756	UST	U001855032 N/A
Nassau County UST:		
Facility ID:	052324	Tank ID:
Tank Location:	Indoors, Belowground	Capacity:
Tank Status:	In Service	Tank Material:
Piping Type:	Other	Material Type:
Int Protection:	None	
Ext Protection:	FIBERGLASS REINFORCED PLASTIC	
Description:	OIL, FUEL #4	
Leak Detect:	IN-TANK SYSTEM	Containment:
Dispense Method:	Suction	Product Gauge:
Fill Type:	Gravity	Install Date:
Total Tanks:	1	

UFI INC STRAIGHT LANE LEVITTOWN, NY 11756	LUST	S100666484 N/A
LUST:		
Facility ID:	9006235	Region of Spill:
Facility Contact:	Not reported	Facility Tele:
Investigator:	ACAMPORA	Spill Type:
Caller Name:	WALTER BERNINGER	Caller Agency:
Caller Phone:	(516) 586-4900	Caller Extension:
Notifier Name:	Not reported	Notifier Agency:
Notifier Phone:	Not reported	Notifier Extension:
Spiller Contact:	Not reported	Spiller Phone:
Spiller:	UFI INC	
Address:	Not reported	
	Not reported	
Spill Class:	Not reported	
Spill Closed Dt:	09/11/1990	
Spill Cause:	Other	Resource Affected:
Water Affected:	Not reported	Spill Source:
Spill Notifier:	Other	PBS Number:
Spill Date:	09/06/1990 10:00	Reported to Dept:
Cleanup Ceased:	09/11/1990	
Last Inspection:	Not reported	
Cleanup Meets Standard:	True	
Recommended Penalty:	No Penalty	
Spiller Cleanup Date:	Not reported	
Enforcement Date:	Not reported	
Investigation Complete:	Not reported	
UST Involvement:	False	
Spill Record Last Update:	09/12/1990	
Corrective Action Plan Submitted:	Not reported	
Date Spill Entered In Computer Data File:	09/07/1990	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
SUMMIT LANE SCHOOL	FINDS	1000300430
SUMMIT LANE	RCRIS-LQG	NYD100379619
LEVITTOWN, NY 11756	UST	

RCRIS:

Owner: LEVITTOWN UFSD
(212) 555-1212

Contact: HCONFIRST EWALD
(516) 520-5301

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>
X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

Nassau County UST:

Facility ID: 052226
Tank Location: Indoors, Belowground
Tank Status: In Service
Piping Type: Double Walled Fiberglass
Int Protection: None
Ext Protection: NONE
Description: OIL, FUEL #2
Leak Detect: ELECTRONIC
Dispense Method: Suction
Fill Type: Gravity
Total Tanks: 1

Tank ID: 0001
Capacity: 00015000
Tank Material: Fiberglass Reinforced Plastic
Material Type: Fresh/Product

Containment: Double Wall Tank
Product Gauge: Yes
Install Date: 0887

NCDPW
NO WANTAGH AVENUE
LEVITTOWN, NY 11756

LUST **S100177590**
N/A

LUST:

Facility ID: 9111735
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: KEN ARNOLD
Caller Phone: (516) 997-8282
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: NCDPW
Address: 425 SALISBURY DRIVE
WESTBURY, NY

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCDPW
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Known release that creates potential for fire or hazard. DEC Response.
Willing Responsible Party. Corrective action taken.

Spill Closed Dt: 04/13/1992
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 02/13/1992 15:30
Cleanup Ceased: 04/13/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported

Resource Affected: Groundwater
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 02/14/1992 10:00

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
NCDPW (Continued)		S100177590
Enforcement Date:	Not reported	
Investigation Complete:	Not reported	
UST Involvement:	True	
Spill Record Last Update:	11/09/1992	
Corrective Action Plan Submitted:	Not reported	
Date Spill Entered In Computer Data File:	02/19/1992	

Exemption 6

LEVITTOWN, NY 11756	LUST	S100665851 N/A
LUST:		
Facility ID: 8903731	Region of Spill: 1	
Facility Contact: Not reported	Facility Tele: Not reported	
Investigator: HOFMANN	Spill Type: Facility	
Caller Name: [REDACTED]	Caller Agency: MEENAN	
Caller Phone: [REDACTED]	Caller Extension: Not reported	
Notifier Name: Not reported	Notifier Agency: Not reported	
Notifier Phone: Not reported	Notifier Extension: Not reported	
Spiller Contact: Not reported	Spiller Phone: [REDACTED]	
Spiller: [REDACTED]		
Address: LEVITTOWN, NY		
Spill Class: Not reported	Resource Affected: Groundwater	
Spill Closed Dt: 09/19/1989	Spill Source: Private Dwelling	
Spill Cause: Other	PBS Number: Not reported	
Water Affected: Not reported	Reported to Dept: 07/13/1989 14:34	
Spill Notifier: Other		
Spill Date: 07/13/1989 08:53		
Cleanup Ceased: 09/19/1989		
Last Inspection: Not reported		
Cleanup Meets Standard: True		
Recommended Penalty: No Penalty		
Spiller Cleanup Date: Not reported		
Enforcement Date: Not reported		
Investigation Complete: Not reported		
UST Involvement: False		
Spill Record Last Update: 09/22/1989		
Corrective Action Plan Submitted: Not reported		
Date Spill Entered In Computer Data File: 07/14/1989		

**HEMPSTEAD TOWNSHIP OF DEPT OF SANIT
1600 MERRICK RD
NASSAU COUNTY, NY**

**RCRIS-SQG 1000125395
FINDS NYD981492101
SWF/LF**

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

HEMPSTEAD TOWNSHIP OF DEPT OF SANIT (Continued)

1000125395

RCRIS:

Owner: TOWNSHIP OF HEMPSTEAD
(212) 555-1212

Contact: A ALBANESE
(516) 378-4210

Classification: Not reported

Waste	Quantity	Waste	Quantity
X001	0.000 (N)	X002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

**LONG BEACH WATER POLLUTION CONTROL
NATIONAL BLVD AT BAY
NASSAU COUNTY, NY**

**FINDS
SWF/LF
RCRIS-LQG**

**1000231519
NYD981563018**

RCRIS:

Owner: CITY OF LONG BEACH
(212) 555-1212

Contact: RONALD FRIEDL
(516) 431-0230

Classification: Large Quantity Generator

Waste	Quantity
X002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

DETAILED ORPHAN LISTING

<u>Site</u>	<u>Database(s)</u>	<u>EDR ID Number</u> <u>EPA ID Number</u>
LONG BEACH WATER POLLUTION CONTROL (Continued)		1000231519
LF:		
Facility ID: 30E03	Telephone: Not reported	
DEC Region: 1	Permit #: 1280900088000080	
Permit issue date: 02/13/1996	Permit Expires: 02/12/2001	
Authrzd/Operate Dt: 02/13/1996	Constrct Perm #: Not reported	
Auth. to Construct: Not reported	Const Permit Exp: Not reported	
Regulatory Status: Permit	Receiving Waste: True	
Started Rec Waste: Not reported	Stop Rec Waste: Not reported	
Aquifer: Sole		
Date Ordered On Consent Signed:	Not reported	
Accomplish Date Of Order:	Not reported	
Inactive HWS: Not reported	Inactive HWS Num: Not reported	
Inactive HWS Class: Not reported		
Waste type: Energy Recovery		
Owner Name: Long Beach RR Corp.	Owner Type: Private	
Mail Address: 70 Water Street		
Long Beach, NY 11561		
Owner Phone Num: (516) 431-2058	Operator Name: Matt Gaskin	
Ny Transverse Mercator Coordinates East:	Not reported	
Ny Transverse Mercator Coordinates North:	Not reported	
Annual Report Submitted to ALB:		
1989: False	1990: False	
1991: False	1992: False	
1993: False	1994: False	
1995: False		
Primary Liner: Not reported	Secondary Liner: Not reported	
Annual Rprt Waived: Not reported	Tiping Fee Rprtd: Not reported	

**NASSAU COUNTY FIRE TRAINING CENTER
WINDING ROAD
OLD BETHPAGE, NY 11714**

SHWS

**S101008281
N/A**

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

NASSAU COUNTY FIRE TRAINING CENTER (Continued)

S101008281

SHWS:

Facility ID: 130042 EPA ID: NYD982531949

Owner: Nassau County
Winding Road
Old Bethpage, NY 11804

Owner Telephone: Not reported
Operator: Vocational Education+Extension Board
899 Jerusalem Ave.
Uniondale, NY 11553

Contact: Not reported Telephone: Not reported

Site Classification: Significant threat to the public health or environment - action required.

Region: 1

Site Type: Structure

Acres: 12 User: Nassau County

HW Started: 1960 HW Ended: 1985

HW Disposed: Chlorinated Solvents (FOO1), Xylene, Toluene, Dichloroethylene, Acetone, Ethyl Benzene, Trichloroethylene (TCE), Tetrachloroethylene (PCE or "perc.")

Units: unknown, unknown, unknown, unknown, unknown, unknown, unknown, unknown

Air Data: Unavailable Surf. Water Data: Unavailable

Grnd. Water Data: Available Soil Data: Available

Sediment Data: Unavailable

Ground Water Standards Contravention: Yes

Drinking Water Standards Contravention: No

Surface Water Standards Contravention: No

Air Standards Contravention: No

Enforcement Status: Order Has Been Signed Legal Action: No

State Action: Yes Fed Action: No

Remedial Action: In Progress

Remed action type: Soil and groundwater remediation

Soil Type: Sand and Gravel

Grnd Water Depth: 40 feet

Assessment of Environmental Problems:

Spillage of chlorinated solvents, acetone, toluene, methyl-ethyl-ketone and other chemicals have resulted in the contamination of the Bethpage State Park clubhouse supply well. The off-site plume of contaminated groundwater extends approximately 5,000 feet downgradient.

Assessment of Health Problems:

Occupational exposures were evaluated by the Site Utilization Plan and found to be within acceptable levels. The remedial investigation shows that petroleum constituents and solvents are in groundwater on-site and off-site. There are public water supply wells hydraulically downgradient of the site including South Farmingdale's water supply well. To date, water supply wells in use have not been found to be contaminated. The remedial action plan for this site includes, institutional controls, subsurface soil remediation and groundwater treatment. These measures are expected to eliminate the potential for the public to be exposed to the contamination at this site.

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
NYSDOT BIN 108119 RTE 135 OVER RTE 24 PLAINEDGE, NY 11714	FINDS RCRIS-LQG	1000556022 NYD986985711
RCRIS:		
Owner:	NYSDOT (212) 555-1212	
Contact:	BRUCE OGUREK (516) 360-6050	
Classification:	Large Quantity Generator	
<u>Waste</u>	<u>Quantity</u>	<u>Waste</u> <u>Quantity</u>
D000	0.000 (N)	D008 0.000 (N)
(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported		
Used Oil Recyc: No		
Violation Status: No violations found		

[REDACTED]	UST	U001447244 N/A
PLAINEDGE, NY 11756		

Exemption 6

Nassau County UST:

Facility ID:	055974	Tank ID:	0001
Tank Location:	Indoors, Belowground	Capacity:	00005000
Tank Status:	6	Tank Material:	STEEL
Piping Type:	Unknown	Material Type:	Fresh/Product
Int Protection:	Unknown		
Ext Protection:	UNKNOWN		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0370
Total Tanks:	1		

UNK RTE 135 PLAINVIEW, NY 11803	LUST NY Spills	S100664144 N/A
--	---------------------------	---------------------------

LUST:

Facility ID:	8902553	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PARISH	Spill Type:	Facility
Caller Name:	TED HORISHNEY	Caller Agency:	NCFM
Caller Phone:	(516) 566-5972	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	UNK		
Address	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. (Highly Improbable)		
Spill Closed Dt:	Not reported		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Passenger Vehicle
Spill Notifier:	Fire Department	PBS Number:	Not reported
Spill Date:	06/12/1989 10:09	Reported to Dept:	06/12/1989 10:38

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

UNK (Continued)

S100664144

Cleanup Ceased: Not reported
 Last Inspection: Not reported
 Cleanup Meets Standard: False
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 07/25/1992
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 06/14/1989

SPILLS:

Facility ID: 8402498	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: DOT	Spill Type: UST
Caller Name: SUPERVISOR PARKER	Caller Agency: NCFM
Caller Phone: (516) 663-5832	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: UNK	
Address: Not reported	
Spill Class: Not reported	
Spill Closed Dt: 04/23/1986	
Material Class: Petroleum	Spilled Code: 0012
Quantity Spilled: 110 gallons	Quant Recovered: 0 gallons
Spill Cause: Abandoned Drums	Resource Affected: On Land
Water Affected: Not reported	Spill Source: Unknown
Spill Notifier: Fire Department	PBS Number: Not reported
Spill Date: 12/13/1984 12:00	Reported to Dept: 12/14/1984 14:27
Tank Number: Not reported	Tank Capacity: 0 Gallons
Test method: Not reported	Leak Rate: 0.00
Gross Leak/Fail: Not reported	
Cleanup Ceased: 04/23/1986	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: False	
Spill Record Last Update: 11/08/1995	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 06/17/1986	

VEHICLE
 RTE 495 WB / EXIT 42
 PLAINVIEW, NY 11803

LUST

S101658263
 N/A

LUST:

Facility ID: 9507635	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: HAAS	Spill Type: Facility
Caller Name: OFFICER COOPER	Caller Agency: NC HIGHWAY PATROL
Caller Phone: (516) 573-8210	Caller Extension: Not reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

VEHICLE (Continued)

S101658263

Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	VEHICLE		
Address	Not reported		
	Not reported		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Unable/unwilling Responsible Party. Corrective action taken. (ISR)		
Spill Closed Dt:	09/22/1995		
Spill Cause:	Tank Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Commercial Vehicle
Spill Notifier:	Police Department	PBS Number:	Not reported
Spill Date:	09/21/1995 19:00	Reported to Dept:	09/21/1995 19:41
Cleanup Ceased:	09/22/1995		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	Not reported		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	09/25/1995		

ENVIRONMENTAL DRILLING AMES CT / COMMERCIAL DR PLAINVIEW, NY 11803

LUST

S100665795
N/A

LUST:

Facility ID:	8809881	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	PARISH	Spill Type:	Facility
Caller Name:	NICK RECCHIA	Caller Agency:	EDER ASSOCIATES
Caller Phone:	(516) 671-8440	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	Not reported
Spiller:	ENVIRONMENTAL DRILLING		
Address	Not reported		
	NEW JERSEY		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	03/24/1989	Spill Source:	Other Commercial/Industrial
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	03/23/1989 11:17
Spill Notifier:	Other		
Spill Date:	03/23/1989 10:00		
Cleanup Ceased:	03/24/1989		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	03/28/1989		
Corrective Action Plan Submitted:	Not reported		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

ENVIRONMENTAL DRILLING (Continued)

S100665795

Date Spill Entered In Computer Data File: 03/24/1989

STRATFORD ROAD SCHOOL
BEDFORD RD-ESSEX RD
PLAINVIEW, NY 11803

FINDS 1000258693
RCRIS-LQG NYD100393164

RCRIS:

Owner: PLAINVIEW OLD BETHPAGE
(212) 555-1212

Contact: RICHARD T MCCAULEY
(516) 937-6412

Classification: Large Quantity Generator

Waste	Quantity
X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

JLD BETHPAGE HIGH SCHOOL
CENTRAL PARK ROAD
PLAINVIEW, NY 11803

LUST

S100664054
N/A

LUST:

Facility ID: 9007474
Facility Contact: Not reported
Investigator: PARISH
Caller Name: GEORGE LAAKSO
Caller Phone: (516) 566-5274
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: OLD BETHPAGE HIGH SCHOOL
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: NCFM
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: (516) 937-6412

Spill Class: Not reported
Spill Closed Dt: 01/03/1992
Spill Cause: Other
Water Affected: Not reported
Spill Notifier: Fire Department
Spill Date: 10/05/1990 15:40
Cleanup Ceased: 01/03/1992

Resource Affected: In Sewer
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 10/05/1990 16:38

Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 01/06/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 10/10/1990

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
FERN PLACE ELEMENTARY SCH FERN PLACE AND ORCHARD ST PLAINVIEW, NY 11803	UST	U001855029 N/A

Nassau County UST:

Facility ID:	052316	Tank ID:	0003
Tank Location:	Indoors, Belowground	Capacity:	00010000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	NONE		
Description:	OIL, FUEL #4		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0488
Total Tanks:	1		

**KRAMER LANE SCHOOL
KRAMER LA.
PLAINVIEW, NY 11803**

**UST U002264562
N/A**

Nassau County UST:

Facility ID:	052347	Tank ID:	0002
Tank Location:	Indoors, Belowground	Capacity:	00010000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Double Walled Fiberglass	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1089
Total Tanks:	1		

**PARKWAY ELEMENTARY SCHOOL
MANETTO HILL RD-CENTRAL PK RD
PLAINVIEW, NY 11803**

**FINDS 1000273053
RCRIS-LOG NYD980552954**

RCRIS:

Owner: PLAINVIEW OLD BETHPAGE
(212) 555-1212

Contact: RICHARD T MCCAULEY
(516) 937-6412

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
NONE	0.000 (N)	X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

DETAILED ORPHAN LISTING

<u>Site</u>	<u>Database(s)</u>	<u>EDR ID Number</u> <u>EPA ID Number</u>
-------------	--------------------	--

MACHINE COMPONENTS CORP
70 NEW RD
PLAINVIEW, NY 11803

FINDS 1000241638
RCRIS-LQG NYD009300229

RCRIS:

Owner: JOSEPH KAPLAN-PRESIDENT
 (212) 555-1212

Contact: LES DUBOV
 (516) 694-7222

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D002	0.000 (N)	X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

PLAINVIEW OFFICE COMPLEX
OLD COUNTRY RD
PLAINVIEW, NY 11803

FINDS 1000258696
RCRIS-LQG NYD986878478

RCRIS:

Owner: COUNTY OF NASSAU
 (212) 555-1212

Contact: P. WITKOWSKI
 (516) 997-8282

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D001	0.000 (N)	D002	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

NYSDOT BIN 1037910
OLD COUNTRY RD OVER RTE 135
PLAINVIEW, NY 11803

RCRIS-LQG 1001028650
NYR000008821

RCRIS:

Owner: NYSDOT
 (516) 952-6053

Contact: KARL DRECHSLER
 (516) 864-4351

Classification: Large Quantity Generator

<u>Waste</u>	<u>Quantity</u>	<u>Waste</u>	<u>Quantity</u>
D000	0.000 (N)	D008	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
<hr/>		
NYS DOT BIN 1037910 (Continued)		1001028650
Used Oil Recyc: No		
Violation Status: No violations found		

**NY TELEPHONE CO.
OLD COUNTRY ROAD
PLAINVIEW, NY 11803**

LUST

**S100148690
N/A**

LUST:

Facility ID: 8607478	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: JEAN-LOUIS	Spill Type: Facility
Caller Name: Not reported	Caller Agency: Not reported
Caller Phone: Not reported	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: NY TELEPHONE CO.	
Address: Not reported	
Spill Class: Not reported	
Spill Closed Dt: 03/26/1987	
Spill Cause: Tank Test Failure	Resource Affected: Groundwater
Water Affected: Not reported	Spill Source: Other Commercial/Industrial
Spill Notifier: Tank Tester	PBS Number: Not reported
Spill Date: 03/09/1987 13:45	Reported to Dept: 03/09/1987 15:09
Cleanup Ceased: 03/26/1987	
Last Inspection: Not reported	
Cleanup Meets Standard: True	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: True	
Spill Record Last Update: 09/11/1987	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 03/12/1987	

**SHELL S/S
OLD COUNTRY ROAD
PLAINVIEW, NY 11803**

LUST

**S100171919
N/A**

LUST:

Facility ID: 8706265	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: GOERTZ	Spill Type: Facility
Caller Name: Not reported	Caller Agency: Not reported
Caller Phone: Not reported	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: Not reported
Spiller: SHELL S/S	
Address: 1 JERICHO PLAZA	
	JERICHO, NY 11753
Spill Class: Not reported	
Spill Closed Dt: 11/25/1987	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

SHELL S/S (Continued)

S100171919

Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	10/23/1987 15:00	Reported to Dept:	10/23/1987 21:02
Cleanup Ceased:	11/25/1987		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	True		
Spill Record Last Update:	11/27/1987		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	10/27/1987		

SHELL OIL OLD COUNTRY ROAD PLAINVIEW, NY 11803

LUST

S100177607
N/A

LUST:

Facility ID:	9111978	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	CHARLIE PRICE	Caller Agency:	ISLAND PUMP & TANK
Caller Phone:	(516) 261-1590	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 942-4121
Spiller:	SHELL OIL		
Address	1 JERICHO PLAZA JERICHO, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	09/16/1992		
Spill Cause:	Tank Test Failure	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Gas Station
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	02/21/1992 14:30	Reported to Dept:	02/21/1992 15:50
Cleanup Ceased:	09/16/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	09/18/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	02/24/1992		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
JAMAICA ASH OLD COUNTRY ROAD PLAINVIEW, NY 11803	LUST	S100664874 N/A

LUST:

Facility ID:	9209403	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	DECANDIA	Spill Type:	Facility
Caller Name:	TOM TROUSDELL	Caller Agency:	NCFM
Caller Phone:	(516) 566-5213	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 333-2777
Spiller:	JAMAICA ASH		
Address:	172 SCHOOL ST WESTBURY, NY		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	12/28/1992		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Other	PBS Number:	Not reported
Spill Date:	11/12/1992 12:00	Reported to Dept:	11/12/1992 13:20
Cleanup Ceased:	12/28/1992		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	12/29/1992		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	11/13/1992		

ISLAND TRANSPORTATION OLD CTRY RD/RD SWAMP ROAD PLAINVIEW, NY 11803	LUST	S100665941 N/A
--	-------------	---------------------------

LUST:

Facility ID:	8909000	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	MANCILLA	Spill Type:	Facility
Caller Name:	INSPECTOR TUSA	Caller Agency:	NCFM
Caller Phone:	(516) 521-3751	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 694-4497
Spiller:	ISLAND TRANSPORTATION		
Address:	299 EDISON AVENUE WEST BABYLON, NY 11704		
Spill Class:	Not reported	Resource Affected:	On Land
Spill Closed Dt:	12/14/1989	Spill Source:	Tank Truck
Spill Cause:	Other	PBS Number:	Not reported
Water Affected:	Not reported	Reported to Dept:	12/13/1989 10:38
Spill Notifier:	Fire Department		
Spill Date:	12/13/1989 10:30		
Cleanup Ceased:	12/14/1989		
Last Inspection:	Not reported		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

ISLAND TRANSPORTATION (Continued)

S100665941

Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 12/19/1989
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 12/19/1989

PLAINVIEW, NY 11803

UST

U001855084
N/A

Nassau County UST:

Facility ID: 053148
 Tank Location: Indoors, Belowground
 Tank Status: In Service
 Piping Type: Galvanized Steel
 Int Protection: None
 Ext Protection: PAINTED [e.g. asphaltic]
 Description: OIL, FUEL #2
 Leak Detect: OTHER
 Dispense Method: Suction
 Fill Type: Gravity
 Total Tanks: 1

Tank ID: 0001
 Capacity: 00001500
 Tank Material: STEEL
 Material Type: Fresh/Product

Containment: Other
 Product Gauge: No
 Install Date: 1269

Exemption 6

SHELL S/S PLAINVIEW / OLD CTRY ROAD PLAINVIEW, NY 11803

LUST

S100492056
N/A

LUST:

Facility ID: 9209688
 Facility Contact: Not reported
 Investigator: T/T/F
 Caller Name: DOUG SCHRIMP
 Caller Phone: (516) 261-1590
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: SHELL S/S
 Address: Not reported
 Spill Class: No spill occurred. (Not Possible)
 Spill Closed Dt: 04/19/1995
 Spill Cause: Tank Test Failure
 Water Affected: Not reported
 Spill Notifier: Tank Tester
 Spill Date: 11/19/1992 18:00
 Cleanup Ceased: 04/19/1995
 Last Inspection: Not reported
 Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: True

Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: ISLAND PUMP & TANK
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: Not reported

Resource Affected: Groundwater
 Spill Source: Gas Station
 PBS Number: Not reported
 Reported to Dept: 11/19/1992 19:24

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
SHELL S/S (Continued)		S100492056

Spill Record Last Update: 04/25/1995
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 11/20/1992

**PASADENA DRIVE ELEMENTARY SCHOOL
 RICHARD CT-BENMUR ST
 PLAINVIEW, NY 11803**

**FINDS 1000145403
 RCRIS-LQG NYD982532707**

RCRIS:

Owner: PLAINVIEW OLD BETHPAGE
 (212) 555-1212

Contact: LAWRENCE HERZOG
 (516) 937-6412

Classification: Large Quantity Generator

Waste	Quantity
X001	0.000 (N)

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

Violation Status: No violations found

**PLAINVIEW FIRE DISTRICT
 ROUND SWAMP / OLD BETHPAG
 PLAINVIEW, NY 11803**

**LUST S100149233
 N/A**

LUST:

Facility ID: 8707415
 Facility Contact: Not reported
 Investigator: GOERTZ
 Caller Name: Not reported
 Caller Phone: Not reported
 Notifier Name: Not reported
 Notifier Phone: Not reported
 Spiller Contact: Not reported
 Spiller: PLAINVIEW FIRE DISTRICT
 Address: ROUND SWAMP & OLD BETHPAG
 PLAINVIEW,N

Region of Spill: 1
 Facility Tele: Not reported
 Spill Type: Facility
 Caller Agency: Not reported
 Caller Extension: Not reported
 Notifier Agency: Not reported
 Notifier Extension: Not reported
 Spiller Phone: (516) 933-2640

Spill Class: Not reported
 Spill Closed Dt: 11/13/1989
 Spill Cause: Tank Test Failure
 Water Affected: Not reported
 Spill Notifier: Tank Tester
 Spill Date: 11/23/1987 13:00
 Cleanup Ceased: 11/13/1989
 Last Inspection: Not reported

Resource Affected: Groundwater
 Spill Source: Other Non Commercial/Industrial
 PBS Number: Not reported
 Reported to Dept: 11/27/1987 12:00

Cleanup Meets Standard: True
 Recommended Penalty: No Penalty
 Spiller Cleanup Date: Not reported
 Enforcement Date: Not reported
 Investigation Complete: Not reported
 UST Involvement: False
 Spill Record Last Update: 11/15/1989
 Corrective Action Plan Submitted: Not reported
 Date Spill Entered In Computer Data File: 12/02/1987

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

SEAFORD OYSTER BAY EXPRES PLAINVIEW, NY 11803

LUST

S102235074
N/A

LUST:

Facility ID:	9516654	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	GIBBONS	Spill Type:	UST
Caller Name:	JOE SANTORO	Caller Agency:	GIFFORDS OIL
Caller Phone:	(516) 576-3000	Caller Extension:	Not reported
Notifier Name:	DRIVER	Notifier Agency:	Not reported
Notifier Phone:	(0) -	Notifier Extension:	Not reported
Spiller Contact:	JOE	Spiller Phone:	(516) 576-3000
Spiller:	GIFFORDS OIL		
Address:	171 EAST AMES COURT PLAINVIEW, NY 11803-		
Spill Class:	Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	06/21/1996		
Spill Cause:	Other	Resource Affected:	On Land
Water Affected:	Not reported	Spill Source:	Tank Truck
Spill Notifier:	Responsible Party	PBS Number:	Not reported
Spill Date:	03/26/1996 14:20	Reported to Dept:	03/26/1996 14:30
Cleanup Ceased:	Not reported		
Last Inspection:	Not reported		
Cleanup Meets Standard:	True		
Recommended Penalty:	No Penalty		
Spiller Cleanup Date:	Not reported		
Enforcement Date:	Not reported		
Investigation Complete:	Not reported		
UST Involvement:	False		
Spill Record Last Update:	06/21/1996		
Corrective Action Plan Submitted:	Not reported		
Date Spill Entered In Computer Data File:	03/26/1996		

OLD BETHPAGE SCHOOL STADFORD ROAD SCHOOL PLAINVIEW, NY 11803

LUST

S101658198
N/A

LUST:

Facility ID:	9506301	Region of Spill:	1
Facility Contact:	Not reported	Facility Tele:	Not reported
Investigator:	T/T/F	Spill Type:	Facility
Caller Name:	STEVE LAZAR	Caller Agency:	UNICO
Caller Phone:	(516) 864-1772	Caller Extension:	Not reported
Notifier Name:	Not reported	Notifier Agency:	Not reported
Notifier Phone:	Not reported	Notifier Extension:	Not reported
Spiller Contact:	Not reported	Spiller Phone:	(516) 349-4793
Spiller:	PLAINVIEW OLD BETHPAGE SC		
Address:	117 CENTRAL PARK ROAD PLAINVIEW, NY 11803-		
Spill Class:	Known release that creates potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.		
Spill Closed Dt:	10/17/1995		
Spill Cause:	Tank Test Failure	Resource Affected:	Groundwater
Water Affected:	Not reported	Spill Source:	Other Commercial/Industrial
Spill Notifier:	Tank Tester	PBS Number:	Not reported
Spill Date:	08/22/1995 10:30	Reported to Dept:	08/22/1995 11:59
Cleanup Ceased:	10/17/1995		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
<hr/>		
OLD BETHPAGE SCHOOL (Continued)		S101658198
<p> Last Inspection: Not reported Cleanup Meets Standard: True Recommended Penalty: No Penalty Spiller Cleanup Date: Not reported Enforcement Date: Not reported Investigation Complete: Not reported UST Involvement: False Spill Record Last Update: 10/18/1995 Corrective Action Plan Submitted: Not reported Date Spill Entered In Computer Data File: 08/23/1995 </p>		

NYSDOT-PLAINVIEW SUNNYSIDE BLVD.& RTE 495 PLAINVIEW, NY 11803	LUST UST	U001446580 N/A
--	---------------------------	---------------------------------

LUST:

Facility ID: 8602110	Region of Spill: 1
Facility Contact: Not reported	Facility Tele: Not reported
Investigator: ACAMPORA	Spill Type: UST
Caller Name: Not reported	Caller Agency: Not reported
Caller Phone: Not reported	Caller Extension: Not reported
Notifier Name: Not reported	Notifier Agency: Not reported
Notifier Phone: Not reported	Notifier Extension: Not reported
Spiller Contact: Not reported	Spiller Phone: (516) 935-6111
Spiller: NYSDOT	
Address: 500 ROBBINS LANE SYOSSET, NY 11791	
Spill Class: Known release with minimal potential for fire or hazard. DEC Response. Willing Responsible Party. Corrective action taken.	
Spill Closed Dt: Not reported	
Spill Cause: Tank Failure	Resource Affected: Groundwater
Water Affected: Not reported	Spill Source: Other Non Commercial/Industrial
Spill Notifier: Responsible Party	PBS Number: Not reported
Spill Date: 06/23/1986	Reported to Dept: 06/27/1986 15:15
Cleanup Ceased: Not reported	
Last Inspection: Not reported	
Cleanup Meets Standard: False	
Recommended Penalty: No Penalty	
Spiller Cleanup Date: Not reported	
Enforcement Date: Not reported	
Investigation Complete: Not reported	
UST Involvement: True	
Spill Record Last Update: 11/10/1995	
Corrective Action Plan Submitted: Not reported	
Date Spill Entered In Computer Data File: 07/15/1986	

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

NYSDOT-PLAINVIEW (Continued)

U001446580

Nassau County UST:

Facility ID:	053184	Tank ID:	0010
Tank Location:	Indoors, Belowground	Capacity:	00002500
Tank Status:	In Service	Tank Material:	STEEL
Piping Type:	Unknown	Material Type:	Fresh/Product
Int Protection:	Unknown		
Ext Protection:	UNKNOWN		
Description:	OIL, FUEL #2		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Gravity	Install Date:	0664
Total Tanks:	1		

H.B.MATTLIN MIDDLE SCHOOL WASHINGTON STREET PLAINVIEW, NY 11803

UST

U001446001
N/A

Nassau County UST:

Facility ID:	052061	Tank ID:	0002
Tank Location:	Indoors, Belowground	Capacity:	00020000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Other	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	NONE		
Description:	OIL, FUEL #2		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Pumped	Install Date:	0388
Total Tanks:	1		

PLAINVIEW-OLD BETHPAGE PK WASHINGTON AVENUE PLAINVIEW, NY 11803

UST

U001855097
N/A

Nassau County UST:

Facility ID:	053203	Tank ID:	0002
Tank Location:	Indoors, Belowground	Capacity:	00003600
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Unknown	Material Type:	Fresh/Product
Int Protection:	Unknown		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	HYPOCHLORITE SOLUTIONS		
Leak Detect:	OTHER	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0186
Total Tanks:	3		

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
------	-------------	--------------------------------

PLAINVIEW-OLD BETHPAGE PK (Continued)

U001855097

Facility ID:	053203	Tank ID:	0003
Tank Location:	Indoors, Belowground	Capacity:	00000500
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Unknown	Material Type:	Fresh/Product
Int Protection:	Unknown		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	ACIDS, NOS		
Leak Detect:	OTHER	Containment:	Other
Dispense Method:	Suction	Product Gauge:	No
Fill Type:	Pumped	Install Date:	0186
Total Tanks:	3		

Facility ID:	053203	Tank ID:	0004
Tank Location:	Indoors, Belowground	Capacity:	00006000
Tank Status:	In Service	Tank Material:	Fiberglass Reinforced Plastic
Piping Type:	Double Walled Fiberglass	Material Type:	Fresh/Product
Int Protection:	None		
Ext Protection:	FIBERGLASS REINFORCED PLASTIC		
Description:	OIL, FUEL #2		
Leak Detect:	ELECTRONIC	Containment:	Double Wall Tank
Dispense Method:	Suction	Product Gauge:	Yes
Fill Type:	Gravity	Install Date:	1189
Total Tanks:	3		

PLAINVIEW COMM PARK
WASHINGTON BLVD
PLAINVIEW, NY 11803

LUST

S100177523
N/A

LUST:

Facility ID: 9110559
Facility Contact: Not reported
Investigator: T/T/F
Caller Name: SCOTT SCHUCK
Caller Phone: (516) 586-4900
Notifier Name: Not reported
Notifier Phone: Not reported
Spiller Contact: Not reported
Spiller: PLAINVIEW COMM PARK
Address: Not reported
Not reported

Region of Spill: 1
Facility Tele: Not reported
Spill Type: Facility
Caller Agency: F&N
Caller Extension: Not reported
Notifier Agency: Not reported
Notifier Extension: Not reported
Spiller Phone: Not reported

Spill Class: Not reported
Spill Closed Dt: 02/03/1992
Spill Cause: Tank Test Failure
Water Affected: Not reported
Spill Notifier: Tank Tester
Spill Date: 12/29/1991 12:00

Resource Affected: Groundwater
Spill Source: Other Non Commercial/Industrial
PBS Number: Not reported
Reported to Dept: 01/08/1992 16:00

Cleanup Ceased: 02/03/1992
Last Inspection: Not reported
Cleanup Meets Standard: True
Recommended Penalty: No Penalty
Spiller Cleanup Date: Not reported
Enforcement Date: Not reported
Investigation Complete: Not reported
UST Involvement: False
Spill Record Last Update: 02/05/1992
Corrective Action Plan Submitted: Not reported
Date Spill Entered In Computer Data File: 01/10/1992

DETAILED ORPHAN LISTING

Site	Database(s)	EDR ID Number EPA ID Number
GRUMMAN AEROSPACE CORP #77 SR A1A 1 MI S OF STUART STUART, FL 11714	CORRACTS RCRIS-LQG RCRIS-TSD RAATS	1000698804 FLD043117522

RCRIS Corrective Action Summary:

Effective Date: 01/12/90
Legal Authority: RCRA 3008(h) or equivalent
Effective Date: 10/29/95
Legal Authority: RCRA 3008(h) or equivalent

RCRIS:

Owner: JOHN OHLMANN, DIR
(516) 575-2385

Contact: JOHN OHLMANN
(516) 575-2385

Classification: Large Quantity Generator, TSDF

Waste	Quantity	Waste	Quantity
D007	0.000 (T)	F002	0.000 (T)
F005	0.000 (T)		

(P) = Pounds , (K) = Kilograms , (M) = Metric Tons , (T) = Tons , (N) = Not Reported

Used Oil Recyc: No

TSDF Activities: Not reported

Violation Status: Violations exist, violations outstanding in the closure/post-closure area

There are 3 compliance/violation record(s) reported at this site:

Evaluation	Area of Violation	Date of Compliance
Compliance Evaluation Inspection (CEI)	Generator-All Requirements	06/26/1986
Compliance Evaluation Inspection (CEI)	Generator-All Requirements	01/29/1986
	Generator-All Requirements	01/29/1986
Compliance Evaluation Inspection (CEI)	Generator-All Requirements	12/04/1984
	Generator-All Requirements	12/04/1984
	Generator-All Requirements	12/04/1984

CORRACTS Data:

Prioritization: High
Status: RCRA Facility Investigation Completed, Determination of Need for a RCRA Facility Investigation, RFI Imposition, RFI Workplan Approved, RCRA Facility Investigation Approved, CMS Workplan Approved, Corrective Measure Study Approved



EPA Waste Codes Addendum

Code	Description
D000	NOT DEFINED
D001	IGNITABLE HAZARDOUS WASTES ARE THOSE WASTES WHICH HAVE A FLASHPOINT OF LESS THAN 140 DEGREES FAHRENHEIT AS DETERMINED BY A PENSKEY-MARTENS CLOSED CUP FLASH POINT TESTER. ANOTHER METHOD OF DETERMINING THE FLASH POINT OF A WASTE IS TO REVIEW THE MATERIAL SAFETY DATA SHEET, WHICH CAN BE OBTAINED FROM THE MANUFACTURER OR DISTRIBUTOR OF THE MATERIAL. LACQUER THINNER IS AN EXAMPLE OF A COMMONLY USED SOLVENT WHICH WOULD BE CONSIDERED AS IGNITABLE HAZARDOUS WASTE.
D002	A WASTE WHICH HAS A PH OF LESS THAN 2 OR GREATER THAN 12.5 IS CONSIDERED TO BE A CORROSIVE HAZARDOUS WASTE. SODIUM HYDROXIDE, A CAUSTIC SOLUTION WITH A HIGH PH, IS OFTEN USED BY INDUSTRIES TO CLEAN OR DEGREASE PARTS. HYDROCHLORIC ACID, A SOLUTION WITH A LOW PH, IS USED BY MANY INDUSTRIES TO CLEAN METAL PARTS PRIOR TO PAINTING. WHEN THESE CAUSTIC OR ACID SOLUTIONS BECOME CONTAMINATED AND MUST BE DISPOSED, THE WASTE WOULD BE A CORROSIVE HAZARDOUS WASTE.
D003	A MATERIAL IS CONSIDERED TO BE A REACTIVE HAZARDOUS WASTE IF IT IS NORMALLY UNSTABLE, REACTS VIOLENTLY WITH WATER, GENERATES TOXIC GASES WHEN EXPOSED TO WATER OR CORROSIVE MATERIALS, OR IF IT IS CAPABLE OF DETONATION OR EXPLOSION WHEN EXPOSED TO HEAT OR A FLAME. ONE EXAMPLE OF SUCH WASTE WOULD BE WASTE GUNPOWDER.
D004	ARSENIC
D005	BARIUM
D006	CADMIUM
D007	CHROMIUM
D008	LEAD
D009	MERCURY
D010	SELENIUM
D011	SILVER
D018	BENZENE
D019	CARBON TETRACHLORIDE
D022	CHLOROFORM
D027	1,4-DICHLOROBENZENE
D028	1,2-DICHLOROETHANE
D029	1,1-DICHLOROETHYLENE
D030	2,4-DINITROTOLUENE

EPA Waste Codes Addendum

Code	Description
D035	METHYL ETHYL KETONE
D039	TETRACHLOROETHYLENE
D040	TRICHLOROETHYLENE
F001	THE FOLLOWING SPENT HALOGENATED SOLVENTS USED IN DEGREASING: TETRACHLOROETHYLENE, TRICHLOROETHYLENE, METHYLENE CHLORIDE, 1,1,1-TRICHLOROETHANE, CARBON TETRACHLORIDE, AND CHLORINATED FLUOROCARBONS; ALL SPENT SOLVENT MIXTURES/BLENDS USED IN DEGREASING CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F002	THE FOLLOWING SPENT HALOGENATED SOLVENTS: TETRACHLOROETHYLENE, METHYLENE CHLORIDE, TRICHLOROETHYLENE, 1,1,1-TRICHLOROETHANE, CHLOROBENZENE, 1,1,2-TRICHLORO-1,2,2-TRIFLUOROETHANE, ORTHO-DICHLOROBENZENE, TRICHLOROFLUOROMETHANE, AND 1,1,2-TRICHLOROETHANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE HALOGENATED SOLVENTS OR THOSE LISTED IN F001, F004, OR F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F003	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: XYLENE, ACETONE, ETHYL ACETATE, ETHYL BENZENE, ETHYL ETHER, METHYL ISOBUTYL KETONE, N-BUTYL ALCOHOL, CYCLOHEXANONE, AND METHANOL; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONLY THE ABOVE SPENT NON-HALOGENATED SOLVENTS; AND ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS, AND, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THOSE SOLVENTS LISTED IN F001, F002, F004, AND F005, AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F004	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: CRESOLS AND CRESYLIC ACID, AND NITROBENZENE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, AND F005; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F005	THE FOLLOWING SPENT NON-HALOGENATED SOLVENTS: TOLUENE, METHYL ETHYL KETONE, CARBON DISULFIDE, ISOBUTANOL, PYRIDINE, BENZENE, 2-ETHOXYETHANOL, AND 2-NITROPROPANE; ALL SPENT SOLVENT MIXTURES/BLENDS CONTAINING, BEFORE USE, A TOTAL OF TEN PERCENT OR MORE (BY VOLUME) OF ONE OR MORE OF THE ABOVE NON-HALOGENATED SOLVENTS OR THOSE SOLVENTS LISTED IN F001, F002, OR F004; AND STILL BOTTOMS FROM THE RECOVERY OF THESE SPENT SOLVENTS AND SPENT SOLVENT MIXTURES.
F006	WASTEWATER TREATMENT SLUDGES FROM ELECTROPLATING OPERATIONS EXCEPT FROM THE FOLLOWING PROCESSES: (1) SULFURIC ACID ANODIZING OF ALUMINUM; (2) TIN PLATING ON CARBON STEEL; (3) ZINC PLATING (SEGREGATED BASIS) ON CARBON STEEL; (4) ALUMINUM OR ZINC-ALUMINUM PLATING ON CARBON STEEL; (5)

EPA Waste Codes Addendum

Code	Description
	CLEANING/STRIPPING ASSOCIATED WITH TIN, ZINC AND ALUMINUM PLATING ON CARBON STEEL; AND (6) CHEMICAL ETCHING AND MILLING OF ALUMINUM.
F007	SPENT CYANIDE PLATING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS
F008	PLATING BATH RESIDUES FROM THE BOTTOM OF PLATING BATHS FROM ELECTROPLATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.
F009	SPENT STRIPPING AND CLEANING BATH SOLUTIONS FROM ELECTROPLATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.
F010	QUENCHING BATH RESIDUES FROM OIL BATHS FROM METAL HEAT TREATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.
F011	SPENT CYANIDE SOLUTIONS FROM SALT BATH POT CLEANING FROM METAL HEAT TREATING OPERATIONS.
F012	QUENCHING WASTE WATER TREATMENT SLUDGES FROM METAL HEAT TREATING OPERATIONS WHERE CYANIDES ARE USED IN THE PROCESS.
F017	NOT DEFINED
F018	NOT DEFINED
F019	WASTEWATER TREATMENT SLUDGES FROM THE CHEMICAL CONVERSION COATING OF ALUMINUM EXCEPT FROM ZIRCONIUM PHOSPHATING IN ALUMINUM CAN WASHING WHEN SUCH PHOSPHATING IS AN EXCLUSIVE CONVERSION COATING PROCESS.
K050	HEAT EXCHANGER BUNDLE CLEANING SLUDGE FROM THE PETROLEUM REFINING INDUSTRY
K052	TANK BOTTOMS (LEADED) FROM THE PETROLEUM REFINING INDUSTRY
NONE	NONE
P003	ACROLEIN
P003	2-PROPENAL
P030	CYANIDES (SOLUBLE CYANIDE SALTS), NOT OTHERWISE SPECIFIED
P064	METHANE, ISOCYANATO-
P064	METHYL ISOCYANATE
P104	SILVER CYANIDE
P104	SILVER CYANIDE AG(CN)
P106	SODIUM CYANIDE
P106	SODIUM CYANIDE NA(CN)
P122	ZINC PHOSPHIDE Zn_3P_2 , WHEN PRESENT AT CONCENTRATIONS GREATER THAN 10% (R,T)

EPA Waste Codes Addendum

Code	Description
U002	ACETONE (I)
U002	2-PROPANONE (I)
U003	ACETONITRILE (I,T)
U028	1,2-BENZENEDICARBOXYLIC ACID, BIS(2-ETHYLHEXYL) ESTER
U028	DIETHYLHEXYL PHTHALATE
U036	CHLORDANE, ALPHA & GAMMA ISOMERS
U036	4,7-METHANO-1H-INDENE, 1,2,4,5,6,7,8,8-OCTACHLORO-2,3,3A,4,7,7A-HEXAHYDRO-
U037	BENZENE, CHLORO-
U037	CHLOROBENZENE
U044	CHLOROFORM
U044	METHANE, TRICHLORO-
U061	BENZENE, 1,1'-(2,2,2-TRICHLOROETHYLIDENE)BIS[4-CHLORO-
U061	DDT
U070	BENZENE, 1,2-DICHLORO-
U070	O-DICHLOROBENZENE
U071	BENZENE, 1,3-DICHLORO-
U071	M-DICHLOROBENZENE
U072	BENZENE, 1,4-DICHLORO-
U072	P-DICHLOROBENZENE
U076	ETHANE, 1,1-DICHLORO-
U076	ETHYLIDENE DICHLORIDE
U080	METHANE, DICHLORO-
U080	METHYLENE CHLORIDE
U105	BENZENE, 1-METHYL-2,4-DINITRO-
U105	2,4-DINITROTOLUENE
U106	BENZENE, 2-METHYL-1,3-DINITRO-
U106	2,6-DINITROTOLUENE

EPA Waste Codes Addendum

Code	Description
U112	ACETIC ACID ETHYL ESTER (I)
U112	ETHYL ACETATE (I)
U117	ETHANE, 1,1'-OXYBIS-(I)
U117	ETHYL ETHER (I)
U122	FORMALDEHYDE
U133	HYDRAZINE (R,T)
U134	HYDROFLUORIC ACID (C,T)
U134	HYDROGEN FLUORIDE (C,T)
U140	ISOBUTYL ALCOHOL (I,T)
U140	1-PROPANOL, 2-METHYL- (I,T)
U147	2,5-FURANDIONE
U147	MALEIC ANHYDRIDE
U151	MERCURY
U154	METHANOL (I)
U154	METHYL ALCOHOL (I)
U159	2-BUTANONE (I,T)
U159	METHYL ETHYL KETONE (MEK) (I,T)
U160	2-BUTANONE, PEROXIDE (R,T)
U160	METHYL ETHYL KETONE PEROXIDE (R,T)
U161	METHYL ISOBUTYL KETONE (I)
U161	4-METHYL-2-PENTANONE (I)
U161	PENTANOL, 4-METHYL-
U165	NAPHTHALENE
U188	PHENOL
U190	1,3-ISOBENZOFURANDIONE
U190	PHTHALIC ANHYDRIDE
U196	PYRIDINE

EPA Waste Codes Addendum

Code	Description
U197	P-BENZOQUINONE
U197	2,5-CYCLOHEXADIENE-1,4-DIONE
U210	ETHENE, TETRACHLORO-
U210	TETRACHLOROETHYLENE
U211	CARBON TETRACHLORIDE
U211	METHANE, TETRACHLORO-
U213	FURAN, TETRAHYDRO-(I)
U213	TETRAHYDROFURAN (I)
U220	BENZENE, METHYL-
U220	TOLUENE
U223	BENZENE, 1,3-DIISOCYANATOMETHYL- (R,T)
U223	TOLUENE DIISOCYANATE (R,T)
U226	ETHANE, 1,1,1-TRICHLORO-
U226	METHYL CHLOROFORM
U228	ETHENE, TRICHLORO-
U228	TRICHLOROETHYLENE
U238	CARBAMIC ACID, ETHYL ESTER
U238	ETHYL CARBAMATE (URETHANE)
U239	BENZENE, DIMETHYL- (I,T)
U239	XYLENE (I)
X001	WASTE OILS
X002	POLYCHLORINATED BIPHENOLS (PCBS)
X003	OTHER STATE REGULATED WASTES [I.E., DIESEL FUEL, GASOLINE AND HOME HEATING OIL]

Thank you for your business.
Please contact EDR at 1-800-352-0050
with any questions or comments.

Disclaimer

This Report contains information obtained from a variety of public sources and EDR makes no representation or warranty regarding the accuracy, reliability, quality, or completeness of said information or the information contained in this report. The customer shall assume full responsibility for the use of this report.

No warranty of merchantability or of fitness for a particular purpose, expressed or implied, shall apply and EDR specifically disclaims the making of such warranties. In no event shall EDR be liable to anyone for special, incidental, consequential or exemplary damages.

GEOCHECK VERSION 2.1 SUMMARY

FEDERAL DATABASE WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>
1	404601073303602
1	404601073303601
2	404546073293701
3	404539073291401
7	404526073301601
8	404526073301401
10	404520073301401
11	404517073310201
11	404517073310101
12	404517073300901
13	404507073301101
16	404418073294502
16	404418073294501
17	404416073294601
17	404416073294602

STATE WATER WELL INFORMATION

<u>MAP ID</u>	<u>WELL ID</u>
4	017
4	016
4	018
5	004
6	003
6	002
9	015
9	014
9	013
14	005
15	008

PUBLIC WATER SUPPLY SYSTEM INFORMATION (EPA-FRDS)

Map ID: 4
PWS ID: NY0002829
PWS Name: HICKSVILLE WATER DISTRICT
4 DEAN STREET
HICKSVILLE, NY 11802

Well currently has or has had major violation(s): No

Map ID: 5
PWS ID: NY0002817
PWS Name: BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Well currently has or has had major violation(s): No

GEOCHECK VERSION 2.1 SUMMARY

PUBLIC WATER SUPPLY SYSTEM INFORMATION (EPA-FRDS)

Map ID: 6
PWS ID: NY0002817
PWS Name: BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Well currently has or has had major violation(s): No

Map ID: 6
PWS ID: NY0002817
PWS Name: BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Well currently has or has had major violation(s): No

Map ID: 9
PWS ID: NY0002829
PWS Name: HICKSVILLE WATER DISTRICT
4 DEAN STREET
HICKSVILLE, NY 11802

Well currently has or has had major violation(s): No

Map ID: 14
PWS ID: NY0002829
PWS Name: HICKSVILLE WATER DISTRICT
4 DEAN STREET
HICKSVILLE, NY 11802

Well currently has or has had major violation(s): No

Map ID: 15
PWS ID: NY0002832
PWS Name: LEVITTOWN WATER DISTRICT
1995 PROSPECT AVE.
EAST MEADOW, NY 11554

Well currently has or has had major violation(s): No

AREA RADON INFORMATION

NASSAU COUNTY, NY

Number of sites tested: 226

Area	Average Activity	% <4 pCi/L	% 4-20 pCi/L	% >20 pCi/L
Living Area	0.640 pCi/L	98%	2%	0%
Basement	1.100 pCi/L	98%	2%	0%

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404601073303602	Map ID:	1
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1950	County:	Nassau
Altitude:	148.00 ft.	State:	New York
Well Depth:	77.00 ft.	Topographic Setting:	Undulating
Depth to Water Table:	61.00 ft.	Prim. Use of Site:	Observation
Date Measured:	02011950	Prim. Use of Water:	Unused

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Mesozoic-Cretaceous-Upper
Principal Lithology of Unit:	Sand
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404601073303601	Map ID:	1
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1938	County:	Nassau
Altitude:	148.00 ft.	State:	New York
Well Depth:	80.00 ft.	Topographic Setting:	Undulating
Depth to Water Table:	79.00 ft.	Prim. Use of Site:	Observation
Date Measured:	10011938	Prim. Use of Water:	Unused

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Mesozoic-Cretaceous-Upper
Principal Lithology of Unit:	Sand
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404546073293701	Map ID:	2
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1986	County:	Nassau
Altitude:	1.00 ft.	State:	New York
Well Depth:	76.00 ft.	Topographic Setting:	Not Reported
Depth to Water Table:	Not Reported	Prim. Use of Site:	Observation
Date Measured:	Not Reported	Prim. Use of Water:	Other

LITHOLOGIC DATA

Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404539073291401	Map ID:	3
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	Not Reported	County:	Nassau
Altitude:	1.00 ft.	State:	New York
Well Depth:	76.00 ft.	Topographic Setting:	Not Reported
Depth to Water Table:	Not Reported	Prim. Use of Site:	Observation
Date Measured:	Not Reported	Prim. Use of Water:	Not Reported

LITHOLOGIC DATA

Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404526073301601	Map ID:	7
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1955	County:	Nassau
Altitude:	130.00 ft.	State:	New York
Well Depth:	150.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	55.00 ft.	Prim. Use of Site:	Withdrawal of water
Date Measured:	05011955	Prim. Use of Water:	Industrial

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Unknown
Principal Lithology of Unit:	Not Reported
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404526073301401	Map ID:	8
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1955	County:	Nassau
Altitude:	130.00 ft.	State:	New York
Well Depth:	150.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	55.00 ft.	Prim. Use of Site:	Withdrawal of water
Date Measured:	08011955	Prim. Use of Water:	Industrial

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Mesozoic-Cretaceous-Upper
Principal Lithology of Unit:	Sand
Further Description:	FINE GRAINED

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404520073301401	Map ID:	10
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	Not Reported	County:	Nassau
Altitude:	1.00 ft.	State:	New York
Well Depth:	77.00 ft.	Topographic Setting:	Not Reported
Depth to Water Table:	Not Reported	Prim. Use of Site:	Observation
Date Measured:	Not Reported	Prim. Use of Water:	Not Reported

LITHOLOGIC DATA

Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404517073310201	Map ID:	11
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1958	County:	Nassau
Altitude:	130.00 ft.	State:	New York
Well Depth:	629.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	52.00 ft.	Prim. Use of Site:	Withdrawal of water
Date Measured:	06011958	Prim. Use of Water:	Public supply

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Mesozoic-Cretaceous-Upper
Principal Lithology of Unit:	Sand
Further Description:	MED GRAINED

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404517073310101	Map ID:	11
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1958	County:	Nassau
Altitude:	130.00 ft.	State:	New York
Well Depth:	626.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	52.00 ft.	Prim. Use of Site:	Withdrawal of water
Date Measured:	06011958	Prim. Use of Water:	Public supply

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Unknown
Principal Lithology of Unit:	Not Reported
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404517073300901	Map ID:	12
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1959	County:	Nassau
Altitude:	125.00 ft.	State:	New York
Well Depth:	136.00 ft.	Topographic Setting:	Not Reported
Depth to Water Table:	Not Reported	Prim. Use of Site:	Withdrawal of water
Date Measured:	Not Reported	Prim. Use of Water:	Commercial

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Unknown
Principal Lithology of Unit:	Not Reported
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404507073301101	Map ID:	13
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1959	County:	Nassau
Altitude:	125.00 ft.	State:	New York
Well Depth:	136.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	60.00 ft.	Prim. Use of Site:	Withdrawal of water
Date Measured:	06011959	Prim. Use of Water:	Commercial

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Mesozoic-Cretaceous-Upper
Principal Lithology of Unit:	Sand
Further Description:	COARSE GRAINED

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404418073294502	Map ID:	16
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1948	County:	Nassau
Altitude:	95.00 ft.	State:	New York
Well Depth:	51.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	31.00 ft.	Prim. Use of Site:	Observation
Date Measured:	02011948	Prim. Use of Water:	Unused

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Cenozoic-Quaternary-Pleistocene
Principal Lithology of Unit:	Sand
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404418073294501	Map ID:	16
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1938	County:	Nassau
Altitude:	95.00 ft.	State:	New York
Well Depth:	54.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	29.00 ft.	Prim. Use of Site:	Observation
Date Measured:	02011939	Prim. Use of Water:	Unused

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Cenozoic-Quaternary-Pleistocene
Principal Lithology of Unit:	Sand
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404416073294601	Map ID:	17
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1960	County:	Nassau
Altitude:	96.00 ft.	State:	New York
Well Depth:	34.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	31.00 ft.	Prim. Use of Site:	Observation
Date Measured:	08011960	Prim. Use of Water:	Unused

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Cenozoic-Quaternary-Pleistocene
Principal Lithology of Unit:	Sand
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
FEDERAL DATABASE WELL INFORMATION

BASIC WELL DATA

Site ID:	404416073294602	Map ID:	17
Site Type:	Single well, other than collector or Ranney type		
Year Constructed:	1965	County:	Nassau
Altitude:	96.00 ft.	State:	New York
Well Depth:	44.00 ft.	Topographic Setting:	Flat surface
Depth to Water Table:	36.00 ft.	Prim. Use of Site:	Observation
Date Measured:	07011965	Prim. Use of Water:	Unused

LITHOLOGIC DATA

Geologic Age ID (Era/System/Series):	Cenozoic-Quaternary-Pleistocene
Principal Lithology of Unit:	Sand
Further Description:	Not Reported

WATER LEVEL VARIABILITY

Not Reported

GEOCHECK VERSION 2.1
STATE DATABASE WELL INFORMATION

Water Well Information:

Map ID:	4	Source ID:	017
Public Water Supply #:	2902829		
PW Supply Name:	HICKSVILLE WATER DISTRICT		
Source Name:	N 8778 WELL # 9-1		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404537	Longitude:	-733046
Source Prod Capacity:	1872000 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	00
Treatment Plant ID:	021	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

Map ID:	4	Source ID:	016
Public Water Supply #:	2902829		
PW Supply Name:	HICKSVILLE WATER DISTRICT		
Source Name:	N10208 WELL #9-3		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404537	Longitude:	-733046
Source Prod Capacity:	2304000 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	00
Treatment Plant ID:	021	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

Map ID:	4	Source ID:	018
Public Water Supply #:	2902829		
PW Supply Name:	HICKSVILLE WATER DISTRICT		
Source Name:	N 8779 WELL # 9-2		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404537	Longitude:	-733046
Source Prod Capacity:	1872000 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	00
Treatment Plant ID:	021	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

Map ID:	5	Source ID:	004
Public Water Supply #:	2902817		
PW Supply Name:	BETHPAGE WATER DISTRICT		
Source Name:	N 6078 WELL NO.9		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404537	Longitude:	-732848
Source Prod Capacity:	2016000 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	00
Treatment Plant ID:	010	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

GEOCHECK VERSION 2.1
STATE DATABASE WELL INFORMATION

Map ID:	6	Source ID:	003
Public Water Supply #:	2902817		
PW Supply Name:	BETHPAGE WATER DISTRICT		
Source Name:	N 8768 WELL NO.8A		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404533	Longitude:	-732848
Source Prod Capacity:	1728000 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	00
Treatment Plant ID:	010	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

Map ID:	6	Source ID:	002
Public Water Supply #:	2902817		
PW Supply Name:	BETHPAGE WATER DISTRICT		
Source Name:	N 8767 WELL NO.7A		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404532	Longitude:	-732848
Source Prod Capacity:	1728000 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	01
Treatment Plant ID:	010	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

Map ID:	9	Source ID:	015
Public Water Supply #:	2902829		
PW Supply Name:	HICKSVILLE WATER DISTRICT		
Source Name:	N 9180 WELL NO. 8-3		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404521	Longitude:	-733102
Source Prod Capacity:	1987200 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	00
Treatment Plant ID:	021	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

Map ID:	9	Source ID:	014
Public Water Supply #:	2902829		
PW Supply Name:	HICKSVILLE WATER DISTRICT		
Source Name:	N 6193 WELL # 8-2		
Source Description:	Groundwater		
Availability/Utilization:	Permanent Utilization	Source Type:	Source Record
Latitude:	404521	Longitude:	-733102
Source Prod Capacity:	1584000 Million Gals/Day	Fed ID of Seller:	Not Reported
Watershed Basin:	17	Watershed Sub-basin:	00
Treatment Plant ID:	021	Date of rec Last Update:	Not Reported
Water Type:	Not Reported	Record Tag:	Existing Record

GEOCHECK VERSION 2.1
STATE DATABASE WELL INFORMATION

Map ID:	9	Source ID:	013
Public Water Supply #:	2902829		
PW Supply Name:	HICKSVILLE WATER DISTRICT		
Source Name:	N 6192 WELL # 8-1		
Source Description:	Groundwater	Source Type:	Source Record
Availability/Utilization:	Permanent Utilization	Longitude:	-733102
Latitude:	404521	Fed ID of Seller:	Not Reported
Source Prod Capacity:	1584000 Million Gals/Day	Watershed Sub-basin:	00
Watershed Basin:	17	Date of rec Last Update:	Not Reported
Treatment Plant ID:	021	Record Tag:	Existing Record
Water Type:	Not Reported		

Map ID:	14	Source ID:	005
Public Water Supply #:	2902829		
PW Supply Name:	HICKSVILLE WATER DISTRICT		
Source Name:	N 8525 DISTRICT NO. 3-2		
Source Description:	Groundwater	Source Type:	Source Record
Availability/Utilization:	Permanent Utilization	Longitude:	-733057
Latitude:	404446	Fed ID of Seller:	Not Reported
Source Prod Capacity:	1728000 Million Gals/Day	Watershed Sub-basin:	00
Watershed Basin:	17	Date of rec Last Update:	Not Reported
Treatment Plant ID:	021	Record Tag:	Existing Record
Water Type:	Not Reported		

Map ID:	15	Source ID:	008
Public Water Supply #:	2902832		
PW Supply Name:	LEVITTOWN WATER DISTRICT		
Source Name:	N 4451 WELL #10 (NOT USED)		
Source Description:	Groundwater	Source Type:	Source Record
Availability/Utilization:	Permanent Utilization	Longitude:	-733053
Latitude:	404429	Fed ID of Seller:	Not Reported
Source Prod Capacity:	0	Watershed Sub-basin:	00
Watershed Basin:	17	Date of rec Last Update:	Not Reported
Treatment Plant ID:	013	Record Tag:	Existing Record
Water Type:	Not Reported		

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NY0002829 PWS Status: Active Map ID: 4
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: HICKSVILLE WATER DISTRICT
4 DEAN STREET
HICKSVILLE, NY 11802

Addressee / Facility: System Owner/Responsible Party
CUSICK GILBERT E
4 DEAN STREET
HICKSVILLE, NY 11801

Facility Latitude:	40 44 41	Facility Longitude:	073 32 09
Facility Latitude:	40 44 46	Facility Longitude:	073 30 57
Facility Latitude:	40 44 55	Facility Longitude:	073 32 03
Facility Latitude:	40 44 55	Facility Longitude:	073 32 49
Facility Latitude:	40 45 21	Facility Longitude:	073 31 02
Facility Latitude:	40 45 37	Facility Longitude:	073 30 46
Facility Latitude:	40 46 05	Facility Longitude:	073 31 43
Facility Latitude:	40 46 26	Facility Longitude:	073 32 31
Facility Latitude:	40 46 39	Facility Longitude:	073 31 11
Facility Latitude:	40 47 06	Facility Longitude:	073 30 52
City Served:	OYSTER BAY (T)		
Treatment Class	Not Reported	Population Served:	Not Reported

Well currently has or has had major violation(s): No

PWS ID: NY0002817 PWS Status: Active Map ID: 5
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Addressee / Facility: System Owner/Responsible Party
GRECO JR. SAL
BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Addressee / Facility: System Owner/Responsible Party
GRECO JR. SAL
BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Facility Latitude:	40 43 43	Facility Longitude:	073 28 41
Facility Latitude:	40 43 54	Facility Longitude:	073 29 12
Facility Latitude:	40 44 03	Facility Longitude:	073 28 31
Facility Latitude:	40 45 32	Facility Longitude:	073 28 48
Facility Latitude:	40 45 33	Facility Longitude:	073 28 48
Facility Latitude:	40 45 37	Facility Longitude:	073 28 48
City Served:	HEMPSTEAD & OYSTER B		
Treatment Class	Not Reported	Population Served:	Not Reported

Well currently has or has had major violation(s): No

GEOCHECK VERSION 2.1
PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NY0002817 PWS Status: Active Map ID: 6
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Addressee / Facility: System Owner/Responsible Party
GRECO JR. SAL
BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Addressee / Facility: System Owner/Responsible Party
GRECO JR. SAL
BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Facility Latitude:	40 43 43	Facility Longitude:	073 28 41
Facility Latitude:	40 43 54	Facility Longitude:	073 29 12
Facility Latitude:	40 44 03	Facility Longitude:	073 28 31
Facility Latitude:	40 45 32	Facility Longitude:	073 28 48
Facility Latitude:	40 45 33	Facility Longitude:	073 28 48
Facility Latitude:	40 45 37	Facility Longitude:	073 28 48
City Served:	HEMPSTEAD & OYSTER B		
Treatment Class	Not Reported	Population Served:	Not Reported

Well currently has or has had major violation(s): No

PWS ID: NY0002817 PWS Status: Active Map ID: 6
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Addressee / Facility: System Owner/Responsible Party
GRECO JR. SAL
BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Addressee / Facility: System Owner/Responsible Party
GRECO JR. SAL
BETHPAGE WATER DISTRICT
25 ADAMS AVENUE
BETHPAGE, NY 11714

Facility Latitude:	40 43 43	Facility Longitude:	073 28 41
Facility Latitude:	40 43 54	Facility Longitude:	073 29 12
Facility Latitude:	40 44 03	Facility Longitude:	073 28 31
Facility Latitude:	40 45 32	Facility Longitude:	073 28 48
Facility Latitude:	40 45 33	Facility Longitude:	073 28 48
Facility Latitude:	40 45 37	Facility Longitude:	073 28 48
City Served:	HEMPSTEAD & OYSTER B		
Treatment Class	Not Reported	Population Served:	Not Reported

Well currently has or has had major violation(s): No

GEOCHECK VERSION 2.1

PUBLIC WATER SUPPLY SYSTEM INFORMATION

PWS SUMMARY:

PWS ID: NY0002829 PWS Status: Active Map ID: 9
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: HICKSVILLE WATER DISTRICT
4 DEAN STREET
HICKSVILLE, NY 11802

Addressee / Facility: System Owner/Responsible Party
CUSICK GILBERT E
4 DEAN STREET
HICKSVILLE, NY 11801

Facility Latitude:	40 44 41	Facility Longitude:	073 32 09
Facility Latitude:	40 44 46	Facility Longitude:	073 30 57
Facility Latitude:	40 44 55	Facility Longitude:	073 32 03
Facility Latitude:	40 44 55	Facility Longitude:	073 32 49
Facility Latitude:	40 45 21	Facility Longitude:	073 31 02
Facility Latitude:	40 45 37	Facility Longitude:	073 30 46
Facility Latitude:	40 46 05	Facility Longitude:	073 31 43
Facility Latitude:	40 46 26	Facility Longitude:	073 32 31
Facility Latitude:	40 46 39	Facility Longitude:	073 31 11
Facility Latitude:	40 47 06	Facility Longitude:	073 30 52
City Served:	OYSTER BAY (T)		
Treatment Class	Not Reported	Population Served:	Not Reported

Well currently has or has had major violation(s): No

PWS ID: NY0002829 PWS Status: Active Map ID: 14
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: HICKSVILLE WATER DISTRICT
4 DEAN STREET
HICKSVILLE, NY 11802

Addressee / Facility: System Owner/Responsible Party
CUSICK GILBERT E
4 DEAN STREET
HICKSVILLE, NY 11801

Facility Latitude:	40 44 41	Facility Longitude:	073 32 09
Facility Latitude:	40 44 46	Facility Longitude:	073 30 57
Facility Latitude:	40 44 55	Facility Longitude:	073 32 03
Facility Latitude:	40 44 55	Facility Longitude:	073 32 49
Facility Latitude:	40 45 21	Facility Longitude:	073 31 02
Facility Latitude:	40 45 37	Facility Longitude:	073 30 46
Facility Latitude:	40 46 05	Facility Longitude:	073 31 43
Facility Latitude:	40 46 26	Facility Longitude:	073 32 31
Facility Latitude:	40 46 39	Facility Longitude:	073 31 11
Facility Latitude:	40 47 06	Facility Longitude:	073 30 52
City Served:	OYSTER BAY (T)		
Treatment Class	Not Reported	Population Served:	Not Reported

Well currently has or has had major violation(s): No

PWS ID: NY0002832 PWS Status: Active Map ID: 15
Date Initiated: Not Reported Date Deactivated: Not Reported
PWS Name: LEVITTOWN WATER DISTRICT
1995 PROSPECT AVE.
EAST MEADOW, NY 11554